Tremont Creek

K21849
REHAB MAP
Zone 6 - D1

Map Date: February 21, 2022

Perimeter Date: 2021-08-20
Hectares: 62523.6HA

120°50'0"W
120°45'0"W
N
51°4'30"N

TUNKWA PARK

Pull Back Berm
Pull Back Berm
Road cave in
Road cave in
Div A Equipment
MS 462 C-M VW
Decked Wood
Fence No Damage
Water Bar
Cross Ditch - Install
Pull Back
Decked Wood
Fence No Damage
Corduroy
Water Bar
Decked Wood
Pull Back
Decked Wood
Decked Wood
Decked Wood
Water Bar
Decked Wood
Decked Wood
Cross Ditch Install
Decked Wood
Cross Ditch Install
Decked Wood
Pull Back
Pull Back
Decked Wood
Decked Wood
Decked Wood
Decked Wood
Pull Back
Decked Wood
Decked Wood
Decked Wood
First Aid
Decked Wood
Pull Back
Pull Back
Decked Wood
Decked Wood
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Decked Wood
Decked Wood
Steep Slope
Decked Wood
Ditch Blocked - Sewer on Other Side of Rd
Tower
5+ Trees Ripped Up
Ditch Blocked - Clearing send Water Down to House
Slope
Could Have Water Issues
Guard Ends
Wetland
Pull Back
High Berm
Stream Crossing
Steep Slope
Helicopter Staging
Helicopter Staging

2 QPS Point [PTType]

PTType

- QPS Cleared Area
- Hazard
- Cross Ditch - Install (CDI)
- Culvert - Insert Wood (WC)
- Decked Wood (DW)
- Fence Damage - Point (FD)
- Fence No Damaged - Point (FND)
- High Berm (HB)
- Other Rehab Treatment Type
- Pull Back (PB)
- Steep Slope >35% (SS)
- Stream Crossing (SC)
- Unassigned
- Unique Point (UP)
- Water Bar (WB)
- Other-Rehab Treatment Type
- Pull Back (PB)
- Fireguard Machine Completed
- Road - Modified Existing
- Rehab - Requires Field Verification
- Rehab - Requires Field Verification
- Per Perimeter

- Trail
- Trail
- Trail
- Trails
- Highway
- Forest Service Road
- Road Permit
- Main Road
- Highway
- Road
- Pipeline
- Pipeline
- Pipeline
- Transmission Lines
- Transmission Line
- Transmission Line
- Transmission Line
- Stream
- Stream - Intermittent
- Lake
- Lake - Intermittent
- Reservoir
- Reservoir - Intermittent
- Wetland
- Freshwater
- Pipeline
- Pipeline
- Pipeline
- Transmission Line
- Failing or Gullied Terrain
- Potentially Unstable Terrain
- InterpretiveForestRecreationReserve
- O&G Facility
- Pipeline
- Pipeline
- Transmission Lines
- Transmission Line
- Transmission Line
- Transmission Line
- Climate Station
- Radio Towers
- Cellular Tower
- Radio Tower
- Groudwater Well
- Dam
- Archaeological Site
- Water Development
- Fence
- Skid Trail
- Fish - Observed
- Lake
- Lake - Intermittent
- Reservoir
- Reservoir - Intermittent
- BC Park, Protected Area, Eco Reserve
- Regional & Local Parks
- Private
- Mixed Ownership
- Federal
- Municipal
- Crown Agency
- Unknown
- Private
- Crown Municipal
- Crown Federal

Index Map



This map may contain CONFIDENTIAL information: for INTERNAL use only

Disclaimer:
Wildfire perimeters for the current fire season, including the date of the most recent update, are derived from various sources. The data is extracted from operational systems, nightly to the public map. Wildfire data may not reflect the most current information and therefore should only be used for reference purposes.

Wildfire data from the incident is updated when perimeters and the occurrence of individual fire updates. Wildfire data is provided for reference and planning purposes only and should not be relied on as accurate. Wildfire data is subject to change without notice and change quickly. The levels of current fire activity within the mapped fire perimeters can vary widely.

Data Sources and Notes:

Projection: NAD 1983 BC Environment Albers
Created by: jrpardon

Province of British Columbia

Ministry of Forests, Lands, Natural Resource Operations and Rural Development
BC Wildfire Service

Document Path: Y:\incSeason\Work\2021\Maps\pdf\K21849\K21849_Rehab_36x48L.mxd