120°55'0"W

120°50'0"W

50°45'0"N

N

Restore Draw

Track 65

Leighton Farm

Leighton

Track 66

Stream Crossing

Track 67

Stream Crossing

Clean Stream Of Introduced Debris

Track 71

Tree in way

Track 70

Safety Zone

Track 73

Restore Draw

Track 72

Restore Draw

Track 90

Track 87

Track 85

Track 86

Track 84

Track 83

Track 82

Track 81

Stream Crossing

Line 4

Track 88

Track 89

Fence Damage

45%30m

35% 20m

Restore Draw

Restore/ Widen Prior To Rip

Track 88

Track 80

Track 79

Track 78

Track 77

Bunched Sx

Stream Crossing

Tight line to Culvocs

Track 76

North Dozer Guard Parking

First Aid

Mid Section

Restore Draw

Stream Crossing

Track 75

Safety Zone

43%12m

48%10m

45%10m

Track 74

45%10m

50% 10m

Stream Crossing

Track 62

35%20m

Restore Draw

49% 10m

36% 10m

Track 63

Stream Crossing

Stream Crossing

Track 63

Track 64

Stream Crossing

Track 54

Tunkwa Lake

ATunkwa

Div. A Tunkwa

Telus 6

MS 462 C-M VW

Track 91

30%20m

46%30m

Restore Draw

50%10m

Pull Back Berm

Pull Back Berm

Road cave in

BOSE HILL

Index Map



This map may contain CONFIDENTIAL information: for INTERNAL use only

Disclaimer:
Fire perimeters for the current fire season, including both active and inactive fires, are supplied from various sources. The data is refreshed from operational systems on a daily basis. The perimeters are the best data for the current fire situation, and therefore should only be used for reference purposes.

Accuracy: The incident is updated when perimeters are the occurrence of individual fire updates will vary. The information is intended for general reference purposes only. Due to the inherent nature of fire/area, fires are dynamic and circumstances may change quickly. The levels of current fire activity within the mapped fire perimeters can vary widely.

Data Sources and Notes:

Projection: NAD 1983 BC Environment Albers
Created by: pcambon

Ministry of Forests, Lands, Natural Resource Operations and Rural Development
BC Wildfire Service

Tremont Creek

K21849
REHAB MAP

Zone T - B1

Map Date: February 21, 2022

Perimeter Date:2021-08-20
Hectares: 62523.6HA

2 OPS Point [PTType]
PTType
- OPS Cleared Area
- Water Source
- Valve
- Cross Ditch - Install (CDI)
- Decked Wood (DW)
- Fence Damage - Point (FD)
- Other Rehab Treatment Type
- Pull Back (PB)
- Restore Draw (RD)
- Safety Zone (SZ)
- Staging Area (SA)
- Steep Slope >35% (SS)
- Stream Crossing (SC)
- Unassigned

- Other Rehab Treatment Type
- Pull Back (PB)
- Recontour (RC)
- Fireguard Manual Completed
- Fireguard Machine Completed
- Road - Modified Existing
- Rehab - Requires Field Verification
- Rehab - Requires Field Verification
- Fire Perimeter

- Trail
- Trail
- Trails
- Forest Service Road
- Road Permit
- Main Road
- Road
- Pipeline
- Pipeline
- Pipeline
- Transmission Lines
- Transmission Line
- Transmission Line
- Stream
- Stream - Intermittent
- Lake
- Lake - Intermittent
- Wetland
- Freshwater
- Pipeline
- Pipeline
- Pipeline
- Failing or Gullied Terrain
- Potentially Unstable Terrain
- Campsite
- Day Use
- O&G Facility
- Pipeline
- Pipeline
- Transmission Lines
- Transmission Line
- Transmission Line
- Climate Station
- Weather Station
- Weather Station
- Groundwater Well
- Dam
- Archaeological Site
- Legacy Archaeological Site
- Fence
- Stock Trail
- Fish - Observed
- Lake
- Lake - Intermittent
- BC Park, Protected Area, Eco Reserve
- Private
- Crown Agency
- Private