



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 1 of 3
Date Printed: 2015/11/19
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-307	Site #:	G6-307	Road Name:	PARSNIP WEST	Inspection Date:	2015/08/24
KM:	81.60	User km:		Crossing Name:	UNK	Next Inspection Date:	2018/08/24
Project File ID #:	6143	Br.	01	Forest District:	Mackenzie Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Superstructure	Concrete Slab Girders			Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad		
Total Length (metres):	10.0	# Spans:	1	Span Length(s) (metres):	10		
UTM Zone:	10	UTM Easting:	455076	UTM Northing:	6193652		
Inspector Name:	Knut Herzog			Year Superstructure Installed:	2006		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Road Surface	Good	

DECK


Span 1

Concrete Deck	Good	
---------------	------	--

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.





BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 2 of 3
Date Printed: 2015/11/19
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-307	Site #:	G6-307	Road Name:	PARSNIP WEST	Inspection Date:	2015/08/24
--------------	--------	---------	--------	------------	--------------	------------------	------------

Curb Rail/Blocks/Posts	Good	
Deck Joints	Good	
Grout Pockets	Good	
Grout Pockets	Good	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Not Applicable	
Hardware	Not Applicable	
Welded/grouted shear connect	Good	

CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.5
	Estimated High Water Level Clearance:	1.5		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									


REPAIRS	#	Status	Priority	Estimate	Description

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.





BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 3 of 3
Date Printed: 2015/11/19
User Id: IDIR\JOLMSTED
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-307	Site #:	G6-307	Road Name:	PARSNIP WEST	Inspection Date:	2015/08/24
GENERAL	Inspector's Comment:	Good bridge					
	Replacement Date for full log haul traffic (year):			2050	Replacement Date for light vehicle traffic (year):		
	Current Inspection Load Rating:	91.00	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Accepted By Jason Olmsted on 11/19/2015 2:27:55PM			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.