BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status:Inspect Management Area: 53 Sort: Forest Service Road Site Status:Active

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length *(metres)*	# Piers	Road Name	KM	User KM	Crossing Name
	Special Equipment Required	**Special Access Required**	**Planned Inspection Comment**									
1	N3-105	WO-2416	2020/09/10	2022/09/10	T	7507-02	15.2	0	-THOMPSON FALLS FSR	7.70	7.70	Unnamed
2	N3-074	N3-074	2019/08/28	2022/08/28	P	8566-01	17.3	0	12 MILE FSR	0.74	3.30	CANYON Cr
3	N3-075	N3-075	2019/08/28	2022/08/28	P	8566-01	14.0	0	12 MILE FSR	5.22	5.20	TWELVE MILE Cr
4	N3-001	N3-001	2019/08/28	2022/08/28	P	4170-01	16.5	0	BEAVERFOOT	3.00	4.30	WASHOUT Cr
5	N3-083	N3-083	2019/08/28	2022/08/28	P	4170-01	16.0	0	BEAVERFOOT	9.07	10.30	FRASER Cr
6	N3-002	N3-002	2019/08/28	2022/08/28	P	4170-01	11.6	0	BEAVERFOOT	38.74	39.10	THOMAS Cr
			IDIR\JRUPAR on 24-JAN-20: JRG Jan 24, 2020 Record cap rotation at every inspection.									
7	N3-003	PS-007	2020/09/10	2022/09/10	T	4170-01	15.2	0	BEAVERFOOT	42.47	42.90	PAUL Cr
			CBR_Conversion on 27-FEB-17: N/A									
8	N3-004	WO5960	2020/09/10	2022/09/10	T	4170-01	24.4	0	BEAVERFOOT	47.06	47.10	SYMOND Cr

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status:Inspect Management Area: 53 Sort: Forest Service Road Site Status:Active

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length *(metres)*	# Piers	Road Name	KM	User KM	Crossing Name
	Special Equipment Required	**Special Access Required**	**Planned Inspection Comment**									
			IDIR\DMALWAY on 03-OCT-14: .									
9	N3-107	TOC-0001	2020/09/10	2022/09/10	T	7521-03	6.1	0	BLACKWATER RIDGE	17.00	25.70	Unnamed
			CBR_Conversion on 27-FEB-17: n/a									
10	N3-108	908832890	2020/09/10	2022/09/10	T	7521-03	12.2	0	BLACKWATER RIDGE	19.50		Susan Lk Cr
			CBR_Conversion on 20-FEB-17: na									
11	N3-007	N3-007	2019/08/28	2022/08/28	P	7507-01	7.6	0	BLAEBERRY FSR	0.69	13.30	WILLOW BANK Cr
			IDIR\JRUPAR on 24-JAN-20: JRG Jan 24, 2020 Record lock block rotation at both abutments at every inspection.									
12	N3-008	N3-008	2019/08/29	2022/08/29	P	7507-01	11.6	0	BLAEBERRY FSR	7.77	20.40	Trapper Cr
13	N3-009	N3-009	2019/08/29	2022/08/29	P	7507-01	11.6	0	BLAEBERRY FSR	9.22	22.10	Unnamed
14	N3-010	N3-010	2019/08/29	2022/08/29	P	7507-01	18.3	0	BLAEBERRY FSR	10.08	10.00	BLAEBERRY R #2
			IDIR\JRUPAR on 24-JAN-20: JRG Jan 24, 2020 Record depth and extent of left abutment scour at each inspection.									
15	N3-011	N3-011	2019/08/29	2022/08/29	P	7507-01	15.4	0	BLAEBERRY FSR	11.52	25.60	SPLIT Cr

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status:Inspect Management Area: 53 Sort: Forest Service Road Site Status:Active

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length *(metres)*	# Piers	Road Name	KM	User KM	Crossing Name
	Special Equipment Required	**Special Access Required**	**Planned Inspection Comment**									
16	N3-037	N3-037	2019/08/29	2022/08/29	MC	9699-01	24.0	0	BLUEWATER CREEK FSR	4.07	41.00	WHITE PINE Cr
17	N3-096	N3-096	2019/08/28	2022/08/28	P	4170-06	18.3	0	BRANCH 19.4	0.21	19.60	Unnamed
18	N3-106	WO-454	2020/09/11	2022/09/11	T	7521-18	18.3	0	BUSH - BR 28	0.26		Succour Cr
			CBR_Conversion on 04-NOV-14: .									
19	N3-018	N3-018	2019/09/09	2022/09/09	P	7521-01	46.0	0	BUSH RIVER	0.40	3.30	WAITABIT R
	Peeper Truck		IDIR\MIPENNER on 18-FEB-19: . IDIR\MIPENNER on 15-OCT-14: 3 year inspection interval seems too long, and bearing monitoring should start in 2015, therefore have set next insp									
20	N3-021	N3-021	2019/08/29	2022/08/29	MC	7521-01	37.0	0	BUSH RIVER	7.75	10.70	BLACKWATER Cr
			IDIR\DMALWAY on 22-FEB-17: Do the same detailed measure up in 2019 of the three sections and the bolt tearing location mapping.									
21	N3-027	N3-027	2019/08/29	2022/08/29	P	7521-01	13.3	0	BUSH RIVER	45.93	57.50	HOPE Cr
			CBR_Conversion on 17-FEB-14: measure curb riser spacing as they do not appear to meet ministry standard, on next inspection. DA. Feb 2014									
22	N3-024	N3-024A	2019/08/29	2022/08/29	P	7521-01	15.3	0	BUSH RIVER	48.70	52.00	Unnamed

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status:Inspect Management Area: 53 Sort: Forest Service Road Site Status:Active

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length *(metres)*	# Piers	Road Name	KM	User KM	Crossing Name
	Special Equipment Required	**Special Access Required**	**Planned Inspection Comment**									
23	N3-029	N3-029	2019/08/30	2022/08/30	P	7521-01	33.2	1	BUSH RIVER	67.40	71.50	VALENCIENNES R
24	N3-030	N3-030	2019/09/09	2022/09/09	P	7521-01	34.0	1	BUSH RIVER	73.00	73.50	BUSH R
	Peeper Truck		IDIR\JRUPAR on 09-MAY-19: JRG May 9, 2019 Thoroughly inspect timber substructure components during next close proximity inspection. Perform inspection at low water to access pier piles below sheathing.									
25	N3-023	N3-023	2019/08/29	2022/08/29	MC	7521-01	18.2	0	BUSH RIVER	77.50	26.80	SUMMIT Cr
26	N3-032	N3-032	2019/08/30	2022/08/30	P	7521-01	15.5	0	BUSH RIVER	86.10	90.80	CAMP DAVID Cr
			IDIR\JRUPAR on 28-JAN-20: JRG Jan 28, 2020 Monitor loss of rip rap at left abutment. Take photos of issue at each inspection.									
27	N3-019	N3-019	2019/08/29	2022/08/29	MC	7521-01	20.2	0	BUSH RIVER	101.9	2.20	MARL Cr
28	N3-055	N3-055	2020/10/02	2021/05/15	P	7663-01	84.2	2	COLUMBIA RIVER WEST	4.90	4.90	BEAVERMOUTH
	Peeper Truck		CBR_Conversion on 27-APR-21: JRG Apr 27, 2021 Annual close proximity inspection required to monitor condition of span 1 downstream girder.									
29	N3-056	N3-056	2019/08/30	2022/08/30	MC	7663-01	26.0	0	COLUMBIA RIVER WEST	8.30	8.30	Unnamed

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status:Inspect Management Area: 53 Sort: Forest Service Road Site Status:Active

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length *(metres)*	# Piers	Road Name	KM	User KM	Crossing Name
	Special Equipment Required	**Special Access Required**	**Planned Inspection Comment**									
30	N3-057	N3-057	2019/08/30	2022/08/30	P	7663-01	27.4	0	COLUMBIA RIVER WEST	14.60	14.60	Schlichting Cr
31	N3-059	N3-059	2019/08/30	2022/08/30	MC	7663-01	36.0	0	COLUMBIA RIVER WEST	17.60	17.60	Unnamed
			IDIR\JRUPAR on 30-JAN-20: JRG Jan 30, 2020 Record inlet and outlet cover depths at next inspection.									
32	N3-109	N3-109	2019/08/30	2022/08/30	MC	7663-01	18.5	0	COLUMBIA RIVER WEST	23.50	23.50	unnamed
33	N3-060	N3-060	2019/08/30	2022/08/30	MC	7663-01	28.0	0	COLUMBIA RIVER WEST	27.70	27.70	Unnamed
34	N3-099	N3-099	2021/09/18	2022/09/18	MC	7663-01	16.0	0	COLUMBIA RIVER WEST	50.50	50.50	Unnamed
			CBR_Conversion on 11-SEP-14: .									
35	N3-064	N3-064	2021/09/18	2022/09/18	T	7663-01	12.0	0	COLUMBIA RIVER WEST	64.00	64.20	SWAN Cr
			IDIR\DMALWAY on 28-JAN-22: BP Jan 28-22 Ensure 5 tonne load posting signs are in place IDIR\JRUPAR on 22-FEB-19: JRG Feb 22 2019 Record rot depth, location, and type (sap/heart) in crib members.									
36	N3-085	N3-085	2021/07/30	2022/07/30	P	3461-01	12.2	0	DONALD FSR	13.98	13.70	CIRQUE Cr

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status:Inspect Management Area: 53 Sort: Forest Service Road Site Status:Active

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length *(metres)*	# Piers	Road Name	KM	User KM	Crossing Name
	Special Equipment Required	**Special Access Required**	**Planned Inspection Comment**									
			IDIR\JRUPAR on 04-APR-22: DA March 2022, Ensure bridge is posted for 5 tonnes.									
37	N3-091	N3-091	2019/08/29	2022/08/29	P	7521-07	12.2	0	HOPE	5.50	5.40	Unnamed
			IDIR\DMALWAY on 13-JAN-16: ensure posted at 5 tonnes load restriction. Determine level of deck rot in more detail, drill required. for 2017 inspection. ATV required for access									
38	N3-087	N3-087	2019/08/28	2022/08/28	P	4170-03	18.3	0	MOOSE	7.14	2.50	BEAVERFOOT R
39	N3-090	N3-090	2021/07/28	2022/07/28	MC	4170-03	14.6	0	MOOSE	13.62	8.20	Unnamed
40	N3-089	N3-089	2019/08/28	2022/08/28	P	4170-03	18.3	0	MOOSE	13.89	8.90	MOOSE Cr
			IDIR\JRUPAR on 31-JAN-20: JRG Jan 31, 2020 Record the angle of the R/B U/S pipe column at every inspection.									
41	N3-073	N3-073A	2019/08/30	2022/08/30	P	0763-01	15.6	0	QUARTZ CREEK FSR	5.57	5.70	Wiseman Lake Cr
			CBR_Conversion on 17-FEB-14: Ensure to get better pictures of rip on L/B, downstream. At time of original installation a repair was required at this spot. DA Feb 2014.									
42	N3-036	N3-036A	2019/08/29	2022/08/29	P	7521-06	8.6	0	RED	0.00	33.00	SUCCOUR Cr
			CBR_Conversion on 22-FEB-17: Needs a site ID number plate. DA									
43	N3-045	N3-045	2019/08/29	2022/08/29	P	7521-05	24.4	0	SULLIVAN	7.80	73.10	CHATTER Cr

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status:Inspect Management Area: 53 Sort: Forest Service Road Site Status:Active

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length *(metres)*	# Piers	Road Name	KM	User KM	Crossing Name
	Special Equipment Required	**Special Access Required**	**Planned Inspection Comment**									
44	N3-115	WO 6521	2020/09/11	2022/09/11	T	7521-05	9.1	0	SULLIVAN	21.30	82.50	unnamed
			IDIR\DMALWAY on 22-FEB-19: JRG Feb 22, 2019 Notable active channel. Monitor creek bedload and measure from underside of upstream girder to thalweg at each inspection.									
45	N3-112	WO2702	2020/09/11	2022/09/11	T	7521-05	12.2	0	SULLIVAN	22.40	83.60	unnamed
			IDIR\DMALWAY on 22-FEB-19: JRG Feb 22, 2019 Notable active channel. Monitor creek bedload and measure from underside of upstream girder to thalweg at each inspection.									
46	N3-050	N3-050	2019/08/29	2022/08/29	MC	7521-05	20.0	0	SULLIVAN	22.49	96.50	Nixon Cr
			CBR_Conversion on 31-JAN-20: .									
47	N3-053	N3-053	2020/09/11	2022/09/11	T	7521-05	39.7	0	SULLIVAN	44.50	105.90	BOULDER Cr
48	N3-044	N3-044	2019/09/09	2022/09/09	P	7521-05	25.9	0	SULLIVAN	51.65	68.20	PRATTLE Cr
	Peeper Truck		CBR_Conversion on 17-FEB-14: Try to inspect at low water, check with district or primary RUP holder to determine best time. Close Proximity inspection completed in 2012, next planned peeper inspection in 2017. DA									
49	N3-043	N3-043	2019/08/29	2022/08/29	P	7521-05	45.6	1	SULLIVAN	57.11	66.40	BUSH R
	Peeper Truck		IDIR\DMALWAY on 19-APR-22: Close proximity can be completed every 10 years for this bridge. IDIR\JRUPAR on 31-JAN-20: JRG Jan 31, 2020 Check size of ties at next inspection.									
50	N3-054	N3-054	2019/08/29	2022/08/29	P	7521-02	12.6	0	SUSAN LAKE	18.28	15.20	BLACKWATER Cr

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status:Inspect Management Area: 53 Sort: Forest Service Road Site Status:Active

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length *(metres)*	# Piers	Road Name	KM	User KM	Crossing Name
	Special Equipment Required	**Special Access Required**	**Planned Inspection Comment**									
51	N3-113	N3-113	2019/08/30	2022/08/30	MC	7521-02	19.0	0	SUSAN LAKE	18.54	32.70	Susan Lake Creek

Permanent Bridge Total: 29 **Temporary Bridge Total: 10** **Major Culvert Total: 12** **Woodbox/Log Culvert Total: 0**