



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 1 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-004

Site #:	N2-004	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	13.54	User km:	13.80	Last Inspection Date:	2019/10/02
Project File ID #:	0001	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	BUGABOO CREEK				
Crossing Name:	BUGABOO Cr		Total Length (metres):	30.4	
Special Access:			Special Equipment:		
Longitude:	-116 30 5.0		Latitude:	50 51 25.0	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 28-FEB-17: Document WO # on steel				

Structure Name: N2-005

Site #:	N2-005	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	20.77	User km:	21.20	Last Inspection Date:	2019/10/02
Project File ID #:	0001	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	BUGABOO CREEK				
Crossing Name:	KAIN Cr		Total Length (metres):	12.6	
Special Access:			Special Equipment:		
Longitude:	-116 35 37.0		Latitude:	50 51 50.0	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans: 1
Planned Inspection Comments:					

Structure Name: N2-006

Site #:	N2-006	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	28.81	User km:	29.40	Last Inspection Date:	2019/10/02
Project File ID #:	0001	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	BUGABOO CREEK				
Crossing Name:	ROCKY POINT Cr		Total Length (metres):	11.6	
Special Access:			Special Equipment:		
Longitude:	-116 40 13.6		Latitude:	50 49 5.6	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 2 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-007

Site #:	N2-007	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	31.08	User km:	31.60	Last Inspection Date:	2019/10/02
Project File ID #:	0001	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	BUGABOO CREEK				
Crossing Name:	Unnamed		Total Length (metres):	11.6	
Special Access:			Special Equipment:		
Longitude:	-116 40 58.0		Latitude:	50 48 2.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-234

Site #:	N2-234	Year Superstructure Installed:	2021	Structure Type/Class:	Permanent Bridge
KM:	31.50	User km:	32.00	Last Inspection Date:	
Project File ID #:	0001	Br.	01	Next Inspection Date:	2022/08/08
Road Name:	BUGABOO CREEK				
Crossing Name:	unknown		Total Length (metres):	8.0	
Special Access:			Special Equipment:		
Longitude:	-116 41 1.8		Latitude:	50 47 55.9	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-008

Site #:	N2-008	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	34.86	User km:	35.50	Last Inspection Date:	2019/10/02
Project File ID #:	0001	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	BUGABOO CREEK				
Crossing Name:	Unnamed		Total Length (metres):	8.6	
Special Access:			Special Equipment:		
Longitude:	-116 41 58.0		Latitude:	50 46 13.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 3 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-009

Site #:	N2-009	Year Superstructure Installed:	1991	Structure Type/Class:	Permanent Bridge
KM:	37.00	User km:	38.00	Last Inspection Date:	2019/10/02
Project File ID #:	0001	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	BUGABOO CREEK				
Crossing Name:	BUGABOO Cr		Total Length (metres):	16.3	
Special Access:			Special Equipment:		
Longitude:	-116 42 6.0		Latitude:	50 45 11.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-015

Site #:	N2-015	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	0.77	User km:	8.40	Last Inspection Date:	2019/10/02
Project File ID #:	0001	Br.	04	Next Inspection Date:	2022/10/02
Road Name:	BUGABOO-TEMPLETON				
Crossing Name:	TEMPLETON Cr		Total Length (metres):	10.6	
Special Access:			Special Equipment:		
Longitude:	-116 27 17.7		Latitude:	50 49 8.4	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-016

Site #:	N2-016	Year Superstructure Installed:	1992	Structure Type/Class:	Temporary Bridge
KM:	5.10	User km:	13.40	Last Inspection Date:	2020/09/14
Project File ID #:	0001	Br.	04	Next Inspection Date:	2022/09/14
Road Name:	BUGABOO-TEMPLETON				
Crossing Name:	TEMPLETON Cr		Total Length (metres):	12.3	
Special Access:			Special Equipment:		
Longitude:	-116 30 2.9		Latitude:	50 48 36.6	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 4 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-170

Site #:	N2-170	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	0.12	User km:	37.10	Last Inspection Date:	2019/10/02
Project File ID #:	0001	Br.	17	Next Inspection Date:	2022/10/02
Road Name:	BUGABOO-CHALICE				
Crossing Name:	BUGABOO Cr		Total Length (metres):	20.6	
Special Access:			Special Equipment:		
Longitude:	-116 42 4.2		Latitude:	50 45 27.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-172

Site #:	N2-172	Year Superstructure Installed:	1996	Structure Type/Class:	Temporary Bridge
KM:	0.17	User km:	42.00	Last Inspection Date:	2020/09/14
Project File ID #:	0001	Br.	19	Next Inspection Date:	2022/09/14
Road Name:	BUGABOO-RANGE				
Crossing Name:	SEPTET Cr		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-116 39 36.8		Latitude:	50 47 4.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: TKO-0013

Site #:	N2-215	Year Superstructure Installed:	2000	Structure Type/Class:	Temporary Bridge
KM:	2.10	User km:	42.00	Last Inspection Date:	2020/09/14
Project File ID #:	0001	Br.	24	Next Inspection Date:	2022/09/14
Road Name:	CR0001.24 SEPTET FAL				
Crossing Name:	Septet Creek		Total Length (metres):	17.1	
Special Access:			Special Equipment:		
Longitude:	-116 40 45.2		Latitude:	50 47 47.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 09-MAR-17: na				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 5 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: TKO-0021

Site #:	N2-227	Year Superstructure Installed:	2018	Structure Type/Class:	Temporary Bridge
KM:	3.00	User km:	3.00	Last Inspection Date:	2020/09/14
Project File ID #:	0001	Br.	25	Next Inspection Date:	2022/09/14
Road Name:	BUGABOO SPUR 14000				
Crossing Name:	unnamed		Total Length (metres):	14.7	
Special Access:			Special Equipment:		
Longitude:	-116 32 33.9		Latitude:	50 51 10.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: TKO-0036

Site #:	N2-237	Year Superstructure Installed:	2021	Structure Type/Class:	Temporary Bridge
KM:	6.10	User km:	6.10	Last Inspection Date:	
Project File ID #:	0001	Br.	25	Next Inspection Date:	2022/08/01
Road Name:	BUGABOO SPUR 14000				
Crossing Name:	unnamed		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-116 34 53.4		Latitude:	50 51 26.1	
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-165

Site #:	N2-229	Year Superstructure Installed:	2019	Structure Type/Class:	Temporary Bridge
KM:	0.30	User km:		Last Inspection Date:	2011/10/04
Project File ID #:	0001	Br.	27	Next Inspection Date:	2022/08/19
Road Name:	KAIN SPUR 1000				
Crossing Name:	Kain Creek		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-116 36 8.7		Latitude:	50 52 35.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 6 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N2-067

Site #:	N2-067	Year Superstructure Installed:	1979	Structure Type/Class:	Major Culvert
KM:	23.31	User km:	23.20	Last Inspection Date:	2019/10/03
Project File ID #:	0105	Br.	01	Next Inspection Date:	2022/10/03
Road Name:	KOOTENAY RIVER				
Crossing Name:	MARY-ANNE Cr	Total Length (metres):	24.3		
Special Access:		Special Equipment:			
Longitude:	-115 41 21.4	Latitude:	50 18 45.5		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: N2-070

Site #:	N2-070	Year Superstructure Installed:	1990	Structure Type/Class:	Temporary Bridge
KM:	43.91	User km:	43.90	Last Inspection Date:	2020/10/05
Project File ID #:	0105	Br.	01	Next Inspection Date:	2022/10/05
Road Name:	KOOTENAY RIVER				
Crossing Name:	FENWICK Cr	Total Length (metres):	14.3		
Special Access:		Special Equipment:			
Longitude:	-115 37 48.6	Latitude:	50 27 38.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-101

Site #:	N2-101	Year Superstructure Installed:	1989	Structure Type/Class:	Permanent Bridge
KM:	23.66	User km:	36.10	Last Inspection Date:	2019/10/03
Project File ID #:	0105	Br.	03	Next Inspection Date:	2022/10/03
Road Name:	KOOTENAY-SETTLERS				
Crossing Name:	PEDLEY Cr	Total Length (metres):	12.3		
Special Access:		Special Equipment:			
Longitude:	-115 40 1.0	Latitude:	50 26 18.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 7 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-089A

Site #:	N2-089	Year Superstructure Installed:	2012	Structure Type/Class:	Permanent Bridge
KM:	1.21	User km:	13.50	Last Inspection Date:	2019/10/03
Project File ID #:	0105	Br.	04	Next Inspection Date:	2022/10/03
Road Name:	KOOTENAY-PALLISER				
Crossing Name:	KOOTENAY R		Total Length (metres):	69.3	
Special Access:			Special Equipment:	Peeper Truck	
Longitude:	-115 48 11.0		Latitude:	50 36 51.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): <i>(looking downstream)</i>	Concrete Cast in	# Spans:	3
Planned Inspection Comments:	CBR_Conversion on 06-MAR-17: Peep truck is only required every 10 years, mostly to ensure piers are fine and check splices etc. DA.				

Structure Name: N2-091

Site #:	N2-091	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	24.41	User km:	36.80	Last Inspection Date:	2019/10/03
Project File ID #:	0105	Br.	04	Next Inspection Date:	2022/10/03
Road Name:	KOOTENAY-PALLISER				
Crossing Name:	PALLISER R		Total Length (metres):	33.5	
Special Access:			Special Equipment:		
Longitude:	-115 37 25.4		Latitude:	50 31 19.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): <i>(looking downstream)</i>	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-176

Site #:	N2-176	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	40.24	User km:	51.00	Last Inspection Date:	2019/10/03
Project File ID #:	0105	Br.	04	Next Inspection Date:	2022/10/03
Road Name:	KOOTENAY-PALLISER				
Crossing Name:	Unnamed		Total Length (metres):	11.6	
Special Access:			Special Equipment:		
Longitude:	-115 25 42.7		Latitude:	50 30 53.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): <i>(looking downstream)</i>	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 8 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-092

Site #:	N2-092	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	42.68	User km:	55.20	Last Inspection Date:	2019/10/03
Project File ID #:	0105	Br.	04	Next Inspection Date:	2022/10/03
Road Name:	KOOTENAY-PALLISER				
Crossing Name:	LODGEPOLE Cr	Total Length (metres):	9.6		
Special Access:		Special Equipment:			
Longitude:	-115 23 49.8	Latitude:	50 30 27.6		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-223A

Site #:	N2-223	Year Superstructure Installed:	2018	Structure Type/Class:	Permanent Bridge
KM:	56.50	User km:	56.50	Last Inspection Date:	2019/10/03
Project File ID #:	0105	Br.	04	Next Inspection Date:	2022/10/03
Road Name:	KOOTENAY-PALLISER				
Crossing Name:	unnamed	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-115 21 36.6	Latitude:	50 30 58.4		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-226

Site #:	N2-226	Year Superstructure Installed:	2018	Structure Type/Class:	Permanent Bridge
KM:	59.00	User km:		Last Inspection Date:	2019/10/03
Project File ID #:	0105	Br.	04	Next Inspection Date:	2022/10/03
Road Name:	KOOTENAY-PALLISER				
Crossing Name:	unknown	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-115 20 3.5	Latitude:	50 31 39.5		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 9 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N2-225

Site #:	N2-225	Year Superstructure Installed:	2018	Structure Type/Class:	Permanent Bridge
KM:	61.00	User km:	61.00	Last Inspection Date:	2019/10/03
Project File ID #:	0105	Br.	04	Next Inspection Date:	2022/10/03
Road Name:	KOOTENAY-PALLISER				
Crossing Name:	unknown	Total Length (metres):	15.2		
Special Access:		Special Equipment:			
Longitude:	-115 18 53.5	Latitude:	50 32 24.9		
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-082

Site #:	N2-082	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	6.78	User km:	19.50	Last Inspection Date:	2019/10/12
Project File ID #:	0105	Br.	05	Next Inspection Date:	2022/10/12
Road Name:	KOOTENAY-EASTSIDE				
Crossing Name:	NINE MILE Cr	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-115 40 48.0	Latitude:	50 13 57.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-073A

Site #:	N2-073	Year Superstructure Installed:	2020	Structure Type/Class:	Permanent Bridge
KM:	5.42	User km:	46.80	Last Inspection Date:	
Project File ID #:	0105	Br.	07	Next Inspection Date:	2022/08/18
Road Name:	KOOTENAY-ALBERT				
Crossing Name:	Unnamed	Total Length (metres):	15.3		
Special Access:		Special Equipment:			
Longitude:	-115 33 35.1	Latitude:	50 33 59.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 10 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N2-074

Site #:	N2-074	Year Superstructure Installed:	1992	Structure Type/Class:	Permanent Bridge
KM:	10.62	User km:	52.10	Last Inspection Date:	2019/10/03
Project File ID #:	0105	Br.	07	Next Inspection Date:	2022/10/03
Road Name:	KOOTENAY-ALBERT				
Crossing Name:	Unnamed	Total Length (metres):	11.3		
Special Access:		Special Equipment:			
Longitude:	-115 33 13.3	Latitude:	50 36 35.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-084

Site #:	N2-084	Year Superstructure Installed:	1990	Structure Type/Class:	Temporary Bridge
KM:	4.35	User km:	25.50	Last Inspection Date:	2021/09/26
Project File ID #:	0105	Br.	09	Next Inspection Date:	2022/09/26
Road Name:	KOOTENAY-NINE MILE				
Crossing Name:	Unnamed	Total Length (metres):	8.3		
Special Access:		Special Equipment:			
Longitude:	-115 38 40.7	Latitude:	50 14 30.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 31-JUL-15: Ensure 63.7 tonnes load restriction is maintained and less than 10km/hr CBR_Conversion on 17-FEB-14: Annual inspection due to age and performance of log crib. DA Jan 2014.				

Structure Name: N2-085

Site #:	N2-085	Year Superstructure Installed:	1990	Structure Type/Class:	Temporary Bridge
KM:	4.87	User km:	26.10	Last Inspection Date:	2020/09/20
Project File ID #:	0105	Br.	09	Next Inspection Date:	2022/09/20
Road Name:	KOOTENAY-NINE MILE				
Crossing Name:	NINE MILE Cr	Total Length (metres):	10.3		
Special Access:		Special Equipment:			
Longitude:	-115 38 19.5	Latitude:	50 14 25.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 06-MAR-17: Ensure 5 tonnes load restriction is posted and maintained. DA. IDIR\DMALWAY on 31-JUL-15: Annual inspection.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 11 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-086

Site #:	N2-086	Year Superstructure Installed:	1990	Structure Type/Class:	Temporary Bridge
KM:	6.06	User km:	27.30	Last Inspection Date:	2020/09/20
Project File ID #:	0105	Br.	09	Next Inspection Date:	2022/09/20
Road Name:	KOOTENAY-NINE MILE				
Crossing Name:	NINE MILE Cr	Total Length (metres):	8.3		
Special Access:		Special Equipment:			
Longitude:	-115 37 33.5	Latitude:	50 14 5.1		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 31-JUL-15: annual inspection				

Structure Name: N2-200

Site #:	N2-200	Year Superstructure Installed:	2003	Structure Type/Class:	Permanent Bridge
KM:	2.97	User km:	23.30	Last Inspection Date:	2019/10/06
Project File ID #:	0108	Br.	01	Next Inspection Date:	2022/10/06
Road Name:	FINDLAY CREEK				
Crossing Name:	Valentine Ck	Total Length (metres):	9.1		
Special Access:		Special Equipment:			
Longitude:	-116 6 59.2	Latitude:	50 9 34.1		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Other	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-199

Site #:	N2-199	Year Superstructure Installed:	2003	Structure Type/Class:	Permanent Bridge
KM:	4.01	User km:	22.20	Last Inspection Date:	2019/10/06
Project File ID #:	0108	Br.	01	Next Inspection Date:	2022/10/06
Road Name:	FINDLAY CREEK				
Crossing Name:	Unnamed	Total Length (metres):	7.3		
Special Access:		Special Equipment:			
Longitude:	-116 6 20.5	Latitude:	50 9 18.6		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 12 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N2-033

Site #:	N2-033	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	16.23	User km:	12.30	Last Inspection Date:	2019/10/06
Project File ID #:	0108	Br.	01	Next Inspection Date:	2022/10/06
Road Name:	FINDLAY CREEK				
Crossing Name:	EMILY Cr	Total Length (metres):	5.6		
Special Access:		Special Equipment:			
Longitude:	-115 57 35.0	Latitude:	50 8 12.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-039

Site #:	N2-039	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	14.51	User km:	25.30	Last Inspection Date:	2018/08/09
Project File ID #:	0108	Br.	03	Next Inspection Date:	2021/08/09
Road Name:	FINDLAY-WHITETAIL				
Crossing Name:	DUTCH Cr	Total Length (metres):	27.4		
Special Access:		Special Equipment:			
Longitude:	-116 3 11.0	Latitude:	50 14 0.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-161

Site #:	N2-161	Year Superstructure Installed:	1991	Structure Type/Class:	Temporary Bridge
KM:	3.92	User km:	20.50	Last Inspection Date:	2020/09/29
Project File ID #:	0108	Br.	08	Next Inspection Date:	2022/09/29
Road Name:	FINDLAY-BEAR SOUTH				
Crossing Name:	Unnamed	Total Length (metres):	6.3		
Special Access:		Special Equipment:			
Longitude:	-115 59 13.0	Latitude:	50 4 24.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 03-FEB-16: Annual inspection due to crib and deck condition				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 13 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-017

Site #:	N2-017	Year Superstructure Installed:	1993	Structure Type/Class:	Permanent Bridge
KM:	13.26	User km:	28.30	Last Inspection Date:	2019/10/03
Project File ID #:	0196	Br.	01	Next Inspection Date:	2022/10/03
Road Name:	CROSS RIVER				
Crossing Name:	TANGLE Cr		Total Length (metres):	10.6	
Special Access:			Special Equipment:		
Longitude:	-115 43 15.0		Latitude:	50 42 19.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 01-MAR-17: review old repairs at each inspection. Specifically the upstream girder repair listed in 2004.				

Structure Name: N2-022

Site #:	N2-022	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	24.65	User km:	39.80	Last Inspection Date:	2019/10/03
Project File ID #:	0196	Br.	01	Next Inspection Date:	2022/10/03
Road Name:	CROSS RIVER				
Crossing Name:	CROSS R		Total Length (metres):	17.0	
Special Access:			Special Equipment:		
Longitude:	-115 35 8.9		Latitude:	50 42 54.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-023

Site #:	N2-023	Year Superstructure Installed:	1991	Structure Type/Class:	Major Culvert
KM:	27.62	User km:	42.90	Last Inspection Date:	2019/10/03
Project File ID #:	0196	Br.	01	Next Inspection Date:	2022/10/03
Road Name:	CROSS RIVER				
Crossing Name:	Unnamed		Total Length (metres):	13.0	
Special Access:			Special Equipment:		
Longitude:	-115 33 40.0		Latitude:	50 44 3.2	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 14 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N2-025

Site #:	N2-025	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	1.07	User km:	23.00	Last Inspection Date:	2019/10/03
Project File ID #:	0196	Br.	02	Next Inspection Date:	2022/10/03
Road Name:	CROSS RIVER-CORRAL				
Crossing Name:	CROSS R	Total Length (metres):	28.3		
Special Access:		Special Equipment:			
Longitude:	-115 47 28.0	Latitude:	50 40 24.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 14-MAR-17: N/A				

Structure Name: N2-030B

Site #:	N2-030	Year Superstructure Installed:		Structure Type/Class:	Major Culvert
KM:	3.01	User km:	36.20	Last Inspection Date:	2019/10/03
Project File ID #:	0196	Br.	03	Next Inspection Date:	2022/10/03
Road Name:	CROSS-MITCHELL				
Crossing Name:	STRUNA Cr	Total Length (metres):	14.1		
Special Access:		Special Equipment:			
Longitude:	-115 40 20.4	Latitude:	50 45 21.3		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\DMALWAY on 01-MAR-17: verify span, height, inlet covert etc on next inspection				

Structure Name: N2-030

Site #:	N2-030	Year Superstructure Installed:	1995	Structure Type/Class:	Major Culvert
KM:	3.01	User km:	36.20	Last Inspection Date:	2019/10/03
Project File ID #:	0196	Br.	03	Next Inspection Date:	2022/10/03
Road Name:	CROSS-MITCHELL				
Crossing Name:	STRUNA Cr	Total Length (metres):	16.5		
Special Access:		Special Equipment:			
Longitude:	-115 40 20.4	Latitude:	50 45 21.3		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 01-MAR-17: N/A				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 15 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N2-032

Site #:	N2-032	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	5.36	User km:	38.60	Last Inspection Date:	2019/10/03
Project File ID #:	0196	Br.	03	Next Inspection Date:	2022/10/03
Road Name:	CROSS-MITCHELL				
Crossing Name:	ASSINIBOINE Cr	Total Length (metres):	16.5		
Special Access:		Special Equipment:			
Longitude:	-115 40 40.7	Latitude:	50 46 34.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-105

Site #:	N2-105	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	15.47	User km:	27.00	Last Inspection Date:	2019/10/06
Project File ID #:	0268	Br.	01	Next Inspection Date:	2022/10/06
Road Name:	SKOOKUMCHUCK CREEK				
Crossing Name:	SANDOWN Cr	Total Length (metres):	14.4		
Special Access:		Special Equipment:			
Longitude:	-115 52 37.0	Latitude:	50 0 15.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-108A

Site #:	N2-108	Year Superstructure Installed:	2017	Structure Type/Class:	Permanent Bridge
KM:	0.09	User km:	41.90	Last Inspection Date:	2019/10/06
Project File ID #:	0268	Br.	03	Next Inspection Date:	2022/10/06
Road Name:	SKOOKUMCHUCK-BUHL				
Crossing Name:	SKOOKUMCHUCK Cr	Total Length (metres):	33.5		
Special Access:		Special Equipment:			
Longitude:	-116 1 42.1	Latitude:	49 57 49.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 16 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N2-110

Site #:	N2-230	Year Superstructure Installed:	2017	Structure Type/Class:	Permanent Bridge
KM:	8.90	User km:	54.50	Last Inspection Date:	2021/09/26
Project File ID #:	0268	Br.	03	Next Inspection Date:	2022/09/26
Road Name:	SKOOKUMCHUCK-BUHL				
Crossing Name:	unknown	Total Length (metres):	7.3		
Special Access:		Special Equipment:			
Longitude:	-116 5 25.8	Latitude:	49 53 42.4		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\BPellett on 12-APR-22: BP Apr 12-22 Inspector to post crossing to 20T if curbs are not replaced by the 2022 inspection date.				

Structure Name: N2-040

Site #:	N2-040	Year Superstructure Installed:	1989	Structure Type/Class:	Temporary Bridge
KM:	0.00	User km:	9.80	Last Inspection Date:	2020/09/14
Project File ID #:	0276	Br.	01	Next Inspection Date:	2022/09/14
Road Name:	FRANCES CREEK				
Crossing Name:	Unnamed	Total Length (metres):	6.3		
Special Access:		Special Equipment:			
Longitude:	-116 27 10.0	Latitude:	50 43 34.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 01-MAR-17: Ensure posted at 5 tonnes. IDIR\DMALWAY on 03-FEB-16: annual inspection required due to issues.				

Structure Name: N2-065

Site #:	N2-065	Year Superstructure Installed:	1990	Structure Type/Class:	Major Culvert
KM:	14.86	User km:	15.60	Last Inspection Date:	2019/10/02
Project File ID #:	4168	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	KINDERSLEY-PINNACLE				
Crossing Name:	LUXOR Cr	Total Length (metres):	21.0		
Special Access:		Special Equipment:			
Longitude:	-116 9 15.3	Latitude:	50 48 35.5		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 17 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-195

Site #:	N2-195	Year Superstructure Installed:	2001	Structure Type/Class:	Temporary Bridge
KM:	0.06	User km:	7.20	Last Inspection Date:	2020/09/14
Project File ID #:	4168	Br.	04	Next Inspection Date:	2022/09/14
Road Name:	KINDERSLEY CREEK				
Crossing Name:	Unnamed		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-116 6 29.0		Latitude:	50 45 56.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-197

Site #:	N2-197	Year Superstructure Installed:	2001	Structure Type/Class:	Temporary Bridge
KM:	2.44	User km:	9.80	Last Inspection Date:	2021/09/19
Project File ID #:	4168	Br.	04	Next Inspection Date:	2022/09/19
Road Name:	KINDERSLEY CREEK				
Crossing Name:	KINDERSLEY Cr		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-116 4 51.8		Latitude:	50 45 11.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:	IDIR\BPellet on 11-APR-22: BP Apr 11-22 Channel appears to be moving leftwards and has mobilized riprap especially in the downstream corner. Closely monitor abutment embedment and support with every annual inspection. Be sure that photographs capture stream channel and abutment conditions with good light and detail.				

Structure Name: N2-198

Site #:	N2-198	Year Superstructure Installed:	2001	Structure Type/Class:	Temporary Bridge
KM:	8.23	User km:	15.80	Last Inspection Date:	2021/09/19
Project File ID #:	4168	Br.	04	Next Inspection Date:	2022/09/19
Road Name:	KINDERSLEY CREEK				
Crossing Name:	KINDERSLEY Cr		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-116 1 43.0		Latitude:	50 43 20.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:	IDIR\BPellet on 11-APR-22: BP Apr 11-22 Channel appears to be downcutting and has mobilized riprap especially in the downstream corners. Closely monitor abutment embedment and support with every annual inspection. Be sure that photographs capture stream channel and abutment conditions with good light and detail.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 18 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-129

Site #:	N2-129	Year Superstructure Installed:	1965	Structure Type/Class:	Major Culvert
KM:	20.89	User km:	21.20	Last Inspection Date:	2019/09/30
Project File ID #:	4603	Br.	01	Next Inspection Date:	2022/09/30
Road Name:	WHITE-SWAN				
Crossing Name:	MUTTON Cr	Total Length (metres):	17.4		
Special Access:		Special Equipment:			
Longitude:	-115 33 0.2	Latitude:	50 7 11.7		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: N2-173

Site #:	N2-173	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	28.75	User km:	30.00	Last Inspection Date:	2019/09/30
Project File ID #:	4603	Br.	01	Next Inspection Date:	2022/09/30
Road Name:	WHITE-SWAN				
Crossing Name:	INLET Cr	Total Length (metres):	11.6		
Special Access:		Special Equipment:			
Longitude:	-115 27 29.2	Latitude:	50 8 44.5		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-132A

Site #:	N2-132	Year Superstructure Installed:	2014	Structure Type/Class:	Permanent Bridge
KM:	47.95	User km:	48.60	Last Inspection Date:	2019/09/19
Project File ID #:	4603	Br.	01	Next Inspection Date:	2022/09/19
Road Name:	WHITE-SWAN				
Crossing Name:	BARR Cr	Total Length (metres):	11.0		
Special Access:		Special Equipment:			
Longitude:	-115 14 19.7	Latitude:	50 10 53.1		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\MACLOET on 22-APR-15: one year post installation inspection				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 19 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-133A

Site #:	N2-133	Year Superstructure Installed:	2014	Structure Type/Class:	Permanent Bridge
KM:	52.84	User km:	53.50	Last Inspection Date:	2019/09/19
Project File ID #:	4603	Br.	01	Next Inspection Date:	2022/09/19
Road Name:	WHITE-SWAN				
Crossing Name:	STORK Cr	Total Length (metres):	18.2		
Special Access:		Special Equipment:			
Longitude:	-115 10 33.5	Latitude:	50 10 10.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\MACLOET on 29-JAN-16: n/a				

Structure Name: N2-216

Site #:	N2-216	Year Superstructure Installed:	2014	Structure Type/Class:	Permanent Bridge
KM:	59.00	User km:	59.00	Last Inspection Date:	2019/09/19
Project File ID #:	4603	Br.	01	Next Inspection Date:	2022/09/19
Road Name:	WHITE-SWAN				
Crossing Name:	East White River	Total Length (metres):	6.0		
Special Access:		Special Equipment:			
Longitude:	-115 6 11.9	Latitude:	50 8 35.9		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\BCOLLIER on 02-APR-15: 1 year post-installation inspection				

Structure Name: N2-134

Site #:	N2-134	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	59.25	User km:	60.10	Last Inspection Date:	2019/09/19
Project File ID #:	4603	Br.	01	Next Inspection Date:	2022/09/19
Road Name:	WHITE-SWAN				
Crossing Name:	EAST WHITE R	Total Length (metres):	9.6		
Special Access:		Special Equipment:			
Longitude:	-115 6 28.2	Latitude:	50 8 36.3		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 20 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-203

Site #:	N2-203	Year Superstructure Installed:	2006	Structure Type/Class:	Permanent Bridge
KM:	0.00	User km:	31.80	Last Inspection Date:	2019/10/12
Project File ID #:	4603	Br.	02	Next Inspection Date:	2022/10/12
Road Name:	WHITE-COYOTE				
Crossing Name:	GOAT Cr	Total Length (metres):	9.1		
Special Access:			Special Equipment:		
Longitude:	-115 29 7.6	Latitude:	50 3 42.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-139

Site #:	N2-139	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	8.47	User km:	29.80	Last Inspection Date:	2019/10/12
Project File ID #:	4603	Br.	03	Next Inspection Date:	2022/10/12
Road Name:	WHITE-LUSSIER				
Crossing Name:	COYOTE Cr	Total Length (metres):	17.0		
Special Access:			Special Equipment:		
Longitude:	-115 30 32.0	Latitude:	50 4 6.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-140

Site #:	N2-140	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	9.81	User km:	31.10	Last Inspection Date:	2019/10/12
Project File ID #:	4603	Br.	03	Next Inspection Date:	2022/10/12
Road Name:	WHITE-LUSSIER				
Crossing Name:	LUSSIER R	Total Length (metres):	24.4		
Special Access:			Special Equipment:		
Longitude:	-115 31 16.0	Latitude:	50 3 49.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 21 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N2-141

Site #:	N2-141	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	34.37	User km:	54.70	Last Inspection Date:	2019/10/12
Project File ID #:	4603	Br.	03	Next Inspection Date:	2022/10/12
Road Name:	WHITE-LUSSIER				
Crossing Name:	NICOL Cr	Total Length (metres):	15.2		
Special Access:			Special Equipment:		
Longitude:	-115 29 34.0		Latitude:	49 51 40.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-136

Site #:	N2-136	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	0.73	User km:	37.40	Last Inspection Date:	2019/10/12
Project File ID #:	4603	Br.	04	Next Inspection Date:	2022/10/12
Road Name:	WHITE-COYOTE RIDGE				
Crossing Name:	LUSSIER R	Total Length (metres):	18.3		
Special Access:			Special Equipment:		
Longitude:	-115 31 20.0		Latitude:	50 0 43.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-148

Site #:	N2-148	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	1.58	User km:	32.10	Last Inspection Date:	2019/09/30
Project File ID #:	4603	Br.	08	Next Inspection Date:	2022/09/30
Road Name:	WHITE-MOSCOW				
Crossing Name:	OUTLET Cr	Total Length (metres):	16.0		
Special Access:			Special Equipment:		
Longitude:	-115 27 53.0		Latitude:	50 10 4.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 22 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-149

Site #:	N2-149	Year Superstructure Installed:	1992	Structure Type/Class:	Major Culvert
KM:	5.76	User km:	36.00	Last Inspection Date:	2019/09/30
Project File ID #:	4603	Br.	08	Next Inspection Date:	2022/09/30
Road Name:	WHITE-MOSCOW				
Crossing Name:	PTARMIGAN Cr	Total Length (metres):	20.0		
Special Access:		Special Equipment:			
Longitude:	-115 28 18.3	Latitude:	50 12 12.9		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: N2-156

Site #:	N2-156	Year Superstructure Installed:	1986	Structure Type/Class:	Major Culvert
KM:	5.74	User km:	38.30	Last Inspection Date:	2019/10/12
Project File ID #:	4603	Br.	09	Next Inspection Date:	2022/10/12
Road Name:	WHITE-ROCK				
Crossing Name:	ROCK Cr	Total Length (metres):	21.5		
Special Access:		Special Equipment:			
Longitude:	-115 27 22.0	Latitude:	50 12 15.4		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: N2-150

Site #:	N2-150	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	1.58	User km:	45.50	Last Inspection Date:	2019/09/30
Project File ID #:	4603	Br.	11	Next Inspection Date:	2022/09/30
Road Name:	WHITE-NORTH FORK				
Crossing Name:	GRAVE Cr	Total Length (metres):	17.0		
Special Access:		Special Equipment:			
Longitude:	-115 17 6.0	Latitude:	50 11 1.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 23 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-151

Site #:	N2-151	Year Superstructure Installed:	2001	Structure Type/Class:	Permanent Bridge
KM:	10.35	User km:	54.20	Last Inspection Date:	2019/09/30
Project File ID #:	4603	Br.	11	Next Inspection Date:	2022/09/30
Road Name:	WHITE-NORTH FORK				
Crossing Name:	COLIN Cr	Total Length (metres):	13.7		
Special Access:			Special Equipment:		
Longitude:	-115 16 34.8	Latitude:	50 15 21.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-187

Site #:	N2-187	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	16.75	User km:	60.90	Last Inspection Date:	2019/09/30
Project File ID #:	4603	Br.	11	Next Inspection Date:	2022/09/30
Road Name:	WHITE-NORTH FORK				
Crossing Name:	KOMATTIN Cr	Total Length (metres):	15.2		
Special Access:			Special Equipment:		
Longitude:	-115 17 40.0	Latitude:	50 18 36.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-188

Site #:	N2-188	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	19.07	User km:	63.20	Last Inspection Date:	2019/09/30
Project File ID #:	4603	Br.	11	Next Inspection Date:	2022/09/30
Road Name:	WHITE-NORTH FORK				
Crossing Name:	NIPAKOO Cr	Total Length (metres):	18.3		
Special Access:			Special Equipment:		
Longitude:	-115 18 9.0	Latitude:	50 19 48.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 24 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-153

Site #:	N2-153	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	26.90	User km:	71.30	Last Inspection Date:	2019/09/30
Project File ID #:	4603	Br.	11	Next Inspection Date:	2022/09/30
Road Name:	WHITE-NORTH FORK				
Crossing Name:	AKUNAN Cr	Total Length (metres):	12.4		
Special Access:			Special Equipment:		
Longitude:	-115 20 54.2	Latitude:	50 23 27.3		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-154

Site #:	N2-154	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	27.09	User km:	71.50	Last Inspection Date:	2019/09/30
Project File ID #:	4603	Br.	11	Next Inspection Date:	2022/09/30
Road Name:	WHITE-NORTH FORK				
Crossing Name:	SCHOFIELD Cr	Total Length (metres):	15.2		
Special Access:			Special Equipment:		
Longitude:	-115 20 56.3	Latitude:	50 23 33.8		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-146A

Site #:	N2-146	Year Superstructure Installed:	2017	Structure Type/Class:	Permanent Bridge
KM:	20.70	User km:	65.70	Last Inspection Date:	2019/09/30
Project File ID #:	4603	Br.	14	Next Inspection Date:	2022/09/30
Road Name:	WHITE-MIDDLE FORK				
Crossing Name:	SEETA Cr	Total Length (metres):	24.4		
Special Access:			Special Equipment:		
Longitude:	-115 13 8.0	Latitude:	50 20 12.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 25 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-224

Site #:	N2-224	Year Superstructure Installed:	2017	Structure Type/Class:	Permanent Bridge
KM:	22.50	User km:	67.50	Last Inspection Date:	2019/09/30
Project File ID #:	4603	Br.	14	Next Inspection Date:	2022/09/30
Road Name:	WHITE-MIDDLE FORK				
Crossing Name:	White River	Total Length (metres):	24.4		
Special Access:		Special Equipment:			
Longitude:	-115 12 12.1	Latitude:	50 20 52.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-217

Site #:	N2-217	Year Superstructure Installed:	2014	Structure Type/Class:	Permanent Bridge
KM:	59.60	User km:	59.60	Last Inspection Date:	2019/09/19
Project File ID #:	4603	Br.	18	Next Inspection Date:	2022/09/19
Road Name:	WHITE-MONROE				
Crossing Name:	East White River	Total Length (metres):	9.8		
Special Access:		Special Equipment:			
Longitude:	-115 6 12.1	Latitude:	50 8 21.3		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\BCOLLIER on 02-APR-15: 1 year post-installation inspection				

Structure Name: N2-164

Site #:	N2-164	Year Superstructure Installed:	1995	Structure Type/Class:	Major Culvert
KM:	0.64	User km:	36.60	Last Inspection Date:	2019/09/30
Project File ID #:	4603	Br.	25	Next Inspection Date:	2022/09/30
Road Name:	WHITE-PTARMIGAN				
Crossing Name:	PTARMIGAN Cr	Total Length (metres):	24.1		
Special Access:		Special Equipment:			
Longitude:	-115 28 49.6	Latitude:	50 12 17.4		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 26 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-003

Site #:	N2-003	Year Superstructure Installed:	1990	Structure Type/Class:	Temporary Bridge
KM:	12.90	User km:	24.20	Last Inspection Date:	2020/09/14
Project File ID #:	4981	Br.	01	Next Inspection Date:	2022/09/14
Road Name:	BREWER CREEK				
Crossing Name:	BREWER Cr		Total Length (metres):	6.3	
Special Access:			Special Equipment:		
Longitude:	-116 9 47.8		Latitude:	50 23 19.8	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 28-FEB-17: downgrade to 5 tonnes at next inspection in 2017, if deck repairs are not completed 2018 CBR_Conversion on 28-FEB-17: Ensure you go to the correct bridge, at user KM 24.2. Do not go to the bailey bridge, this is MOTI. MFR structure is a 6.3 o/o steel girder. Possibly needs site ID tag. DA				

Structure Name: N2-162

Site #:	N2-162	Year Superstructure Installed:	1990	Structure Type/Class:	Temporary Bridge
KM:	3.78	User km:	3.80	Last Inspection Date:	2020/09/14
Project File ID #:	5324	Br.	01	Next Inspection Date:	2022/09/14
Road Name:	MADIAS CREEK				
Crossing Name:	TATLEY Cr		Total Length (metres):	6.3	
Special Access:			Special Equipment:		
Longitude:	-115 51 20.4		Latitude:	50 25 5.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 01-FEB-16: inspect annually CBR_Conversion on 17-FEB-14: Ensure posted at 5 tonnes until 2015. DA Jan 2014.				

Structure Name: N2-042

Site #:	N2-042	Year Superstructure Installed:	1991	Structure Type/Class:	Permanent Bridge
KM:	1.26	User km:	1.50	Last Inspection Date:	2019/10/02
Project File ID #:	5467	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	HORSETHIEF CREEK				
Crossing Name:	COLUMBIA R		Total Length (metres):	106.7	
Special Access:			Special Equipment:		
Longitude:	-116 6 22.8		Latitude:	50 37 25.5	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	4
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 27 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N2-044

Site #:	N2-044	Year Superstructure Installed:	1991	Structure Type/Class:	Permanent Bridge
KM:	1.51	User km:	1.90	Last Inspection Date:	2019/10/02
Project File ID #:	5467	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	HORSETHIEF CREEK				
Crossing Name:	Columbia R.	Total Length (metres):	30.5		
Special Access:			Special Equipment:		
Longitude:	-116 6 36.0	Latitude:	50 37 27.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-045

Site #:	N2-045	Year Superstructure Installed:	1989	Structure Type/Class:	Permanent Bridge
KM:	10.41	User km:	10.90	Last Inspection Date:	2019/10/02
Project File ID #:	5467	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	HORSETHIEF CREEK				
Crossing Name:	FORSTER Cr #1	Total Length (metres):	28.3		
Special Access:			Special Equipment:		
Longitude:	-116 9 32.0	Latitude:	50 35 39.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-047A

Site #:	N2-047	Year Superstructure Installed:	2012	Structure Type/Class:	Permanent Bridge
KM:	27.72	User km:	28.60	Last Inspection Date:	2019/10/02
Project File ID #:	5467	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	HORSETHIEF CREEK				
Crossing Name:	GOPHER Cr	Total Length (metres):	18.3		
Special Access:			Special Equipment:		
Longitude:	-116 21 56.7	Latitude:	50 33 53.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Ensure to comment on monitor items. DA. Dec 18, 2013.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 28 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N2-048

Site #:	N2-048	Year Superstructure Installed:	1991	Structure Type/Class:	Permanent Bridge
KM:	32.70	User km:	33.60	Last Inspection Date:	2019/10/02
Project File ID #:	5467	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	HORSETHIEF CREEK				
Crossing Name:	MCDONALD Cr	Total Length (metres):	12.3		
Special Access:		Special Equipment:			
Longitude:	-116 25 27.0	Latitude:	50 34 12.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 02-MAR-17: Measure size and spacing of timber ties utilized on next inspection.				

Structure Name: N2-049A

Site #:	N2-049	Year Superstructure Installed:	2012	Structure Type/Class:	Permanent Bridge
KM:	41.68	User km:	42.40	Last Inspection Date:	2019/10/02
Project File ID #:	5467	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	HORSETHIEF CREEK				
Crossing Name:	HORSETHIEF #2	Total Length (metres):	24.4		
Special Access:		Special Equipment:			
Longitude:	-116 31 29.0	Latitude:	50 32 18.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Other	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-051A

Site #:	N2-051	Year Superstructure Installed:	2010	Structure Type/Class:	Permanent Bridge
KM:	46.19	User km:	47.50	Last Inspection Date:	2019/10/02
Project File ID #:	5467	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	HORSETHIEF CREEK				
Crossing Name:	Unnamed	Total Length (metres):	9.1		
Special Access:		Special Equipment:			
Longitude:	-116 33 37.4	Latitude:	50 30 30.1		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 02-MAR-17: N/A				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 29 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-053

Site #:	N2-053	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	5.00	User km:	18.60	Last Inspection Date:	2019/10/02
Project File ID #:	5467	Br.	02	Next Inspection Date:	2022/10/02
Road Name:	HORSETHIEF-FORSTER				
Crossing Name:	FORSTER Cr #3		Total Length (metres):	21.4	
Special Access:			Special Equipment:		
Longitude:	-116 14 12.0		Latitude:	50 36 56.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: PS-022

Site #:	N2-057	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	22.06	User km:	35.90	Last Inspection Date:	2019/10/02
Project File ID #:	5467	Br.	02	Next Inspection Date:	2022/10/02
Road Name:	HORSETHIEF-FORSTER				
Crossing Name:	IRISH Cr		Total Length (metres):	14.5	
Special Access:			Special Equipment:		
Longitude:	-116 26 21.0		Latitude:	50 38 31.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 03-FEB-16: one year post construction inspection				

Structure Name: PS-039

Site #:	N2-058	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	23.58	User km:	37.50	Last Inspection Date:	2019/10/02
Project File ID #:	5467	Br.	02	Next Inspection Date:	2022/10/02
Road Name:	HORSETHIEF-FORSTER				
Crossing Name:	WELSH Cr		Total Length (metres):	12.3	
Special Access:			Special Equipment:		
Longitude:	-116 27 31.4		Latitude:	50 38 47.6	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 09-MAR-17: verify c/c span length, measure upstream and downstream girders.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 30 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N2-059A

Site #:	N2-059	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	26.49	User km:	40.40	Last Inspection Date:	2019/10/02
Project File ID #:	5467	Br.	02	Next Inspection Date:	2022/10/02
Road Name:	HORSETHIEF-FORSTER				
Crossing Name:	FORSTER Cr #5		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-116 29 27.9		Latitude:	50 39 17.3	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-205

Site #:	N2-205	Year Superstructure Installed:	2008	Structure Type/Class:	Temporary Bridge
KM:	0.40	User km:	4.70	Last Inspection Date:	2020/09/14
Project File ID #:	5467	Br.	04	Next Inspection Date:	2022/09/14
Road Name:	CR5467.04MCDONALDCKF				
Crossing Name:	MCDONALD CRK #1		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-116 26 24.0		Latitude:	50 32 39.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 09-MAR-17: determine if timber sill has been upgraded.				

Structure Name: N2-052

Site #:	N2-052	Year Superstructure Installed:	1992	Structure Type/Class:	Permanent Bridge
KM:	9.52	User km:	24.60	Last Inspection Date:	2019/10/02
Project File ID #:	5467	Br.	05	Next Inspection Date:	2022/10/02
Road Name:	HORSETHIEF-DOGLEG				
Crossing Name:	FRANCES Cr		Total Length (metres):	14.3	
Special Access:			Special Equipment:		
Longitude:	-116 11 41.0		Latitude:	50 37 41.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 31 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-112A

Site #:	N2-112	Year Superstructure Installed:	2011	Structure Type/Class:	Permanent Bridge
KM:	0.40	User km:	0.40	Last Inspection Date:	2019/10/01
Project File ID #:	7752	Br.	01	Next Inspection Date:	2022/10/01
Road Name:	PARSON RIVER CROSSIN				
Crossing Name:	COLUMBIA R #1	Total Length (metres):	122.0		
Special Access:		Special Equipment:	Peeper Truck		
Longitude:	-116 38 33.1	Latitude:	51 4 10.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	5
Planned Inspection Comments:	CBR_Conversion on 07-MAR-17: To be peeper inspected every 10 years. Next peeper inspection in 2021. DA.				

Structure Name: N2-114B

Site #:	N2-114	Year Superstructure Installed:	2010	Structure Type/Class:	Major Culvert
KM:	0.93	User km:	1.00	Last Inspection Date:	2019/10/01
Project File ID #:	7752	Br.	01	Next Inspection Date:	2022/10/01
Road Name:	PARSON RIVER CROSSIN				
Crossing Name:	COLUMBIA R #3	Total Length (metres):	24.0		
Special Access:		Special Equipment:			
Longitude:	-116 38 45.0	Latitude:	51 3 53.0		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Just complete one inspection for the site of N2-114				

Structure Name: N2-115B

Site #:	N2-115	Year Superstructure Installed:	2010	Structure Type/Class:	Major Culvert
KM:	1.15	User km:	1.30	Last Inspection Date:	2019/10/01
Project File ID #:	7752	Br.	01	Next Inspection Date:	2022/10/01
Road Name:	PARSON RIVER CROSSIN				
Crossing Name:	COLUMBIA R #4	Total Length (metres):	19.5		
Special Access:		Special Equipment:			
Longitude:	-116 38 53.0	Latitude:	51 3 45.0		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Inspect at same time as other culvert.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 32 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-116A

Site #:	N2-116	Year Superstructure Installed:	2011	Structure Type/Class:	Permanent Bridge
KM:	1.26	User km:	1.40	Last Inspection Date:	2019/10/01
Project File ID #:	7752	Br.	01	Next Inspection Date:	2022/10/01
Road Name:	PARSON RIVER CROSSIN				
Crossing Name:	COLUMBIA R #5	Total Length (metres):	36.5		
Special Access:			Special Equipment:		
Longitude:	-116 38 58.0		Latitude:	51 3 43.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	3
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Post construction inspection then on regular frequency. DA. March 2012				

Structure Name: N2-208

Site #:	N2-208	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	38.00	User km:	38.00	Last Inspection Date:	2019/10/01
Project File ID #:	7752	Br.	01	Next Inspection Date:	2022/10/01
Road Name:	PARSON RIVER CROSSIN				
Crossing Name:	Unnamed	Total Length (metres):	6.1		
Special Access:			Special Equipment:		
Longitude:	-116 58 46.4		Latitude:	51 6 55.9	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 09-MAR-17: Na				

Structure Name: WO-209

Site #:	N2-118	Year Superstructure Installed:	2014	Structure Type/Class:	Temporary Bridge
KM:	52.69	User km:	54.00	Last Inspection Date:	2020/09/14
Project File ID #:	7752	Br.	01	Next Inspection Date:	2022/09/14
Road Name:	PARSON RIVER CROSSIN				
Crossing Name:	DAM Cr	Total Length (metres):	22.3		
Special Access:			Special Equipment:		
Longitude:	-117 8 54.5		Latitude:	51 10 2.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 07-MAR-17: measure the actual C/C spacing of bearing. document the type of bearing sills utilized.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 33 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N2-119

Site #:	N2-119	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	58.02	User km:	57.20	Last Inspection Date:	2019/10/01
Project File ID #:	7752	Br.	01	Next Inspection Date:	2022/10/01
Road Name:	PARSON RIVER CROSSIN				
Crossing Name:	SPILLIMACHEEN R		Total Length (metres):	16.6	
Special Access:			Special Equipment:		
Longitude:	-117 12 59.0		Latitude:	51 10 36.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-122

Site #:	N2-122	Year Superstructure Installed:	1995	Structure Type/Class:	Temporary Bridge
KM:	33.68	User km:	51.40	Last Inspection Date:	2020/09/14
Project File ID #:	7752	Br.	02	Next Inspection Date:	2022/09/14
Road Name:	SPILLIMACHEEN-S.FORK				
Crossing Name:	VERMONT Cr		Total Length (metres):	12.3	
Special Access:			Special Equipment:		
Longitude:	-116 55 18.0		Latitude:	50 57 38.3	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile - Temporary Materials	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 07-MAR-17: N/A				

Structure Name: N2-128

Site #:	N2-128	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	0.15	User km:	56.10	Last Inspection Date:	2019/10/01
Project File ID #:	7752	Br.	03	Next Inspection Date:	2022/10/01
Road Name:	SPILLIMACHEEN-VOWEL				
Crossing Name:	VOWELL Cr		Total Length (metres):	27.4	
Special Access:			Special Equipment:		
Longitude:	-116 55 43.0		Latitude:	50 55 38.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 34 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-126A

Site #:	N2-126	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	7.21	User km:	55.20	Last Inspection Date:	2019/10/01
Project File ID #:	7752	Br.	04	Next Inspection Date:	2022/10/01
Road Name:	SPILLIMACHEEN-MCMURD				
Crossing Name:	MCMURDO Cr #2	Total Length (metres):	15.2		
Special Access:			Special Equipment:		
Longitude:	-117 8 43.0		Latitude:	51 5 24.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-127A

Site #:	N2-127	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	9.02	User km:	56.70	Last Inspection Date:	2019/10/01
Project File ID #:	7752	Br.	04	Next Inspection Date:	2022/10/01
Road Name:	SPILLIMACHEEN-MCMURD				
Crossing Name:	MCMURDO Cr #3	Total Length (metres):	15.2		
Special Access:			Special Equipment:		
Longitude:	-117 9 23.0		Latitude:	51 4 43.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: One year post construction inspection, then back on regular routine. Clean bearings and flanges off at time of next inspection. DA.				

Structure Name: N2-060

Site #:	N2-060	Year Superstructure Installed:	1990	Structure Type/Class:	Permanent Bridge
KM:	1.23	User km:	1.30	Last Inspection Date:	2019/09/24
Project File ID #:	7825	Br.	01	Next Inspection Date:	2022/09/24
Road Name:	JUMBO CREEK				
Crossing Name:	JUMBO Cr	Total Length (metres):	14.3		
Special Access:			Special Equipment:		
Longitude:	-116 25 13.0		Latitude:	50 21 13.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 35 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: PS-031

Site #:	N2-221	Year Superstructure Installed:	2014	Structure Type/Class:	Temporary Bridge
KM:	5.00	User km:	5.00	Last Inspection Date:	2020/09/14
Project File ID #:	7825	Br.	01	Next Inspection Date:	2022/09/14
Road Name:	JUMBO CREEK				
Crossing Name:	Unknown		Total Length (metres):	10.3	
Special Access:			Special Equipment:		
Longitude:	-116 27 55.3		Latitude:	50 21 54.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-177A

Site #:	N2-177	Year Superstructure Installed:	2012	Structure Type/Class:	Permanent Bridge
KM:	6.31	User km:	6.20	Last Inspection Date:	2019/09/24
Project File ID #:	7825	Br.	01	Next Inspection Date:	2022/09/24
Road Name:	JUMBO CREEK				
Crossing Name:	JUMBO Cr		Total Length (metres):	24.4	
Special Access:			Special Equipment:		
Longitude:	-116 28 53.0		Latitude:	50 21 45.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: PS-012

Site #:	N2-180	Year Superstructure Installed:	2012	Structure Type/Class:	Permanent Bridge
KM:	13.21	User km:	13.10	Last Inspection Date:	2019/09/24
Project File ID #:	7825	Br.	01	Next Inspection Date:	2022/09/24
Road Name:	JUMBO CREEK				
Crossing Name:	LEONA Cr		Total Length (metres):	21.4	
Special Access:			Special Equipment:		
Longitude:	-116 34 24.6		Latitude:	50 21 9.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	CBR Conversion on 17-FEB-14: PB June 4.2013 Inspect lowchain upstream ballast wall and sill for damage or spalling. Bulkhead is in contact with precast sill.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 36 of 36
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N2-012

Site #:	N2-012	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	6.20	User km:	14.50	Last Inspection Date:	2019/10/02
Project File ID #:	9905	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	LEADQUEEN				
Crossing Name:	TEMPLETON Cr		Total Length (metres):	13.6	
Special Access:			Special Equipment:		
Longitude:	-116 27 29.4		Latitude:	50 49 54.5	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: N2-192

Site #:	N2-192	Year Superstructure Installed:	2001	Structure Type/Class:	Permanent Bridge
KM:	8.05	User km:	49.50	Last Inspection Date:	2019/10/02
Project File ID #:	9905	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	LEADQUEEN				
Crossing Name:	DUNBAR Cr		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-116 25 8.0		Latitude:	50 47 45.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Type/Class Totals

Permanent Bridge Total: 75	Major Culvert Total: 11
Temporary Bridge Total: 21	Woodbox/Log Culvert Total: 0