



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 1 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-119

Site #:	62-119	Year Superstructure Installed:	2014	Structure Type/Class:	Temporary Bridge
KM:	8.60	User km:	8.60	Last Inspection Date:	2020/09/27
Project File ID #:	10561	Br.	01	Next Inspection Date:	2022/09/27
Road Name:	STOBART CREEK				
Crossing Name:	no name		Total Length (metres):	10.7	
Special Access:			Special Equipment:		
Longitude:	-122 52 26.8		Latitude:	51 25 1.0	
Superstructure:	Log Stringers		Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans: 1
Planned Inspection Comments:					

Structure Name: 62-121

Site #:	62-121	Year Superstructure Installed:	2014	Structure Type/Class:	Temporary Bridge
KM:	9.20	User km:	9.20	Last Inspection Date:	2020/09/27
Project File ID #:	10561	Br.	03	Next Inspection Date:	2022/09/27
Road Name:	STOBART CREEK-BR.3				
Crossing Name:	NoName		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-122 52 45.1		Latitude:	51 25 20.1	
Superstructure:	Log Stringers		Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans: 1
Planned Inspection Comments:					

Structure Name: 62-108

Site #:	62-108	Year Superstructure Installed:	2012	Structure Type/Class:	Temporary Bridge
KM:	10.30	User km:	10.30	Last Inspection Date:	2020/09/25
Project File ID #:	8380	Br.	14	Next Inspection Date:	2022/09/25
Road Name:	KANGAROO CK-ROLLIE L				
Crossing Name:	unnamed		Total Length (metres):	9.1	
Special Access:			Special Equipment:		
Longitude:	-121 34 19.2		Latitude:	52 45 58.0	
Superstructure:	Log Stringers		Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 2 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-125

Site #:	62-125	Year Superstructure Installed:	2008	Structure Type/Class:	Permanent Bridge
KM:	9.10	User km:	9.10	Last Inspection Date:	2019/10/07
Project File ID #:	9162	Br.	01	Next Inspection Date:	2022/10/07
Road Name:	Sausser Lake				
Crossing Name:	Unnamed	Total Length (metres):	6.0		
Special Access:		Special Equipment:			
Longitude:	-121 34 13.2	Latitude:	52 14 23.6		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: 65-050

Site #:	65-050	Year Superstructure Installed:	2020	Structure Type/Class:	Permanent Bridge
KM:	67.40	User km:	67.40	Last Inspection Date:	
Project File ID #:	5265	Br.	02	Next Inspection Date:	2022/08/15
Road Name:	ALEX GRAHAM-PALMER				
Crossing Name:	Unnamed Creek	Total Length (metres):	24.4		
Special Access:		Special Equipment:			
Longitude:	-123 13 13.6	Latitude:	52 24 6.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 14-APR-22: Post installation inspection				

Structure Name: 65-057

Site #:	65-057	Year Superstructure Installed:	2021	Structure Type/Class:	Permanent Bridge
KM:	7.50	User km:	44.80	Last Inspection Date:	
Project File ID #:	7356	Br.	01	Next Inspection Date:	2022/08/15
Road Name:	CLUSKO R-THUNDER MTN				
Crossing Name:	Unnamed	Total Length (metres):	21.7		
Special Access:		Special Equipment:			
Longitude:	-124 2 0.1	Latitude:	52 27 4.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 19-APR-22: One year post installation inspection				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 3 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 65-055

Site #:	65-055	Year Superstructure Installed:	2018	Structure Type/Class:	Temporary Bridge
KM:	84.00	User km:	81.00	Last Inspection Date:	2020/09/29
Project File ID #:	7356	Br.	01	Next Inspection Date:	2022/09/29
Road Name:	CLUSKO R-THUNDER MTN				
Crossing Name:	Moore Cr	Total Length (metres):	18.0		
Special Access:		Special Equipment:			
Longitude:	-124 22 59.3	Latitude:	52 39 31.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: 65-048

Site #:	65-048	Year Superstructure Installed:		Structure Type/Class:	Temporary Bridge
KM:	9.40	User km:	9.40	Last Inspection Date:	2020/09/29
Project File ID #:	7356	Br.	41	Next Inspection Date:	2022/09/29
Road Name:	CLUSKO RIVER - BR.41				
Crossing Name:	Unnamed	Total Length (metres):	9.0		
Special Access:		Special Equipment:			
Longitude:	-124 20 7.4	Latitude:	52 34 48.2		
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: 65-047

Site #:	65-047	Year Superstructure Installed:	2015	Structure Type/Class:	Temporary Bridge
KM:	14.70	User km:	14.70	Last Inspection Date:	2020/09/29
Project File ID #:	7356	Br.	41	Next Inspection Date:	2022/09/29
Road Name:	CLUSKO RIVER - BR.41				
Crossing Name:	Unnamed	Total Length (metres):	8.0		
Special Access:		Special Equipment:			
Longitude:	-124 22 35.3	Latitude:	52 32 51.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 4 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: PS 62-049

Site #:	65-049	Year Superstructure Installed:	2016	Structure Type/Class:	Temporary Bridge
KM:	0.41	User km:	0.41	Last Inspection Date:	2020/09/28
Project File ID #:	7356	Br.	42	Next Inspection Date:	2022/09/28
Road Name:	CLUSKO RIVER - BR.42				
Crossing Name:	Unnamed	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-123 55 35.5	Latitude:	52 37 21.9		
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: PS62-057

Site #:	62-129	Year Superstructure Installed:	2020	Structure Type/Class:	Temporary Bridge
KM:	0.80	User km:	0.80	Last Inspection Date:	
Project File ID #:	6142	Br.	07	Next Inspection Date:	2021/08/20
Road Name:	6142.07				
Crossing Name:	Unknown	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-121 25 32.0	Latitude:	52 43 54.3		
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 07-MAY-21: One year post installation inspection				

Structure Name: PS62-052

Site #:	62-124	Year Superstructure Installed:	2015	Structure Type/Class:	Temporary Bridge
KM:	0.22	User km:	0.22	Last Inspection Date:	2020/09/27
Project File ID #:	6416	Br.	1	Next Inspection Date:	2022/09/27
Road Name:	6416.01				
Crossing Name:	Unnamed	Total Length (metres):	12.0		
Special Access:		Special Equipment:			
Longitude:	-122 42 40.3	Latitude:	51 34 49.5		
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 5 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 65-032

Site #:	65-032	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	6.50	User km:	6.30	Last Inspection Date:	2019/10/04
Project File ID #:	5265	Br.	18	Next Inspection Date:	2022/10/04
Road Name:	ALEX GRAHAM-ANAHAM S				
Crossing Name:	S. Anaheim Cr	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-123 4 47.9	Latitude:	52 8 2.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: inaccessible due to snow in 2012, rescheduled for 2013 low risk BT				

Structure Name: 65-011

Site #:	65-011	Year Superstructure Installed:	2011	Structure Type/Class:	Major Culvert
KM:	41.40	User km:	41.40	Last Inspection Date:	2019/10/04
Project File ID #:	5265	Br.	02	Next Inspection Date:	2022/10/04
Road Name:	ALEX GRAHAM-PALMER				
Crossing Name:	Anahim Creek	Total Length (metres):	29.9		
Special Access:		Special Equipment:			
Longitude:	-123 6 27.4	Latitude:	52 11 54.4		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: one year after installation				

Structure Name: 65-040

Site #:	65-040	Year Superstructure Installed:	2009	Structure Type/Class:	Temporary Bridge
KM:	72.00	User km:	72.00	Last Inspection Date:	2020/09/29
Project File ID #:	5265	Br.	02	Next Inspection Date:	2022/09/29
Road Name:	ALEX GRAHAM-PALMER				
Crossing Name:	Unnamed west of Rosita Lk	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-123 13 30.0	Latitude:	52 25 4.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 6 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 65-002

Site #:	65-002	Year Superstructure Installed:	1988	Structure Type/Class:	Permanent Bridge
KM:	7.06	User km:	11.00	Last Inspection Date:	2019/10/04
Project File ID #:	4633	Br.	01	Next Inspection Date:	2022/10/04
Road Name:	ANAH LAKE				
Crossing Name:	Anahim Cr	Total Length (metres):	15.0		
Special Access:		Special Equipment:			
Longitude:	-123 11 26.0	Latitude:	52 9 28.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: 2 xties & 8 ft of decking replaced in 2009				

Structure Name: 62-095

Site #:	62-095	Year Superstructure Installed:	2008	Structure Type/Class:	Temporary Bridge
KM:	1.50	User km:	1.50	Last Inspection Date:	2020/09/28
Project File ID #:	9444	Br.	05	Next Inspection Date:	2022/09/28
Road Name:	BAMBRICK CREEK - BR.5				
Crossing Name:	Bambrick Creek	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-123 10 48.4	Latitude:	51 38 59.7		
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: 65-017

Site #:	65-017	Year Superstructure Installed:	1990	Structure Type/Class:	Temporary Bridge
KM:	2.10	User km:	2.10	Last Inspection Date:	2020/09/29
Project File ID #:	9454	Br.	06	Next Inspection Date:	2022/09/29
Road Name:	BIG STICK-REC SITE				
Crossing Name:	Marjarie Creek	Total Length (metres):	8.0		
Special Access:		Special Equipment:			
Longitude:	-125 1 24.7	Latitude:	52 1 59.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 7 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-036

Site #:	62-036	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	5.65	User km:	5.00	Last Inspection Date:	2019/10/07
Project File ID #:	1253	Br.	01	Next Inspection Date:	2022/10/07
Road Name:	BLACK CK - BOSK LAKE				
Crossing Name:	McKinley Cr Lower	Total Length (metres):	34.0		
Special Access:		Special Equipment:			
Longitude:	-121 0 18.5	Latitude:	52 16 49.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:	IDIR\RMGETZLA on 12-DEC-19: nothing on file regarding load limits				

Structure Name: 62-037

Site #:	62-037	Year Superstructure Installed:	1992	Structure Type/Class:	Permanent Bridge
KM:	19.20	User km:	19.00	Last Inspection Date:	2019/10/07
Project File ID #:	1253	Br.	01	Next Inspection Date:	2022/10/07
Road Name:	BLACK CK - BOSK LAKE				
Crossing Name:	McKinley Cr Middle	Total Length (metres):	12.0		
Special Access:		Special Equipment:			
Longitude:	-120 52 37.5	Latitude:	52 13 46.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: 62-039A

Site #:	62-039	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	0.75	User km:	0.00	Last Inspection Date:	2019/10/06
Project File ID #:	6142	Br.	01	Next Inspection Date:	2022/10/06
Road Name:	CARIBOO RIVER				
Crossing Name:	Cariboo R	Total Length (metres):	91.4		
Special Access:		Special Equipment:			
Longitude:	-121 26 39.1	Latitude:	52 43 4.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	3
Planned Inspection Comments:	IDIR\MRFENNEL on 12-JAN-16: One year post installation inspection				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 8 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-041

Site #:	62-041	Year Superstructure Installed:	1991	Structure Type/Class:	Permanent Bridge
KM:	34.60	User km:	32.90	Last Inspection Date:	2019/10/06
Project File ID #:	6142	Br.	01	Next Inspection Date:	2022/10/06
Road Name:	CARIBOO RIVER				
Crossing Name:	Ishkloo R	Total Length (metres):	18.2		
Special Access:		Special Equipment:			
Longitude:	-121 4 21.0	Latitude:	52 46 45.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: 62-042

Site #:	62-042	Year Superstructure Installed:	1991	Structure Type/Class:	Permanent Bridge
KM:	35.10	User km:	33.40	Last Inspection Date:	2019/10/06
Project File ID #:	6142	Br.	01	Next Inspection Date:	2022/10/06
Road Name:	CARIBOO RIVER				
Crossing Name:	Little R	Total Length (metres):	14.0		
Special Access:		Special Equipment:			
Longitude:	-121 4 2.4	Latitude:	52 46 38.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: 62-043

Site #:	62-043	Year Superstructure Installed:	1991	Structure Type/Class:	Permanent Bridge
KM:	47.40	User km:	44.10	Last Inspection Date:	2019/10/06
Project File ID #:	6142	Br.	01	Next Inspection Date:	2022/10/06
Road Name:	CARIBOO RIVER				
Crossing Name:	Little R	Total Length (metres):	12.0		
Special Access:		Special Equipment:			
Longitude:	-120 55 50.0	Latitude:	52 49 10.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 9 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-078

Site #:	62-078	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	155.21	User km:	5.90	Last Inspection Date:	2019/10/11
Project File ID #:	6142	Br.	01	Next Inspection Date:	2022/10/11
Road Name:	CARIBOO RIVER				
Crossing Name:	Cameron Cr down Cameron Ck Road		Total Length (metres):	31.0	
Special Access:			Special Equipment:		
Longitude:	-120 49 34.1		Latitude:	52 50 7.9	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: not inspected in 2010 due to limited ATV use and access due to snow				

Structure Name: 62-077

Site #:	62-077	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	156.10	User km:	1.50	Last Inspection Date:	2019/10/11
Project File ID #:	6142	Br.	01	Next Inspection Date:	2022/10/11
Road Name:	CARIBOO RIVER				
Crossing Name:	Grizzly Cr down Cameron Ck RD		Total Length (metres):	16.7	
Special Access:			Special Equipment:		
Longitude:	-120 52 3.3		Latitude:	52 50 48.9	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: very limited ATV use, not inspected in 2010 due to access and snow				

Structure Name: 62-045

Site #:	62-045	Year Superstructure Installed:	1993	Structure Type/Class:	Permanent Bridge
KM:	0.69	User km:	1.00	Last Inspection Date:	2019/10/11
Project File ID #:	6142	Br.	03	Next Inspection Date:	2022/10/11
Road Name:	CARIBOO RIVER-NORTH				
Crossing Name:	Little R		Total Length (metres):	25.0	
Special Access:			Special Equipment:		
Longitude:	-121 12 8.6		Latitude:	52 49 6.0	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans: 2
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: major works done in 2008 to address scour & log jam on this structure.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 10 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 65-018

Site #:	65-018	Year Superstructure Installed:	2000	Structure Type/Class:	Temporary Bridge
KM:	0.10	User km:	0.10	Last Inspection Date:	2020/09/29
Project File ID #:	5475	Br.	14	Next Inspection Date:	2022/09/29
Road Name:	CHILANKO CONNECTOR				
Crossing Name:	Chilanko Loop	Total Length (metres):	8.0		
Special Access:		Special Equipment:			
Longitude:	-124 8 12.9	Latitude:	52 5 10.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: 400 Road inspspect in 2013, limited used & not inspected in 2012, due to snow BT				

Structure Name: 65-003

Site #:	65-003	Year Superstructure Installed:	1975	Structure Type/Class:	Permanent Bridge
KM:	0.10	User km:	0.10	Last Inspection Date:	2019/10/02
Project File ID #:	6252	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	CHILKO LAKE				
Crossing Name:	Chilko R	Total Length (metres):	50.0		
Special Access:		Special Equipment:			
Longitude:	-124 6 25.2	Latitude:	51 42 54.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	3
Planned Inspection Comments:	CBR_Conversion on 21-MAY-21:				

Structure Name: 65-004

Site #:	65-004	Year Superstructure Installed:	1999	Structure Type/Class:	Major Culvert
KM:	0.20	User km:	0.28	Last Inspection Date:	2019/10/02
Project File ID #:	6252	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	CHILKO LAKE				
Crossing Name:	Chilko Flood Plain	Total Length (metres):	16.0		
Special Access:		Special Equipment:			
Longitude:	-124 6 20.1	Latitude:	51 42 52.2		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: changed inspection to 2013 due to inaccessibility in fall 2012 BT				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 11 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 65-005

Site #:	65-005	Year Superstructure Installed:	1999	Structure Type/Class:	Major Culvert
KM:	0.30	User km:	0.35	Last Inspection Date:	2019/10/02
Project File ID #:	6252	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	CHILKO LAKE				
Crossing Name:	Chilko Flood Plain	Total Length (metres):	16.0		
Special Access:		Special Equipment:			
Longitude:	-124 6 17.9	Latitude:	51 42 51.0		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: changed inspection to 2012 due to inaccessibility in fall 2012 BT				

Structure Name: 65-007A

Site #:	65-007	Year Superstructure Installed:	2014	Structure Type/Class:	Temporary Bridge
KM:	84.34	User km:	83.40	Last Inspection Date:	2020/09/28
Project File ID #:	7356	Br.	04	Next Inspection Date:	2022/09/28
Road Name:	CLUSKO R - ANEKO CK				
Crossing Name:	Maxwell Cr	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-123 55 24.5	Latitude:	52 37 22.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: 65-037

Site #:	65-037	Year Superstructure Installed:	2019	Structure Type/Class:	Temporary Bridge
KM:	3.33	User km:	3.00	Last Inspection Date:	2020/09/28
Project File ID #:	7356	Br.	21	Next Inspection Date:	2022/09/28
Road Name:	CLUSKO R - SPARROWHAWK				
Crossing Name:	Avon Creek	Total Length (metres):	9.0		
Special Access:		Special Equipment:			
Longitude:	-123 18 40.4	Latitude:	52 14 52.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 12 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 65-025

Site #:	65-025	Year Superstructure Installed:		Structure Type/Class:	Major Culvert
KM:	14.50	User km:	154.00	Last Inspection Date:	2019/10/02
Project File ID #:	7356	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	CLUSKO R-THUNDER MTN				
Crossing Name:	Unnamed		Total Length (metres):	29.5	
Special Access:			Special Equipment:		
Longitude:	-124 6 42.8		Latitude:	52 30 33.2	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: changed inspection to 2013, low risk site BT				

Structure Name: 65-012

Site #:	65-012	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	20.30	User km:	159.00	Last Inspection Date:	2019/10/02
Project File ID #:	7356	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	CLUSKO R-THUNDER MTN				
Crossing Name:	Clusko R		Total Length (metres):	21.4	
Special Access:			Special Equipment:		
Longitude:	-124 8 46.2		Latitude:	52 33 19.7	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: changed inspection to 2013, low risk site..BT				

Structure Name: PS 62-012

Site #:	65-039	Year Superstructure Installed:	2010	Structure Type/Class:	Temporary Bridge
KM:	0.60	User km:	0.60	Last Inspection Date:	2020/09/28
Project File ID #:	7356	Br.	36	Next Inspection Date:	2022/09/28
Road Name:	CLUSKO RIVER - BR.36				
Crossing Name:	Aneko R trib		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-123 52 36.0		Latitude:	52 33 18.6	
Superstructure:	Steel Box Beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: one year after installation				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 13 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 65-042A

Site #:	65-042	Year Superstructure Installed:	2016	Structure Type/Class:	Temporary Bridge
KM:	4.60	User km:	4.60	Last Inspection Date:	2020/09/28
Project File ID #:	7356	Br.	38	Next Inspection Date:	2022/09/28
Road Name:	CLUSKO RIVER - BR.38				
Crossing Name:	Aneko Ck		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-123 46 43.7		Latitude:	52 34 13.5	
Superstructure:	Steel Box Beam		Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans: 1
Planned Inspection Comments:					

Structure Name: 62-126

Site #:	62-126	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	0.10	User km:	0.10	Last Inspection Date:	2019/10/07
Project File ID #:	8294	Br.	01	Next Inspection Date:	2022/10/07
Road Name:	China Cabin Creek				
Crossing Name:	Moffat Creek		Total Length (metres):	27.8	
Special Access:			Special Equipment:		
Longitude:	-121 27 46.1		Latitude:	52 16 50.1	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:					

Structure Name: 65-029

Site #:	65-029	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	0.30	User km:	0.30	Last Inspection Date:	2019/10/02
Project File ID #:	9334	Br.	07	Next Inspection Date:	2022/10/02
Road Name:	DUSTY LK-DEAN				
Crossing Name:	Unnamed		Total Length (metres):	8.0	
Special Access:			Special Equipment:		
Longitude:	-124 57 10.6		Latitude:	52 15 4.8	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:	CBR Conversion on 17-FEB-14: changed 2012 inspection to 2013, low use road & inaccessible late fall 2012 BT				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 14 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-002

Site #:	62-002	Year Superstructure Installed:	1990	Structure Type/Class:	Major Culvert
KM:	0.10	User km:	0.10	Last Inspection Date:	2019/10/05
Project File ID #:	6970	Br.	01	Next Inspection Date:	2022/10/05
Road Name:	FARWELL CANYON				
Crossing Name:	Cattle underpass		Total Length (metres):	20.0	
Special Access:			Special Equipment:		
Longitude:	-122 31 39.0		Latitude:	51 57 48.4	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					

Structure Name: 62-003A

Site #:	62-003	Year Superstructure Installed:	2007	Structure Type/Class:	Permanent Bridge
KM:	19.00	User km:	21.00	Last Inspection Date:	2019/10/05
Project File ID #:	6970	Br.	01	Next Inspection Date:	2022/10/05
Road Name:	FARWELL CANYON				
Crossing Name:	Chilcotin R		Total Length (metres):	95.0	
Special Access:			Special Equipment:		
Longitude:	-122 33 47.1		Latitude:	51 49 40.5	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 3
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: monitor hairline cracks in pier footings. expansion grout between deck spans failed shortly after construction.				

Structure Name: 62-004

Site #:	62-004	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	3.79	User km:	19.00	Last Inspection Date:	2021/10/06
Project File ID #:	6416	Br.	01	Next Inspection Date:	2022/03/01
Road Name:	GASPARD				
Crossing Name:	Gaspard Cr		Total Length (metres):	13.0	
Special Access:			Special Equipment:		
Longitude:	-122 38 27.1		Latitude:	51 38 24.6	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\HABEURSK on 07-MAR-18: Added to 2018 inspection, with 2017 fire perimeter				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 15 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-032

Site #:	62-032	Year Superstructure Installed:	2006	Structure Type/Class:	Permanent Bridge
KM:	0.30	User km:	6.00	Last Inspection Date:	2018/09/18
Project File ID #:	6416	Br.	24	Next Inspection Date:	2021/09/18
Road Name:	GASPARD CREEK - BR.24				
Crossing Name:	Branch 24 xing Gaspard Ck		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-122 47 39.8		Latitude:	51 35 49.0	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:					

Structure Name: 62-097

Site #:	62-097	Year Superstructure Installed:	2007	Structure Type/Class:	Major Culvert
KM:	3.30	User km:	3.30	Last Inspection Date:	2019/10/05
Project File ID #:	6416	Br.	27	Next Inspection Date:	2022/10/05
Road Name:	GASPARD CREEK - BR.27				
Crossing Name:	Unnamed Mons Ck area 2418Left		Total Length (metres):	6.1	
Special Access:			Special Equipment:		
Longitude:	-122 56 38.5		Latitude:	51 35 52.9	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					

Structure Name: 62-098

Site #:	62-098	Year Superstructure Installed:	2007	Structure Type/Class:	Major Culvert
KM:	4.60	User km:	4.60	Last Inspection Date:	2019/10/05
Project File ID #:	6416	Br.	27	Next Inspection Date:	2022/10/05
Road Name:	GASPARD CREEK - BR.27				
Crossing Name:	Unnamed Mons Ck area 2418Left		Total Length (metres):	6.1	
Special Access:			Special Equipment:		
Longitude:	-122 55 40.3		Latitude:	51 35 42.5	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 16 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-102

Site #:	62-102	Year Superstructure Installed:		2007	Structure Type/Class:	Major Culvert	
KM:	5.62	User km:	5.62	Last Inspection Date:		2019/10/05	
Project File ID #:	6416	Br.	27	Next Inspection Date:		2022/10/05	
Road Name:		GASPARD CREEK - BR.27					
Crossing Name:		Unnamed trib Mons Ck 2418Left		Total Length (metres):		6.1	
Special Access:				Special Equipment:			
Longitude:		-122 54 46.6		Latitude:		51 35 35.8	
Superstructure:				Abutments (Left/Right): <i>(looking downstream)</i>		# Spans: 0	
Planned Inspection Comments:							

Structure Name: 62-101

Site #:	62-101	Year Superstructure Installed:		2007	Structure Type/Class:	Major Culvert	
KM:	0.70	User km:	0.70	Last Inspection Date:		2019/10/05	
Project File ID #:	6416	Br.	28	Next Inspection Date:		2022/10/05	
Road Name:		GASPARD CREEK - BR.28					
Crossing Name:		Unnamed Mons Ck area 2422 Left		Total Length (metres):		6.1	
Special Access:				Special Equipment:			
Longitude:		-122 59 4.3		Latitude:		51 34 28.5	
Superstructure:				Abutments (Left/Right): <i>(looking downstream)</i>		# Spans: 0	
Planned Inspection Comments:							

Structure Name: 62-099

Site #:	62-099	Year Superstructure Installed:		2007	Structure Type/Class:	Major Culvert	
KM:	1.20	User km:	1.20	Last Inspection Date:		2019/10/05	
Project File ID #:	6416	Br.	29	Next Inspection Date:		2022/10/05	
Road Name:		GASPARD CREEK - BR.29					
Crossing Name:		Unnamed Mons Ck area 2422 Left		Total Length (metres):		6.1	
Special Access:				Special Equipment:			
Longitude:		-122 58 57.1		Latitude:		51 34 10.5	
Superstructure:				Abutments (Left/Right): <i>(looking downstream)</i>		# Spans: 0	
Planned Inspection Comments:							



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 17 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-100

Site #:	62-100	Year Superstructure Installed:		2007	Structure Type/Class:	Major Culvert	
KM:	1.80	User km:	1.80	Last Inspection Date:		2019/10/05	
Project File ID #:	6416	Br.	29	Next Inspection Date:		2022/10/05	
Road Name:		GASPARD CREEK - BR.29					
Crossing Name:		Unnamed Mons Ck area 2422 Left		Total Length (metres):		6.1	
Special Access:				Special Equipment:			
Longitude:		-122 58 24.7		Latitude:		51 34 14.0	
Superstructure:				Abutments (Left/Right): <i>(looking downstream)</i>		# Spans: 0	
Planned Inspection Comments:							

Structure Name: PS 62-036

Site #:	62-104	Year Superstructure Installed:	2009	Structure Type/Class:	Temporary Bridge
KM:	0.30	User km:	0.30	Last Inspection Date:	2020/09/27
Project File ID #:	6416	Br.	31	Next Inspection Date:	2022/09/27
Road Name:	GASPARD CREEK - BR.31				
Crossing Name:	Unnamed north of Gaspard Lk		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-122 46 18.2		Latitude:	51 28 37.8	
Superstructure:	Steel Box Beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:	IDIR\BPelletT on 29-MAR-22: BP Mar 29-22 Ask TCC if new bridge tags are available to install during inspection.				

Structure Name: PS62-045

Site #:	62-110	Year Superstructure Installed:	2013	Structure Type/Class:	Temporary Bridge
KM:	0.20	User km:	0.20	Last Inspection Date:	2020/09/27
Project File ID #:	6416	Br.	32	Next Inspection Date:	2022/09/27
Road Name:	GASPARD CREEK - BR.32				
Crossing Name:	unamed		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-122 52 16.0		Latitude:	51 12 37.8	
Superstructure:	Steel Box Beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 18 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-021

Site #:	62-021	Year Superstructure Installed:		1998	Structure Type/Class:	Major Culvert	
KM:	3.00	User km:	0.00	Last Inspection Date:		2019/10/05	
Project File ID #:	6416	Br.	02	Next Inspection Date:		2022/10/05	
Road Name:		GASPARD-CHURN					
Crossing Name:		3100 Rd Unnamed		Total Length (metres):		14.0	
Special Access:				Special Equipment:			
Longitude:		-122 36 17.1		Latitude:		51 32 18.0	
Superstructure:				Abutments (Left/Right): <i>(looking downstream)</i>		# Spans: 0	
Planned Inspection Comments:		CBR_Conversion on 17-FEB-14: check culvert dimensions					

Structure Name: 62-008

Site #:	62-008	Year Superstructure Installed:	1993	Structure Type/Class:	Permanent Bridge
KM:	41.70	User km:	41.50	Last Inspection Date:	2019/10/05
Project File ID #:	6416	Br.	02	Next Inspection Date:	2022/10/05
Road Name:	GASPARD-CHURN				
Crossing Name:	West Churn Cr		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-122 44 12.6		Latitude:	51 18 13.1	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:					

Structure Name: 62-020

Site #:	62-020	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	55.20	User km:	55.20	Last Inspection Date:	2019/10/05
Project File ID #:	6416	Br.	02	Next Inspection Date:	2022/10/05
Road Name:	GASPARD-CHURN				
Crossing Name:	Dash Cr		Total Length (metres):	21.7	
Special Access:			Special Equipment:		
Longitude:	-122 46 29.7		Latitude:	51 14 15.4	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans: 1
Planned Inspection Comments:	IDIR\RMGETZLA on 13-DEC-19: FILE INDICATED L75 CBR_Conversion on 17-FEB-14: South side of structure has unstable fill materials and slopes				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 19 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: PS62-042

Site #:	62-111	Year Superstructure Installed:	2013	Structure Type/Class:	Temporary Bridge
KM:	8.50	User km:	8.50	Last Inspection Date:	2020/09/27
Project File ID #:	6416	Br.	20	Next Inspection Date:	2022/09/27
Road Name:	GASPARD-DASH CREEK				
Crossing Name:	Unnamed		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-122 52 29.9		Latitude:	51 12 36.2	
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: PS62-041

Site #:	62-112	Year Superstructure Installed:	2013	Structure Type/Class:	Temporary Bridge
KM:	8.60	User km:	8.60	Last Inspection Date:	2020/09/27
Project File ID #:	6416	Br.	20	Next Inspection Date:	2022/09/27
Road Name:	GASPARD-DASH CREEK				
Crossing Name:	Unnamed		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-122 52 36.6		Latitude:	51 12 35.6	
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: 62-133

Site #:	62-133	Year Superstructure Installed:		Structure Type/Class:	Major Culvert
KM:	10.50	User km:	10.50	Last Inspection Date:	2019/10/05
Project File ID #:	6416	Br.	20	Next Inspection Date:	2022/10/05
Road Name:	GASPARD-DASH CREEK				
Crossing Name:	Unnamed		Total Length (metres):	14.0	
Special Access:			Special Equipment:		
Longitude:	-122 53 57.7		Latitude:	51 12 28.7	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 20 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: PS62-044

Site #:	62-113	Year Superstructure Installed:	2013	Structure Type/Class:	Temporary Bridge
KM:	10.50	User km:	10.50	Last Inspection Date:	2020/09/27
Project File ID #:	6416	Br.	20	Next Inspection Date:	2022/09/27
Road Name:	GASPARD-DASH CREEK				
Crossing Name:	Unnamed		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-122 53 57.7		Latitude:	51 12 28.7	
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: PS62-043

Site #:	62-115	Year Superstructure Installed:	2013	Structure Type/Class:	Temporary Bridge
KM:	12.90	User km:	12.90	Last Inspection Date:	2020/09/27
Project File ID #:	6416	Br.	20	Next Inspection Date:	2022/09/27
Road Name:	GASPARD-DASH CREEK				
Crossing Name:	Unnamed		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-122 55 25.5		Latitude:	51 12 50.2	
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: PS62-046

Site #:	62-117	Year Superstructure Installed:	2013	Structure Type/Class:	Temporary Bridge
KM:	13.80	User km:	13.80	Last Inspection Date:	2020/09/27
Project File ID #:	6416	Br.	20	Next Inspection Date:	2022/09/27
Road Name:	GASPARD-DASH CREEK				
Crossing Name:	Unnamed		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-122 55 55.1		Latitude:	51 13 3.6	
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 21 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-096

Site #:	62-096	Year Superstructure Installed:		Structure Type/Class:	Major Culvert
KM:	12.20	User km:	11.90	Last Inspection Date:	2019/10/05
Project File ID #:	6416	Br.	15	Next Inspection Date:	2022/10/05
Road Name:	GASPARD-EAST CHURN				
Crossing Name:	Little Churn Creek		Total Length (metres):	24.0	
Special Access:	ATV		Special Equipment:		
Longitude:	-122 34 30.5		Latitude:	51 19 40.7	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					

Structure Name: 62-023

Site #:	62-023	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	17.50	User km:	17.50	Last Inspection Date:	2019/10/05
Project File ID #:	6416	Br.	15	Next Inspection Date:	2022/10/05
Road Name:	GASPARD-EAST CHURN				
Crossing Name:	Borin Cr		Total Length (metres):	13.0	
Special Access:	ATV		Special Equipment:		
Longitude:	-122 33 31.9		Latitude:	51 21 44.4	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: 62-033

Site #:	62-033	Year Superstructure Installed:	2006	Structure Type/Class:	Major Culvert
KM:	17.42	User km:	17.00	Last Inspection Date:	2019/10/05
Project File ID #:	6416	Br.	04	Next Inspection Date:	2022/10/05
Road Name:	GASPARD-MONS CREEK				
Crossing Name:	Mons Creek		Total Length (metres):	26.8	
Special Access:			Special Equipment:		
Longitude:	-122 58 45.2		Latitude:	51 36 48.8	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 22 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-015

Site #:	62-015	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	5.90	User km:	5.90	Last Inspection Date:	2019/10/05
Project File ID #:	6416	Br.	07	Next Inspection Date:	2022/10/05
Road Name:	GASPARD-RED MTN				
Crossing Name:	Churn Cr	Total Length (metres):	30.0		
Special Access:	ATV	Special Equipment:			
Longitude:	-122 40 18.3	Latitude:	51 16 49.1		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: 62-016

Site #:	62-016	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	7.00	User km:	7.00	Last Inspection Date:	2019/10/05
Project File ID #:	6416	Br.	07	Next Inspection Date:	2022/10/05
Road Name:	GASPARD-RED MTN				
Crossing Name:	East Churn Cr	Total Length (metres):	20.0		
Special Access:	ATV	Special Equipment:			
Longitude:	-122 40 4.3	Latitude:	51 16 19.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: 62-017

Site #:	62-017	Year Superstructure Installed:	1996	Structure Type/Class:	Major Culvert
KM:	8.00	User km:	7.80	Last Inspection Date:	2019/10/05
Project File ID #:	6416	Br.	07	Next Inspection Date:	2022/10/05
Road Name:	GASPARD-RED MTN				
Crossing Name:	Unnamed	Total Length (metres):	14.0		
Special Access:	ATV	Special Equipment:			
Longitude:	-122 40 36.6	Latitude:	51 16 0.2		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 23 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-006

Site #:	62-006	Year Superstructure Installed:	1990	Structure Type/Class:	Temporary Bridge
KM:	1.70	User km:	1.70	Last Inspection Date:	2020/09/27
Project File ID #:	6416	Br.	05	Next Inspection Date:	2022/09/27
Road Name:	GASPARD-WEST CHURN				
Crossing Name:	Stobart Cr	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-122 42 21.2	Latitude:	51 23 30.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: some work was being done in Sept on this bridge. do a quick inspection on deck elements in 2009				

Structure Name: 62-027

Site #:	62-027	Year Superstructure Installed:	1997	Structure Type/Class:	Temporary Bridge
KM:	15.50	User km:	15.50	Last Inspection Date:	2020/09/28
Project File ID #:	8363	Br.	01	Next Inspection Date:	2022/09/28
Road Name:	Groundhog Creek				
Crossing Name:	Bambrick Cr	Total Length (metres):	9.0		
Special Access:		Special Equipment:			
Longitude:	-123 19 45.7	Latitude:	51 33 33.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: PS 62-040

Site #:	62-103	Year Superstructure Installed:	2009	Structure Type/Class:	Temporary Bridge
KM:	1.95	User km:	16.70	Last Inspection Date:	2020/09/28
Project File ID #:	8363	Br.	09	Next Inspection Date:	2022/09/28
Road Name:	Groundhog Creek - Branch 9				
Crossing Name:	Upper Bambrick Ck Groundhog Branch	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-123 18 37.4	Latitude:	51 32 34.7		
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: inspect first year after installation				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 24 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-093A

Site #:	62-093	Year Superstructure Installed:	2010	Structure Type/Class:	Permanent Bridge
KM:	5.28	User km:	10.00	Last Inspection Date:	2019/10/07
Project File ID #:	5382	Br.	01	Next Inspection Date:	2022/10/07
Road Name:	HENDRIX CREEK				
Crossing Name:	Basset Ck	Total Length (metres):	24.3		
Special Access:		Special Equipment:			
Longitude:	-120 45 18.2	Latitude:	52 12 34.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: 64-017

Site #:	64-017	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	10.90	User km:	10.00	Last Inspection Date:	2019/10/07
Project File ID #:	5382	Br.	01	Next Inspection Date:	2022/10/07
Road Name:	HENDRIX CREEK				
Crossing Name:	Upper McKinley Cr	Total Length (metres):	20.0		
Special Access:		Special Equipment:			
Longitude:	-120 46 2.5	Latitude:	52 9 50.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: 64-043

Site #:	64-043	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	1.10	User km:	1.00	Last Inspection Date:	2019/10/07
Project File ID #:	5382	Br.	06	Next Inspection Date:	2022/10/07
Road Name:	HENDRIX-DIETRICH				
Crossing Name:	HendrixDietrichFSR xing Dietrich Cr	Total Length (metres):	12.0		
Special Access:		Special Equipment:			
Longitude:	-120 46 46.9	Latitude:	52 6 57.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 25 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-057

Site #:	62-057	Year Superstructure Installed:	1990	Structure Type/Class:	Permanent Bridge
KM:	19.47	User km:	8.00	Last Inspection Date:	2019/10/01
Project File ID #:	4160	Br.	01	Next Inspection Date:	2022/10/01
Road Name:	HORSEFLY - LIKELY				
Crossing Name:	Edney Cr	Total Length (metres):	17.0		
Special Access:		Special Equipment:			
Longitude:	-121 30 35.4	Latitude:	52 29 33.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: redecked in 2006				

Structure Name: 62-047

Site #:	62-047	Year Superstructure Installed:	1986	Structure Type/Class:	Permanent Bridge
KM:	29.18	User km:	29.00	Last Inspection Date:	2019/10/07
Project File ID #:	1242	Br.	01	Next Inspection Date:	2022/10/07
Road Name:	HORSEFLY RIVER				
Crossing Name:	Horsefly R	Total Length (metres):	24.0		
Special Access:		Special Equipment:			
Longitude:	-120 43 38.1	Latitude:	52 23 11.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: PS62-011

Site #:	62-118	Year Superstructure Installed:	2013	Structure Type/Class:	Temporary Bridge
KM:	5.00	User km:	5.00	Last Inspection Date:	2020/09/30
Project File ID #:	9175	Br.	08	Next Inspection Date:	2022/09/30
Road Name:	Halfway - SouthWest Flyshacker				
Crossing Name:	Unnamed	Total Length (metres):	8.0		
Special Access:		Special Equipment:			
Longitude:	-124 56 30.7	Latitude:	51 48 46.8		
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 26 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-046

Site #:	62-046	Year Superstructure Installed:	1985	Structure Type/Class:	Permanent Bridge
KM:	7.23	User km:	6.80	Last Inspection Date:	2019/10/11
Project File ID #:	8359	Br.	01	Next Inspection Date:	2022/10/11
Road Name:	Harveys Creek				
Crossing Name:	Pine Cr	Total Length (metres):	12.0		
Special Access:		Special Equipment:			
Longitude:	-121 19 38.8	Latitude:	52 47 48.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: 62-082

Site #:	62-082	Year Superstructure Installed:	1978	Structure Type/Class:	Major Culvert
KM:	8.45	User km:	8.00	Last Inspection Date:	2019/10/11
Project File ID #:	8359	Br.	01	Next Inspection Date:	2022/10/11
Road Name:	Harveys Creek				
Crossing Name:	Beer Can Cr	Total Length (metres):	36.0		
Special Access:		Special Equipment:			
Longitude:	-121 18 20.0	Latitude:	52 48 53.5		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: 62-030A

Site #:	62-030	Year Superstructure Installed:	2011	Structure Type/Class:	Permanent Bridge
KM:	3.37	User km:	3.30	Last Inspection Date:	2019/10/01
Project File ID #:	8998	Br.	01	Next Inspection Date:	2022/10/01
Road Name:	Jacobie Lake				
Crossing Name:	Unnamed	Total Length (metres):	6.0		
Special Access:		Special Equipment:			
Longitude:	-121 46 1.0	Latitude:	52 32 48.2		
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: first year after install & collect as built information				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 27 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-107

Site #:	62-107	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	4.70	User km:	4.70	Last Inspection Date:	2019/10/11
Project File ID #:	8380	Br.	14	Next Inspection Date:	2022/10/11
Road Name:	KANGAROO CK-ROLLIE L				
Crossing Name:	Ehie Creek (Rollie Lk area)		Total Length (metres):	6.8	
Special Access:			Special Equipment:		
Longitude:	-121 33 54.2		Latitude:	52 44 48.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\RMGETZLA on 18-DEC-19: NOTHING ON FILE INDICATING LOAD RATING CBR_Conversion on 17-FEB-14: either close road or have the timber xties and deck/curbs replaced				

Structure Name: 65-046

Site #:	65-046	Year Superstructure Installed:	2012	Structure Type/Class:	Temporary Bridge
KM:	15.60	User km:	15.60	Last Inspection Date:	2020/09/30
Project File ID #:	9175	Br.	01	Next Inspection Date:	2022/09/30
Road Name:	MINER LAKE				
Crossing Name:	Minor Creek		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-125 0 23.4		Latitude:	51 51 57.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: 65-044

Site #:	65-044	Year Superstructure Installed:	1986	Structure Type/Class:	Temporary Bridge
KM:	15.30	User km:	15.30	Last Inspection Date:	2019/10/02
Project File ID #:	7651	Br.	01	Next Inspection Date:	2021/10/02
Road Name:	MOSLEY CREEK				
Crossing Name:	Hell Raving Creek		Total Length (metres):	16.0	
Special Access:			Special Equipment:		
Longitude:	-124 57 30.5		Latitude:	51 39 21.6	
Superstructure:	Rail Car	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: railway car has been installed although creek very active on this fan and heavy sediment & bed load may make this structure ineffective due to natural channel realignments				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 28 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-009

Site #:	62-009	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	12.21	User km:	11.00	Last Inspection Date:	2019/10/04
Project File ID #:	6426	Br.	02	Next Inspection Date:	2022/10/04
Road Name:	ROSITA-MACKIN				
Crossing Name:	Mackin Cr	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-122 41 49.3	Latitude:	52 12 8.4		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: 62-022

Site #:	62-022	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	14.00	User km:	14.00	Last Inspection Date:	2019/10/04
Project File ID #:	6426	Br.	02	Next Inspection Date:	2022/10/04
Road Name:	ROSITA-MACKIN				
Crossing Name:	Taylor Cr Trib	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-122 42 24.8	Latitude:	52 11 10.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: 62-109

Site #:	62-109	Year Superstructure Installed:	2013	Structure Type/Class:	Temporary Bridge
KM:	14.50	User km:	14.50	Last Inspection Date:	2020/10/01
Project File ID #:	6426	Br.	02	Next Inspection Date:	2022/10/01
Road Name:	ROSITA-MACKIN				
Crossing Name:	Unnamed	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-122 42 5.2	Latitude:	52 10 53.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 29 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-010

Site #:	62-010	Year Superstructure Installed:	1991	Structure Type/Class:	Major Culvert
KM:	16.46	User km:	16.00	Last Inspection Date:	2019/10/04
Project File ID #:	6426	Br.	01	Next Inspection Date:	2022/10/04
Road Name:	ROSITA-MELDRUM				
Crossing Name:	Mackin Cr	Total Length (metres):	20.0		
Special Access:		Special Equipment:			
Longitude:	-122 34 1.6	Latitude:	52 15 44.2		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: 62-025

Site #:	62-025	Year Superstructure Installed:	2000	Structure Type/Class:	Major Culvert
KM:	39.56	User km:	39.00	Last Inspection Date:	2019/10/04
Project File ID #:	6426	Br.	01	Next Inspection Date:	2022/10/04
Road Name:	ROSITA-MELDRUM				
Crossing Name:	Twan Cr	Total Length (metres):	28.0		
Special Access:	ATV	Special Equipment:			
Longitude:	-122 54 10.0	Latitude:	52 18 35.6		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: PS 62-035

Site #:	62-105	Year Superstructure Installed:	2008	Structure Type/Class:	Temporary Bridge
KM:	7.30	User km:	7.30	Last Inspection Date:	2020/09/27
Project File ID #:	10561	Br.	01	Next Inspection Date:	2022/09/27
Road Name:	STOBART CREEK				
Crossing Name:	Stobart Ck FSR Unnamed Ck	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-122 47 6.4	Latitude:	51 25 43.8		
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 30 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-120

Site #:	62-120	Year Superstructure Installed:	2014	Structure Type/Class:	Temporary Bridge
KM:	10.50	User km:	10.50	Last Inspection Date:	2020/09/27
Project File ID #:	10561	Br.	01	Next Inspection Date:	2022/09/27
Road Name:	STOBART CREEK				
Crossing Name:	No Name	Total Length (metres):	12.0		
Special Access:		Special Equipment:			
Longitude:	-122 53 17.9	Latitude:	51 24 18.5		
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: 62-122

Site #:	62-122	Year Superstructure Installed:	2014	Structure Type/Class:	Temporary Bridge
KM:	9.90	User km:	9.90	Last Inspection Date:	2020/09/27
Project File ID #:	10561	Br.	03	Next Inspection Date:	2022/09/27
Road Name:	STOBART CREEK-BR.3				
Crossing Name:	Noname	Total Length (metres):	7.7		
Special Access:		Special Equipment:			
Longitude:	-122 53 10.6	Latitude:	51 25 7.4		
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: 65-031

Site #:	65-031	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	0.50	User km:	0.50	Last Inspection Date:	2019/10/04
Project File ID #:	9896	Br.	02	Next Inspection Date:	2022/10/04
Road Name:	TETE ANGELA - BR.2				
Crossing Name:	Unnamed	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-123 28 27.9	Latitude:	51 31 11.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: changed 2012 nspection to 2013 due to inaccessibility late fall 2012 low use BT				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 31 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 65-030

Site #:	65-030	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	1.80	User km:	8.50	Last Inspection Date:	2019/10/04
Project File ID #:	9896	Br.	01	Next Inspection Date:	2022/10/04
Road Name:	Tete Angela South				
Crossing Name:	Unnamed		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-123 27 45.0		Latitude:	51 31 20.2	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: changed 2012 inspection to 2013 due to inaccessibility in late 2012 BT				

Structure Name: 62-094

Site #:	62-094	Year Superstructure Installed:	1993	Structure Type/Class:	Major Culvert
KM:	5.33	User km:	5.80	Last Inspection Date:	2019/10/11
Project File ID #:	9320	Br.	01	Next Inspection Date:	2022/10/11
Road Name:	Yanks Peak				
Crossing Name:	Four Cr		Total Length (metres):	18.0	
Special Access:			Special Equipment:		
Longitude:	-121 25 54.4		Latitude:	52 47 31.4	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					

Structure Name: 62-086

Site #:	62-086	Year Superstructure Installed:	1993	Structure Type/Class:	Major Culvert
KM:	7.17	User km:	7.70	Last Inspection Date:	2019/10/11
Project File ID #:	9320	Br.	01	Next Inspection Date:	2022/10/11
Road Name:	Yanks Peak				
Crossing Name:	Weaver Cr		Total Length (metres):	32.0	
Special Access:			Special Equipment:		
Longitude:	-121 26 37.0		Latitude:	52 47 49.8	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 32 of 32
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cariboo-Chilcotin Natural Resource District Next Planned Inspection Date: < 2022/12/31 Inspection Status:Inspect Sort:

Structure Name: 62-068

Site #:	62-068	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	11.21	User km:	11.70	Last Inspection Date:	2019/10/06
Project File ID #:	9320	Br.	01	Next Inspection Date:	2022/10/06
Road Name:	Yanks Peak				
Crossing Name:	French Snowshoe Cr	Total Length (metres):	21.0		
Special Access:		Special Equipment:			
Longitude:	-121 28 27.2	Latitude:	52 49 20.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1

Planned Inspection Comments:

Structure Type/Class Totals

Permanent Bridge Total: 39	Major Culvert Total: 21
Temporary Bridge Total: 34	Woodbox/Log Culvert Total: 0