



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 1 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K1117

Site #:	K1117	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	2.01	User km:	29.00	Last Inspection Date:	2021/10/10
Project File ID #:	0814	Br.	15	Next Inspection Date:	2022/10/10
Road Name:	-SKUHOST BRANCH 15				
Crossing Name:	Skuhost #2		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-121 2 20.7		Latitude:	50 20 35.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 25-FEB-22: BP Feb 25-22 Measure-up completed in 2018 (DA 2016-02-12) please measure girders depth, flange thickness etc. As we need to verify we have the correct shop drawings on file.				

Structure Name: K1092

Site #:	K1092	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	5.48	User km:	5.30	Last Inspection Date:	2019/10/04
Project File ID #:	8479	Br.	01	Next Inspection Date:	2022/10/04
Road Name:	ARRASTRA CREEK				
Crossing Name:	Newton Cr		Total Length (metres):	12.6	
Special Access:			Special Equipment:		
Longitude:	-120 44 20.4		Latitude:	49 27 50.4	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1091

Site #:	K1091	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	14.81	User km:	14.60	Last Inspection Date:	2019/10/04
Project File ID #:	8479	Br.	01	Next Inspection Date:	2022/10/04
Road Name:	ARRASTRA CREEK				
Crossing Name:	Arrastra Cr		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-120 46 40.8		Latitude:	49 24 43.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 2 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: TKA008

Site #:	K1609	Year Superstructure Installed:	2013	Structure Type/Class:	Permanent Bridge
KM:	19.10	User km:	19.10	Last Inspection Date:	2019/10/04
Project File ID #:	8479	Br.	01	Next Inspection Date:	2022/10/04
Road Name:	ARRASTRA CREEK				
Crossing Name:	Trib to Arrastra Cr		Total Length (metres):	9.6	
Special Access:			Special Equipment:		
Longitude:	-120 49 15.8		Latitude:	49 23 22.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: requires structure id				

Structure Name: WO2125

Site #:	K1610	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	19.50	User km:	19.50	Last Inspection Date:	2019/10/04
Project File ID #:	8479	Br.	01	Next Inspection Date:	2022/10/04
Road Name:	ARRASTRA CREEK				
Crossing Name:	Arrastra Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-120 49 37.8		Latitude:	49 23 23.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: 930-B007

Site #:	K1577	Year Superstructure Installed:		Structure Type/Class:	Temporary Bridge
KM:	2.30	User km:	2.30	Last Inspection Date:	2021/08/05
Project File ID #:	8529	Br.	62	Next Inspection Date:	2022/08/05
Road Name:	BRANCH 62				
Crossing Name:	Galena Cr		Total Length (metres):	7.6	
Special Access:			Special Equipment:		
Longitude:	-120 15 12.4		Latitude:	49 48 58.1	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Drill timber sill to determine if any rot has occurred. DA.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 3 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K719

Site #:	K719	Year Superstructure Installed:	1988	Structure Type/Class:	Permanent Bridge
KM:	10.88	User km:	11.00	Last Inspection Date:	2019/07/07
Project File ID #:	8529	Br.	01	Next Inspection Date:	2022/07/07
Road Name:	DILLARD CREEK				
Crossing Name:	Shrimpton Cr		Total Length (metres):	7.4	
Special Access:			Special Equipment:		
Longitude:	-120 31 48.5		Latitude:	49 48 30.1	
Superstructure:	Concrete I/T Beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:					

Structure Name: 930-B006

Site #:	K1575	Year Superstructure Installed:		Structure Type/Class:	Permanent Bridge
KM:	2.90	User km:		Last Inspection Date:	2021/08/05
Project File ID #:	8529	Br.	60	Next Inspection Date:	2022/08/05
Road Name:	ELKHART-GALENA				
Crossing Name:	Galena Cr		Total Length (metres):	11.6	
Special Access:			Special Equipment:		
Longitude:	-120 16 23.5		Latitude:	49 48 27.6	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\BPellet on 10-MAR-22: BP Mar 10-22 Measure lean in posts and gap between slabs and cap beams with every annual inspection.				

Structure Name: K2042

Site #:	K2042	Year Superstructure Installed:	2000	Structure Type/Class:	Major Culvert
KM:	17.93	User km:	17.80	Last Inspection Date:	2019/10/02
Project File ID #:	8529	Br.	04	Next Inspection Date:	2022/10/02
Road Name:	GALENA				
Crossing Name:	Elusive Cr		Total Length (metres):	18.0	
Special Access:			Special Equipment:		
Longitude:	-120 20 18.3		Latitude:	49 47 30.6	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 4 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K718

Site #:	K718	Year Superstructure Installed:	1986	Structure Type/Class:	Major Culvert
KM:	19.11	User km:	30.40	Last Inspection Date:	2019/10/02
Project File ID #:	8529	Br.	04	Next Inspection Date:	2022/10/02
Road Name:	GALENA				
Crossing Name:	Galena Cr		Total Length (metres):	24.0	
Special Access:			Special Equipment:		
Longitude:	-120 19 50.8		Latitude:	49 47 2.1	
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:					

Structure Name: K1348

Site #:	K1348	Year Superstructure Installed:	2006	Structure Type/Class:	Permanent Bridge
KM:	0.03	User km:	16.00	Last Inspection Date:	2019/10/04
Project File ID #:	3600	Br.	05	Next Inspection Date:	2022/10/04
Road Name:	GARRISON				
Crossing Name:	Whipsaw Cr		Total Length (metres):	13.6	
Special Access:			Special Equipment:		
Longitude:	-120 41 6.6		Latitude:	49 16 44.4	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: K790

Site #:	K790	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	12.06	User km:	27.50	Last Inspection Date:	2019/10/04
Project File ID #:	3600	Br.	05	Next Inspection Date:	2022/10/04
Road Name:	GARRISON				
Crossing Name:	Copper Cr		Total Length (metres):	11.6	
Special Access:			Special Equipment:		
Longitude:	-120 43 26.0		Latitude:	49 12 26.0	
Superstructure:	Concrete Box Beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 5 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K791

Site #:	K791	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	12.17	User km:	27.60	Last Inspection Date:	2019/10/04
Project File ID #:	3600	Br.	05	Next Inspection Date:	2022/10/04
Road Name:	GARRISON				
Crossing Name:	Copper Cr Trib		Total Length (metres):	14.0	
Special Access:			Special Equipment:		
Longitude:	-120 43 42.6		Latitude:	49 12 24.6	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:					

Structure Name: K842

Site #:	K842	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	0.16	User km:	0.20	Last Inspection Date:	2019/10/02
Project File ID #:	8615	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	GRANT CREEK				
Crossing Name:	Hayes Cr		Total Length (metres):	16.0	
Special Access:			Special Equipment:		
Longitude:	-120 21 15.9		Latitude:	49 37 55.0	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\PBLUESCH on 14-FEB-20: PB Feb14.2020 Repairs completed. IDIR\DMALWAY on 25-JAN-17: Structure now at 5 tonnes load restriction until 2019 inspection, if no curb repairs completed then it should be posted as closed. CBR_Conversion on 17-FEB-14: Structure was restricted to 20 tonnes in 2011, ensure posted. If no curb repairs are completed in 2016, then post at 5 tonnes restriction. Feb 2013.				

Structure Name: K1396

Site #:	K1396	Year Superstructure Installed:	2004	Structure Type/Class:	Temporary Bridge
KM:	0.00	User km:	16.70	Last Inspection Date:	2021/09/17
Project File ID #:	3601	Br.	16	Next Inspection Date:	2022/09/17
Road Name:	HORNET BR 16				
Crossing Name:	Allison Cr		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-120 33 53.2		Latitude:	49 43 35.3	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 12-APR-22: .				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 6 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K1347

Site #:	K1347	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:	0.09	User km:	18.00	Last Inspection Date:	2019/07/07
Project File ID #:	3601	Br.	14	Next Inspection Date:	2022/07/07
Road Name:	HORNET-MYSTERY BR 14				
Crossing Name:	Allison Cr	Total Length (metres):	9.1		
Special Access:		Special Equipment:			
Longitude:	-120 33 21.0	Latitude:	49 43 5.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K666

Site #:	K666	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	3.43	User km:	3.40	Last Inspection Date:	2021/10/12
Project File ID #:	8708	Br.	01	Next Inspection Date:	2022/10/12
Road Name:	JULIET CREEK				
Crossing Name:	Unnamed	Total Length (metres):	8.0		
Special Access:		Special Equipment:			
Longitude:	-121 3 30.5	Latitude:	49 44 14.7		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K488

Site #:	K488	Year Superstructure Installed:	1990	Structure Type/Class:	Permanent Bridge
KM:	3.69	User km:	3.60	Last Inspection Date:	2021/10/12
Project File ID #:	8708	Br.	01	Next Inspection Date:	2022/10/12
Road Name:	JULIET CREEK				
Crossing Name:	Juliet Cr	Total Length (metres):	16.3		
Special Access:		Special Equipment:			
Longitude:	-121 3 42.2	Latitude:	49 44 10.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 22-JAN-19: PB Jan22.2019 Assess footings for scour and girders for damage from debris loading at midspan. Upstream girder is likely deflected (the bottom interior diaphragm member is bent at midspan).				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 7 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K426

Site #:	K426	Year Superstructure Installed:	1986	Structure Type/Class:	Temporary Bridge
KM:	0.32	User km:	9.30	Last Inspection Date:	2010/09/21
Project File ID #:	3600	Br.	04	Next Inspection Date:	2012/09/21
Road Name:	KENNEDY				
Crossing Name:	Whipsaw Cr		Total Length (metres):	7.4	
Special Access:			Special Equipment:		
Longitude:	-120 38 31.1		Latitude:	49 19 17.8	
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1161

Site #:	K1161	Year Superstructure Installed:	2006	Structure Type/Class:	Major Culvert
KM:	0.00	User km:	17.00	Last Inspection Date:	2019/07/08
Project File ID #:	4156	Br.	02	Next Inspection Date:	2022/07/08
Road Name:	LALUWISSIN-N. LALUWI				
Crossing Name:	Laluwissin Cr trib		Total Length (metres):	20.0	
Special Access:			Special Equipment:		
Longitude:	-121 35 37.1		Latitude:	50 30 31.3	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\DMALWAY on 14-FEB-20: n/a				

Structure Name: K1138

Site #:	K1138	Year Superstructure Installed:	2000	Structure Type/Class:	Major Culvert
KM:	11.32	User km:	19.80	Last Inspection Date:	2009/08/28
Project File ID #:	5104	Br.	01	Next Inspection Date:	2012/08/28
Road Name:	LAWLESS CREEK				
Crossing Name:	Unnamed		Total Length (metres):	14.0	
Special Access:			Special Equipment:		
Longitude:	-120 53 38.5		Latitude:	49 37 20.1	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 8 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K1139

Site #:	K1139	Year Superstructure Installed:	2000	Structure Type/Class:	Major Culvert
KM:	11.43	User km:	19.90	Last Inspection Date:	2010/09/22
Project File ID #:	5104	Br.	01	Next Inspection Date:	2013/09/22
Road Name:	LAWLESS CREEK				
Crossing Name:	Unnamed		Total Length (metres):	14.0	
Special Access:			Special Equipment:		
Longitude:	-120 54 36.6		Latitude:	49 38 13.7	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					

Structure Name: K664

Site #:	K664	Year Superstructure Installed:	1995	Structure Type/Class:	Woodbox/Log Culvert
KM:	13.35	User km:	22.10	Last Inspection Date:	2011/07/14
Project File ID #:	5104	Br.	01	Next Inspection Date:	2013/07/14
Road Name:	LAWLESS CREEK				
Crossing Name:	Pioneer Cr		Total Length (metres):	13.0	
Special Access:			Special Equipment:		
Longitude:	-120 54 37.0		Latitude:	49 38 14.2	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					

Structure Name: K715

Site #:	K715	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	3.85	User km:	4.00	Last Inspection Date:	2019/10/05
Project File ID #:	6069	Br.	04	Next Inspection Date:	2022/10/05
Road Name:	MAKA-MICHAEL				
Crossing Name:	Debbie Cr		Total Length (metres):	9.0	
Special Access:			Special Equipment:		
Longitude:	-121 2 10.2		Latitude:	49 47 38.4	
Superstructure:	Concrete Box Beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 9 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K439

Site #:	K439	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	0.03	User km:	0.10	Last Inspection Date:	2019/09/07
Project File ID #:	4670	Br.	01	Next Inspection Date:	2022/09/07
Road Name:	MANNING CREEK				
Crossing Name:	Nicola R	Total Length (metres):	51.5		
Special Access:		Special Equipment:	Peeper Truck		
Longitude:	-121 6 58.2	Latitude:	50 15 16.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	2
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Peep inspection frequency should be every 6 years				

Structure Name: K1488

Site #:	K1488	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	0.50	User km:	6.50	Last Inspection Date:	2019/10/02
Project File ID #:	7469	Br.	02	Next Inspection Date:	2022/10/02
Road Name:	ME7469.02				
Crossing Name:	Simen Cr	Total Length (metres):	15.2		
Special Access:		Special Equipment:			
Longitude:	-120 18 22.3	Latitude:	49 43 56.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Check user KM, also monitor approaches. DA Jan 2014				

Structure Name: WO-295

Site #:	K1756	Year Superstructure Installed:	2021	Structure Type/Class:	Temporary Bridge
KM:	2.40	User km:	2.40	Last Inspection Date:	
Project File ID #:	7573	Br.	08	Next Inspection Date:	2022/09/25
Road Name:	ME7573.08				
Crossing Name:	Unknown	Total Length (metres):	12.3		
Special Access:		Special Equipment:			
Longitude:	-120 35 51.2	Latitude:	49 1 59.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 25-SEP-19: Inspection one year after installation.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 10 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: WO3228

Site #:	K1486	Year Superstructure Installed:	2010	Structure Type/Class:	Temporary Bridge
KM:	0.40	User km:	0.40	Last Inspection Date:	2021/08/05
Project File ID #:	8614	Br.	07	Next Inspection Date:	2022/08/05
Road Name:	ME8614.07				
Crossing Name:	Unnamed Cr		Total Length (metres):	7.6	
Special Access:			Special Equipment:		
Longitude:	-120 15 39.3		Latitude:	49 32 34.9	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 10-MAR-22: BP Mar 10-22 Annual inspection until deck is replaced. Monitor all wooden deck components for rot progression and safety to road users.				

Structure Name: K1031

Site #:	K1031	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	11.04	User km:	9.80	Last Inspection Date:	2021/10/07
Project File ID #:	8551	Br.	01	Next Inspection Date:	2022/10/07
Road Name:	MELLIN LAKE				
Crossing Name:	Spahomin Cr		Total Length (metres):	14.4	
Special Access:			Special Equipment:		
Longitude:	-120 6 39.6		Latitude:	50 3 3.0	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: K649

Site #:	K649	Year Superstructure Installed:	2002	Structure Type/Class:	Permanent Bridge
KM:	5.04	User km:	30.50	Last Inspection Date:	2019/10/04
Project File ID #:	3600	Br.	06	Next Inspection Date:	2022/10/04
Road Name:	NICOMEN				
Crossing Name:	Copper CrTtrib		Total Length (metres):	10.6	
Special Access:			Special Equipment:		
Longitude:	-120 44 53.0		Latitude:	49 11 44.8	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 25-JAN-17: N/A				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 11 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K650

Site #:	K650	Year Superstructure Installed:	2003	Structure Type/Class:	Temporary Bridge
KM:	10.79	User km:	36.40	Last Inspection Date:	2021/09/17
Project File ID #:	3600	Br.	06	Next Inspection Date:	2022/09/17
Road Name:	NICOMEN				
Crossing Name:	Copper Cr Trib		Total Length (metres):	11.3	
Special Access:			Special Equipment:		
Longitude:	-120 48 7.9		Latitude:	49 12 25.7	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:	IDIR\BPellet on 27-APR-22: BP Apr 27-22 Inspector to thoroughly search for fabricator markings and photograph any found				

Structure Name: K445

Site #:	K445	Year Superstructure Installed:	1982	Structure Type/Class:	Permanent Bridge
KM:	0.27	User km:	0.30	Last Inspection Date:	2020/07/04
Project File ID #:	7573	Br.	01	Next Inspection Date:	2022/07/04
Road Name:	PASAYTEN RIVER				
Crossing Name:	Similkameen R		Total Length (metres):	32.0	
Special Access:			Special Equipment:	Peeper Truck	
Longitude:	-120 36 8.0		Latitude:	49 8 50.0	
Superstructure:	Glulam Girder		Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans: 1
Planned Inspection Comments:	IDIR\DMALWAY on 23-APR-18: Close Proximity Inspections to occur every 5 years.				

Structure Name: K448

Site #:	K448	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:	24.79	User km:	25.50	Last Inspection Date:	2019/10/04
Project File ID #:	7573	Br.	01	Next Inspection Date:	2022/10/04
Road Name:	PASAYTEN RIVER				
Crossing Name:	Upper Peeve Cr		Total Length (metres):	15.2	
Special Access:	ATV		Special Equipment:		
Longitude:	-120 30 48.0		Latitude:	49 0 40.8	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Ensure to bring quad due to brush, check with district prior to next inspection. Jan 2014 DA.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 12 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: WO-1634

Site #:	K1722	Year Superstructure Installed:	1998	Structure Type/Class:	Temporary Bridge
KM:	0.50	User km:	0.50	Last Inspection Date:	2021/10/07
Project File ID #:	10273	Br.	14	Next Inspection Date:	2022/10/07
Road Name:	PLATEAU LAKE				
Crossing Name:	Unknown		Total Length (metres):	9.1	
Special Access:			Special Equipment:		
Longitude:	-120 17 8.6		Latitude:	50 18 39.3	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Other	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 17-MAR-22: BP Mar 17-22 Planned for deactivation in 2022 or 2023. Check with BCTS if site has been deactivated before inspecting.				

Structure Name: K682

Site #:	K682	Year Superstructure Installed:	1993	Structure Type/Class:	Permanent Bridge
KM:	29.19	User km:	0.50	Last Inspection Date:	2021/10/11
Project File ID #:	4669	Br.	03	Next Inspection Date:	2022/10/11
Road Name:	PROSPECT BR 03				
Crossing Name:	Spius Cr		Total Length (metres):	16.0	
Special Access:			Special Equipment:		
Longitude:	-121 1 45.7		Latitude:	50 8 9.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Cast in Place	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Do not inspect prior to August 15 so as to allow for lower water levels to assess abutments appropriately. MRF 11/2013				

Structure Name: K870

Site #:	K870	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	0.28	User km:	13.70	Last Inspection Date:	2019/10/06
Project File ID #:	4669	Br.	02	Next Inspection Date:	2022/10/06
Road Name:	PROSPECT MINER A				
Crossing Name:	Miner Cr		Total Length (metres):	13.0	
Special Access:			Special Equipment:		
Longitude:	-121 9 1.8		Latitude:	50 2 27.6	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 13 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K1438

Site #:	K1438	Year Superstructure Installed:	2008	Structure Type/Class:	Permanent Bridge
KM:	12.24	User km:	25.50	Last Inspection Date:	2021/09/17
Project File ID #:	4669	Br.	02	Next Inspection Date:	2022/09/17
Road Name:	PROSPECT MINER A				
Crossing Name:	Silver Cr	Total Length (metres):	11.6		
Special Access:		Special Equipment:			
Longitude:	-121 10 36.4	Latitude:	49 58 10.6		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\BLUESCH on 23-JAN-19: PB Jan23.2019 Continue to monitor left bank scour at toe of rip rap (upstream). Approaches require fill to ensure safe traffic, slab girder ends are exposed and a hazard to public traffic.				

Structure Name: K1501

Site #:	K1501	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	36.80	User km:	39.00	Last Inspection Date:	2019/10/03
Project File ID #:	8614	Br.	01	Next Inspection Date:	2022/10/03
Road Name:	RED CREEK				
Crossing Name:	Unknown	Total Length (metres):	10.5		
Special Access:		Special Equipment:			
Longitude:	-120 5 50.7	Latitude:	49 32 43.6		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K407

Site #:	K407	Year Superstructure Installed:	2001	Structure Type/Class:	Permanent Bridge
KM:	40.23	User km:	41.90	Last Inspection Date:	2019/10/03
Project File ID #:	8614	Br.	01	Next Inspection Date:	2022/10/03
Road Name:	RED CREEK				
Crossing Name:	McNulty Cr	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-120 5 25.2	Latitude:	49 34 25.2		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 14 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K406

Site #:	K406	Year Superstructure Installed:	2001	Structure Type/Class:	Permanent Bridge
KM:	40.59	User km:	42.30	Last Inspection Date:	2019/10/03
Project File ID #:	8614	Br.	01	Next Inspection Date:	2022/10/03
Road Name:	RED CREEK				
Crossing Name:	McNulty Cr	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-120 5 33.4	Latitude:	49 34 20.2		
Superstructure:	Concrete Box Beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1500

Site #:	K1500	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	24.80	User km:		Last Inspection Date:	2019/10/03
Project File ID #:	8614	Br.	04	Next Inspection Date:	2022/10/03
Road Name:	RED-ISINTOK BR 04				
Crossing Name:	Unnamed	Total Length (metres):	11.4		
Special Access:		Special Equipment:			
Longitude:	-120 11 43.5	Latitude:	49 32 56.1		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 19-FEB-20: PB Feb19.2020 Monitor abutments for rotation.				

Structure Name: K351

Site #:	K351	Year Superstructure Installed:	1983	Structure Type/Class:	Permanent Bridge
KM:	0.14	User km:	27.60	Last Inspection Date:	2021/10/07
Project File ID #:	7666	Br.	01	Next Inspection Date:	2022/10/07
Road Name:	SALMON RIVER				
Crossing Name:	Salmon R	Total Length (metres):	6.0		
Special Access:		Special Equipment:			
Longitude:	-119 57 53.4	Latitude:	50 19 6.6		
Superstructure:	Concrete Cast in Place	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 13-FEB-18: na				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 15 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K1512

Site #:	K1512	Year Superstructure Installed:	2007	Structure Type/Class:	Major Culvert
KM:	0.20	User km:	14.50	Last Inspection Date:	2021/09/16
Project File ID #:	0814	Br.	40	Next Inspection Date:	2022/09/16
Road Name:	SKUHUN-CALLING LAKE				
Crossing Name:	Calling lake OverFlow		Total Length (metres):	9.8	
Special Access:			Special Equipment:		
Longitude:	-121 6 43.3		Latitude:	50 27 43.1	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					

Structure Name: K888

Site #:	K888	Year Superstructure Installed:	2004	Structure Type/Class:	Permanent Bridge
KM:	0.81	User km:	12.00	Last Inspection Date:	2019/07/08
Project File ID #:	0814	Br.	32	Next Inspection Date:	2022/07/08
Road Name:	SKUHUN-INKIKUN 32				
Crossing Name:	Inkukuh Cr		Total Length (metres):	7.6	
Special Access:			Special Equipment:		
Longitude:	-121 8 3.0		Latitude:	50 28 15.0	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Missed in the 2012 inspection year, re-scheduled for 2013. Check with district for detailed access location. DA.				

Structure Name: K423

Site #:	K423	Year Superstructure Installed:	1987	Structure Type/Class:	Permanent Bridge
KM:	10.56	User km:	10.50	Last Inspection Date:	2019/07/08
Project File ID #:	0814	Br.	03	Next Inspection Date:	2022/07/08
Road Name:	SKUHUN-PIMAINUS				
Crossing Name:	Chataway Cr		Total Length (metres):	7.0	
Special Access:			Special Equipment:		
Longitude:	-120 55 52.8		Latitude:	50 19 18.0	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 16 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K1401

Site #:	K1401	Year Superstructure Installed:	2006	Structure Type/Class:	Major Culvert
KM:	25.40	User km:	33.00	Last Inspection Date:	2019/07/08
Project File ID #:	0814	Br.	03	Next Inspection Date:	2022/07/08
Road Name:	SKUHUN-PIMAINUS				
Crossing Name:	Skuhost Cr		Total Length (metres):	23.5	
Special Access:			Special Equipment:		
Longitude:	-121 1 50.4		Latitude:	50 25 2.7	
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Gather culvert length, inlet cover depth and outlet cover depth. MRF 09/2013				

Structure Name: K484

Site #:	K484	Year Superstructure Installed:	1990	Structure Type/Class:	Permanent Bridge
KM:	0.21	User km:	40.10	Last Inspection Date:	2019/07/08
Project File ID #:	0814	Br.	08	Next Inspection Date:	2022/07/08
Road Name:	SKUHUN-SPAIST WEST				
Crossing Name:	Pimainus Cr		Total Length (metres):	7.6	
Special Access:			Special Equipment:		
Longitude:	-121 6 58.2		Latitude:	50 23 57.6	
Superstructure:	Concrete Box Beam		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:					

Structure Name: K1059

Site #:	K1059	Year Superstructure Installed:	1965	Structure Type/Class:	Permanent Bridge
KM:	0.01	User km:	22.70	Last Inspection Date:	2013/06/25
Project File ID #:	4332	Br.	01	Next Inspection Date:	2016/06/25
Road Name:	SPIUS CREEK				
Crossing Name:	Unnamed		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-121 13 6.3		Latitude:	49 56 0.9	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 17 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K427

Site #:	K427	Year Superstructure Installed:	1986	Structure Type/Class:	Permanent Bridge
KM:	10.35	User km:	21.00	Last Inspection Date:	2019/10/06
Project File ID #:	4332	Br.	01	Next Inspection Date:	2022/10/06
Road Name:	SPIUS CREEK				
Crossing Name:	Spius Cr		Total Length (metres):	23.0	
Special Access:			Special Equipment:		
Longitude:	-121 4 52.2		Latitude:	49 58 0.6	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: K476

Site #:	K476	Year Superstructure Installed:	1990	Structure Type/Class:	Permanent Bridge
KM:	12.60	User km:	23.10	Last Inspection Date:	2021/10/12
Project File ID #:	4332	Br.	01	Next Inspection Date:	2022/10/12
Road Name:	SPIUS CREEK				
Crossing Name:	Silver Cr		Total Length (metres):	16.0	
Special Access:			Special Equipment:		
Longitude:	-121 5 49.0		Latitude:	49 57 1.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Reinspect to determine if rounded logs on curbs have been replaced. DA. Jan 2014				

Structure Name: K714

Site #:	K714	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	14.48	User km:	14.30	Last Inspection Date:	2019/10/06
Project File ID #:	4332	Br.	01	Next Inspection Date:	2022/10/06
Road Name:	SPIUS CREEK				
Crossing Name:	S Fork Spius		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-121 6 36.6		Latitude:	49 56 12.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 18 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K486

Site #:	K486	Year Superstructure Installed:	1990	Structure Type/Class:	Permanent Bridge
KM:	14.69	User km:	14.50	Last Inspection Date:	2019/10/06
Project File ID #:	4332	Br.	01	Next Inspection Date:	2022/10/06
Road Name:	SPIUS CREEK				
Crossing Name:	Spius Cr		Total Length (metres):	22.0	
Special Access:			Special Equipment:		
Longitude:	-121 6 45.6		Latitude:	49 56 11.4	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:					

Structure Name: K1057

Site #:	K1057	Year Superstructure Installed:	1986	Structure Type/Class:	Temporary Bridge
KM:	20.70	User km:	31.30	Last Inspection Date:	2013/06/25
Project File ID #:	4332	Br.	01	Next Inspection Date:	2015/06/25
Road Name:	SPIUS CREEK				
Crossing Name:	Unnamed		Total Length (metres):	6.0	
Special Access:			Special Equipment:		
Longitude:	-121 11 36.5		Latitude:	49 56 7.2	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Structure to be deactivated or downgraded further upon next inspection. DA. Jan 2014.				

Structure Name: K1058

Site #:	K1058	Year Superstructure Installed:	1965	Structure Type/Class:	Permanent Bridge
KM:	22.57	User km:	33.20	Last Inspection Date:	2013/06/25
Project File ID #:	4332	Br.	01	Next Inspection Date:	2016/06/25
Road Name:	SPIUS CREEK				
Crossing Name:	Unnamed		Total Length (metres):	9.9	
Special Access:			Special Equipment:		
Longitude:	-121 13 1.2		Latitude:	49 56 6.9	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 19 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K626

Site #:	K626	Year Superstructure Installed:	2001	Structure Type/Class:	Permanent Bridge
KM:	3.66	User km:	19.50	Last Inspection Date:	2019/10/06
Project File ID #:	4332	Br.	02	Next Inspection Date:	2022/10/06
Road Name:	SPIUS SOUTH				
Crossing Name:	S Fork Spius		Total Length (metres):	17.4	
Special Access:			Special Equipment:		
Longitude:	-121 7 7.8		Latitude:	49 54 39.7	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: K350

Site #:	K350	Year Superstructure Installed:	1991	Structure Type/Class:	Major Culvert
KM:	1.63	User km:	16.90	Last Inspection Date:	2019/10/03
Project File ID #:	6427	Br.	02	Next Inspection Date:	2022/10/03
Road Name:	STEMWINDER-HEDLEY MT				
Crossing Name:	McNulty Cr		Total Length (metres):	37.0	
Special Access:			Special Equipment:		
Longitude:	-120 6 52.8		Latitude:	49 28 9.0	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					

Structure Name: SCEP 023-3

Site #:	K1576	Year Superstructure Installed:	1980	Structure Type/Class:	Major Culvert
KM:	2.70	User km:		Last Inspection Date:	
Project File ID #:	8529	Br.	61	Next Inspection Date:	2012/07/18
Road Name:	SUNDAY LAKE				
Crossing Name:	Unnamed		Total Length (metres):	9.8	
Special Access:			Special Equipment:		
Longitude:	-120 15 28.3		Latitude:	49 47 42.3	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 20 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K995

Site #:	K995	Year Superstructure Installed:	1989	Structure Type/Class:	Major Culvert
KM:	1.09	User km:	1.00	Last Inspection Date:	2019/07/08
Project File ID #:	8071	Br.	02	Next Inspection Date:	2022/07/08
Road Name:	SWAKUM-HELMER				
Crossing Name:	Clapperton Cr	Total Length (metres):	9.0		
Special Access:		Special Equipment:			
Longitude:	-120 39 19.3	Latitude:	50 18 52.9		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: K1492

Site #:	K1492	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	7.80	User km:	1.00	Last Inspection Date:	2019/10/02
Project File ID #:	10334	Br.	01	Next Inspection Date:	2022/10/02
Road Name:	TEPEE LAKES BR 01				
Crossing Name:	Tepee Cr	Total Length (metres):	17.0		
Special Access:		Special Equipment:			
Longitude:	-120 12 35.7	Latitude:	49 45 42.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 06-DEC-16: na				

Structure Name: WO 1619

Site #:	K1642	Year Superstructure Installed:	2015	Structure Type/Class:	Temporary Bridge
KM:	0.20	User km:	0.20	Last Inspection Date:	2020/07/04
Project File ID #:	3600	Br.	13	Next Inspection Date:	2022/07/04
Road Name:	THREE BROTHERS				
Crossing Name:	Copper Creek	Total Length (metres):	15.2		
Special Access:		Special Equipment:			
Longitude:	-120 46 34.7	Latitude:	49 13 43.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Other	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 06-FEB-17: n/a				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 21 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K671

Site #:	K671	Year Superstructure Installed:	1993	Structure Type/Class:	Major Culvert
KM:	7.59	User km:	6.70	Last Inspection Date:	2019/10/06
Project File ID #:	1045	Br.	02	Next Inspection Date:	2022/10/06
Road Name:	THYNNE-LOWER MCPHAIL				
Crossing Name:	McPhail Cr	Total Length (metres):	18.0		
Special Access:		Special Equipment:			
Longitude:	-120 52 36.3	Latitude:	49 43 38.9		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: K623

Site #:	K623	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	3.75	User km:	3.30	Last Inspection Date:	2021/08/04
Project File ID #:	8528	Br.	01	Next Inspection Date:	2021/09/20
Road Name:	TULAMEEN				
Crossing Name:	Switchback Cr	Total Length (metres):	30.0		
Special Access:		Special Equipment:			
Longitude:	-120 59 57.5	Latitude:	49 37 18.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K457

Site #:	K457	Year Superstructure Installed:	1984	Structure Type/Class:	Permanent Bridge
KM:	21.62	User km:	21.60	Last Inspection Date:	2020/07/05
Project File ID #:	8528	Br.	01	Next Inspection Date:	2022/07/05
Road Name:	TULAMEEN				
Crossing Name:	McGee Cr	Total Length (metres):	9.6		
Special Access:		Special Equipment:			
Longitude:	-120 57 13.8	Latitude:	49 30 44.8		
Superstructure:	Concrete Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\PBUESCH on 21-FEB-20: PB Feb21,2020 assess metal tabs on deck connecting box beam girder				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 22 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K458

Site #:	K458	Year Superstructure Installed:	1984	Structure Type/Class:	Permanent Bridge
KM:	27.20	User km:	27.00	Last Inspection Date:	2020/07/05
Project File ID #:	8528	Br.	01	Next Inspection Date:	2022/07/05
Road Name:	TULAMEEN				
Crossing Name:	Jim Kelly Cr		Total Length (metres):	9.6	
Special Access:			Special Equipment:		
Longitude:	-120 58 13.8		Latitude:	49 28 33.0	
Superstructure:	Concrete I/T Beam	Abutments (Left/Right): <i>(looking downstream)</i>	Concrete Cast in Place	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Wing wall measurements as per monitoring are required at time of routine inspection. DA				

Structure Name: K459

Site #:	K459	Year Superstructure Installed:	1984	Structure Type/Class:	Permanent Bridge
KM:	31.21	User km:	30.80	Last Inspection Date:	2020/07/05
Project File ID #:	8528	Br.	01	Next Inspection Date:	2022/07/05
Road Name:	TULAMEEN				
Crossing Name:	Railroad Cr		Total Length (metres):	6.1	
Special Access:			Special Equipment:		
Longitude:	-121 0 9.6		Latitude:	49 27 3.0	
Superstructure:	Concrete Box Beam	Abutments (Left/Right): <i>(looking downstream)</i>	Concrete Cast in Place	# Spans:	1
Planned Inspection Comments:					

Structure Name: K461

Site #:	K461	Year Superstructure Installed:	1988	Structure Type/Class:	Permanent Bridge
KM:	33.61	User km:	33.20	Last Inspection Date:	2019/10/05
Project File ID #:	8528	Br.	01	Next Inspection Date:	2022/10/05
Road Name:	TULAMEEN				
Crossing Name:	Sutter Cr		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-121 0 49.2		Latitude:	49 26 2.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): <i>(looking downstream)</i>	Concrete Precast	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 23 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K1113

Site #:	K1113	Year Superstructure Installed:	1998	Structure Type/Class:	Major Culvert
KM:	36.71	User km:	36.30	Last Inspection Date:	2019/10/05
Project File ID #:	8528	Br.	01	Next Inspection Date:	2022/10/05
Road Name:	TULAMEEN				
Crossing Name:	Unnamed		Total Length (metres):	18.0	
Special Access:			Special Equipment:		
Longitude:	-121 2 5.4		Latitude:	49 24 55.8	
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 06-DEC-16: Need to measure actual cover depth at inlet and outlet on next inspection. DA. Completed in 2016 inspection				

Structure Name: K1118

Site #:	K1118	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	37.65	User km:	37.20	Last Inspection Date:	2019/10/05
Project File ID #:	8528	Br.	01	Next Inspection Date:	2022/10/05
Road Name:	TULAMEEN				
Crossing Name:	Vuich Cr		Total Length (metres):	17.0	
Special Access:			Special Equipment:		
Longitude:	-121 2 8.8		Latitude:	49 24 28.5	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: K463A

Site #:	K463	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	46.00	User km:	47.20	Last Inspection Date:	2019/10/05
Project File ID #:	8528	Br.	01	Next Inspection Date:	2022/10/05
Road Name:	TULAMEEN				
Crossing Name:	Podunk Cr		Total Length (metres):	24.4	
Special Access:			Special Equipment:		
Longitude:	-121 3 21.3		Latitude:	49 20 33.9	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 11-JAN-17: n/A				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 24 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K464

Site #:	K464	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	48.19	User km:	49.20	Last Inspection Date:	2019/10/05
Project File ID #:	8528	Br.	01	Next Inspection Date:	2022/10/05
Road Name:	TULAMEEN				
Crossing Name:	Chan Cr	Total Length (metres):	18.3		
Special Access:		Special Equipment:			
Longitude:	-121 1 51.8	Latitude:	49 20 25.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Structure was replaced by Tolko Sept 09 UTMs converted from Lat/Long- check in field.				

Structure Name: K465

Site #:	K465	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	50.96	User km:	52.00	Last Inspection Date:	2019/10/05
Project File ID #:	8528	Br.	01	Next Inspection Date:	2022/10/05
Road Name:	TULAMEEN				
Crossing Name:	White Cloud Cr	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-120 59 51.0	Latitude:	49 20 55.2		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1093

Site #:	K1093	Year Superstructure Installed:	2001	Structure Type/Class:	Major Culvert
KM:	53.93	User km:	53.00	Last Inspection Date:	2019/10/05
Project File ID #:	8528	Br.	01	Next Inspection Date:	2022/10/05
Road Name:	TULAMEEN				
Crossing Name:	Ugly Cr	Total Length (metres):	23.0		
Special Access:		Special Equipment:			
Longitude:	-120 57 52.8	Latitude:	49 21 40.8		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 25 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K466

Site #:	K466	Year Superstructure Installed:	1986	Structure Type/Class:	Permanent Bridge
KM:	0.12	User km:	0.20	Last Inspection Date:	2021/08/04
Project File ID #:	8528	Br.	02	Next Inspection Date:	2022/08/04
Road Name:	TULAMEEN-CHAMPION				
Crossing Name:	Tulameen R		Total Length (metres):	28.0	
Special Access:			Special Equipment:	Peeper Truck	
Longitude:	-120 57 15.0		Latitude:	49 29 5.3	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Cast in Place	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 15-FEB-16: Check the monitor item for the wing wall measurements from top girder flange to flat on wing-walls. See the measures and sketch in the attach doc and folders tab from 2013. DA. Peeper inspecton require in 2012 at same time as K636.				

Structure Name: K483

Site #:	K483	Year Superstructure Installed:	1989	Structure Type/Class:	Permanent Bridge
KM:	13.60	User km:	10.00	Last Inspection Date:	2021/08/04
Project File ID #:	8528	Br.	02	Next Inspection Date:	2022/08/04
Road Name:	TULAMEEN-CHAMPION				
Crossing Name:	Champion Cr		Total Length (metres):	22.9	
Special Access:			Special Equipment:		
Longitude:	-120 55 13.8		Latitude:	49 26 56.8	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Cast in Place	# Spans:	1
Planned Inspection Comments:					

Structure Name: K033

Site #:	K033	Year Superstructure Installed:	1995	Structure Type/Class:	Major Culvert
KM:	3.83	User km:	3.00	Last Inspection Date:	2019/10/05
Project File ID #:	8528	Br.	04	Next Inspection Date:	2022/10/05
Road Name:	TULAMEEN-RAILROAD CR				
Crossing Name:	Railroad Cr		Total Length (metres):	14.3	
Special Access:			Special Equipment:		
Longitude:	-121 1 49.2		Latitude:	49 27 40.8	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 26 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K490

Site #:	K490	Year Superstructure Installed:	1991	Structure Type/Class:	Permanent Bridge
KM:	1.40	User km:	1.40	Last Inspection Date:	2019/10/06
Project File ID #:	9279	Br.	01	Next Inspection Date:	2022/10/06
Road Name:	UPPER COLDWATER				
Crossing Name:	Coldwater R	Total Length (metres):	15.0		
Special Access:		Special Equipment:			
Longitude:	-121 1 50.4	Latitude:	49 38 46.2		
Superstructure:	Concrete Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: K475

Site #:	K475	Year Superstructure Installed:	1992	Structure Type/Class:	Permanent Bridge
KM:	5.44	User km:	6.60	Last Inspection Date:	2019/10/06
Project File ID #:	9279	Br.	01	Next Inspection Date:	2022/10/06
Road Name:	UPPER COLDWATER				
Crossing Name:	Little Douglas Cr	Total Length (metres):	16.3		
Special Access:		Special Equipment:			
Longitude:	-121 5 34.2	Latitude:	49 38 28.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: K479

Site #:	K479	Year Superstructure Installed:	1987	Structure Type/Class:	Permanent Bridge
KM:	6.48	User km:	4.90	Last Inspection Date:	2019/10/06
Project File ID #:	9279	Br.	01	Next Inspection Date:	2022/10/06
Road Name:	UPPER COLDWATER				
Crossing Name:	Unnamed	Total Length (metres):	11.0		
Special Access:		Special Equipment:			
Longitude:	-121 4 21.0	Latitude:	49 38 34.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 27 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K753

Site #:	K753	Year Superstructure Installed:	1983	Structure Type/Class:	Major Culvert
KM:	4.53	User km:	4.50	Last Inspection Date:	2019/10/04
Project File ID #:	3600	Br.	01	Next Inspection Date:	2022/10/04
Road Name:	WHIPSAW CREEK				
Crossing Name:	Corral Cr	Total Length (metres):	22.0		
Special Access:		Special Equipment:			
Longitude:	-120 36 54.0	Latitude:	49 21 1.7		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: K751

Site #:	K751	Year Superstructure Installed:	1986	Structure Type/Class:	Major Culvert
KM:	9.56	User km:	9.80	Last Inspection Date:	2019/10/04
Project File ID #:	3600	Br.	01	Next Inspection Date:	2022/10/04
Road Name:	WHIPSAW CREEK				
Crossing Name:	Fifteen Mile Cr	Total Length (metres):	30.0		
Special Access:		Special Equipment:			
Longitude:	-120 38 46.2	Latitude:	49 19 13.8		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: K754

Site #:	K754	Year Superstructure Installed:	1979	Structure Type/Class:	Major Culvert
KM:	3.09	User km:	5.20	Last Inspection Date:	2021/10/13
Project File ID #:	3600	Br.	02	Next Inspection Date:	2022/10/13
Road Name:	WHIPSAW-LAMONT				
Crossing Name:	Lamont Cr	Total Length (metres):	40.0		
Special Access:		Special Equipment:			
Longitude:	-120 36 59.4	Latitude:	49 22 54.5		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\PBLUESCH on 24-FEB-20: PB Feb24.2020 Downstream values should be assessed. This is a 40m long deep fill culvert 1500mm dia. The pipe may be failing, roof deflection has been monitored for some time. Should this culvert fail a very large volume of ponded water may be formed behind the road prism. The risk of a dam burst scenario should be determined.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 28 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K421

Site #:	K421	Year Superstructure Installed:	1987	Structure Type/Class:	Permanent Bridge
KM:	12.80	User km:	13.00	Last Inspection Date:	2021/10/10
Project File ID #:	0814	Br.	01	Next Inspection Date:	2022/10/10
Road Name:					
Crossing Name:	Skuhost Cr		Total Length (metres):	6.5	
Special Access:	ATV		Special Equipment:		
Longitude:	-121 1 52.8		Latitude:	50 19 16.8	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:	BCEID\SENTENG on 20-DEC-14: Road badly washed out on the way to this bridge.				

Structure Name: PS-028

Site #:	STORE 10	Year Superstructure Installed:	2018	Structure Type/Class:	Temporary Bridge
KM:		User km:		Last Inspection Date:	2020/07/07
Project File ID #:		Br.		Next Inspection Date:	2022/07/07
Road Name:					
Crossing Name:	Nicola		Total Length (metres):	19.3	
Special Access:			Special Equipment:		
Longitude:			Latitude:		
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Other	# Spans: 1
Planned Inspection Comments:					

Structure Name: WO2124

Site #:	STORE 10	Year Superstructure Installed:	2000	Structure Type/Class:	Temporary Bridge
KM:		User km:		Last Inspection Date:	
Project File ID #:		Br.		Next Inspection Date:	2022/08/27
Road Name:					
Crossing Name:	Nicola		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:			Latitude:		
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Other	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 29 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: WO1636

Site #:	STORE 10	Year Superstructure Installed:		Structure Type/Class:	Temporary Bridge
KM:		User km:		Last Inspection Date:	
Project File ID #:		Br.		Next Inspection Date:	2013/03/11
Road Name:					
Crossing Name:	Nicola	Total Length (metres):	7.6		
Special Access:		Special Equipment:			
Longitude:		Latitude:			
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Other	# Spans:	1
Planned Inspection Comments:					

Structure Name: PS-049

Site #:	STORE 10	Year Superstructure Installed:		Structure Type/Class:	Temporary Bridge
KM:		User km:		Last Inspection Date:	
Project File ID #:		Br.		Next Inspection Date:	2018/02/14
Road Name:					
Crossing Name:	Nicola	Total Length (metres):	7.0		
Special Access:		Special Equipment:			
Longitude:		Latitude:			
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Other	# Spans:	1
Planned Inspection Comments:					

Structure Name: PS-010

Site #:	STORE 10	Year Superstructure Installed:	1985	Structure Type/Class:	Temporary Bridge
KM:		User km:		Last Inspection Date:	
Project File ID #:		Br.		Next Inspection Date:	2010/11/12
Road Name:					
Crossing Name:	Nicola	Total Length (metres):	6.8		
Special Access:		Special Equipment:			
Longitude:		Latitude:			
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Other	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 30 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: WO1428

Site #:	STORE 10	Year Superstructure Installed:	1997	Structure Type/Class:	Temporary Bridge
KM:		User km:		Last Inspection Date:	
Project File ID #:		Br.		Next Inspection Date:	2013/07/17
Road Name:					
Crossing Name:	Nicola	Total Length (metres):	9.1		
Special Access:		Special Equipment:			
Longitude:		Latitude:			
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Other	# Spans:	1
Planned Inspection Comments:					

Structure Name: WO7042

Site #:	STORE 10	Year Superstructure Installed:	1987	Structure Type/Class:	Temporary Bridge
KM:		User km:		Last Inspection Date:	
Project File ID #:		Br.		Next Inspection Date:	2013/03/13
Road Name:					
Crossing Name:	Nicola	Total Length (metres):	10.3		
Special Access:		Special Equipment:			
Longitude:		Latitude:			
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Other	# Spans:	1
Planned Inspection Comments:					

Structure Name: K838

Site #:	K838	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	0.05	User km:	0.00	Last Inspection Date:	2019/07/11
Project File ID #:	7649	Br.	02	Next Inspection Date:	2022/07/11
Road Name:	-BURKHOLDER B				
Crossing Name:	Yalakom B	Total Length (metres):	16.0		
Special Access:		Special Equipment:			
Longitude:	-122 25 20.4	Latitude:	51 0 52.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 31 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K882

Site #:	K882	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	1.17	User km:	0.10	Last Inspection Date:	2019/07/10
Project File ID #:	4768	Br.	01	Next Inspection Date:	2022/07/10
Road Name:	4768				
Crossing Name:	Kwoiek #1		Total Length (metres):	24.6	
Special Access:			Special Equipment:		
Longitude:	-121 34 39.8		Latitude:	50 6 16.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K890A

Site #:	K890	Year Superstructure Installed:	2011	Structure Type/Class:	Temporary Bridge
KM:	3.69	User km:	3.80	Last Inspection Date:	2020/06/23
Project File ID #:	4768	Br.	01	Next Inspection Date:	2022/06/23
Road Name:	4768				
Crossing Name:	Kwoiek #4		Total Length (metres):	26.8	
Special Access:			Special Equipment:		
Longitude:	-121 36 20.7		Latitude:	50 7 1.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: K546A

Site #:	K546	Year Superstructure Installed:	2011	Structure Type/Class:	Temporary Bridge
KM:	4.53	User km:	4.70	Last Inspection Date:	2020/06/23
Project File ID #:	4768	Br.	01	Next Inspection Date:	2022/06/23
Road Name:	4768				
Crossing Name:	Kwoiek #5		Total Length (metres):	26.8	
Special Access:			Special Equipment:		
Longitude:	-121 37 1.1		Latitude:	50 6 54.6	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 32 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K559

Site #:	K559	Year Superstructure Installed:	1986	Structure Type/Class:	Temporary Bridge
KM:	0.20	User km:	1.60	Last Inspection Date:	
Project File ID #:	6678	Br.	02	Next Inspection Date:	2009/08/14
Road Name:	6678				
Crossing Name:	Skimath #3		Total Length (metres):	10.8	
Special Access:			Special Equipment:		
Longitude:	-121 54 56.7		Latitude:	50 28 41.4	
Superstructure:	Log Stringers		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Previously quad access, now may be pickup access.				

Structure Name: K1168

Site #:	K1168	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	0.62	User km:	1.50	Last Inspection Date:	2019/07/09
Project File ID #:	9856	Br.	01	Next Inspection Date:	2022/07/09
Road Name:	9856				
Crossing Name:	Tommy Cr		Total Length (metres):	23.6	
Special Access:	Helicopter		Special Equipment:		
Longitude:	-122 31 24.6		Latitude:	50 50 26.9	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: K1304

Site #:	K1304	Year Superstructure Installed:	2001	Structure Type/Class:	Woodbox/Log Culvert
KM:	6.53	User km:	2.70	Last Inspection Date:	2019/07/09
Project File ID #:	9856	Br.	01	Next Inspection Date:	2021/07/09
Road Name:	9856				
Crossing Name:	Unnamed		Total Length (metres):	10.0	
Special Access:	Helicopter		Special Equipment:		
Longitude:	-122 31 20.4		Latitude:	50 49 3.6	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Heli access required, not to be inspected with Routine inspections. Check with district prior to inspections. DA 2010.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 33 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K530A

Site #:	K530	Year Superstructure Installed:	2012	Structure Type/Class:	Permanent Bridge
KM:	9.74	User km:	9.70	Last Inspection Date:	2019/07/12
Project File ID #:	8490	Br.	01	Next Inspection Date:	2022/07/12
Road Name:	BRIDGE RIVER				
Crossing Name:	Cathy Cr	Total Length (metres):	18.3		
Special Access:		Special Equipment:			
Longitude:	-122 57 43.9	Latitude:	50 49 32.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1589

Site #:	K1589	Year Superstructure Installed:	2007	Structure Type/Class:	Temporary Bridge
KM:	1.50	User km:		Last Inspection Date:	2020/06/26
Project File ID #:	10806	Br.	01	Next Inspection Date:	2022/06/26
Road Name:	DOWNTON CREEK				
Crossing Name:	Downton Cr	Total Length (metres):	16.6		
Special Access:		Special Equipment:			
Longitude:	-122 6 21.1	Latitude:	50 35 29.5		
Superstructure:	Rail Car	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 10-JAN-17: Ensure railcars are bolted to each other with 19 mm dia bolts with nuts and washers @ 600 mm OC spacing. DA Jan 2017				

Structure Name: K1590

Site #:	K1590	Year Superstructure Installed:	2007	Structure Type/Class:	Temporary Bridge
KM:	2.50	User km:		Last Inspection Date:	2020/06/26
Project File ID #:	10806	Br.	01	Next Inspection Date:	2022/06/26
Road Name:	DOWNTON CREEK				
Crossing Name:	Downton Cr	Total Length (metres):	16.6		
Special Access:		Special Equipment:			
Longitude:	-122 7 12.0	Latitude:	50 35 24.6		
Superstructure:	Rail Car	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 10-JAN-17: Ensure hardware is in-place as per repair item #5. DA				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 34 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K1591

Site #:	K1591	Year Superstructure Installed:	2007	Structure Type/Class:	Temporary Bridge
KM:	2.70	User km:		Last Inspection Date:	2020/06/26
Project File ID #:	10806	Br.	01	Next Inspection Date:	2022/06/26
Road Name:	DOWNTON CREEK				
Crossing Name:	Downton Cr	Total Length (metres):	11.4		
Special Access:		Special Equipment:			
Longitude:	-122 7 19.3	Latitude:	50 35 22.8		
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1593

Site #:	K1593	Year Superstructure Installed:	2007	Structure Type/Class:	Temporary Bridge
KM:	4.90	User km:	4.90	Last Inspection Date:	2020/06/26
Project File ID #:	10806	Br.	01	Next Inspection Date:	2022/06/26
Road Name:	DOWNTON CREEK				
Crossing Name:	Downton Cr	Total Length (metres):	12.0		
Special Access:		Special Equipment:			
Longitude:	-122 8 55.3	Latitude:	50 35 19.8		
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1495

Site #:	K1495	Year Superstructure Installed:	2009	Structure Type/Class:	Major Culvert
KM:	0.30	User km:	0.30	Last Inspection Date:	2019/07/13
Project File ID #:	10583	Br.	02	Next Inspection Date:	2022/07/13
Road Name:	DUFFEY LAKE				
Crossing Name:	Unnamed	Total Length (metres):	12.0		
Special Access:		Special Equipment:			
Longitude:	-122 14 47.0	Latitude:	50 26 13.0		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR Conversion on 17-FEB-14: Changed the frequency to two years, due to temporary nature of design and or extra maintenance requirements. DA Jan 2014.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 35 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: PS001

Site #:	K533	Year Superstructure Installed:	2018	Structure Type/Class:	Temporary Bridge
KM:	0.28	User km:	7.30	Last Inspection Date:	2020/06/25
Project File ID #:	9150	Br.	03	Next Inspection Date:	2021/07/12
Road Name:	EAST HOPE CREEK				
Crossing Name:	Hope Cr	Total Length (metres):	18.3		
Special Access:		Special Equipment:	Peeper Truck		
Longitude:	-122 57 23.9	Latitude:	50 37 24.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 03-JUN-21: CBR_Conversion on 17-FEB-14: GMc mar 30/09 Check with district if structure is still inplace. If it is, inspect. Data was only estimated confirm at next inspection. GMc Jan 9/09 Measure up girders as practically possible i.e girder section size next inspection Quad access required 2012/01/18				

Structure Name: K534

Site #:	K534	Year Superstructure Installed:	1995	Structure Type/Class:	Temporary Bridge
KM:	0.63	User km:	7.50	Last Inspection Date:	2020/06/25
Project File ID #:	9150	Br.	03	Next Inspection Date:	2022/06/25
Road Name:	EAST HOPE CREEK				
Crossing Name:	Unnamed	Total Length (metres):	12.3		
Special Access:		Special Equipment:			
Longitude:	-122 57 12.4	Latitude:	50 37 20.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: K532

Site #:	K532	Year Superstructure Installed:	2005	Structure Type/Class:	Temporary Bridge
KM:	8.13	User km:	8.50	Last Inspection Date:	2020/06/25
Project File ID #:	9150	Br.	01	Next Inspection Date:	2022/06/25
Road Name:	HOPE CREEK				
Crossing Name:	West Hope Cr	Total Length (metres):	10.7		
Special Access:		Special Equipment:			
Longitude:	-122 57 40.2	Latitude:	50 37 3.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 20-FEB-18: Measure the c/c span on the next inspection in 2019				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 36 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K914

Site #:	K914	Year Superstructure Installed:	1995	Structure Type/Class:	Temporary Bridge
KM:	0.59	User km:	9.80	Last Inspection Date:	2021/09/01
Project File ID #:	9150	Br.	05	Next Inspection Date:	2022/09/01
Road Name:	HOPE CREEK BR 05				
Crossing Name:	Hope Cr	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-122 58 1.2	Latitude:	50 36 23.0		
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\BPellet on 17-MAR-22: BP Mar 17-22 Drill all sills and stringers for rot with every annual inspection. Ensure that bridge is posted closed if it has not been barricaded. IDIR\DMALWAY on 21-FEB-18: Post closed upon next inspection in 2019 if deck components deteriorate and are not replaced.				

Structure Name: K1021

Site #:	K1021	Year Superstructure Installed:	1970	Structure Type/Class:	Temporary Bridge
KM:	0.01	User km:	5.10	Last Inspection Date:	2011/10/19
Project File ID #:	10194	Br.	04	Next Inspection Date:	2013/10/19
Road Name:	HURLEY RIVER SOUTH				
Crossing Name:	Unnamed	Total Length (metres):	15.2		
Special Access:	Helicopter	Special Equipment:			
Longitude:	-123 5 3.6	Latitude:	50 39 19.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Quick inspection, as no vehicular access.				

Structure Name: K535

Site #:	K535	Year Superstructure Installed:	1980	Structure Type/Class:	Temporary Bridge
KM:	0.50	User km:	4.30	Last Inspection Date:	2011/10/19
Project File ID #:	10194	Br.	05	Next Inspection Date:	2013/10/19
Road Name:	HURLEY RVR-SOUTH				
Crossing Name:	Hurley R	Total Length (metres):	15.6		
Special Access:	Helicopter	Special Equipment:			
Longitude:	-123 4 27.6	Latitude:	50 39 48.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Just a quick ocular inspection as no vehicular access.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 37 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K638

Site #:	K638	Year Superstructure Installed:	2004	Structure Type/Class:	Permanent Bridge
KM:	0.00	User km:	19.10	Last Inspection Date:	2020/06/25
Project File ID #:	8059	Br.	01	Next Inspection Date:	2022/07/11
Road Name:	KINGDOM LAKE BR 01				
Crossing Name:	Piebiter Cr	Total Length (metres):	15.2		
Special Access:		Special Equipment:			
Longitude:	-122 39 30.4	Latitude:	50 42 59.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 18-JAN-17: N/A				

Structure Name: K637

Site #:	K637	Year Superstructure Installed:	2004	Structure Type/Class:	Permanent Bridge
KM:	5.20	User km:	14.40	Last Inspection Date:	2019/07/11
Project File ID #:	8059	Br.	01	Next Inspection Date:	2022/07/11
Road Name:	KINGDOM LAKE BR 01				
Crossing Name:	Hawthorn Cr	Total Length (metres):	14.0		
Special Access:		Special Equipment:			
Longitude:	-122 42 38.3	Latitude:	50 44 33.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1007

Site #:	K1007	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	25.71	User km:	24.40	Last Inspection Date:	2021/09/02
Project File ID #:	8059	Br.	01	Next Inspection Date:	2022/09/02
Road Name:	KINGDOM LAKE BR 01				
Crossing Name:	Cadwallader Cr	Total Length (metres):	15.2		
Special Access:		Special Equipment:			
Longitude:	-122 38 34.6	Latitude:	50 40 39.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\BPelletT on 24-FEB-22: BP Feb 24-22 Ensure site is posted closed or barricaded. Note any signs of traffic. Monitor for damage to girders bearing directly on lock blocks. CBR_Conversion on 17-FEB-14: Ensure posted at 20 tonnes load restriction. DA. 2012.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 38 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K1023

Site #:	K1023	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	0.70	User km:	11.20	Last Inspection Date:	2019/07/11
Project File ID #:	8059	Br.	03	Next Inspection Date:	2022/07/11
Road Name:	KINGDOM LAKE BR 03				
Crossing Name:	Cadwallader Cr		Total Length (metres):	27.4	
Special Access:			Special Equipment:		
Longitude:	-122 44 41.8		Latitude:	50 45 0.6	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: K639

Site #:	K639	Year Superstructure Installed:	2003	Structure Type/Class:	Permanent Bridge
KM:	1.25	User km:	12.50	Last Inspection Date:	2019/07/11
Project File ID #:	8059	Br.	03	Next Inspection Date:	2022/07/11
Road Name:	KINGDOM LAKE BR 03				
Crossing Name:	Crazy #1		Total Length (metres):	14.0	
Special Access:			Special Equipment:		
Longitude:	-122 44 26.0		Latitude:	50 44 48.8	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1344

Site #:	K1344	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:	1.53	User km:	14.10	Last Inspection Date:	2019/07/11
Project File ID #:	8059	Br.	04	Next Inspection Date:	2022/07/11
Road Name:	KINGDOM LAKE BR 04				
Crossing Name:	Plutus Cr.		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-122 43 11.8		Latitude:	50 44 16.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 39 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K504

Site #:	K504	Year Superstructure Installed:	2005	Structure Type/Class:	Temporary Bridge
KM:	15.45	User km:	15.90	Last Inspection Date:	2020/06/24
Project File ID #:	5496	Br.	02	Next Inspection Date:	2022/06/24
Road Name:	MUD-NOAXE CREEK				
Crossing Name:	Noaxe Cr	Total Length (metres):	12.0		
Special Access:		Special Equipment:			
Longitude:	-122 42 3.0	Latitude:	51 4 0.0		
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 06-FEB-17: Note the stringers are peeled Fd, not spruce. Consider to move to annual inspection going forward after 2018.				

Structure Name: K1716

Site #:	K1716	Year Superstructure Installed:	2018	Structure Type/Class:	Permanent Bridge
KM:	117.00	User km:	117.00	Last Inspection Date:	2019/07/11
Project File ID #:	5496	Br.	02	Next Inspection Date:	2022/07/11
Road Name:	MUD-NOAXE CREEK				
Crossing Name:	Quartz Creek	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-122 43 12.0	Latitude:	51 4 30.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 11-MAR-19: One year post installation inspection				

Structure Name: K509

Site #:	K509	Year Superstructure Installed:	2001	Structure Type/Class:	Permanent Bridge
KM:	0.01	User km:	0.20	Last Inspection Date:	2019/07/11
Project File ID #:	5496	Br.	15	Next Inspection Date:	2022/07/11
Road Name:	MUD-PACKHORSE				
Crossing Name:	Mud Cr	Total Length (metres):	23.4		
Special Access:		Special Equipment:			
Longitude:	-122 45 20.5	Latitude:	51 5 47.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 40 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K563

Site #:	K563	Year Superstructure Installed:	1997	Structure Type/Class:	Temporary Bridge
KM:	5.20	User km:	7.00	Last Inspection Date:	2020/06/22
Project File ID #:	6879	Br.	05	Next Inspection Date:	2022/06/22
Road Name:	MURRAY CREEK N-WEST				
Crossing Name:	Unnamed		Total Length (metres):	6.2	
Special Access:			Special Equipment:		
Longitude:	-121 32 20.2		Latitude:	50 33 0.9	
Superstructure:	Log Stringers		Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans: 1
Planned Inspection Comments:	IDIR\DMALWAY on 15-FEB-16: annual inspection				

Structure Name: K570

Site #:	K570	Year Superstructure Installed:	1970	Structure Type/Class:	Temporary Bridge
KM:	1.70	User km:	18.00	Last Inspection Date:	2021/10/09
Project File ID #:	6879	Br.	04	Next Inspection Date:	2022/10/09
Road Name:	MURRAY CREEK WEST				
Crossing Name:	Murray Cr North		Total Length (metres):	6.2	
Special Access:			Special Equipment:		
Longitude:	-121 31 15.6		Latitude:	50 30 15.6	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans: 1
Planned Inspection Comments:	IDIR\BPELLETT on 25-FEB-22: BP Feb 25-22 Monitor contact between girders and lock blocks, and note any damage to girders. CBR_Conversion on 17-FEB-14:				

Structure Name: K922A

Site #:	K922	Year Superstructure Installed:	2012	Structure Type/Class:	Permanent Bridge
KM:	0.16	User km:	0.00	Last Inspection Date:	
Project File ID #:	4767	Br.	01	Next Inspection Date:	2015/08/14
Road Name:	NICOAMEN RIVER				
Crossing Name:	Nicoamen Cr		Total Length (metres):	39.6	
Special Access:			Special Equipment:		
Longitude:	-121 23 58.2		Latitude:	50 16 3.9	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 41 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K1094

Site #:	K1094	Year Superstructure Installed:	2002	Structure Type/Class:	Temporary Bridge
KM:	16.20	User km:	16.20	Last Inspection Date:	2020/06/23
Project File ID #:	4767	Br.	01	Next Inspection Date:	2022/06/23
Road Name:	NICOAMEN RIVER				
Crossing Name:	Unnamed		Total Length (metres):	8.7	
Special Access:			Special Equipment:		
Longitude:	-121 24 21.6		Latitude:	50 12 19.2	
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1394

Site #:	K1394	Year Superstructure Installed:	2006	Structure Type/Class:	Temporary Bridge
KM:	7.44	User km:	7.90	Last Inspection Date:	2020/06/25
Project File ID #:	9177	Br.	01	Next Inspection Date:	2022/06/25
Road Name:	NOEL CREEK				
Crossing Name:	Noel Cr		Total Length (metres):	27.4	
Special Access:			Special Equipment:		
Longitude:	-122 48 13.6		Latitude:	50 43 4.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: PS-029

Site #:	K1300	Year Superstructure Installed:	2014	Structure Type/Class:	Temporary Bridge
KM:	0.14	User km:	8.30	Last Inspection Date:	2020/06/25
Project File ID #:	9177	Br.	02	Next Inspection Date:	2022/06/25
Road Name:	NOEL CREEK-WEST				
Crossing Name:	Noel Cr		Total Length (metres):	20.0	
Special Access:			Special Equipment:		
Longitude:	-122 48 9.0		Latitude:	50 42 45.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 42 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K552

Site #:	K552	Year Superstructure Installed:	1983	Structure Type/Class:	Temporary Bridge
KM:	2.03	User km:	2.20	Last Inspection Date:	2007/07/12
Project File ID #:	R15756	Br.	233.1	Next Inspection Date:	2008/07/01
Road Name:	TEXAS CREEK				
Crossing Name:	Texas #2		Total Length (metres):	10.6	
Special Access:			Special Equipment:		
Longitude:	-121 50 17.0		Latitude:	50 32 36.0	
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: K553

Site #:	K553	Year Superstructure Installed:	1983	Structure Type/Class:	Temporary Bridge
KM:	2.77	User km:	3.00	Last Inspection Date:	2007/07/12
Project File ID #:	R15756	Br.	233.1	Next Inspection Date:	2008/07/01
Road Name:	TEXAS CREEK				
Crossing Name:	Texas #3		Total Length (metres):	10.6	
Special Access:			Special Equipment:		
Longitude:	-121 50 13.6		Latitude:	50 32 13.9	
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: K554

Site #:	K554	Year Superstructure Installed:	1983	Structure Type/Class:	Temporary Bridge
KM:	4.16	User km:	4.40	Last Inspection Date:	2007/07/13
Project File ID #:	R15756	Br.	233.1	Next Inspection Date:	2008/07/06
Road Name:	TEXAS CREEK				
Crossing Name:	Texas #4		Total Length (metres):	9.5	
Special Access:			Special Equipment:		
Longitude:	-121 50 23.4		Latitude:	50 31 37.2	
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 43 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K541

Site #:	K541	Year Superstructure Installed:	2001	Structure Type/Class:	Permanent Bridge
KM:	8.45	User km:	8.70	Last Inspection Date:	2019/07/12
Project File ID #:	8060	Br.	01	Next Inspection Date:	2022/07/12
Road Name:	TRUAX CREEK				
Crossing Name:	Unnamed		Total Length (metres):	10.6	
Special Access:			Special Equipment:		
Longitude:	-122 41 24.0		Latitude:	50 51 13.8	
Superstructure:	Concrete Box Beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K543

Site #:	K543	Year Superstructure Installed:	1993	Structure Type/Class:	Temporary Bridge
KM:	10.05	User km:	9.70	Last Inspection Date:	2014/08/30
Project File ID #:	8060	Br.	01	Next Inspection Date:	2016/08/30
Road Name:	TRUAX CREEK				
Crossing Name:	Truax Cr		Total Length (metres):	10.5	
Special Access:			Special Equipment:		
Longitude:	-122 41 27.0		Latitude:	50 50 24.8	
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: To be deactivated in 2013, reinspect to ensure posted and no liability for pick up traffic. DA Jan 2012				

Structure Name: K1587

Site #:	K1587	Year Superstructure Installed:		Structure Type/Class:	Major Culvert
KM:	5.90	User km:		Last Inspection Date:	
Project File ID #:	10808	Br.	01	Next Inspection Date:	2019/06/17
Road Name:	VAN HORLICK				
Crossing Name:	Unnamed		Total Length (metres):	9.0	
Special Access:			Special Equipment:		
Longitude:	-122 18 12.0		Latitude:	50 21 3.9	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Complete one inspection for both culverts at the same time.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 44 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: K564

Site #:	K564	Year Superstructure Installed:	1997	Structure Type/Class:	Temporary Bridge
KM:	6.99	User km:	7.00	Last Inspection Date:	2020/07/08
Project File ID #:	5848	Br.	05	Next Inspection Date:	2022/07/08
Road Name:	W. PAVILION-PONY VLY				
Crossing Name:	Pony Valley Cr	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-122 23 14.4	Latitude:	51 12 28.2		
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 19-APR-16: Ensure posted at 10 tonnes, due to deck tie spacing. Do a good job of drilling ties for condition and stringers as it is now 19 years old. The stringers appear in Fair condition from previous inspections.				

Structure Name: K629

Site #:	K629	Year Superstructure Installed:	2004	Structure Type/Class:	Woodbox/Log Culvert
KM:	0.22	User km:	95.10	Last Inspection Date:	2009/10/08
Project File ID #:	5848	Br.	14	Next Inspection Date:	2011/10/08
Road Name:	WEST PAVILION BR 14				
Crossing Name:	Ward Cr	Total Length (metres):	8.0		
Special Access:		Special Equipment:			
Longitude:	-122 10 30.2	Latitude:	51 8 34.0		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Check span on next inspection. DA				

Structure Name: K919

Site #:	K919	Year Superstructure Installed:	1993	Structure Type/Class:	Permanent Bridge
KM:	93.28	User km:	102.00	Last Inspection Date:	2019/07/13
Project File ID #:	5848	Br.	01	Next Inspection Date:	2022/07/13
Road Name:	West Pavilion				
Crossing Name:	South French Bar Cr	Total Length (metres):	10.3		
Special Access:		Special Equipment:			
Longitude:	-122 15 28.0	Latitude:	51 10 34.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 06-FEB-17: full measure up and sketch required.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 45 of 45
Date Printed: 2022/05/05
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2022/12/31 Sort: Forest Service Road

Structure Name: WO101

Site #:	STORE 8	Year Superstructure Installed:	1990	Structure Type/Class:	Temporary Bridge
KM:		User km:		Last Inspection Date:	
Project File ID #:		Br.		Next Inspection Date:	2013/03/13
Road Name:					
Crossing Name:	Lillooet	Total Length (metres):	12.3		
Special Access:		Special Equipment:			
Longitude:		Latitude:			
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Other	# Spans:	1
Planned Inspection Comments:					

Structure Name: K922

Site #:	STORE 8	Year Superstructure Installed:	1968	Structure Type/Class:	Permanent Bridge
KM:		User km:		Last Inspection Date:	2011/10/24
Project File ID #:		Br.		Next Inspection Date:	2014/10/24
Road Name:					
Crossing Name:	Lillooet	Total Length (metres):	37.0		
Special Access:		Special Equipment:			
Longitude:		Latitude:			
Superstructure:	Glulam Girder	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Due to its age and proximity this bridge should be Peeper Truck Inspection Annually				

Structure Name: K1751

Site #:	K1751	Year Superstructure Installed:	2021	Structure Type/Class:	Permanent Bridge
KM:	15.30	User km:	15.30	Last Inspection Date:	
Project File ID #:	6069	Br.	01	Next Inspection Date:	2022/08/15
Road Name:	MAKA-MURRAY				
Crossing Name:	Unnamed Creek	Total Length (metres):	18.3		
Special Access:		Special Equipment:			
Longitude:	-121 2 40.0	Latitude:	49 52 42.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 19-APR-22: One year post installation inspection				

Structure Type/Class Totals

Permanent Bridge Total: 72	Major Culvert Total: 19
Temporary Bridge Total: 41	Woodbox/Log Culvert Total: 3