



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 1 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-232

Site #:	N5-232	Year Superstructure Installed:	2017	Structure Type/Class:	Permanent Bridge
KM:	0.10	User km:	0.10	Last Inspection Date:	2019/09/21
Project File ID #:	0219	Br.	04	Next Inspection Date:	2022/09/21
Road Name:	ACTIVEFSR				
Crossing Name:	active	Total Length (metres):	18.3		
Special Access:		Special Equipment:			
Longitude:	-117 8 2.1	Latitude:	49 14 42.1		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-221

Site #:	N5-221	Year Superstructure Installed:	2014	Structure Type/Class:	Permanent Bridge
KM:	0.00	User km:	0.00	Last Inspection Date:	2019/09/21
Project File ID #:	0221	Br.	09	Next Inspection Date:	2022/09/21
Road Name:	AR0221.09 BENNETT FS				
Crossing Name:	Sheep Creek	Total Length (metres):	24.8		
Special Access:		Special Equipment:			
Longitude:	-117 10 50.3	Latitude:	49 8 43.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-222

Site #:	N5-222	Year Superstructure Installed:		Structure Type/Class:	Permanent Bridge
KM:	0.10	User km:	0.10	Last Inspection Date:	2019/09/21
Project File ID #:	0221	Br.	09	Next Inspection Date:	2022/09/21
Road Name:	AR0221.09 BENNETT FS				
Crossing Name:	Unnamed Creek	Total Length (metres):	6.0		
Special Access:		Special Equipment:			
Longitude:	-117 10 48.0	Latitude:	49 8 43.2		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 2 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-250

Site #:	N5-250	Year Superstructure Installed:	2017	Structure Type/Class:	Permanent Bridge
KM:	0.10	User km:	0.10	Last Inspection Date:	2019/09/22
Project File ID #:	9536	Br.	05	Next Inspection Date:	2022/09/22
Road Name:	AR9536.05 LOST MTN F				
Crossing Name:	Lost Creek		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-117 8 26.3		Latitude:	49 5 31.5	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-239

Site #:	N5-239	Year Superstructure Installed:	1994	Structure Type/Class:	Temporary Bridge
KM:	19.00	User km:	30.80	Last Inspection Date:	2020/08/23
Project File ID #:	9568	Br.	01	Next Inspection Date:	2022/08/23
Road Name:	BARNES CREEK WEST				
Crossing Name:	Holding Cr		Total Length (metres):	9.4	
Special Access:			Special Equipment:		
Longitude:	-118 17 22.0		Latitude:	50 4 37.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-138

Site #:	N5-138	Year Superstructure Installed:	1980	Structure Type/Class:	Major Culvert
KM:	10.87	User km:	6.00	Last Inspection Date:	2019/09/19
Project File ID #:	0168	Br.	01	Next Inspection Date:	2022/09/19
Road Name:	BENCH CREEK				
Crossing Name:	GALLOPING Cr		Total Length (metres):	24.0	
Special Access:			Special Equipment:		
Longitude:	-118 18 13.2		Latitude:	49 55 25.1	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 3 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-217

Site #:	N5-217	Year Superstructure Installed:	2011	Structure Type/Class:	Temporary Bridge
KM:	12.00	User km:		Last Inspection Date:	2020/09/01
Project File ID #:	0011	Br.	01	Next Inspection Date:	2022/09/01
Road Name:	BIG SHEEP CREEK				
Crossing Name:	Esling Creek		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-117 57 1.6		Latitude:	49 6 6.9	
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-254

Site #:	N5-254	Year Superstructure Installed:	2018	Structure Type/Class:	Major Culvert
KM:	28.00	User km:	28.00	Last Inspection Date:	2019/09/24
Project File ID #:	0058	Br.	01	Next Inspection Date:	2022/09/24
Road Name:	BULLDOG				
Crossing Name:	Brooklyn Cr		Total Length (metres):	23.0	
Special Access:			Special Equipment:		
Longitude:	-118 3 12.8		Latitude:	49 23 6.9	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: N5-255

Site #:	N5-255	Year Superstructure Installed:	2018	Structure Type/Class:	Permanent Bridge
KM:	28.10	User km:	28.10	Last Inspection Date:	2019/09/24
Project File ID #:	0058	Br.	01	Next Inspection Date:	2022/09/24
Road Name:	BULLDOG				
Crossing Name:	Pup Creek		Total Length (metres):	9.0	
Special Access:			Special Equipment:		
Longitude:	-118 3 9.8		Latitude:	49 23 6.6	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 4 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-010

Site #:	N5-010	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	0.00	User km:	6.30	Last Inspection Date:	2019/09/03
Project File ID #:	0181	Br.	01	Next Inspection Date:	2022/09/03
Road Name:	CARIBOU ONE				
Crossing Name:	MINERAL Cr		Total Length (metres):	8.6	
Special Access:			Special Equipment:		
Longitude:	-117 48 24.1		Latitude:	50 1 30.9	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-259

Site #:	N5-259	Year Superstructure Installed:	2020	Structure Type/Class:	Permanent Bridge
KM:	4.80	User km:	4.80	Last Inspection Date:	
Project File ID #:	0181	Br.	01	Next Inspection Date:	2022/08/01
Road Name:	CARIBOU ONE				
Crossing Name:	Rodd Creek		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-117 49 15.3		Latitude:	50 1 21.8	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-011

Site #:	N5-011	Year Superstructure Installed:	1989	Structure Type/Class:	Major Culvert
KM:	5.68	User km:	8.60	Last Inspection Date:	2019/09/03
Project File ID #:	0181	Br.	02	Next Inspection Date:	2022/09/03
Road Name:	CARIBOU SOUTH				
Crossing Name:	RODD Cr		Total Length (metres):	15.0	
Special Access:			Special Equipment:		
Longitude:	-117 49 2.5		Latitude:	50 1 14.0	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 5 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-227

Site #:	N5-227	Year Superstructure Installed:		Structure Type/Class:	Temporary Bridge
KM:	0.10	User km:	0.10	Last Inspection Date:	2020/08/28
Project File ID #:	0205	Br.	01	Next Inspection Date:	2022/08/28
Road Name:	CARPENTER CREEK				
Crossing Name:	Carpenter Cr	Total Length (metres):	9.2		
Special Access:		Special Equipment:			
Longitude:	-117 11 40.6	Latitude:	49 58 32.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-246

Site #:	N5-246	Year Superstructure Installed:	1975	Structure Type/Class:	Major Culvert
KM:	3.46	User km:	29.00	Last Inspection Date:	2019/09/23
Project File ID #:	7874	Br.	01	Next Inspection Date:	2022/09/23
Road Name:	CASCADE HWY				
Crossing Name:	Santa Rosa Cr	Total Length (metres):	18.4		
Special Access:		Special Equipment:			
Longitude:	-117 59 5.0	Latitude:	49 1 5.0		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\JNAUL on 18-JAN-18: Please pick up corrugation profile. IDIR\HABEURSK on 31-MAR-17: found structure. Pick-up as built information on next inspection.				

Structure Name: N5-173

Site #:	N5-173	Year Superstructure Installed:	1980	Structure Type/Class:	Major Culvert
KM:	10.99	User km:	12.40	Last Inspection Date:	2019/09/22
Project File ID #:	0022	Br.	01	Next Inspection Date:	2022/09/22
Road Name:	DEER CREEK				
Crossing Name:	Little Cayuse Creek crossing.	Total Length (metres):	18.3		
Special Access:		Special Equipment:			
Longitude:	-118 0 15.3	Latitude:	49 24 45.7		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 6 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-165A

Site #:	N5-165	Year Superstructure Installed:	2018	Structure Type/Class:	Permanent Bridge
KM:	19.16	User km:	3.60	Last Inspection Date:	2019/09/22
Project File ID #:	0022	Br.	01	Next Inspection Date:	2022/09/22
Road Name:	DEER CREEK				
Crossing Name:	TULIP Cr		Total Length (metres):	15.6	
Special Access:			Special Equipment:		
Longitude:	-117 55 55.1		Latitude:	49 21 52.1	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-016

Site #:	N5-016	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	20.70	User km:	2.50	Last Inspection Date:	2019/09/22
Project File ID #:	0022	Br.	01	Next Inspection Date:	2022/09/22
Road Name:	DEER CREEK				
Crossing Name:	LARGE CREVICE		Total Length (metres):	12.3	
Special Access:			Special Equipment:		
Longitude:	-117 54 56.2		Latitude:	49 21 34.2	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Cast in Place	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-025

Site #:	N5-025	Year Superstructure Installed:	1992	Structure Type/Class:	Permanent Bridge
KM:	10.36	User km:	10.10	Last Inspection Date:	2019/09/22
Project File ID #:	0040	Br.	03	Next Inspection Date:	2022/09/22
Road Name:	ERIE CR. GRASSY ONE				
Crossing Name:	ERIE Cr		Total Length (metres):	16.3	
Special Access:			Special Equipment:		
Longitude:	-117 23 21.3		Latitude:	49 15 36.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 07-JAN-16: JN; 2016-01-07: Investigate cause of sink hole in Right bin wall and take detailed measurements of corrosion in left bin wall. Repair as directed by a professional engineer.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 7 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-203

Site #:	N5-203	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	12.90	User km:		Last Inspection Date:	2019/09/22
Project File ID #:	0040	Br.	03	Next Inspection Date:	2022/09/22
Road Name:	ERIE CR. GRASSY ONE				
Crossing Name:	Unnamed		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-117 25 2.2		Latitude:	49 16 11.1	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Location coordinates are dummy. Inspector to collect accurate location coordinates. NEW COORDINATES: Easting 0469645 Northing 5457528 10/2013				

Structure Name: N5-238

Site #:	N5-238	Year Superstructure Installed:	1995	Structure Type/Class:	Temporary Bridge
KM:	0.20	User km:	29.00	Last Inspection Date:	2020/08/23
Project File ID #:	9568	Br.	27	Next Inspection Date:	2022/08/23
Road Name:	EUREKA FSR				
Crossing Name:	HOLDING CR		Total Length (metres):	12.1	
Special Access:			Special Equipment:		
Longitude:	-118 19 27.3		Latitude:	50 5 0.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-240

Site #:	N5-240	Year Superstructure Installed:	1994	Structure Type/Class:	Temporary Bridge
KM:	2.10	User km:		Last Inspection Date:	2020/08/23
Project File ID #:	9568	Br.	27	Next Inspection Date:	2022/08/23
Road Name:	EUREKA FSR				
Crossing Name:	unknown		Total Length (metres):	4.9	
Special Access:			Special Equipment:		
Longitude:	-118 18 52.2		Latitude:	50 4 41.8	
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 8 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-029

Site #:	N5-029	Year Superstructure Installed:	1992	Structure Type/Class:	Temporary Bridge
KM:	0.02	User km:	0.00	Last Inspection Date:	2020/08/26
Project File ID #:	0330	Br.	01	Next Inspection Date:	2022/08/13
Road Name:	HADOW CREEK				
Crossing Name:	INCOMAPPLEUX R	Total Length (metres):	30.4		
Special Access:		Special Equipment:	Peeper Truck		
Longitude:	-117 41 39.5	Latitude:	50 45 26.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	<p>IDIR\BPELLETT on 02-MAY-22: BP May 2-22 Inspector to thoroughly search for fabricator markings and photograph any found</p> <p>IDIR\JNAUL on 13-MAY-19: Hire Ron Peace and peeper to inspect cribs in 2021</p> <p>IDIR\JNAUL on 16-MAR-15: Bridge has a new deck including ties, planks and curbs. Rot has been detected in cribs and sills and sills may require replacement in 2 to 3 years according to SNT report in 2013.</p> <p>JN; 2015-03-16: Re-inspect cribs and voids annually and after every major storm event. Bridge should be surveyed in 2015 for replacement in 2016. For replacement design Ga, I would prefer to have concrete abutments tied into the bed rock.</p> <p>CBR_Conversion on 17-FEB-14: Inspect rot in sill logs.</p>				

Structure Name: N5-160A

Site #:	N5-160	Year Superstructure Installed:	2012	Structure Type/Class:	Major Culvert
KM:	6.28	User km:	6.20	Last Inspection Date:	2019/09/04
Project File ID #:	0330	Br.	01	Next Inspection Date:	2022/09/04
Road Name:	HADOW CREEK				
Crossing Name:	ROYAL Cr	Total Length (metres):	15.0		
Special Access:		Special Equipment:			
Longitude:	-117 45 15.3	Latitude:	50 45 46.3		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: N5-251

Site #:	N5-251	Year Superstructure Installed:		Structure Type/Class:	Major Culvert
KM:	2.80	User km:	2.90	Last Inspection Date:	2019/09/04
Project File ID #:	0176	Br.	03	Next Inspection Date:	2022/09/04
Road Name:	HALFWAY RIVER SOUTH				
Crossing Name:	unknown	Total Length (metres):	14.6		
Special Access:		Special Equipment:			
Longitude:	-117 52 1.4	Latitude:	50 27 56.3		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 9 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Planned Inspection Comments:

Structure Name: N5-030

Site #:	N5-030	Year Superstructure Installed:	1989	Structure Type/Class:	Permanent Bridge
KM:	12.30	User km:	12.30	Last Inspection Date:	2019/09/04
Project File ID #:	0176	Br.	02	Next Inspection Date:	2022/09/04
Road Name:	HALFWAY-DEEP				
Crossing Name:	Unnamed		Total Length (metres):	6.5	
Special Access:			Special Equipment:		
Longitude:	-117 46 26.9		Latitude:	50 30 3.3	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1

Planned Inspection Comments:

Structure Name: N5-202

Site #:	N5-202	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	3.50	User km:		Last Inspection Date:	2019/09/03
Project File ID #:	0319	Br.	05	Next Inspection Date:	2022/09/03
Road Name:	Ice FSR				
Crossing Name:	Ice Creek		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-117 48 47.1		Latitude:	49 56 3.3	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1

Planned Inspection Comments: CBR_Conversion on 17-FEB-14: Location coordinates are dummy. Inspector to collect accurate location coordinates.

Structure Name: N5-139

Site #:	N5-139	Year Superstructure Installed:	1980	Structure Type/Class:	Major Culvert
KM:	17.40	User km:	17.40	Last Inspection Date:	2019/09/20
Project File ID #:	0145	Br.	01	Next Inspection Date:	2022/09/20
Road Name:	KOCH CREEK				
Crossing Name:	COUGAR Cr		Total Length (metres):	16.6	
Special Access:			Special Equipment:		
Longitude:	-117 47 48.3		Latitude:	49 37 24.4	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0

Planned Inspection Comments: IDIR\JNAUL on 01-APR-14: JN; 2014-04-01: There are no design drawings on file. Measure depth of cover. Recommend fish habitat assessment prior to structure replacement.



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 10 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-065

Site #:	N5-065	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	17.48	User km:	26.10	Last Inspection Date:	2019/09/20
Project File ID #:	0145	Br.	01	Next Inspection Date:	2022/09/20
Road Name:	KOCH CREEK				
Crossing Name:	WILTON Cr		Total Length (metres):	10.3	
Special Access:			Special Equipment:		
Longitude:	-117 52 55.5		Latitude:	49 39 59.4	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-041

Site #:	N5-041	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	19.70	User km:	19.70	Last Inspection Date:	2019/09/03
Project File ID #:	0042	Br.	01	Next Inspection Date:	2022/09/03
Road Name:	KUSKANAX				
Crossing Name:	Unnamed		Total Length (metres):	9.6	
Special Access:			Special Equipment:		
Longitude:	-117 29 34.7		Latitude:	50 22 52.8	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-046

Site #:	N5-046	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	0.44	User km:	14.60	Last Inspection Date:	2019/09/23
Project File ID #:	4172	Br.	01	Next Inspection Date:	2022/09/23
Road Name:	LADYBIRD CREEK				
Crossing Name:	Unnamed		Total Length (metres):	11.4	
Special Access:			Special Equipment:		
Longitude:	-117 49 37.2		Latitude:	49 27 4.9	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 11 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-191

Site #:	N5-191	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:	4.80	User km:	9.00	Last Inspection Date:	2019/09/23
Project File ID #:	4172	Br.	02	Next Inspection Date:	2022/09/23
Road Name:	LADYBIRD-NORNS				
Crossing Name:	NORNS Cr	Total Length (metres):	18.3		
Special Access:		Special Equipment:			
Longitude:	-117 46 11.9	Latitude:	49 27 52.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-048

Site #:	N5-048	Year Superstructure Installed:	1989	Structure Type/Class:	Temporary Bridge
KM:	1.06	User km:	0.30	Last Inspection Date:	2019/09/04
Project File ID #:	0322	Br.	01	Next Inspection Date:	2021/09/04
Road Name:	LARDEAU CREEK				
Crossing Name:	LARDEAU Cr	Total Length (metres):	26.0		
Special Access:		Special Equipment:	Peeper Truck		
Longitude:	-117 28 43.9	Latitude:	50 40 21.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 14-MAR-14: JN; 2014-03-14: Need peeper inspection of steel superstructure. Check bearing stiffeners during next routine inspection.				

Structure Name: N5-233

Site #:	N5-233	Year Superstructure Installed:		Structure Type/Class:	Woodbox/Log Culvert
KM:	4.10	User km:		Last Inspection Date:	2020/08/26
Project File ID #:	0322	Br.	01	Next Inspection Date:	2022/08/26
Road Name:	LARDEAU CREEK				
Crossing Name:	unknown	Total Length (metres):	20.0		
Special Access:		Special Equipment:			
Longitude:	-117 26 52.0	Latitude:	50 39 50.8		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\JNAUL on 18-JAN-21: Structure appears to have been replaced with a culvert. We do not have drawings for this install. IDIR\HABEURSK on 25-APR-16: Take back Structure. Record structure information and update CBR				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 12 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-234

Site #:	N5-234	Year Superstructure Installed:		Structure Type/Class:	Woodbox/Log Culvert
KM:	5.10	User km:		Last Inspection Date:	2020/08/26
Project File ID #:	0322	Br.	01	Next Inspection Date:	2022/08/26
Road Name:	LARDEAU CREEK				
Crossing Name:	unknown	Total Length (metres):	20.0		
Special Access:		Special Equipment:			
Longitude:	-117 26 10.3	Latitude:	50 39 46.8		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\JNAUL on 13-DEC-16: Monitor for failure after every freshet, after major rain on snow events, and after major rain storm events. IDIR\HABEURSK on 25-APR-16: take back structure. Inspect and record information to update CBR.				

Structure Name: N5-050

Site #:	N5-050	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	1.29	User km:	10.60	Last Inspection Date:	2021/09/11
Project File ID #:	0209	Br.	01	Next Inspection Date:	2022/09/16
Road Name:	LEMON CREEK-MAIN				
Crossing Name:	HOLMSEN Cr	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-117 21 35.4	Latitude:	49 41 35.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-248

Site #:	N5-248	Year Superstructure Installed:	2017	Structure Type/Class:	Permanent Bridge
KM:	1.50	User km:	1.50	Last Inspection Date:	2021/08/13
Project File ID #:	0209	Br.	01	Next Inspection Date:	2022/08/13
Road Name:	LEMON CREEK-MAIN				
Crossing Name:	South Lemon	Total Length (metres):	13.5		
Special Access:		Special Equipment:			
Longitude:	-117 27 43.5	Latitude:	49 41 52.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\BPELLETT on 21-APR-22: BP Apr 21-22 Monitor effects of Lemon Creek on left approach and left downstream corner				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 13 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-051A

Site #:	N5-051	Year Superstructure Installed:	2017	Structure Type/Class:	Permanent Bridge
KM:	2.61	User km:	12.00	Last Inspection Date:	2019/09/20
Project File ID #:	0209	Br.	01	Next Inspection Date:	2022/09/20
Road Name:	LEMON CREEK-MAIN				
Crossing Name:	MONUMENT Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-117 20 33.1		Latitude:	49 41 27.6	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-150

Site #:	N5-150	Year Superstructure Installed:	1999	Structure Type/Class:	Major Culvert
KM:	4.93	User km:	14.00	Last Inspection Date:	2019/09/20
Project File ID #:	0209	Br.	01	Next Inspection Date:	2022/09/20
Road Name:	LEMON CREEK-MAIN				
Crossing Name:	Unnamed		Total Length (metres):	22.0	
Special Access:			Special Equipment:		
Longitude:	-117 18 48.3		Latitude:	49 41 41.8	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\JNAUL on 01-APR-14: JN; 2014-04-01: Depth of cover in CBR does not match as built information on file (3 m average on file).				

Structure Name: N5-257

Site #:	N5-257	Year Superstructure Installed:	2017	Structure Type/Class:	Temporary Bridge
KM:	0.30	User km:	0.30	Last Inspection Date:	2020/08/23
Project File ID #:	8218	Br.	01	Next Inspection Date:	2022/08/23
Road Name:	LINDSAY LAKE				
Crossing Name:	Lindsey Creek		Total Length (metres):	9.1	
Special Access:			Special Equipment:		
Longitude:	-118 12 6.6		Latitude:	49 53 59.6	
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 14 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N7-274

Site #:	N5-274	Year Superstructure Installed:	1997	Structure Type/Class:	Temporary Bridge
KM:	7.40	User km:	7.40	Last Inspection Date:	
Project File ID #:	10523	Br.	11	Next Inspection Date:	2022/08/01
Road Name:	MICHENER FSR				
Crossing Name:	Dog Creek		Total Length (metres):	10.4	
Special Access:			Special Equipment:		
Longitude:	-118 7 44.7		Latitude:	49 16 46.9	
Superstructure:	Concrete I/T Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-275

Site #:	N5-275	Year Superstructure Installed:	1997	Structure Type/Class:	Temporary Bridge
KM:	9.00	User km:	9.00	Last Inspection Date:	
Project File ID #:	10523	Br.	11	Next Inspection Date:	2022/08/01
Road Name:	MICHENER FSR				
Crossing Name:	dog Creek Trib		Total Length (metres):	11.4	
Special Access:			Special Equipment:		
Longitude:	-118 7 39.9		Latitude:	49 17 35.1	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-276

Site #:	N5-276	Year Superstructure Installed:	1997	Structure Type/Class:	Temporary Bridge
KM:	11.40	User km:	11.40	Last Inspection Date:	
Project File ID #:	10523	Br.	11	Next Inspection Date:	2022/08/01
Road Name:	MICHENER FSR				
Crossing Name:	Dog Creek		Total Length (metres):	9.1	
Special Access:			Special Equipment:		
Longitude:	-118 7 15.2		Latitude:	49 18 15.3	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 15 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: TKO-0035

Site #:	N5-277	Year Superstructure Installed:	1997	Structure Type/Class:	Temporary Bridge
KM:	11.60	User km:	11.60	Last Inspection Date:	
Project File ID #:	10523	Br.	11	Next Inspection Date:	2022/08/01
Road Name:	MICHENER FSR				
Crossing Name:	porcupine Creek		Total Length (metres):	14.0	
Special Access:			Special Equipment:		
Longitude:	-118 7 17.6		Latitude:	49 18 52.5	
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:	IDIR\HABEURSK on 22-APR-22: There is an existing 11.4 that is being over-spanned				

Structure Name: N5-278

Site #:	N5-278	Year Superstructure Installed:	1997	Structure Type/Class:	Temporary Bridge
KM:	11.90	User km:	11.90	Last Inspection Date:	
Project File ID #:	10523	Br.	11	Next Inspection Date:	2022/08/01
Road Name:	MICHENER FSR				
Crossing Name:	Dog Creek		Total Length (metres):	10.4	
Special Access:			Special Equipment:		
Longitude:	-118 7 18.8		Latitude:	49 19 0.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-279

Site #:	N5-279	Year Superstructure Installed:	1998	Structure Type/Class:	Temporary Bridge
KM:	14.50	User km:	14.50	Last Inspection Date:	
Project File ID #:	10523	Br.	11	Next Inspection Date:	2022/08/01
Road Name:	MICHENER FSR				
Crossing Name:	Dog Creek		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-118 7 48.5		Latitude:	49 20 12.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 16 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-210

Site #:	N5-210	Year Superstructure Installed:	2010	Structure Type/Class:	Permanent Bridge
KM:	15.30	User km:		Last Inspection Date:	2019/09/03
Project File ID #:	0178	Br.	01	Next Inspection Date:	2022/09/03
Road Name:	MOUNTAIN MEADOWS				
Crossing Name:	Rodd Creek	Total Length (metres):	9.2		
Special Access:			Special Equipment:		
Longitude:	-117 49 19.2		Latitude:	50 2 56.5	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 19-JAN-16: JN; Re-inspect in 2016 to determine if the repairs have been completed per FLNRO prescription. IDIR\JNAUL on 21-OCT-14: JN, 2014-10-21: Reinspect this bridge in 2015 to check if the repairs have been completed. IDIR\JNAUL on 15-MAR-14: JN; 2014-03-15: SNT inspected this structure in 2013 and provided recommended rip rap repair. Re-inspect in 2014 to assess if repairs are completed. Inspector to post this bridge at 5 tonnes if rip rap repairs are not completed.				

Structure Name: N5-211

Site #:	N5-211	Year Superstructure Installed:	2009	Structure Type/Class:	Major Culvert
KM:	17.50	User km:		Last Inspection Date:	2019/09/03
Project File ID #:	0178	Br.	01	Next Inspection Date:	2022/09/03
Road Name:	MOUNTAIN MEADOWS				
Crossing Name:	Rodd Creek	Total Length (metres):	15.1		
Special Access:			Special Equipment:		
Longitude:	-117 49 3.8		Latitude:	50 3 52.3	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: MPenner Dec 18, 2012: confirm footing type at next inspection				

Structure Name: N5-120

Site #:	N5-120	Year Superstructure Installed:	1992	Structure Type/Class:	Temporary Bridge
KM:	4.03	User km:	4.00	Last Inspection Date:	2021/08/15
Project File ID #:	9464	Br.	05	Next Inspection Date:	2022/08/15
Road Name:	MUD LAKE-FIVE				
Crossing Name:	SUMMS Cr	Total Length (metres):	7.8		
Special Access:			Special Equipment:		
Longitude:	-118 1 55.5		Latitude:	49 13 37.0	
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 04-APR-14: JN; 2014-04-04: Inspect annually.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 17 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-137

Site #:	N5-137	Year Superstructure Installed:	2000	Structure Type/Class:	Major Culvert
KM:	0.58	User km:	0.30	Last Inspection Date:	2019/09/24
Project File ID #:	9464	Br.	01	Next Inspection Date:	2022/09/24
Road Name:	MUD LAKE-ONE				
Crossing Name:	BLUEBERRY Cr	Total Length (metres):	12.0		
Special Access:		Special Equipment:			
Longitude:	-117 57 56.3	Latitude:	49 14 40.4		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: N5-071

Site #:	N5-071	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	5.18	User km:	7.50	Last Inspection Date:	2019/09/20
Project File ID #:	0208	Br.	02	Next Inspection Date:	2022/09/20
Road Name:	NEW OTTAWA FSR				
Crossing Name:	DAYTON Cr	Total Length (metres):	9.1		
Special Access:		Special Equipment:			
Longitude:	-117 25 5.1	Latitude:	49 46 8.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-072

Site #:	N5-072	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	9.96	User km:	12.50	Last Inspection Date:	2019/09/20
Project File ID #:	0208	Br.	02	Next Inspection Date:	2022/09/20
Road Name:	NEW OTTAWA FSR				
Crossing Name:	SPRINGER Cr	Total Length (metres):	20.0		
Special Access:		Special Equipment:			
Longitude:	-117 22 25.0	Latitude:	49 46 56.1		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 08-JAN-16: JN; this bridge was not inspected in 2013. Must inspect in 2016 spring in order to facilitate N5-051 installation in 2016.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 18 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-167

Site #:	N5-167	Year Superstructure Installed:	2001	Structure Type/Class:	Temporary Bridge
KM:	13.33	User km:	13.80	Last Inspection Date:	2020/08/31
Project File ID #:	8391	Br.	01	Next Inspection Date:	2022/08/31
Road Name:	OSCAR CREEK				
Crossing Name:	Unnamed		Total Length (metres):	6.0	
Special Access:			Special Equipment:		
Longitude:	-117 5 32.7		Latitude:	49 18 2.4	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans: 1
Planned Inspection Comments:					

Structure Name: N5-074A

Site #:	N5-074	Year Superstructure Installed:	2016	Structure Type/Class:	Permanent Bridge
KM:	8.40	User km:	1.30	Last Inspection Date:	2019/09/21
Project File ID #:	0219	Br.	01	Next Inspection Date:	2022/09/21
Road Name:	PORCUPINE ONE				
Crossing Name:	PORCUPINE Cr		Total Length (metres):	21.8	
Special Access:			Special Equipment:		
Longitude:	-117 11 56.9		Latitude:	49 15 28.1	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\HABEURSK on 19-OCT-17: Monitor MSE Walls.				

Structure Name: N5-152

Site #:	N5-152	Year Superstructure Installed:	1998	Structure Type/Class:	Major Culvert
KM:	0.11	User km:	0.20	Last Inspection Date:	2019/08/11
Project File ID #:	0023	Br.	02	Next Inspection Date:	2022/08/11
Road Name:	RENATA-BOWMAN				
Crossing Name:	Unnamed		Total Length (metres):	15.0	
Special Access:			Special Equipment:		
Longitude:	-118 11 29.2		Latitude:	49 28 0.2	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 19 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-076

Site #:	N5-076	Year Superstructure Installed:	1989	Structure Type/Class:	Temporary Bridge
KM:	0.09	User km:	0.50	Last Inspection Date:	2018/09/05
Project File ID #:	0023	Br.	04	Next Inspection Date:	2022/09/14
Road Name:	RENATA-DOG				
Crossing Name:	DOG Cr	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-118 6 32.0	Latitude:	49 25 19.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 14-MAR-14: JN; 2014-03-14: Reinspect in 2014 to evaluate condition of cribs.				

Structure Name: N5-078

Site #:	N5-078	Year Superstructure Installed:	1992	Structure Type/Class:	Major Culvert
KM:	1.03	User km:	12.90	Last Inspection Date:	2019/09/23
Project File ID #:	8021	Br.	01	Next Inspection Date:	2022/09/23
Road Name:	RIALTO CREEK - ONE				
Crossing Name:	BALFOUR Cr	Total Length (metres):	14.0		
Special Access:		Special Equipment:			
Longitude:	-117 45 4.7	Latitude:	49 22 45.7		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: N5-079

Site #:	N5-079	Year Superstructure Installed:	1994	Structure Type/Class:	Major Culvert
KM:	1.11	User km:	14.90	Last Inspection Date:	2019/09/23
Project File ID #:	8021	Br.	01	Next Inspection Date:	2022/09/23
Road Name:	RIALTO CREEK - ONE				
Crossing Name:	RIALTO Cr	Total Length (metres):	13.8		
Special Access:		Special Equipment:			
Longitude:	-117 46 0.2	Latitude:	49 22 53.5		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 20 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-077

Site #:	N5-077	Year Superstructure Installed:	1994	Structure Type/Class:	Major Culvert
KM:	8.49	User km:	7.20	Last Inspection Date:	2019/09/23
Project File ID #:	8021	Br.	01	Next Inspection Date:	2022/09/23
Road Name:	RIALTO CREEK - ONE				
Crossing Name:	BALFOUR Cr	Total Length (metres):	14.0		
Special Access:			Special Equipment:		
Longitude:	-117 43 59.8		Latitude:	49 21 37.4	
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:					

Structure Name: N5-047

Site #:	N5-047	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	0.01	User km:	15.00	Last Inspection Date:	2019/09/23
Project File ID #:	R04294	Br.	1A	Next Inspection Date:	2022/09/23
Road Name:	SECTION_ONE_A				
Crossing Name:	LADYBIRD Cr	Total Length (metres):	16.5		
Special Access:			Special Equipment:		
Longitude:	-117 49 55.8		Latitude:	49 27 0.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-083A

Site #:	N5-083	Year Superstructure Installed:	2020	Structure Type/Class:	Permanent Bridge
KM:	5.48	User km:	22.40	Last Inspection Date:	
Project File ID #:	0216	Br.	03	Next Inspection Date:	2022/08/01
Road Name:	SHANNON-CARIBOU				
Crossing Name:	Unnamed	Total Length (metres):	15.2		
Special Access:			Special Equipment:		
Longitude:	-117 37 44.4		Latitude:	50 2 39.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 21 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-084A

Site #:	N5-084	Year Superstructure Installed:	2021	Structure Type/Class:	Permanent Bridge
KM:	8.78	User km:	25.60	Last Inspection Date:	2021/08/05
Project File ID #:	0216	Br.	03	Next Inspection Date:	2022/08/24
Road Name:	SHANNON-CARIBOU				
Crossing Name:	Unnamed		Total Length (metres):	10.6	
Special Access:			Special Equipment:		
Longitude:	-117 37 33.9		Latitude:	50 1 35.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-085A

Site #:	N5-085	Year Superstructure Installed:	2021	Structure Type/Class:	Permanent Bridge
KM:	11.43	User km:	28.30	Last Inspection Date:	
Project File ID #:	0216	Br.	03	Next Inspection Date:	2022/07/28
Road Name:	SHANNON-CARIBOU				
Crossing Name:	CARIBOU Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-117 38 27.0		Latitude:	50 0 34.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-188A

Site #:	N5-188	Year Superstructure Installed:	2021	Structure Type/Class:	Permanent Bridge
KM:	15.00	User km:	31.00	Last Inspection Date:	
Project File ID #:	0216	Br.	03	Next Inspection Date:	2022/08/01
Road Name:	SHANNON-CARIBOU				
Crossing Name:	CARIBOU Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-117 39 12.0		Latitude:	50 2 8.1	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 22 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-088

Site #:	N5-088	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:	4.22	User km:	2.00	Last Inspection Date:	2019/09/19
Project File ID #:	0216	Br.	05	Next Inspection Date:	2022/09/19
Road Name:	SHANNON-SLOCAN LAKE				
Crossing Name:	WRAGGE Cr	Total Length (metres):	15.2		
Special Access:			Special Equipment:		
Longitude:	-117 27 46.7	Latitude:	50 3 23.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-086A

Site #:	N5-086	Year Superstructure Installed:	2018	Structure Type/Class:	Permanent Bridge
KM:	2.70	User km:	4.90	Last Inspection Date:	2019/09/19
Project File ID #:	0216	Br.	02	Next Inspection Date:	2022/09/19
Road Name:	SHANNON-WRAGGE CREEK				
Crossing Name:	SHANNON Cr	Total Length (metres):	15.6		
Special Access:			Special Equipment:		
Longitude:	-117 29 11.8	Latitude:	50 4 9.3		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-256

Site #:	N5-256	Year Superstructure Installed:	2018	Structure Type/Class:	Permanent Bridge
KM:	0.20	User km:	0.20	Last Inspection Date:	2019/09/22
Project File ID #:	9536	Br.	11	Next Inspection Date:	2022/09/22
Road Name:	SHENANGO ROAD				
Crossing Name:	Sheango cr	Total Length (metres):	7.0		
Special Access:			Special Equipment:		
Longitude:	-117 17 41.4	Latitude:	49 1 53.3		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 23 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-119

Site #:	N5-119	Year Superstructure Installed:	1992	Structure Type/Class:	Temporary Bridge
KM:	0.18	User km:	13.10	Last Inspection Date:	2021/08/04
Project File ID #:	9564	Br.	02	Next Inspection Date:	2022/08/04
Road Name:	SOUTH FIFE TWO				
Crossing Name:	SOUTH FIFE Cr		Total Length (metres):	8.3	
Special Access:			Special Equipment:		
Longitude:	-118 10 42.0		Latitude:	50 7 13.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\BPELLETT on 22-APR-22: BP Apr 22-22 Inspector to photograph fabricator markings on girders IDIR\JNAUL on 01-APR-14: JN; 2014-04-01: reinspect cribs for scour and rot.				

Structure Name: TKO-0029

Site #:	N5-230	Year Superstructure Installed:	2015	Structure Type/Class:	Temporary Bridge
KM:	1.00	User km:	1.00	Last Inspection Date:	2020/09/01
Project File ID #:	0011	Br.	03	Next Inspection Date:	2022/09/01
Road Name:	ST. THOMAS FSR				
Crossing Name:	St. Thomas Creek		Total Length (metres):	9.1	
Special Access:			Special Equipment:		
Longitude:	-117 58 54.8		Latitude:	49 7 26.1	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-204

Site #:	N5-204	Year Superstructure Installed:		Structure Type/Class:	Major Culvert
KM:	0.03	User km:	4.60	Last Inspection Date:	2019/09/21
Project File ID #:	9560	Br.	02	Next Inspection Date:	2022/09/21
Road Name:	STEWART CREEK TWO				
Crossing Name:	Stewart Cr.		Total Length (metres):	22.0	
Special Access:			Special Equipment:		
Longitude:	-117 15 51.4		Latitude:	49 17 32.0	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\JNAUL on 15-MAR-14: JN; 2014-03-15: No concrete precast cut off walls visible in photos. Professional inspection required in 2014 (see comments above). CBR_Conversion on 17-FEB-14: collect as built information and confirm coordinates				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 24 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-098

Site #:	N5-098	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	6.70	User km:	17.50	Last Inspection Date:	2019/09/22
Project File ID #:	8908	Br.	01	Next Inspection Date:	2022/09/22
Road Name:	SUNSHINE CREEK ONE				
Crossing Name:	TWOBIT Cr		Total Length (metres):	6.3	
Special Access:			Special Equipment:		
Longitude:	-118 6 5.5		Latitude:	49 31 6.7	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Cast in Place	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 13-DEC-18: Please post this bridge at 5 tonnes if curbs are not replaced next year.				

Structure Name: N5-201

Site #:	N5-201	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	0.40	User km:	4.40	Last Inspection Date:	2019/09/23
Project File ID #:	10167	Br.	1	Next Inspection Date:	2022/09/23
Road Name:	SWEHAW				
Crossing Name:	Unnamed Crk		Total Length (metres):	13.5	
Special Access:			Special Equipment:		
Longitude:	-117 59 28.5		Latitude:	49 3 8.6	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Location coordinates are dummy. Inspector to collect accurate location coordinates. Followup note: Inspection on August 24, 2010, determined the actual coordinates as well as the User Km.				

Structure Name: N5-151

Site #:	N5-151	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	6.44	User km:	6.70	Last Inspection Date:	2021/08/13
Project File ID #:	7609	Br.	01	Next Inspection Date:	2022/08/13
Road Name:	TROZZO CREEK				
Crossing Name:	TROZZO Cr		Total Length (metres):	12.3	
Special Access:			Special Equipment:		
Longitude:	-117 27 20.9		Latitude:	49 38 12.6	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\BPELLETT on 26-APR-22: BP Apr 26-22 Monitor curb conditions and post bridge appropriately				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 25 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-190

Site #:	N5-190	Year Superstructure Installed:	2004	Structure Type/Class:	Permanent Bridge
KM:	5.39	User km:	3.40	Last Inspection Date:	2019/09/02
Project File ID #:	9564	Br.	05	Next Inspection Date:	2022/09/02
Road Name:	WEST WHATSHAN				
Crossing Name:	Unnamed		Total Length (metres):	9.0	
Special Access:			Special Equipment:		
Longitude:	-118 6 24.7		Latitude:	50 4 10.5	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-131

Site #:	N5-131	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	20.11	User km:	27.70	Last Inspection Date:	2019/09/02
Project File ID #:	2010	Br.	01	Next Inspection Date:	2022/09/02
Road Name:	WHATSHAN FSR				
Crossing Name:	STEVENS Cr		Total Length (metres):	12.3	
Special Access:			Special Equipment:		
Longitude:	-118 4 34.7		Latitude:	50 5 30.1	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-249

Site #:	N5-249	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	22.90	User km:	30.40	Last Inspection Date:	2019/09/02
Project File ID #:	2010	Br.	01	Next Inspection Date:	2022/09/02
Road Name:	WHATSHAN FSR				
Crossing Name:	Stevens Cr		Total Length (metres):	10.4	
Special Access:			Special Equipment:		
Longitude:	-118 2 53.8		Latitude:	50 6 4.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 29-SEP-16: Fill out inventory sheet as found structure with no shop drawings and values entered in Details are estimates.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 26 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-105

Site #:	N5-105	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	5.14	User km:	37.20	Last Inspection Date:	2019/09/19
Project File ID #:	0035	Br.	01	Next Inspection Date:	2022/09/19
Road Name:	WILSON CREEK				
Crossing Name:	HARLOW Cr		Total Length (metres):	14.0	
Special Access:			Special Equipment:		
Longitude:	-117 36 59.9		Latitude:	50 13 38.5	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-103A

Site #:	N5-103	Year Superstructure Installed:	2010	Structure Type/Class:	Permanent Bridge
KM:	10.31	User km:	31.80	Last Inspection Date:	2019/09/19
Project File ID #:	0035	Br.	01	Next Inspection Date:	2022/09/19
Road Name:	WILSON CREEK				
Crossing Name:	HAMLING Cr		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-117 33 24.1		Latitude:	50 13 56.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-121

Site #:	N5-121	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	41.62	User km:	0.90	Last Inspection Date:	2019/09/19
Project File ID #:	0035	Br.	01	Next Inspection Date:	2022/09/19
Road Name:	WILSON CREEK				
Crossing Name:	DENNIS Cr		Total Length (metres):	18.0	
Special Access:			Special Equipment:		
Longitude:	-117 23 39.9		Latitude:	50 2 5.6	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 27 of 27
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

Structure Name: N5-148

Site #:	N5-148	Year Superstructure Installed:		1985	Structure Type/Class:	Major Culvert	
KM:	15.40	User km:	15.40	Last Inspection Date:		2019/08/12	
Project File ID #:	0095	Br.	01	Next Inspection Date:		2022/08/12	
Road Name:		WORTHINGTON					
Crossing Name:		JOHNSTON Cr		Total Length (metres):		11.2	
Special Access:				Special Equipment:			
Longitude:		-118 15 23.3		Latitude:		49 44 17.3	
Superstructure:				Abutments (Left/Right): <i>(looking downstream)</i>		# Spans: 0	
Planned Inspection Comments:		IDIR\JNAUL on 01-APR-14: JN; 2014-04-10: Confirm depth of cover and culvert gradient.					

Structure Name: N5-T04

Site #:	N5-T04	Year Superstructure Installed:		1997	Structure Type/Class:	Permanent Bridge		
KM:	1.99	User km:	24.20	Last Inspection Date:		2019/08/12		
Project File ID #:	0095	Br.	12	Next Inspection Date:		2022/08/12		
Road Name:		WORTHINGTON-TWELVE						
Crossing Name:		JOHNSTON Cr		Total Length (metres):		9.1		
Special Access:				Special Equipment:				
Longitude:		-118 17 15.9		Latitude:		49 47 51.0		
Superstructure:	Steel I-beam		Abutments (Left/Right): <i>(looking downstream)</i>		Sill - Permanent		# Spans:	1
Planned Inspection Comments:		IDIR\JNAUL on 19-MAR-15: JN; 2015-03-15: reinspect in 2016 and post bridge at 5 tonnes and 5 km/hr speed signs if curbs and deck are not repaired. Please send us photos for our records.						

Structure Name: N5-175A

Site #:	N5-175	Year Superstructure Installed:		2019	Structure Type/Class:	Temporary Bridge	
KM:	1.88	User km:	5.90	Last Inspection Date:		2020/08/31	
Project File ID #:	0217	Br.	01	Next Inspection Date:		2022/08/31	
Road Name:		YMIR CREEK					
Crossing Name:		HUCKLEBERRY Cr		Total Length (metres):		12.2	
Special Access:				Special Equipment:			
Longitude:		-117 9 57.8		Latitude:		49 19 1.1	
Superstructure:	Steel I-beam		Abutments (Left/Right): <i>(looking downstream)</i>		Sill - Permanent Materials		# Spans: 1
Planned Inspection Comments:							

Structure Type/Class Totals

Permanent Bridge Total: 42	Major Culvert Total: 17
Temporary Bridge Total: 20	Woodbox/Log Culvert Total: 2