



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 1 of 12
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/31 Inspection Status:Inspect Management Area: 57 Sort: Forest Service Road Site

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
	Special Equipment Required	Special Access Required	Planned Inspection Comment									
1	N5-232	N5-232	2019/09/21	2022/09/21	P	0219-04	18.3	0	ACTIVEFSR	0.10	0.10	active
2	N5-221	N5-221	2019/09/21	2022/09/21	P	0221-09	24.8	0	AR0221.09 BENNETT FS	0.00	0.00	Sheep Creek
3	N5-222	N5-222	2019/09/21	2022/09/21	P	0221-09	6.0	0	AR0221.09 BENNETT FS	0.10	0.10	Unnamed Creek
4	N5-250	N5-250	2019/09/22	2022/09/22	P	9536-05	15.2	0	AR9536.05 LOST MTN F	0.10	0.10	Lost Creek
5	N5-239	N5-239	2020/08/23	2022/08/23	T	9568-01	9.4	0	BARNES CREEK WEST	19.00	30.80	Holding Cr
6	N5-138	N5-138	2019/09/19	2022/09/19	MC	0168-01	24.0	0	BENCH CREEK	10.87	6.00	GALLOPING Cr
7	N5-217	N5-217	2020/09/01	2022/09/01	T	0011-01	12.2	0	BIG SHEEP CREEK	12.00		Esling Creek
8	N5-254	N5-254	2019/09/24	2022/09/24	MC	0058-01	23.0	0	BULLDOG	28.00	28.00	Brooklyn Cr



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 2 of 12
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/31 Inspection Status: Inspect Management Area: 57 Sort: Forest Service Road Site

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required	Special Access Required	Planned Inspection Comment										
9	N5-255	N5-255	2019/09/24	2022/09/24	P	0058-01	9.0	0	BULLDOG	28.10	28.10	Pup Creek
10	N5-010	N5-010	2019/09/03	2022/09/03	P	0181-01	8.6	0	CARIBOU ONE	0.00	6.30	MINERAL Cr
11	N5-259	N5-259		2022/08/01	P	0181-01	12.0	0	CARIBOU ONE	4.80	4.80	Rodd Creek
12	N5-011	N5-011	2019/09/03	2022/09/03	MC	0181-02	15.0	0	CARIBOU SOUTH	5.68	8.60	RODD Cr
13	N5-227	N5-227	2020/08/28	2022/08/28	T	0205-01	9.2	0	CARPENTER CREEK	0.10	0.10	Carpenter Cr
14	N5-246	N5-246	2019/09/23	2022/09/23	MC	7874-01	18.4	0	CASCADE HWY	3.46	29.00	Santa Rosa Cr
			IDIR\JNAUL on 18-JAN-18: Please pick up corrugation profile. IDIR\HABEURSK on 31-MAR-17: found structure. Pick-up as built information on next inspection.									
15	N5-173	N5-173	2019/09/22	2022/09/22	MC	0022-01	18.3	0	DEER CREEK	10.99	12.40	Little Cayuse Creek



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 3 of 12
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/31 Inspection Status: Inspect Management Area: 57 Sort: Forest Service Road Site

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required		Special Access Required	Planned Inspection Comment									
16	N5-165	N5-165A	2019/09/22	2022/09/22	P	0022-01	15.6	0	DEER CREEK	19.16	3.60	TULIP Cr
17	N5-016	N5-016	2019/09/22	2022/09/22	P	0022-01	12.3	0	DEER CREEK	20.70	2.50	LARGE CREVICE
18	N5-025	N5-025	2019/09/22	2022/09/22	P	0040-03	16.3	0	ERIE CR. GRASSY ONE	10.36	10.10	ERIE Cr
			IDIR\JNAUL on 07-JAN-16: JN; 2016-01-07: Investigate cause of sink hole in Right bin wall and take detailed measurements of corrosion in left bin wall. Repair as directed by a professional engineer.									
19	N5-203	N5-203	2019/09/22	2022/09/22	P	0040-03	10.0	0	ERIE CR. GRASSY ONE	12.90		Unnamed
			CBR_Conversion on 17-FEB-14: Location coordinates are dummy. Inspector to collect accurate location coordinates. NEW COORDINATES: Easting 0469645 Northing 5457528 10/2013									
20	N5-238	N5-238	2020/08/23	2022/08/23	T	9568-27	12.1	0	EUREKA FSR	0.20	29.00	HOLDING CR
21	N5-240	N5-240	2020/08/23	2022/08/23	T	9568-27	4.9	0	EUREKA FSR	2.10		unknown
22	N5-029	N5-029	2020/08/26	2022/08/13	T	0330-01	30.4	0	HADOW CREEK	0.02	0.00	INCOMAPPLEUX R



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 4 of 12
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/31 Inspection Status: Inspect Management Area: 57 Sort: Forest Service Road Site

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
	Special Equipment Required	Special Access Required	Planned Inspection Comment									
	Peeper Truck		IDIR\BPELLETT on 02-MAY-22: BP May 2-22 Inspector to thoroughly search for fabricator markings and photograph any found IDIR\JNAUL on 13-MAY-19: Hire Ron Peace and peeper to inspect cribs in 2021									
23	N5-160	N5-160A	2019/09/04	2022/09/04	MC	0330-01	15.0	0	HADOW CREEK	6.28	6.20	ROYAL Cr
24	N5-251	N5-251	2019/09/04	2022/09/04	MC	0176-03	14.6	0	HALFWAY RIVER SOUTH	2.80	2.90	unknown
25	N5-030	N5-030	2019/09/04	2022/09/04	P	0176-02	6.5	0	HALFWAY-DEEP	12.30	12.30	Unnamed
26	N5-202	N5-202	2019/09/03	2022/09/03	P	0319-05	12.0	0	Ice FSR	3.50		Ice Creek
			CBR_Conversion on 17-FEB-14: Location coordinates are dummy. Inspector to collect accurate location coordinates.									
27	N5-139	N5-139	2019/09/20	2022/09/20	MC	0145-01	16.6	0	KOCH CREEK	17.40	17.40	COUGAR Cr
			IDIR\JNAUL on 01-APR-14: JN; 2014-04-01: There are no design drawings on file. Measure depth of cover. Recommend fish habitat assessment prior to structure replacement.									
28	N5-065	N5-065	2019/09/20	2022/09/20	P	0145-01	10.3	0	KOCH CREEK	17.48	26.10	WILTON Cr
29	N5-041	N5-041	2019/09/03	2022/09/03	P	0042-01	9.6	0	KUSKANAX	19.70	19.70	Unnamed



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 5 of 12
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/31 Inspection Status: Inspect Management Area: 57 Sort: Forest Service Road Site

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
30	N5-046	N5-046	2019/09/23	2022/09/23	P	4172-01	11.4	0	LADYBIRD CREEK	0.44	14.60	Unnamed
31	N5-191	N5-191	2019/09/23	2022/09/23	P	4172-02	18.3	0	LADYBIRD-NORNS	4.80	9.00	NORNS Cr
32	N5-048	N5-048	2019/09/04	2021/09/04	T	0322-01	26.0	0	LARDEAU CREEK	1.06	0.30	LARDEAU Cr
	Peeper Truck		IDIR\JNAUL on 14-MAR-14: JN; 2014-03-14: Need peeper inspection of steel superstructure. Check bearing stiffeners during next routine inspection.									
33	N5-233	N5-233	2020/08/26	2022/08/26	W	0322-01	20.0	0	LARDEAU CREEK	4.10		unknown
			IDIR\JNAUL on 18-JAN-21: Structure appears to have been replaced with a culvert. We do not have drawings for this install. IDIR\HABEURSK on 25-APR-16: Take back Structure. Record structure information and update CBR									
34	N5-234	N5-234	2020/08/26	2022/08/26	W	0322-01	20.0	0	LARDEAU CREEK	5.10		unknown
			IDIR\JNAUL on 13-DEC-16: Monitor for failure after every freshet, after major rain on snow events, and after major rain storm events. IDIR\HABEURSK on 25-APR-16: take back structure. Inspect and record information to update CBR.									
35	N5-050	N5-050	2021/09/11	2022/09/16	P	0209-01	12.2	0	LEMON CREEK-MAIN	1.29	10.60	HOLMSEN Cr
36	N5-248	N5-248	2021/08/13	2022/08/13	P	0209-01	13.5	0	LEMON CREEK-MAIN	1.50	1.50	South Lemon



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 6 of 12
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/31 Inspection Status: Inspect Management Area: 57 Sort: Forest Service Road Site

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
		Special Equipment Required	Special Access Required	Planned Inspection Comment								
				IDIR\BPelletT on 21-APR-22: BP Apr 21-22 Monitor effects of Lemon Creek on left approach and left downstream corner								
37	N5-051	N5-051A	2019/09/20	2022/09/20	P	0209-01	15.2	0	LEMON CREEK-MAIN	2.61	12.00	MONUMENT Cr
38	N5-150	N5-150	2019/09/20	2022/09/20	MC	0209-01	22.0	0	LEMON CREEK-MAIN	4.93	14.00	Unnamed
				IDIR\JNAUL on 01-APR-14: JN; 2014-04-01: Depth of cover in CBR does not match as built information on file (3 m average on file).								
39	N5-257	N5-257	2020/08/23	2022/08/23	T	8218-01	9.1	0	LINDSAY LAKE	0.30	0.30	Lindsey Creek
40	N5-274	N7-274		2022/08/01	T	10523-11	10.4	0	MICHENER FSR	7.40	7.40	Dog Creek
41	N5-275	N5-275		2022/08/01	T	10523-11	11.4	0	MICHENER FSR	9.00	9.00	dog Creek Trib
42	N5-276	N5-276		2022/08/01	T	10523-11	9.1	0	MICHENER FSR	11.40	11.40	Dog Creek
43	N5-277	TKO-0035		2022/08/01	T	10523-11	14.0	0	MICHENER FSR	11.60	11.60	porcupine Creek



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 7 of 12
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/31 Inspection Status: Inspect Management Area: 57 Sort: Forest Service Road Site

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
			IDIR\HABEURSK on 22-APR-22: There is an existing 11.4 that is being over-spanned									
44	N5-278	N5-278		2022/08/01	T	10523-11	10.4	0	MICHENER FSR	11.90	11.90	Dog Creek
45	N5-279	N5-279		2022/08/01	T	10523-11	12.2	0	MICHENER FSR	14.50	14.50	Dog Creek
46	N5-210	N5-210	2019/09/03	2022/09/03	P	0178-01	9.2	0	MOUNTAIN MEADOWS	15.30		Rodd Creek
			IDIR\JNAUL on 19-JAN-16: JN; Re-inspect in 2016 to determine if the repairs have been completed per FLNRO prescription. IDIR\JNAUL on 21-OCT-14: JN, 2014-10-21: Reinspect this bridge in 2015 to check if the repairs have been completed.									
47	N5-211	N5-211	2019/09/03	2022/09/03	MC	0178-01	15.1	0	MOUNTAIN MEADOWS	17.50		Rodd Creek
			CBR_Conversion on 17-FEB-14: MPenner Dec 18, 2012: confirm footing type at next inspection									
48	N5-120	N5-120	2021/08/15	2022/08/15	T	9464-05	7.8	0	MUD LAKE-FIVE	4.03	4.00	SUMMS Cr
			IDIR\JNAUL on 04-APR-14: JN; 2014-04-04: Inspect annually.									
49	N5-137	N5-137	2019/09/24	2022/09/24	MC	9464-01	12.0	0	MUD LAKE-ONE	0.58	0.30	BLUEBERRY Cr
50	N5-071	N5-071	2019/09/20	2022/09/20	P	0208-02	9.1	0	NEW OTTAWA FSR	5.18	7.50	DAYTON Cr



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 8 of 12
 Date Printed: 2022/05/05
 User Id: IDIR\HABEURSK
 Database: PROD
 Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/31 Inspection Status: Inspect Management Area: 57 Sort: Forest Service Road Site

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
51	N5-072	N5-072	2019/09/20	2022/09/20	P	0208-02	20.0	0	NEW OTTAWA FSR	9.96	12.50	SPRINGER Cr
			IDIR\JNAUL on 08-JAN-16: JN; this bridge was not inspected in 2013. Must inspect in 2016 spring in order to facilitate N5-051 installation in 2016.									
52	N5-167	N5-167	2020/08/31	2022/08/31	T	8391-01	6.0	0	OSCAR CREEK	13.33	13.80	Unnamed
53	N5-074	N5-074A	2019/09/21	2022/09/21	P	0219-01	21.8	0	PORCUPINE ONE	8.40	1.30	PORCUPINE Cr
			IDIR\HABEURSK on 19-OCT-17: Monitor MSE Walls.									
54	N5-152	N5-152	2019/08/11	2022/08/11	MC	0023-02	15.0	0	RENATA-BOWMAN	0.11	0.20	Unnamed
55	N5-076	N5-076	2018/09/05	2022/09/14	T	0023-04	12.2	0	RENATA-DOG	0.09	0.50	DOG Cr
			IDIR\JNAUL on 14-MAR-14: JN; 2014-03-14: Reinspect in 2014 to evaluate condition of cribs.									
56	N5-078	N5-078	2019/09/23	2022/09/23	MC	8021-01	14.0	0	RIALTO CREEK - ONE	1.03	12.90	BALFOUR Cr
57	N5-079	N5-079	2019/09/23	2022/09/23	MC	8021-01	13.8	0	RIALTO CREEK - ONE	1.11	14.90	RIALTO Cr



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 9 of 12
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/31 Inspection Status: Inspect Management Area: 57 Sort: Forest Service Road Site

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
58	N5-077	N5-077	2019/09/23	2022/09/23	MC	8021-01	14.0	0	RIALTO CREEK - ONE	8.49	7.20	BALFOUR Cr
59	N5-047	N5-047	2019/09/23	2022/09/23	P	R04294-1A	16.5	0	SECTION_ONE_A	0.01	15.00	LADYBIRD Cr
60	N5-083	N5-083A		2022/08/01	P	0216-03	15.2	0	SHANNON-CARIBOU	5.48	22.40	Unnamed
61	N5-084	N5-084A	2021/08/05	2022/08/24	P	0216-03	10.6	0	SHANNON-CARIBOU	8.78	25.60	Unnamed
62	N5-085	N5-085A		2022/07/28	P	0216-03	15.2	0	SHANNON-CARIBOU	11.43	28.30	CARIBOU Cr
63	N5-188	N5-188A		2022/08/01	P	0216-03	15.2	0	SHANNON-CARIBOU	15.00	31.00	CARIBOU Cr
64	N5-088	N5-088	2019/09/19	2022/09/19	P	0216-05	15.2	0	SHANNON-SLOCAN LAKE	4.22	2.00	WRAGGE Cr



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 10 of 12
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/31 Inspection Status: Inspect Management Area: 57 Sort: Forest Service Road Site

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required	Special Access Required	Planned Inspection Comment										
65	N5-086	N5-086A	2019/09/19	2022/09/19	P	0216-02	15.6	0	SHANNON-WRAGGE CREEK	2.70	4.90	SHANNON Cr
66	N5-256	N5-256	2019/09/22	2022/09/22	P	9536-11	7.0	0	SHENANGO ROAD	0.20	0.20	Sheango cr
67	N5-119	N5-119	2021/08/04	2022/08/04	T	9564-02	8.3	0	SOUTH FIFE TWO	0.18	13.10	SOUTH FIFE Cr
			IDIR\BPELLETT on 22-APR-22: BP Apr 22-22 Inspector to photograph fabricator markings on girders IDIR\JNAUL on 01-APR-14: JN; 2014-04-01: reinspect cribs for scour and rot.									
68	N5-230	TKO-0029	2020/09/01	2022/09/01	T	0011-03	9.1	0	ST. THOMAS FSR	1.00	1.00	St. Thomas Creek
69	N5-204	N5-204	2019/09/21	2022/09/21	MC	9560-02	22.0	0	STEWART CREEK TWO	0.03	4.60	Stewart Cr.
			IDIR\JNAUL on 15-MAR-14: JN; 2014-03-15: No concrete precast cut off walls visible in photos.									
70	N5-098	N5-098	2019/09/22	2022/09/22	P	8908-01	6.3	0	SUNSHINE CREEK ONE	6.70	17.50	TWOBIT Cr
			IDIR\JNAUL on 13-DEC-18: Please post this bridge at 5 tonnes if curbs are not replaced next year.									
71	N5-201	N5-201	2019/09/23	2022/09/23	P	10167-1	13.5	0	SWEHAW	0.40	4.40	Unnamed Crk



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 11 of 12
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/31 Inspection Status: Inspect Management Area: 57 Sort: Forest Service Road Site

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
			Planned Inspection Comment									
			CBR_Conversion on 17-FEB-14: Location coordinates are dummy. Inspector to collect accurate location coordinates. Followup note: Inspection on August 24, 2010, determined the actual coordinates as well as the User Km.									
72	N5-151	N5-151	2021/08/13	2022/08/13	P	7609-01	12.3	0	TROZZO CREEK	6.44	6.70	TROZZO Cr
			IDIR\BPelletT on 26-APR-22: BP Apr 26-22 Monitor curb conditions and post bridge appropriately									
73	N5-190	N5-190	2019/09/02	2022/09/02	P	9564-05	9.0	0	WEST WHATSHAN	5.39	3.40	Unnamed
74	N5-131	N5-131	2019/09/02	2022/09/02	P	2010-01	12.3	0	WHATSHAN FSR	20.11	27.70	STEVENS Cr
75	N5-249	N5-249	2019/09/02	2022/09/02	P	2010-01	10.4	0	WHATSHAN FSR	22.90	30.40	Stevens Cr
			IDIR\MRFENNEL on 29-SEP-16: Fill out inventory sheet as found structure with no shop drawings and values entered in Details are estimates.									
76	N5-105	N5-105	2019/09/19	2022/09/19	P	0035-01	14.0	0	WILSON CREEK	5.14	37.20	HARLOW Cr
77	N5-103	N5-103A	2019/09/19	2022/09/19	P	0035-01	18.3	0	WILSON CREEK	10.31	31.80	HAMLING Cr
78	N5-121	N5-121	2019/09/19	2022/09/19	P	0035-01	18.0	0	WILSON CREEK	41.62	0.90	DENNIS Cr



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 12 of 12
Date Printed: 2022/05/05
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR004

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/31 Inspection Status: Inspect Management Area: 57 Sort: Forest Service Road Site

Forest District: Selkirk Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required	Special Access Required	Planned Inspection Comment										
79	N5-148	N5-148	2019/08/12	2022/08/12	MC	0095-01	11.2	0	WORTHINGTON	15.40	15.40	JOHNSTON Cr
			IDIR\JNAUL on 01-APR-14: JN; 2014-04-10: Confirm depth of cover and culvert gradient.									
80	N5-T04	N5-T04	2019/08/12	2022/08/12	P	0095-12	9.1	0	WORTHINGTON-TWELVE	1.99	24.20	JOHNSTON Cr
			IDIR\JNAUL on 19-MAR-15: JN; 2015-03-15: reinspect in 2016 and post bridge at 5 tonnes and 5 km/hr speed signs if curbs and deck are not repaired. Please send us photos for our records.									
81	N5-175	N5-175A	2020/08/31	2022/08/31	T	0217-01	12.2	0	YMIR CREEK	1.88	5.90	HUCKLEBERRY Cr

Permanent Bridge Total: 42

Temporary Bridge Total: 20

Major Culvert Total: 17

Woodbox/Log Culvert Total: 2