



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 1 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status: Inspect

### Structure Name: N6-003

|                              |                                                                                                         |                                                 |                            |                       |                  |
|------------------------------|---------------------------------------------------------------------------------------------------------|-------------------------------------------------|----------------------------|-----------------------|------------------|
| Site #:                      | N6-003                                                                                                  | Year Superstructure Installed:                  | 2005                       | Structure Type/Class: | Permanent Bridge |
| KM:                          | 12.90                                                                                                   | User km:                                        | 10.30                      | Last Inspection Date: | 2019/08/10       |
| Project File ID #:           | 6333                                                                                                    | Br.                                             | 01                         | Next Inspection Date: | 2022/08/10       |
| Road Name:                   | ALMOND CREEK                                                                                            |                                                 |                            |                       |                  |
| Crossing Name:               | ALMOND Cr #2                                                                                            | Total Length (metres):                          | 14.0                       |                       |                  |
| Special Access:              |                                                                                                         | Special Equipment:                              |                            |                       |                  |
| Longitude:                   | -118 30 6.4                                                                                             | Latitude:                                       | 49 18 8.9                  |                       |                  |
| Superstructure:              | Steel I-beam                                                                                            | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JNAUL on 07-JAN-20: JRG Jan 7, 2020 Monitor left abutment for loss of rip rap and potential scour. |                                                 |                            |                       |                  |

### Structure Name: N6-160

|                              |                                                                                                                                                                                     |                                                 |                      |                       |                  |
|------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|----------------------|-----------------------|------------------|
| Site #:                      | N6-160                                                                                                                                                                              | Year Superstructure Installed:                  | 1997                 | Structure Type/Class: | Permanent Bridge |
| KM:                          | 3.30                                                                                                                                                                                | User km:                                        |                      | Last Inspection Date: | 2019/08/10       |
| Project File ID #:           | 0018                                                                                                                                                                                | Br.                                             | 13                   | Next Inspection Date: | 2022/08/10       |
| Road Name:                   | BD0018.13HOWE CREEK                                                                                                                                                                 |                                                 |                      |                       |                  |
| Crossing Name:               | Howe Creek                                                                                                                                                                          | Total Length (metres):                          | 12.0                 |                       |                  |
| Special Access:              |                                                                                                                                                                                     | Special Equipment:                              |                      |                       |                  |
| Longitude:                   | -118 29 7.6                                                                                                                                                                         | Latitude:                                       | 49 30 42.0           |                       |                  |
| Superstructure:              | Steel I-beam                                                                                                                                                                        | Abutments (Left/Right):<br>(looking downstream) | Concrete Lock Blocks | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JRUPAR on 07-JAN-20: JRG Jan 7, 2020 Monitor abutments for settlement and monitor gap between and sill at lock blocks at right abutment. Record gap at location on blue arrow. |                                                 |                      |                       |                  |

### Structure Name: N6-182

|                              |              |                                                 |            |                       |               |
|------------------------------|--------------|-------------------------------------------------|------------|-----------------------|---------------|
| Site #:                      | N6-182       | Year Superstructure Installed:                  | 2013       | Structure Type/Class: | Major Culvert |
| KM:                          | 1.70         | User km:                                        | 1.70       | Last Inspection Date: | 2019/08/09    |
| Project File ID #:           | 0018         | Br.                                             | 23         | Next Inspection Date: | 2022/08/09    |
| Road Name:                   | BD0018.23ROB |                                                 |            |                       |               |
| Crossing Name:               | Unnamed      | Total Length (metres):                          | 17.0       |                       |               |
| Special Access:              |              | Special Equipment:                              |            |                       |               |
| Longitude:                   | -118 37 39.1 | Latitude:                                       | 49 22 10.5 |                       |               |
| Superstructure:              |              | Abutments (Left/Right):<br>(looking downstream) |            | # Spans:              | 0             |
| Planned Inspection Comments: |              |                                                 |            |                       |               |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 2 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-171

|                              |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |                                                 |                        |                       |                  |
|------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|------------------------|-----------------------|------------------|
| Site #:                      | N6-171                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | Year Superstructure Installed:                  |                        | Structure Type/Class: | Temporary Bridge |
| KM:                          | 5.30                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | User km:                                        |                        | Last Inspection Date: | 2021/09/10       |
| Project File ID #:           | 0018                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | Br.                                             | 25                     | Next Inspection Date: | 2022/09/10       |
| Road Name:                   | BD0018.25UPPERTRAVER                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                                                 |                        |                       |                  |
| Crossing Name:               | North Fork Traverse Crk                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                 | Total Length (metres): | 10.3                  |                  |
| Special Access:              |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |                                                 | Special Equipment:     |                       |                  |
| Longitude:                   | -118 36 12.5                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                                                 | Latitude:              | 49 33 7.5             |                  |
| Superstructure:              | Steel I-beam                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | Abutments (Left/Right):<br>(looking downstream) | Concrete Lock Blocks   | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JRUPAR on 22-FEB-21: JRG Feb 22, 2021 Close the bridge if the curb system has not been replaced.<br>CBR_Conversion on 17-FEB-14: JNaul, 2013-12-18: For our records, we would need either the shop drawings of steel girders or actual measurements of steel girders - flange thickness and width; girder spacing; girder length; depth of girders; web thicknesses; and bracing locations and dimension.<br>MPenner, Jan 30,2013:check girders for ID and load rating info. |                                                 |                        |                       |                  |

### Structure Name: N6-065

|                              |                                                                                        |                                                 |                        |                       |                  |
|------------------------------|----------------------------------------------------------------------------------------|-------------------------------------------------|------------------------|-----------------------|------------------|
| Site #:                      | N6-065                                                                                 | Year Superstructure Installed:                  | 2001                   | Structure Type/Class: | Permanent Bridge |
| KM:                          | 24.10                                                                                  | User km:                                        | 29.10                  | Last Inspection Date: | 2021/09/10       |
| Project File ID #:           | 0018                                                                                   | Br.                                             | 27                     | Next Inspection Date: | 2022/09/10       |
| Road Name:                   | BD0018.27NORTH BOULD                                                                   |                                                 |                        |                       |                  |
| Crossing Name:               | Traverse Cr.                                                                           |                                                 | Total Length (metres): | 10.0                  |                  |
| Special Access:              |                                                                                        |                                                 | Special Equipment:     |                       |                  |
| Longitude:                   | -118 39 43.4                                                                           |                                                 | Latitude:              | 49 29 37.9            |                  |
| Superstructure:              | Steel I-beam                                                                           | Abutments (Left/Right):<br>(looking downstream) | Concrete Precast       | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JNAUL on 07-JAN-20: .<br>IDIR\JNAUL on 07-JAN-20: .<br>IDIR\JNAUL on 07-JAN-20: . |                                                 |                        |                       |                  |

### Structure Name: N6-164

|                              |                                                                                                                                                                                                           |                                                 |                        |                       |                  |
|------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|------------------------|-----------------------|------------------|
| Site #:                      | N6-164                                                                                                                                                                                                    | Year Superstructure Installed:                  |                        | Structure Type/Class: | Permanent Bridge |
| KM:                          | 0.10                                                                                                                                                                                                      | User km:                                        | 0.10                   | Last Inspection Date: | 2019/08/10       |
| Project File ID #:           | 0018                                                                                                                                                                                                      | Br.                                             | 52                     | Next Inspection Date: | 2022/08/10       |
| Road Name:                   | BD0018.52GABLE 16600                                                                                                                                                                                      |                                                 |                        |                       |                  |
| Crossing Name:               | West Gable Cr.                                                                                                                                                                                            |                                                 | Total Length (metres): | 12.0                  |                  |
| Special Access:              |                                                                                                                                                                                                           |                                                 | Special Equipment:     |                       |                  |
| Longitude:                   | -118 39 21.8                                                                                                                                                                                              |                                                 | Latitude:              | 49 25 25.7            |                  |
| Superstructure:              | Steel I-beam                                                                                                                                                                                              | Abutments (Left/Right):<br>(looking downstream) | Concrete Lock Blocks   | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JNAUL on 07-JAN-20: JRG Jan 7, 2020 Monitor settlement of left abutment. 2015 inspection identified the following gaps between the left abutment lock blocks and the sill timber: Lock block labeled |                                                 |                        |                       |                  |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 3 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

#1 15 mm, lock block labelled #2 23 mm.

CBR\_Conversion on 07-JAN-20: .

### Structure Name: N6-147

|                              |                      |                                                 |                            |                       |                  |
|------------------------------|----------------------|-------------------------------------------------|----------------------------|-----------------------|------------------|
| Site #:                      | N6-147               | Year Superstructure Installed:                  | 2006                       | Structure Type/Class: | Permanent Bridge |
| KM:                          | 0.10                 | User km:                                        | 0.10                       | Last Inspection Date: | 2019/09/25       |
| Project File ID #:           | 0282                 | Br.                                             | 3                          | Next Inspection Date: | 2022/09/25       |
| Road Name:                   | BD0282EastCrouse(03) |                                                 |                            |                       |                  |
| Crossing Name:               | Crouse Crk           | Total Length (metres):                          | 12.2                       |                       |                  |
| Special Access:              |                      | Special Equipment:                              |                            |                       |                  |
| Longitude:                   | -118 56 54.6         | Latitude:                                       | 49 26 6.1                  |                       |                  |
| Superstructure:              | Steel I-beam         | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans:              | 1                |
| Planned Inspection Comments: |                      |                                                 |                            |                       |                  |

### Structure Name: N6-154

|                              |                                                                                                                                                                                                                             |                                                 |                      |                       |                  |
|------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|----------------------|-----------------------|------------------|
| Site #:                      | N6-154                                                                                                                                                                                                                      | Year Superstructure Installed:                  | 2008                 | Structure Type/Class: | Permanent Bridge |
| KM:                          | 0.20                                                                                                                                                                                                                        | User km:                                        | 0.20                 | Last Inspection Date: | 2019/09/25       |
| Project File ID #:           | 8244                                                                                                                                                                                                                        | Br.                                             | 04                   | Next Inspection Date: | 2022/09/25       |
| Road Name:                   | BD8244.04NORTH CANYO                                                                                                                                                                                                        |                                                 |                      |                       |                  |
| Crossing Name:               | Canyon Cr                                                                                                                                                                                                                   | Total Length (metres):                          | 10.2                 |                       |                  |
| Special Access:              |                                                                                                                                                                                                                             | Special Equipment:                              |                      |                       |                  |
| Longitude:                   | -118 54 43.2                                                                                                                                                                                                                | Latitude:                                       | 49 27 35.4           |                       |                  |
| Superstructure:              | Steel I-beam                                                                                                                                                                                                                | Abutments (Left/Right):<br>(looking downstream) | Concrete Lock Blocks | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JNAUL on 08-JAN-20: JRG Jan 8, 2020 Monitor abutments for settlement by recording gaps between sill timber and lock blocks.<br>CBR_Conversion on 08-JAN-20: JRG Jan 8, 2020 Record all information on girder ID plate. |                                                 |                      |                       |                  |

### Structure Name: N6-168

|                              |                                                                                                                                       |                                                 |                      |                       |                  |
|------------------------------|---------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|----------------------|-----------------------|------------------|
| Site #:                      | N6-168                                                                                                                                | Year Superstructure Installed:                  |                      | Structure Type/Class: | Permanent Bridge |
| KM:                          | 2.20                                                                                                                                  | User km:                                        |                      | Last Inspection Date: | 2019/09/26       |
| Project File ID #:           | 9267                                                                                                                                  | Br.                                             | 27                   | Next Inspection Date: | 2022/09/26       |
| Road Name:                   | BD9267.27POWERHOUSE                                                                                                                   |                                                 |                      |                       |                  |
| Crossing Name:               | Thurston Creek                                                                                                                        | Total Length (metres):                          | 10.0                 |                       |                  |
| Special Access:              |                                                                                                                                       | Special Equipment:                              |                      |                       |                  |
| Longitude:                   | -118 43 16.9                                                                                                                          | Latitude:                                       | 49 40 13.1           |                       |                  |
| Superstructure:              | Steel I-beam                                                                                                                          | Abutments (Left/Right):<br>(looking downstream) | Concrete Lock Blocks | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JRUPAR on 08-JAN-20: JRG Jan 8, 2020 Take photos of any markings on steel components that may indicate girder work order number. |                                                 |                      |                       |                  |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 4 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-169

|                              |                                                                                        |                                |                                                 |                       |                  |
|------------------------------|----------------------------------------------------------------------------------------|--------------------------------|-------------------------------------------------|-----------------------|------------------|
| Site #:                      | N6-169                                                                                 | Year Superstructure Installed: |                                                 | Structure Type/Class: | Permanent Bridge |
| KM:                          | 2.80                                                                                   | User km:                       |                                                 | Last Inspection Date: | 2019/09/26       |
| Project File ID #:           | 9267                                                                                   | Br.                            | 27                                              | Next Inspection Date: | 2022/09/26       |
| Road Name:                   | BD9267.27POWERHOUSE                                                                    |                                |                                                 |                       |                  |
| Crossing Name:               | Cochrane Creek                                                                         |                                | Total Length (metres):                          | 14.0                  |                  |
| Special Access:              |                                                                                        |                                | Special Equipment:                              |                       |                  |
| Longitude:                   | -118 43 37.1                                                                           |                                | Latitude:                                       | 49 40 0.2             |                  |
| Superstructure:              | Steel I-beam                                                                           |                                | Abutments (Left/Right):<br>(looking downstream) | Concrete Lock Blocks  | # Spans: 1       |
| Planned Inspection Comments: | IDIR\JNAUL on 09-JAN-20: JRG Jan 9, 2020 Monitor left bank erosion upstream of bridge. |                                |                                                 |                       |                  |

### Structure Name: N6-005A

|                              |                       |                                |                                                 |                       |                  |
|------------------------------|-----------------------|--------------------------------|-------------------------------------------------|-----------------------|------------------|
| Site #:                      | N6-005                | Year Superstructure Installed: | 2013                                            | Structure Type/Class: | Permanent Bridge |
| KM:                          | 1.00                  | User km:                       | 6.50                                            | Last Inspection Date: | 2019/09/25       |
| Project File ID #:           | 0073                  | Br.                            | 01                                              | Next Inspection Date: | 2022/09/25       |
| Road Name:                   | BEAVERDELL-STATE CR   |                                |                                                 |                       |                  |
| Crossing Name:               | BEAVERDELL Cr         |                                | Total Length (metres):                          | 12.0                  |                  |
| Special Access:              |                       |                                | Special Equipment:                              |                       |                  |
| Longitude:                   | -119 1 46.2           |                                | Latitude:                                       | 49 29 9.3             |                  |
| Superstructure:              | Concrete Slab Girders |                                | Abutments (Left/Right):<br>(looking downstream) | Concrete Lock Blocks  | # Spans: 1       |
| Planned Inspection Comments: |                       |                                |                                                 |                       |                  |

### Structure Name: TKO-0011

|                              |              |                                |                                                 |                       |                  |
|------------------------------|--------------|--------------------------------|-------------------------------------------------|-----------------------|------------------|
| Site #:                      | N6-179       | Year Superstructure Installed: | 1998                                            | Structure Type/Class: | Temporary Bridge |
| KM:                          | 2.90         | User km:                       | 2.90                                            | Last Inspection Date: | 2020/08/20       |
| Project File ID #:           | 10910        | Br.                            | 01                                              | Next Inspection Date: | 2022/08/20       |
| Road Name:                   | BELCHROME    |                                |                                                 |                       |                  |
| Crossing Name:               | Unnamed      |                                | Total Length (metres):                          | 4.9                   |                  |
| Special Access:              |              |                                | Special Equipment:                              |                       |                  |
| Longitude:                   | -119 10 13.0 |                                | Latitude:                                       | 49 7 37.8             |                  |
| Superstructure:              | Steel I-beam |                                | Abutments (Left/Right):<br>(looking downstream) | Concrete Lock Blocks  | # Spans: 1       |
| Planned Inspection Comments: |              |                                |                                                 |                       |                  |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 5 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-140

|                              |                                                                                                                              |                                                 |            |                       |               |
|------------------------------|------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|------------|-----------------------|---------------|
| Site #:                      | N6-140                                                                                                                       | Year Superstructure Installed:                  | 2002       | Structure Type/Class: | Major Culvert |
| KM:                          | 7.30                                                                                                                         | User km:                                        | 1.00       | Last Inspection Date: | 2019/08/09    |
| Project File ID #:           | 3719                                                                                                                         | Br.                                             | 05         | Next Inspection Date: | 2022/08/09    |
| Road Name:                   | BLIND VALLEY                                                                                                                 |                                                 |            |                       |               |
| Crossing Name:               | BLIND CRK                                                                                                                    | Total Length (metres):                          | 12.3       |                       |               |
| Special Access:              |                                                                                                                              | Special Equipment:                              |            |                       |               |
| Longitude:                   | -118 45 58.0                                                                                                                 | Latitude:                                       | 49 11 22.9 |                       |               |
| Superstructure:              |                                                                                                                              | Abutments (Left/Right):<br>(looking downstream) |            | # Spans:              | 0             |
| Planned Inspection Comments: | IDIR\JNAUL on 12-MAR-14: JN; 2014-03-09: Re-inspect culvert to monitor scour. Measure culvert rise and span for deformation. |                                                 |            |                       |               |

### Structure Name: N6-050

|                              |                                                                                                          |                                                 |                            |                       |                  |
|------------------------------|----------------------------------------------------------------------------------------------------------|-------------------------------------------------|----------------------------|-----------------------|------------------|
| Site #:                      | N6-050                                                                                                   | Year Superstructure Installed:                  | 1996                       | Structure Type/Class: | Permanent Bridge |
| KM:                          | 2.28                                                                                                     | User km:                                        | 16.80                      | Last Inspection Date: | 2019/08/10       |
| Project File ID #:           | 0018                                                                                                     | Br.                                             | 06                         | Next Inspection Date: | 2022/08/10       |
| Road Name:                   | BLUEJOINT LOOKOUT                                                                                        |                                                 |                            |                       |                  |
| Crossing Name:               | HOWE Cr                                                                                                  | Total Length (metres):                          | 10.5                       |                       |                  |
| Special Access:              |                                                                                                          | Special Equipment:                              |                            |                       |                  |
| Longitude:                   | -118 31 58.9                                                                                             | Latitude:                                       | 49 29 14.0                 |                       |                  |
| Superstructure:              | Concrete Slab Girders                                                                                    | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JRUPAR on 09-JAN-20: JRG Jan 9, 2020 Monitor left abutment for loss of rip rap and potential scour. |                                                 |                            |                       |                  |

### Structure Name: N6-064

|                              |               |                                                 |            |                       |               |
|------------------------------|---------------|-------------------------------------------------|------------|-----------------------|---------------|
| Site #:                      | N6-064        | Year Superstructure Installed:                  | 1995       | Structure Type/Class: | Major Culvert |
| KM:                          | 7.10          | User km:                                        | 21.80      | Last Inspection Date: | 2019/08/10    |
| Project File ID #:           | 0018          | Br.                                             | 05         | Next Inspection Date: | 2022/08/10    |
| Road Name:                   | BOULDER CREEK |                                                 |            |                       |               |
| Crossing Name:               | Unnamed       | Total Length (metres):                          | 14.0       |                       |               |
| Special Access:              |               | Special Equipment:                              |            |                       |               |
| Longitude:                   | -118 35 21.6  | Latitude:                                       | 49 28 34.8 |                       |               |
| Superstructure:              |               | Abutments (Left/Right):<br>(looking downstream) |            | # Spans:              | 0             |
| Planned Inspection Comments: |               |                                                 |            |                       |               |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 6 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-142

|                              |        |                                |       |                                                        |                       |               |  |
|------------------------------|--------|--------------------------------|-------|--------------------------------------------------------|-----------------------|---------------|--|
| Site #:                      | N6-142 | Year Superstructure Installed: |       | 2002                                                   | Structure Type/Class: | Major Culvert |  |
| KM:                          | 13.30  | User km:                       | 13.00 | Last Inspection Date:                                  |                       | 2019/08/10    |  |
| Project File ID #:           | 0018   | Br.                            | 05    | Next Inspection Date:                                  |                       | 2022/08/10    |  |
| Road Name:                   |        | BOULDER CREEK                  |       |                                                        |                       |               |  |
| Crossing Name:               |        | TRAVERSE - Boulder Cr          |       | Total Length (metres):                                 |                       | 16.0          |  |
| Special Access:              |        |                                |       | Special Equipment:                                     |                       |               |  |
| Longitude:                   |        | -118 38 58.9                   |       | Latitude:                                              |                       | 49 29 25.9    |  |
| Superstructure:              |        |                                |       | Abutments (Left/Right):<br><i>(looking downstream)</i> |                       | # Spans: 0    |  |
| Planned Inspection Comments: |        |                                |       |                                                        |                       |               |  |

### Structure Name: N6-007

|                              |                |                                |                                                 |                        |                  |
|------------------------------|----------------|--------------------------------|-------------------------------------------------|------------------------|------------------|
| Site #:                      | N6-007         | Year Superstructure Installed: | 1981                                            | Structure Type/Class:  | Permanent Bridge |
| KM:                          | 0.01           | User km:                       | 0.20                                            | Last Inspection Date:  | 2019/08/09       |
| Project File ID #:           | 3719           | Br.                            | 01                                              | Next Inspection Date:  | 2022/08/09       |
| Road Name:                   | BOUNDARY CREEK |                                |                                                 |                        |                  |
| Crossing Name:               | BOUNDARY Cr    |                                | Total Length (metres):                          | 18.3                   |                  |
| Special Access:              |                |                                | Special Equipment:                              |                        |                  |
| Longitude:                   | -118 41 59.4   |                                | Latitude:                                       | 49 11 21.7             |                  |
| Superstructure:              | Steel I-beam   |                                | Abutments (Left/Right):<br>(looking downstream) | Concrete Cast in Place | # Spans: 1       |
| Planned Inspection Comments: |                |                                |                                                 |                        |                  |

### Structure Name: N6-011

|                              |        |                                                                                                                                                                                                                                                                                                   |      |                                                        |                       |               |  |
|------------------------------|--------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|--------------------------------------------------------|-----------------------|---------------|--|
| Site #:                      | N6-011 | Year Superstructure Installed:                                                                                                                                                                                                                                                                    |      | 1990                                                   | Structure Type/Class: | Major Culvert |  |
| KM:                          | 0.02   | User km:                                                                                                                                                                                                                                                                                          | 8.90 | Last Inspection Date:                                  |                       | 2019/08/09    |  |
| Project File ID #:           | 3719   | Br.                                                                                                                                                                                                                                                                                               | 02   | Next Inspection Date:                                  |                       | 2022/08/09    |  |
| Road Name:                   |        | BOUNDARY EAST                                                                                                                                                                                                                                                                                     |      |                                                        |                       |               |  |
| Crossing Name:               |        | SOUTH FORK                                                                                                                                                                                                                                                                                        |      | Total Length (metres):                                 |                       | 19.0          |  |
| Special Access:              |        |                                                                                                                                                                                                                                                                                                   |      | Special Equipment:                                     |                       |               |  |
| Longitude:                   |        | -118 40 31.9                                                                                                                                                                                                                                                                                      |      | Latitude:                                              |                       | 49 13 4.4     |  |
| Superstructure:              |        |                                                                                                                                                                                                                                                                                                   |      | Abutments (Left/Right):<br><i>(looking downstream)</i> |                       | # Spans: 0    |  |
| Planned Inspection Comments: |        | IDIR\JNAUL on 26-FEB-14: JNaul; 2014-02-24: No drawings on file. As built information says 2 x 1400 mm diameter culverts 14 m long. Please confirm as built information. Measure bed load buildup for culvert capacity estimation. Inspector to look for presence of fish during next inspection. |      |                                                        |                       |               |  |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 7 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-012

|                              |                                                                                                                                                                                                                                                                                                                                                                                      |                                |                                                 |                       |               |
|------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-012                                                                                                                                                                                                                                                                                                                                                                               | Year Superstructure Installed: | 1990                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 8.39                                                                                                                                                                                                                                                                                                                                                                                 | User km:                       | 11.40                                           | Last Inspection Date: | 2019/08/09    |
| Project File ID #:           | 3719                                                                                                                                                                                                                                                                                                                                                                                 | Br.                            | 02                                              | Next Inspection Date: | 2022/08/09    |
| Road Name:                   | BOUNDARY EAST                                                                                                                                                                                                                                                                                                                                                                        |                                |                                                 |                       |               |
| Crossing Name:               | MIDDLE FORK                                                                                                                                                                                                                                                                                                                                                                          | Total Length (metres):         | 12.0                                            |                       |               |
| Special Access:              |                                                                                                                                                                                                                                                                                                                                                                                      |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -118 39 22.4                                                                                                                                                                                                                                                                                                                                                                         | Latitude:                      | 49 14 20.9                                      |                       |               |
| Superstructure:              |                                                                                                                                                                                                                                                                                                                                                                                      |                                | Abutments (Left/Right):<br>(looking downstream) | # Spans:              | 0             |
| Planned Inspection Comments: | IDIR\JNAUL on 25-FEB-14: JNaul; 204-02-25: No design drawings on file. As built information on file has two 1400 mm x 12 m long culverts, which is different from CBR. Confirm as built measurements on site during next routine inspection. 500 mm tear reported on the side wall in 1999 - inspector to measure and report damage to the culvert walls in next routine inspection. |                                |                                                 |                       |               |

### Structure Name: N6-014

|                              |                            |                                                 |                            |                       |                  |
|------------------------------|----------------------------|-------------------------------------------------|----------------------------|-----------------------|------------------|
| Site #:                      | N6-014                     | Year Superstructure Installed:                  | 1996                       | Structure Type/Class: | Permanent Bridge |
| KM:                          | 12.54                      | User km:                                        | 16.70                      | Last Inspection Date: | 2019/08/09       |
| Project File ID #:           | 3719                       | Br.                                             | 02                         | Next Inspection Date: | 2022/08/09       |
| Road Name:                   | BOUNDARY EAST              |                                                 |                            |                       |                  |
| Crossing Name:               | BOUNDARY Cr                | Total Length (metres):                          | 16.0                       |                       |                  |
| Special Access:              |                            |                                                 | Special Equipment:         |                       |                  |
| Longitude:                   | -118 41 2.8                | Latitude:                                       | 49 17 3.9                  |                       |                  |
| Superstructure:              | Steel I-beam               | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JNAUL on 10-JAN-20: . |                                                 |                            |                       |                  |

### Structure Name: N6-015

|                              |               |                                |                                                 |                       |               |
|------------------------------|---------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-015        | Year Superstructure Installed: | 1964                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 20.63         | User km:                       | 17.90                                           | Last Inspection Date: | 2019/08/09    |
| Project File ID #:           | 3719          | Br.                            | 03                                              | Next Inspection Date: | 2022/08/09    |
| Road Name:                   | BOUNDARY WEST |                                |                                                 |                       |               |
| Crossing Name:               | Unnamed       | Total Length (metres):         | 9.1                                             |                       |               |
| Special Access:              |               |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -118 42 3.0   | Latitude:                      | 49 19 27.6                                      |                       |               |
| Superstructure:              |               |                                | Abutments (Left/Right):<br>(looking downstream) | # Spans:              | 0             |
| Planned Inspection Comments: |               |                                |                                                 |                       |               |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 8 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-020

|                              |                                                                                                                                                                                                                                                                               |                                |                                                 |                       |               |
|------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-020                                                                                                                                                                                                                                                                        | Year Superstructure Installed: | 1974                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 13.06                                                                                                                                                                                                                                                                         | User km:                       | 13.00                                           | Last Inspection Date: | 2019/08/11    |
| Project File ID #:           | 0099                                                                                                                                                                                                                                                                          | Br.                            | 01                                              | Next Inspection Date: | 2022/08/11    |
| Road Name:                   | BURRELL CREEK                                                                                                                                                                                                                                                                 |                                |                                                 |                       |               |
| Crossing Name:               | ST ANNE'S Cr #1                                                                                                                                                                                                                                                               |                                | Total Length (metres):                          | 9.1                   |               |
| Special Access:              |                                                                                                                                                                                                                                                                               |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -118 23 51.7                                                                                                                                                                                                                                                                  |                                | Latitude:                                       | 49 28 10.4            |               |
| Superstructure:              |                                                                                                                                                                                                                                                                               |                                | Abutments (Left/Right):<br>(looking downstream) | # Spans:              | 0             |
| Planned Inspection Comments: | IDIR\JNAUL on 25-FEB-14: JNaul; 2014-02-35: Depth of cover in the CBR does not match with the cover on file. Inspectors to measure road fill cover over culverts and upstream gradient during next routine inspection. Also measure aggradation (if any) inside the culverts. |                                |                                                 |                       |               |

### Structure Name: N6-021

|                              |                 |                                                 |                        |                       |                  |
|------------------------------|-----------------|-------------------------------------------------|------------------------|-----------------------|------------------|
| Site #:                      | N6-021          | Year Superstructure Installed:                  | 1990                   | Structure Type/Class: | Permanent Bridge |
| KM:                          | 13.13           | User km:                                        | 13.10                  | Last Inspection Date: | 2019/08/11       |
| Project File ID #:           | 0099            | Br.                                             | 01                     | Next Inspection Date: | 2022/08/11       |
| Road Name:                   | BURRELL CREEK   |                                                 |                        |                       |                  |
| Crossing Name:               | ST ANNE'S Cr #2 |                                                 | Total Length (metres): | 10.3                  |                  |
| Special Access:              |                 |                                                 | Special Equipment:     |                       |                  |
| Longitude:                   | -118 23 49.5    |                                                 | Latitude:              | 49 28 12.2            |                  |
| Superstructure:              | Steel I-beam    | Abutments (Left/Right):<br>(looking downstream) | Binwall                | # Spans:              | 1                |
| Planned Inspection Comments: |                 |                                                 |                        |                       |                  |

### Structure Name: N6-022

|                              |               |                                                 |                            |                       |                  |
|------------------------------|---------------|-------------------------------------------------|----------------------------|-----------------------|------------------|
| Site #:                      | N6-022        | Year Superstructure Installed:                  | 1998                       | Structure Type/Class: | Permanent Bridge |
| KM:                          | 22.44         | User km:                                        | 22.60                      | Last Inspection Date: | 2019/08/11       |
| Project File ID #:           | 0099          | Br.                                             | 01                         | Next Inspection Date: | 2022/08/11       |
| Road Name:                   | BURRELL CREEK |                                                 |                            |                       |                  |
| Crossing Name:               | NICOL Cr      |                                                 | Total Length (metres):     | 15.3                  |                  |
| Special Access:              |               |                                                 | Special Equipment:         |                       |                  |
| Longitude:                   | -118 21 9.9   |                                                 | Latitude:                  | 49 32 19.4            |                  |
| Superstructure:              | Steel I-beam  | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans:              | 1                |
| Planned Inspection Comments: |               |                                                 |                            |                       |                  |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 9 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-023

|                              |               |                                                 |                  |                       |                  |
|------------------------------|---------------|-------------------------------------------------|------------------|-----------------------|------------------|
| Site #:                      | N6-023        | Year Superstructure Installed:                  | 1998             | Structure Type/Class: | Permanent Bridge |
| KM:                          | 23.00         | User km:                                        | 23.00            | Last Inspection Date: | 2019/08/11       |
| Project File ID #:           | 0099          | Br.                                             | 01               | Next Inspection Date: | 2022/08/11       |
| Road Name:                   | BURRELL CREEK |                                                 |                  |                       |                  |
| Crossing Name:               | DINSMORE Cr   | Total Length (metres):                          | 19.8             |                       |                  |
| Special Access:              |               | Special Equipment:                              |                  |                       |                  |
| Longitude:                   | -118 20 54.9  | Latitude:                                       | 49 32 25.7       |                       |                  |
| Superstructure:              | Steel I-beam  | Abutments (Left/Right):<br>(looking downstream) | Concrete Precast | # Spans:              | 1                |
| Planned Inspection Comments: |               |                                                 |                  |                       |                  |

### Structure Name: N6-024A

|                              |                       |                                                 |                            |                       |                  |
|------------------------------|-----------------------|-------------------------------------------------|----------------------------|-----------------------|------------------|
| Site #:                      | N6-024                | Year Superstructure Installed:                  | 2011                       | Structure Type/Class: | Permanent Bridge |
| KM:                          | 27.46                 | User km:                                        | 27.60                      | Last Inspection Date: | 2019/08/11       |
| Project File ID #:           | 0099                  | Br.                                             | 01                         | Next Inspection Date: | 2022/08/11       |
| Road Name:                   | BURRELL CREEK         |                                                 |                            |                       |                  |
| Crossing Name:               | 17 MILE Cr            | Total Length (metres):                          | 12.6                       |                       |                  |
| Special Access:              |                       | Special Equipment:                              |                            |                       |                  |
| Longitude:                   | -118 19 21.8          | Latitude:                                       | 49 34 29.4                 |                       |                  |
| Superstructure:              | Concrete Slab Girders | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans:              | 1                |
| Planned Inspection Comments: |                       |                                                 |                            |                       |                  |

### Structure Name: N6-150

|                              |                                                                                                                                                                                                                                                                                                                     |                                                 |                  |                       |                  |
|------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|------------------|-----------------------|------------------|
| Site #:                      | N6-184                                                                                                                                                                                                                                                                                                              | Year Superstructure Installed:                  | 2017             | Structure Type/Class: | Permanent Bridge |
| KM:                          | 0.40                                                                                                                                                                                                                                                                                                                | User km:                                        | 0.40             | Last Inspection Date: | 2019/08/10       |
| Project File ID #:           | 3473                                                                                                                                                                                                                                                                                                                | Br.                                             | 02               | Next Inspection Date: | 2022/08/10       |
| Road Name:                   | CANNON FSR                                                                                                                                                                                                                                                                                                          |                                                 |                  |                       |                  |
| Crossing Name:               | Wiseman Creek                                                                                                                                                                                                                                                                                                       | Total Length (metres):                          | 10.2             |                       |                  |
| Special Access:              |                                                                                                                                                                                                                                                                                                                     | Special Equipment:                              |                  |                       |                  |
| Longitude:                   | -118 26 56.3                                                                                                                                                                                                                                                                                                        | Latitude:                                       | 49 21 7.9        |                       |                  |
| Superstructure:              | Steel I-beam                                                                                                                                                                                                                                                                                                        | Abutments (Left/Right):<br>(looking downstream) | Concrete Precast | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JRUPAR on 29-FEB-20: JRG Feb 29, 2020 Confirm girder geometry matches A.A. Williams dwg WB 260-1 for girders previously at site N6-002. These drawings show: 10.2 m o/o length, 3 m girder c/c spacing, 254 mm x 12.7 mm top and bottom flange, 8 mm web, total girder height 738 mm, 4.8 m diaphragm spacing. |                                                 |                  |                       |                  |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 10 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-193

|                              |              |                                                 |                      |                       |                  |
|------------------------------|--------------|-------------------------------------------------|----------------------|-----------------------|------------------|
| Site #:                      | N6-193       | Year Superstructure Installed:                  | 2020                 | Structure Type/Class: | Temporary Bridge |
| KM:                          | 7.30         | User km:                                        | 6.30                 | Last Inspection Date: |                  |
| Project File ID #:           | 3473         | Br.                                             | 02                   | Next Inspection Date: | 2022/08/01       |
| Road Name:                   | CANNON FSR   |                                                 |                      |                       |                  |
| Crossing Name:               | Cannon Creek | Total Length (metres):                          | 12.2                 |                       |                  |
| Special Access:              |              | Special Equipment:                              |                      |                       |                  |
| Longitude:                   | -118 28 4.1  | Latitude:                                       | 49 19 27.1           |                       |                  |
| Superstructure:              | Steel I-beam | Abutments (Left/Right):<br>(looking downstream) | Concrete Lock Blocks | # Spans:              | 1                |
| Planned Inspection Comments: |              |                                                 |                      |                       |                  |

### Structure Name: N6-037

|                              |                                                                                                                     |                                                 |            |                       |               |
|------------------------------|---------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|------------|-----------------------|---------------|
| Site #:                      | N6-037                                                                                                              | Year Superstructure Installed:                  | 1981       | Structure Type/Class: | Major Culvert |
| KM:                          | 2.04                                                                                                                | User km:                                        | 2.20       | Last Inspection Date: | 2019/09/25    |
| Project File ID #:           | 3928                                                                                                                | Br.                                             | 01         | Next Inspection Date: | 2022/09/25    |
| Road Name:                   | CARMI CREEK                                                                                                         |                                                 |            |                       |               |
| Crossing Name:               | CARMI Cr                                                                                                            | Total Length (metres):                          | 25.1       |                       |               |
| Special Access:              |                                                                                                                     | Special Equipment:                              |            |                       |               |
| Longitude:                   | -119 8 27.2                                                                                                         | Latitude:                                       | 49 29 24.2 |                       |               |
| Superstructure:              |                                                                                                                     | Abutments (Left/Right):<br>(looking downstream) |            | # Spans:              | 0             |
| Planned Inspection Comments: | IDIR\JNAUL on 27-FEB-14: JN; 2014-02-27: Inspector to confirm as built measurements during next routine inspection. |                                                 |            |                       |               |

### Structure Name: N6-077A

|                              |                                                                                                            |                                                 |                            |                       |                  |
|------------------------------|------------------------------------------------------------------------------------------------------------|-------------------------------------------------|----------------------------|-----------------------|------------------|
| Site #:                      | N6-077                                                                                                     | Year Superstructure Installed:                  | 2018                       | Structure Type/Class: | Permanent Bridge |
| KM:                          | 6.31                                                                                                       | User km:                                        | 6.30                       | Last Inspection Date: | 2019/09/27       |
| Project File ID #:           | 0060                                                                                                       | Br.                                             | 06                         | Next Inspection Date: | 2022/09/27       |
| Road Name:                   | CENTRE MOUNTAIN                                                                                            |                                                 |                            |                       |                  |
| Crossing Name:               | RENDELL Cr #1                                                                                              | Total Length (metres):                          | 18.3                       |                       |                  |
| Special Access:              |                                                                                                            | Special Equipment:                              |                            |                       |                  |
| Longitude:                   | -118 39 32.2                                                                                               | Latitude:                                       | 49 46 59.8                 |                       |                  |
| Superstructure:              | Steel I-beam                                                                                               | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JRUPAR on 13-JAN-20: JRG Jan 13, 2020 Inspect end deck panel guardrail anchorage at every inspection. |                                                 |                            |                       |                  |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 11 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-155

|                              |                                                                                         |                                |                                                 |                       |               |
|------------------------------|-----------------------------------------------------------------------------------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-155                                                                                  | Year Superstructure Installed: | 2009                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 36.50                                                                                   | User km:                       |                                                 | Last Inspection Date: | 2019/09/25    |
| Project File ID #:           | 0161                                                                                    | Br.                            | 06                                              | Next Inspection Date: | 2022/09/25    |
| Road Name:                   | CONKEL EAST CREEK                                                                       |                                |                                                 |                       |               |
| Crossing Name:               | Unnamed Creek                                                                           |                                | Total Length (metres):                          | 12.7                  |               |
| Special Access:              |                                                                                         |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -119 11 27.4                                                                            |                                | Latitude:                                       | 49 15 5.5             |               |
| Superstructure:              |                                                                                         |                                | Abutments (Left/Right):<br>(looking downstream) |                       | # Spans: 0    |
| Planned Inspection Comments: | IDIR\JRUPAR on 13-JAN-20: JRG Jan 13, 2020 Monitor right abutment for movement/bulging. |                                |                                                 |                       |               |

### Structure Name: N6-159

|                              |                                |                                |                                                 |                       |               |
|------------------------------|--------------------------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-159                         | Year Superstructure Installed: | 2009                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 36.60                          | User km:                       |                                                 | Last Inspection Date: | 2019/09/25    |
| Project File ID #:           | 0161                           | Br.                            | 06                                              | Next Inspection Date: | 2022/09/25    |
| Road Name:                   | CONKEL EAST CREEK              |                                |                                                 |                       |               |
| Crossing Name:               | unnamed                        |                                | Total Length (metres):                          | 12.7                  |               |
| Special Access:              |                                |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -119 11 22.8                   |                                | Latitude:                                       | 49 15 5.4             |               |
| Superstructure:              |                                |                                | Abutments (Left/Right):<br>(looking downstream) |                       | # Spans: 0    |
| Planned Inspection Comments: | CBR_Conversion on 13-JAN-20: . |                                |                                                 |                       |               |

### Structure Name: N6-101

|                              |                    |                                |                                                 |                       |               |
|------------------------------|--------------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-101             | Year Superstructure Installed: | 1980                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 0.14               | User km:                       | 23.50                                           | Last Inspection Date: | 2019/09/25    |
| Project File ID #:           | 3929               | Br.                            | 02                                              | Next Inspection Date: | 2022/09/25    |
| Road Name:                   | COPPERKETTLE CREEK |                                |                                                 |                       |               |
| Crossing Name:               | COPPERKETTLE Cr    |                                | Total Length (metres):                          | 12.2                  |               |
| Special Access:              |                    |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -118 51 7.5        |                                | Latitude:                                       | 49 40 36.2            |               |
| Superstructure:              |                    |                                | Abutments (Left/Right):<br>(looking downstream) |                       | # Spans: 0    |
| Planned Inspection Comments: |                    |                                |                                                 |                       |               |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 12 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-100

|                              |                    |                                |                                                 |                       |               |
|------------------------------|--------------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-100             | Year Superstructure Installed: | 1980                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 2.46               | User km:                       | 21.10                                           | Last Inspection Date: | 2019/09/25    |
| Project File ID #:           | 3929               | Br.                            | 02                                              | Next Inspection Date: | 2022/09/25    |
| Road Name:                   | COPPERKETTLE CREEK |                                |                                                 |                       |               |
| Crossing Name:               | W COPPERKETTLE     |                                | Total Length (metres):                          | 9.7                   |               |
| Special Access:              |                    |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -118 52 33.4       |                                | Latitude:                                       | 49 40 5.8             |               |
| Superstructure:              |                    |                                | Abutments (Left/Right):<br>(looking downstream) |                       | # Spans: 0    |
| Planned Inspection Comments: |                    |                                |                                                 |                       |               |

### Structure Name: N6-099

|                              |                                                                                                                      |                                |                                                 |                            |                  |
|------------------------------|----------------------------------------------------------------------------------------------------------------------|--------------------------------|-------------------------------------------------|----------------------------|------------------|
| Site #:                      | N6-099                                                                                                               | Year Superstructure Installed: | 2000                                            | Structure Type/Class:      | Permanent Bridge |
| KM:                          | 11.88                                                                                                                | User km:                       | 11.80                                           | Last Inspection Date:      | 2019/09/25       |
| Project File ID #:           | 3929                                                                                                                 | Br.                            | 02                                              | Next Inspection Date:      | 2022/09/25       |
| Road Name:                   | COPPERKETTLE CREEK                                                                                                   |                                |                                                 |                            |                  |
| Crossing Name:               | TRAPPING Cr                                                                                                          |                                | Total Length (metres):                          | 18.3                       |                  |
| Special Access:              |                                                                                                                      |                                | Special Equipment:                              |                            |                  |
| Longitude:                   | -118 58 20.5                                                                                                         |                                | Latitude:                                       | 49 38 8.1                  |                  |
| Superstructure:              | Steel I-beam                                                                                                         |                                | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans: 1       |
| Planned Inspection Comments: | IDIR\JRUPAR on 13-JAN-20: JRG Jan 13, 2020 Monitor loss of left abutment rip rap. Look closely for exposed footings. |                                |                                                 |                            |                  |

### Structure Name: N6-102

|                              |                                                                                                                       |                                |                                                 |                       |               |
|------------------------------|-----------------------------------------------------------------------------------------------------------------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-102                                                                                                                | Year Superstructure Installed: | 1980                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 22.24                                                                                                                 | User km:                       | 25.10                                           | Last Inspection Date: | 2019/09/25    |
| Project File ID #:           | 3929                                                                                                                  | Br.                            | 02                                              | Next Inspection Date: | 2022/09/25    |
| Road Name:                   | COPPERKETTLE CREEK                                                                                                    |                                |                                                 |                       |               |
| Crossing Name:               | E COPPERKETTLE                                                                                                        |                                | Total Length (metres):                          | 9.1                   |               |
| Special Access:              |                                                                                                                       |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -118 49 57.2                                                                                                          |                                | Latitude:                                       | 49 40 43.0            |               |
| Superstructure:              |                                                                                                                       |                                | Abutments (Left/Right):<br>(looking downstream) |                       | # Spans: 0    |
| Planned Inspection Comments: | IDIR\JRUPAR on 14-JAN-20: JRG Jan 14, 2020 Perforated pipes in place to prevent beaver dams. Monitor beaver activity. |                                |                                                 |                       |               |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 13 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-103A

|                              |                                                                                                           |                                                 |                            |                       |                  |
|------------------------------|-----------------------------------------------------------------------------------------------------------|-------------------------------------------------|----------------------------|-----------------------|------------------|
| Site #:                      | N6-103                                                                                                    | Year Superstructure Installed:                  | 2013                       | Structure Type/Class: | Permanent Bridge |
| KM:                          | 32.67                                                                                                     | User km:                                        | 36.40                      | Last Inspection Date: | 2019/09/25       |
| Project File ID #:           | 3929                                                                                                      | Br.                                             | 02                         | Next Inspection Date: | 2022/09/25       |
| Road Name:                   | COPPERKETTLE CREEK                                                                                        |                                                 |                            |                       |                  |
| Crossing Name:               | WHITEFOOT Cr                                                                                              | Total Length (metres):                          | 15.3                       |                       |                  |
| Special Access:              |                                                                                                           | Special Equipment:                              |                            |                       |                  |
| Longitude:                   | -118 49 50.8                                                                                              | Latitude:                                       | 49 44 55.2                 |                       |                  |
| Superstructure:              | Steel I-beam                                                                                              | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JRUPAR on 14-JAN-20: JRG Jan 14, 2020 Monitor left abutment for loss of rip rap and potential scour. |                                                 |                            |                       |                  |

### Structure Name: N6-029

|                              |                 |                                                 |            |                       |               |
|------------------------------|-----------------|-------------------------------------------------|------------|-----------------------|---------------|
| Site #:                      | N6-029          | Year Superstructure Installed:                  | 1986       | Structure Type/Class: | Major Culvert |
| KM:                          | 9.59            | User km:                                        | 19.90      | Last Inspection Date: | 2019/08/11    |
| Project File ID #:           | 0099            | Br.                                             | 08         | Next Inspection Date: | 2022/08/11    |
| Road Name:                   | DEADEYE CREEK   |                                                 |            |                       |               |
| Crossing Name:               | ST ANNE'S Cr #1 | Total Length (metres):                          | 20.0       |                       |               |
| Special Access:              |                 | Special Equipment:                              |            |                       |               |
| Longitude:                   | -118 18 50.8    | Latitude:                                       | 49 25 42.1 |                       |               |
| Superstructure:              |                 | Abutments (Left/Right):<br>(looking downstream) |            | # Spans:              | 0             |
| Planned Inspection Comments: |                 |                                                 |            |                       |               |

### Structure Name: N6-030

|                              |                                                                  |                                                 |            |                       |               |
|------------------------------|------------------------------------------------------------------|-------------------------------------------------|------------|-----------------------|---------------|
| Site #:                      | N6-030                                                           | Year Superstructure Installed:                  | 1986       | Structure Type/Class: | Major Culvert |
| KM:                          | 11.47                                                            | User km:                                        | 21.80      | Last Inspection Date: | 2019/08/11    |
| Project File ID #:           | 0099                                                             | Br.                                             | 08         | Next Inspection Date: | 2022/08/11    |
| Road Name:                   | DEADEYE CREEK                                                    |                                                 |            |                       |               |
| Crossing Name:               | ST ANNE'S Cr #2                                                  | Total Length (metres):                          | 20.0       |                       |               |
| Special Access:              |                                                                  | Special Equipment:                              |            |                       |               |
| Longitude:                   | -118 17 56.6                                                     | Latitude:                                       | 49 26 27.9 |                       |               |
| Superstructure:              |                                                                  | Abutments (Left/Right):<br>(looking downstream) |            | # Spans:              | 0             |
| Planned Inspection Comments: | IDIR\JNAUL on 26-FEB-14: JN; 2014-02-26: Measure depth of cover. |                                                 |            |                       |               |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 14 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-059

|                              |                 |                                |                                                 |                       |               |
|------------------------------|-----------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-059          | Year Superstructure Installed: | 1994                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 0.44            | User km:                       | 18.10                                           | Last Inspection Date: | 2019/08/10    |
| Project File ID #:           | 0018            | Br.                            | 02                                              | Next Inspection Date: | 2022/08/10    |
| Road Name:                   | GABLE CREEK     |                                |                                                 |                       |               |
| Crossing Name:               | S FORK GABLE Cr |                                | Total Length (metres):                          | 14.0                  |               |
| Special Access:              |                 |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -118 38 10.2    |                                | Latitude:                                       | 49 23 56.5            |               |
| Superstructure:              |                 |                                | Abutments (Left/Right):<br>(looking downstream) |                       | # Spans: 0    |
| Planned Inspection Comments: |                 |                                |                                                 |                       |               |

### Structure Name: N6-060

|                              |                                                                                   |                                |                                                 |                            |                  |
|------------------------------|-----------------------------------------------------------------------------------|--------------------------------|-------------------------------------------------|----------------------------|------------------|
| Site #:                      | N6-060                                                                            | Year Superstructure Installed: | 1995                                            | Structure Type/Class:      | Permanent Bridge |
| KM:                          | 1.86                                                                              | User km:                       | 19.70                                           | Last Inspection Date:      | 2019/08/10       |
| Project File ID #:           | 0018                                                                              | Br.                            | 02                                              | Next Inspection Date:      | 2022/08/10       |
| Road Name:                   | GABLE CREEK                                                                       |                                |                                                 |                            |                  |
| Crossing Name:               | GABLE Cr                                                                          |                                | Total Length (metres):                          | 15.5                       |                  |
| Special Access:              |                                                                                   |                                | Special Equipment:                              |                            |                  |
| Longitude:                   | -118 38 56.0                                                                      |                                | Latitude:                                       | 49 24 40.4                 |                  |
| Superstructure:              | Steel I-beam                                                                      |                                | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans: 1       |
| Planned Inspection Comments: | IDIR\JRUPAR on 14-JAN-20: JRG Jan 14, 2020 Monitor abutments for loss of rip rap. |                                |                                                 |                            |                  |

### Structure Name: N6-058

|                              |                                                                                                                                                                                                                                                                                                                                                      |                                |                                                 |                       |               |
|------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-058                                                                                                                                                                                                                                                                                                                                               | Year Superstructure Installed: | 1994                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 4.92                                                                                                                                                                                                                                                                                                                                                 | User km:                       | 16.70                                           | Last Inspection Date: | 2019/08/10    |
| Project File ID #:           | 0018                                                                                                                                                                                                                                                                                                                                                 | Br.                            | 02                                              | Next Inspection Date: | 2022/08/10    |
| Road Name:                   | GABLE CREEK                                                                                                                                                                                                                                                                                                                                          |                                |                                                 |                       |               |
| Crossing Name:               | UNO Cr                                                                                                                                                                                                                                                                                                                                               |                                | Total Length (metres):                          | 14.5                  |               |
| Special Access:              |                                                                                                                                                                                                                                                                                                                                                      |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -118 37 21.7                                                                                                                                                                                                                                                                                                                                         |                                | Latitude:                                       | 49 23 35.5            |               |
| Superstructure:              |                                                                                                                                                                                                                                                                                                                                                      |                                | Abutments (Left/Right):<br>(looking downstream) |                       | # Spans: 0    |
| Planned Inspection Comments: | IDIR\JNAUL on 28-FEB-14: JN; 2014-02-28: Changed culvert type to round and culvert gradient to 3% based on as built information on file. No drawings on file. As built information on file appears to indicate that there are two round steel culverts - 1800 mm and 1200 mm diameter. Confirm as built measurements during next routine inspection. |                                |                                                 |                       |               |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 15 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-057

|                              |              |                                                 |                            |                       |                  |
|------------------------------|--------------|-------------------------------------------------|----------------------------|-----------------------|------------------|
| Site #:                      | N6-057       | Year Superstructure Installed:                  | 1996                       | Structure Type/Class: | Permanent Bridge |
| KM:                          | 10.73        | User km:                                        | 10.70                      | Last Inspection Date: | 2019/08/10       |
| Project File ID #:           | 0018         | Br.                                             | 02                         | Next Inspection Date: | 2022/08/10       |
| Road Name:                   | GABLE CREEK  |                                                 |                            |                       |                  |
| Crossing Name:               | GABLE Cr     | Total Length (metres):                          | 18.0                       |                       |                  |
| Special Access:              |              | Special Equipment:                              |                            |                       |                  |
| Longitude:                   | -118 33 45.4 | Latitude:                                       | 49 24 5.6                  |                       |                  |
| Superstructure:              | Steel I-beam | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans:              | 1                |
| Planned Inspection Comments: |              |                                                 |                            |                       |                  |

### Structure Name: N6-056

|                              |              |                                                 |            |                       |                  |
|------------------------------|--------------|-------------------------------------------------|------------|-----------------------|------------------|
| Site #:                      | N6-056       | Year Superstructure Installed:                  | 1990       | Structure Type/Class: | Permanent Bridge |
| KM:                          | 15.06        | User km:                                        | 6.20       | Last Inspection Date: | 2019/08/11       |
| Project File ID #:           | 0018         | Br.                                             | 02         | Next Inspection Date: | 2022/08/11       |
| Road Name:                   | GABLE CREEK  |                                                 |            |                       |                  |
| Crossing Name:               | GRANBY R     | Total Length (metres):                          | 28.3       |                       |                  |
| Special Access:              |              | Special Equipment:                              |            |                       |                  |
| Longitude:                   | -118 30 25.5 | Latitude:                                       | 49 23 47.1 |                       |                  |
| Superstructure:              | Steel I-beam | Abutments (Left/Right):<br>(looking downstream) | Binwall    | # Spans:              | 1                |
| Planned Inspection Comments: |              |                                                 |            |                       |                  |

### Structure Name: N6-061

|                              |                                                                                                                                                          |                                                 |            |                       |               |
|------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|------------|-----------------------|---------------|
| Site #:                      | N6-061                                                                                                                                                   | Year Superstructure Installed:                  | 1995       | Structure Type/Class: | Major Culvert |
| KM:                          | 1.20                                                                                                                                                     | User km:                                        | 29.20      | Last Inspection Date: | 2019/08/11    |
| Project File ID #:           | 0018                                                                                                                                                     | Br.                                             | 08         | Next Inspection Date: | 2022/08/11    |
| Road Name:                   | GABLE-TRAVERSE                                                                                                                                           |                                                 |            |                       |               |
| Crossing Name:               | Unnamed                                                                                                                                                  | Total Length (metres):                          | 14.0       |                       |               |
| Special Access:              |                                                                                                                                                          | Special Equipment:                              |            |                       |               |
| Longitude:                   | -118 35 51.1                                                                                                                                             | Latitude:                                       | 49 27 10.0 |                       |               |
| Superstructure:              |                                                                                                                                                          | Abutments (Left/Right):<br>(looking downstream) |            | # Spans:              | 0             |
| Planned Inspection Comments: | IDIR\JNAUL on 28-FEB-14: JN; 2014-02-28: Inspector to look for presence of fish. Measure depth of cover and inspect inside the culvert for joint damage. |                                                 |            |                       |               |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 16 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-109

|                              |                                                                                                                                             |                                                 |                  |                       |                  |
|------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|------------------|-----------------------|------------------|
| Site #:                      | N6-109                                                                                                                                      | Year Superstructure Installed:                  | 1990             | Structure Type/Class: | Permanent Bridge |
| KM:                          | 0.30                                                                                                                                        | User km:                                        | 0.10             | Last Inspection Date: | 2021/09/11       |
| Project File ID #:           | 8973                                                                                                                                        | Br.                                             | 01               | Next Inspection Date: | 2022/09/11       |
| Road Name:                   | GLOUCESTER CREEK                                                                                                                            |                                                 |                  |                       |                  |
| Crossing Name:               | BURRELL Cr                                                                                                                                  | Total Length (metres):                          | 14.3             |                       |                  |
| Special Access:              |                                                                                                                                             | Special Equipment:                              |                  |                       |                  |
| Longitude:                   | -118 20 43.1                                                                                                                                | Latitude:                                       | 49 33 27.6       |                       |                  |
| Superstructure:              | Steel I-beam                                                                                                                                | Abutments (Left/Right):<br>(looking downstream) | Concrete Precast | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JRUPAR on 16-JAN-20: JRG Jan 16, 2020 Carefully inspect left abutment lock blocks for scour. There are only three rows of lock blocks. |                                                 |                  |                       |                  |

### Structure Name: N6-122

|                              |                |                                                 |                  |                       |                  |
|------------------------------|----------------|-------------------------------------------------|------------------|-----------------------|------------------|
| Site #:                      | N6-122         | Year Superstructure Installed:                  | 1997             | Structure Type/Class: | Permanent Bridge |
| KM:                          | 13.03          | User km:                                        | 12.00            | Last Inspection Date: | 2019/09/26       |
| Project File ID #:           | 9267           | Br.                                             | 02               | Next Inspection Date: | 2022/09/26       |
| Road Name:                   | GOATSKIN CREEK |                                                 |                  |                       |                  |
| Crossing Name:               | Unnamed        | Total Length (metres):                          | 10.5             |                       |                  |
| Special Access:              |                | Special Equipment:                              |                  |                       |                  |
| Longitude:                   | -118 34 46.6   | Latitude:                                       | 49 45 35.6       |                       |                  |
| Superstructure:              | Steel I-beam   | Abutments (Left/Right):<br>(looking downstream) | Concrete Precast | # Spans:              | 1                |
| Planned Inspection Comments: |                |                                                 |                  |                       |                  |

### Structure Name: N6-132

|                              |               |                                                 |                      |                       |                  |
|------------------------------|---------------|-------------------------------------------------|----------------------|-----------------------|------------------|
| Site #:                      | N6-132        | Year Superstructure Installed:                  | 1999                 | Structure Type/Class: | Permanent Bridge |
| KM:                          | 0.00          | User km:                                        | 6.50                 | Last Inspection Date: | 2019/09/26       |
| Project File ID #:           | 9267          | Br.                                             | 04                   | Next Inspection Date: | 2022/09/26       |
| Road Name:                   | GOATSKIN EAST |                                                 |                      |                       |                  |
| Crossing Name:               | Unnamed       | Total Length (metres):                          | 5.6                  |                       |                  |
| Special Access:              |               | Special Equipment:                              |                      |                       |                  |
| Longitude:                   | -118 32 16.0  | Latitude:                                       | 49 46 46.2           |                       |                  |
| Superstructure:              | Steel I-beam  | Abutments (Left/Right):<br>(looking downstream) | Concrete Lock Blocks | # Spans:              | 1                |
| Planned Inspection Comments: |               |                                                 |                      |                       |                  |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 17 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-049

|                              |              |                                                 |            |                       |               |
|------------------------------|--------------|-------------------------------------------------|------------|-----------------------|---------------|
| Site #:                      | N6-049       | Year Superstructure Installed:                  | 1975       | Structure Type/Class: | Major Culvert |
| KM:                          | 11.00        | User km:                                        | 3.50       | Last Inspection Date: | 2019/08/10    |
| Project File ID #:           | 0018         | Br.                                             | 01         | Next Inspection Date: | 2022/08/10    |
| Road Name:                   | GRANBY RIVER |                                                 |            |                       |               |
| Crossing Name:               | BURNS Cr     | Total Length (metres):                          | 12.2       |                       |               |
| Special Access:              |              | Special Equipment:                              |            |                       |               |
| Longitude:                   | -118 29 20.9 | Latitude:                                       | 49 23 20.4 |                       |               |
| Superstructure:              |              | Abutments (Left/Right):<br>(looking downstream) |            | # Spans:              | 0             |
| Planned Inspection Comments: |              |                                                 |            |                       |               |

### Structure Name: N6-118

|                              |              |                                                 |                            |                       |                  |
|------------------------------|--------------|-------------------------------------------------|----------------------------|-----------------------|------------------|
| Site #:                      | N6-118       | Year Superstructure Installed:                  | 1996                       | Structure Type/Class: | Permanent Bridge |
| KM:                          | 0.24         | User km:                                        | 19.40                      | Last Inspection Date: | 2019/09/26       |
| Project File ID #:           | 5412         | Br.                                             | 01                         | Next Inspection Date: | 2022/09/26       |
| Road Name:                   | GRANO CREEK  |                                                 |                            |                       |                  |
| Crossing Name:               | COCHRANE Cr  | Total Length (metres):                          | 15.3                       |                       |                  |
| Special Access:              | Gate Key     | Special Equipment:                              |                            |                       |                  |
| Longitude:                   | -118 40 36.9 | Latitude:                                       | 49 39 1.4                  |                       |                  |
| Superstructure:              | Steel I-beam | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans:              | 1                |
| Planned Inspection Comments: |              |                                                 |                            |                       |                  |

### Structure Name: N6-068

|                              |                                                                                                                                                                                                                                                                                                                                                                                                            |                                                 |                        |                       |                  |
|------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|------------------------|-----------------------|------------------|
| Site #:                      | N6-068                                                                                                                                                                                                                                                                                                                                                                                                     | Year Superstructure Installed:                  | 1987                   | Structure Type/Class: | Permanent Bridge |
| KM:                          | 0.71                                                                                                                                                                                                                                                                                                                                                                                                       | User km:                                        | 0.70                   | Last Inspection Date: | 2019/09/26       |
| Project File ID #:           | 5412                                                                                                                                                                                                                                                                                                                                                                                                       | Br.                                             | 01                     | Next Inspection Date: | 2022/09/26       |
| Road Name:                   | GRANO CREEK                                                                                                                                                                                                                                                                                                                                                                                                |                                                 |                        |                       |                  |
| Crossing Name:               | Kettle R                                                                                                                                                                                                                                                                                                                                                                                                   | Total Length (metres):                          | 44.9                   |                       |                  |
| Special Access:              |                                                                                                                                                                                                                                                                                                                                                                                                            | Special Equipment:                              |                        |                       |                  |
| Longitude:                   | -118 47 40.0                                                                                                                                                                                                                                                                                                                                                                                               | Latitude:                                       | 49 33 55.4             |                       |                  |
| Superstructure:              | Steel I-beam                                                                                                                                                                                                                                                                                                                                                                                               | Abutments (Left/Right):<br>(looking downstream) | Concrete Cast in Place | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JNAUL on 20-JAN-16: JN: Re-inspect in 2016 and measure distance of bearing pads for reference. Need professional engineers certification for the bearing pad restrainer details and repairs.<br>IDIR\JNAUL on 03-MAR-14: JN; 2014-03-03: Need professional inspection to determine cause of bearing pad movement and a new load rating. Professional engineer may require close proximity inspection. |                                                 |                        |                       |                  |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 18 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-070

|                              |              |                                |                                                        |                        |                           |                  |            |
|------------------------------|--------------|--------------------------------|--------------------------------------------------------|------------------------|---------------------------|------------------|------------|
| Site #:                      | N6-070       | Year Superstructure Installed: |                                                        |                        | Structure Type/Class:     | Permanent Bridge |            |
| KM:                          | 8.11         | User km:                       | 8.20                                                   | Last Inspection Date:  |                           | 2019/09/27       |            |
| Project File ID #:           | 0060         | Br.                            | 01                                                     | Next Inspection Date:  |                           | 2022/09/27       |            |
| Road Name:                   |              | KETTLE RIVER                   |                                                        |                        |                           |                  |            |
| Crossing Name:               |              | DAMFINO Cr                     |                                                        | Total Length (metres): |                           | 24.4             |            |
| Special Access:              |              |                                |                                                        | Special Equipment:     |                           |                  |            |
| Longitude:                   |              | -118 46 15.2                   |                                                        | Latitude:              |                           | 49 42 7.4        |            |
| Superstructure:              | Steel I-beam |                                | Abutments (Left/Right):<br><i>(looking downstream)</i> |                        | Pile -Permanent Materials |                  | # Spans: 1 |
| Planned Inspection Comments: |              |                                |                                                        |                        |                           |                  |            |

### Structure Name: N6-116

|                              |        |                                |       |                                                        |                       |               |  |
|------------------------------|--------|--------------------------------|-------|--------------------------------------------------------|-----------------------|---------------|--|
| Site #:                      | N6-116 | Year Superstructure Installed: |       | 1992                                                   | Structure Type/Class: | Major Culvert |  |
| KM:                          | 2.13   | User km:                       | 10.00 | Last Inspection Date:                                  |                       | 2019/09/26    |  |
| Project File ID #:           | 0136   | Br.                            | 05    | Next Inspection Date:                                  |                       | 2022/09/26    |  |
| Road Name:                   |        | LOSTHORSE EAST                 |       |                                                        |                       |               |  |
| Crossing Name:               |        | LOST HORSE Cr                  |       | Total Length (metres):                                 |                       | 14.0          |  |
| Special Access:              |        |                                |       | Special Equipment:                                     |                       |               |  |
| Longitude:                   |        | -118 47 8.8                    |       | Latitude:                                              |                       | 49 22 52.2    |  |
| Superstructure:              |        |                                |       | Abutments (Left/Right):<br><i>(looking downstream)</i> |                       | # Spans: 0    |  |
| Planned Inspection Comments: |        | IDIR\JNAUL on 20-JAN-20: .     |       |                                                        |                       |               |  |

### Structure Name: N6-115

|                              |        |                                |      |                                                        |                       |               |  |
|------------------------------|--------|--------------------------------|------|--------------------------------------------------------|-----------------------|---------------|--|
| Site #:                      | N6-115 | Year Superstructure Installed: |      | 1992                                                   | Structure Type/Class: | Major Culvert |  |
| KM:                          | 0.62   | User km:                       | 7.30 | Last Inspection Date:                                  |                       | 2019/10/01    |  |
| Project File ID #:           | 0136   | Br.                            | 04   | Next Inspection Date:                                  |                       | 2022/10/01    |  |
| Road Name:                   |        | LOSTHORSE NORTH                |      |                                                        |                       |               |  |
| Crossing Name:               |        | LOST HORSE Cr                  |      | Total Length (metres):                                 |                       | 12.0          |  |
| Special Access:              |        |                                |      | Special Equipment:                                     |                       |               |  |
| Longitude:                   |        | -118 49 12.6                   |      | Latitude:                                              |                       | 49 23 6.7     |  |
| Superstructure:              |        |                                |      | Abutments (Left/Right):<br><i>(looking downstream)</i> |                       | # Spans: 0    |  |
| Planned Inspection Comments: |        |                                |      |                                                        |                       |               |  |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 19 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-034

|                              |                                                                                     |                                                 |                  |                       |                  |
|------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------|------------------|-----------------------|------------------|
| Site #:                      | N6-034                                                                              | Year Superstructure Installed:                  | 1994             | Structure Type/Class: | Permanent Bridge |
| KM:                          | 7.30                                                                                | User km:                                        | 39.20            | Last Inspection Date: | 2019/08/12       |
| Project File ID #:           | 0099                                                                                | Br.                                             | 03               | Next Inspection Date: | 2022/08/12       |
| Road Name:                   | MCFARLANE CREEK                                                                     |                                                 |                  |                       |                  |
| Crossing Name:               | PHILIPPA Cr                                                                         | Total Length (metres):                          | 11.0             |                       |                  |
| Special Access:              |                                                                                     | Special Equipment:                              |                  |                       |                  |
| Longitude:                   | -118 20 21.3                                                                        | Latitude:                                       | 49 39 39.8       |                       |                  |
| Superstructure:              | Concrete Slab Girders                                                               | Abutments (Left/Right):<br>(looking downstream) | Concrete Precast | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JRUPAR on 20-JAN-20: JRG Jan 20, 2020 Monitor hairline cracks in slab girders. |                                                 |                  |                       |                  |

### Structure Name: N6-032

|                              |                                                                                                                                          |                                                 |            |                       |                  |
|------------------------------|------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|------------|-----------------------|------------------|
| Site #:                      | N6-032                                                                                                                                   | Year Superstructure Installed:                  | 1992       | Structure Type/Class: | Permanent Bridge |
| KM:                          | 12.51                                                                                                                                    | User km:                                        | 33.90      | Last Inspection Date: | 2019/08/11       |
| Project File ID #:           | 0099                                                                                                                                     | Br.                                             | 03         | Next Inspection Date: | 2022/08/11       |
| Road Name:                   | MCFARLANE CREEK                                                                                                                          |                                                 |            |                       |                  |
| Crossing Name:               | BURRELL Cr                                                                                                                               | Total Length (metres):                          | 18.3       |                       |                  |
| Special Access:              |                                                                                                                                          | Special Equipment:                              |            |                       |                  |
| Longitude:                   | -118 19 18.1                                                                                                                             | Latitude:                                       | 49 37 25.3 |                       |                  |
| Superstructure:              | Steel I-beam                                                                                                                             | Abutments (Left/Right):<br>(looking downstream) | Binwall    | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JNAUL on 08-APR-15: Reinspect in 2016 for condition of curbs and deck ties. Load rating is based on historical information on file. |                                                 |            |                       |                  |

### Structure Name: N6-082A

|                              |                                                                                |                                                 |                      |                       |                  |
|------------------------------|--------------------------------------------------------------------------------|-------------------------------------------------|----------------------|-----------------------|------------------|
| Site #:                      | N6-082                                                                         | Year Superstructure Installed:                  | 2013                 | Structure Type/Class: | Permanent Bridge |
| KM:                          | 2.30                                                                           | User km:                                        | 11.20                | Last Inspection Date: | 2021/09/13       |
| Project File ID #:           | 5457                                                                           | Br.                                             | 01                   | Next Inspection Date: | 2022/09/13       |
| Road Name:                   | MCKINNEY CREEK                                                                 |                                                 |                      |                       |                  |
| Crossing Name:               | MCKINNEY Cr                                                                    | Total Length (metres):                          | 7.0                  |                       |                  |
| Special Access:              |                                                                                | Special Equipment:                              |                      |                       |                  |
| Longitude:                   | -119 12 47.2                                                                   | Latitude:                                       | 49 5 9.5             |                       |                  |
| Superstructure:              | Concrete Slab Girders                                                          | Abutments (Left/Right):<br>(looking downstream) | Concrete Lock Blocks | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JRUPAR on 18-FEB-21: JRG 18, 2021 Monitor two tier lock blocks for scour. |                                                 |                      |                       |                  |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 20 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-127

|                              |                                                                                                                                                                                                           |                                |                                                 |                       |               |
|------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-127                                                                                                                                                                                                    | Year Superstructure Installed: | 1997                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 1.93                                                                                                                                                                                                      | User km:                       | 1.90                                            | Last Inspection Date: | 2019/08/08    |
| Project File ID #:           | 5457                                                                                                                                                                                                      | Br.                            | 02                                              | Next Inspection Date: | 2022/08/08    |
| Road Name:                   | MCKINNEY SOUTH                                                                                                                                                                                            |                                |                                                 |                       |               |
| Crossing Name:               | MCKINNEY Cr                                                                                                                                                                                               | Total Length (metres):         | 18.0                                            |                       |               |
| Special Access:              |                                                                                                                                                                                                           |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -119 12 21.5                                                                                                                                                                                              | Latitude:                      | 49 4 11.0                                       |                       |               |
| Superstructure:              |                                                                                                                                                                                                           |                                | Abutments (Left/Right):<br>(looking downstream) | # Spans:              | 0             |
| Planned Inspection Comments: | IDIR\JNAUL on 08-MAR-14: JN; 2014-03-08: Design embeddment of culvert does should be checked against ministry standards. Inspector to measure bedload type and depth inside the culvert for fish passage. |                                |                                                 |                       |               |

### Structure Name: N6-148

|                              |                       |                                                 |                    |                       |                  |
|------------------------------|-----------------------|-------------------------------------------------|--------------------|-----------------------|------------------|
| Site #:                      | N6-148                | Year Superstructure Installed:                  | 2006               | Structure Type/Class: | Permanent Bridge |
| KM:                          | 8.67                  | User km:                                        | 2.30               | Last Inspection Date: | 2019/08/10       |
| Project File ID #:           | 5595                  | Br.                                             | 01                 | Next Inspection Date: | 2022/08/10       |
| Road Name:                   | MILLER CREEK          |                                                 |                    |                       |                  |
| Crossing Name:               | Cameron Cr            | Total Length (metres):                          | 8.3                |                       |                  |
| Special Access:              |                       |                                                 | Special Equipment: |                       |                  |
| Longitude:                   | -118 21 51.1          | Latitude:                                       | 49 12 24.7         |                       |                  |
| Superstructure:              | Concrete Slab Girders | Abutments (Left/Right):<br>(looking downstream) | Concrete Precast   | # Spans:              | 1                |
| Planned Inspection Comments: |                       |                                                 |                    |                       |                  |

### Structure Name: N6-089

|                              |              |                                |                                                 |                       |               |
|------------------------------|--------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-089       | Year Superstructure Installed: | 1984                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 23.96        | User km:                       | 3.20                                            | Last Inspection Date: | 2019/08/09    |
| Project File ID #:           | 4354         | Br.                            | 01                                              | Next Inspection Date: | 2022/08/09    |
| Road Name:                   | PASS         |                                |                                                 |                       |               |
| Crossing Name:               | PASS Cr #2   | Total Length (metres):         | 12.2                                            |                       |               |
| Special Access:              |              |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -118 29 55.3 | Latitude:                      | 49 11 31.0                                      |                       |               |
| Superstructure:              |              |                                | Abutments (Left/Right):<br>(looking downstream) | # Spans:              | 0             |
| Planned Inspection Comments: |              |                                |                                                 |                       |               |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 21 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-088

|                              |              |                                                 |            |                       |               |
|------------------------------|--------------|-------------------------------------------------|------------|-----------------------|---------------|
| Site #:                      | N6-088       | Year Superstructure Installed:                  | 1984       | Structure Type/Class: | Major Culvert |
| KM:                          | 24.28        | User km:                                        | 2.80       | Last Inspection Date: | 2019/08/09    |
| Project File ID #:           | 4354         | Br.                                             | 01         | Next Inspection Date: | 2022/08/09    |
| Road Name:                   | PASS         |                                                 |            |                       |               |
| Crossing Name:               | PASS Cr #1   | Total Length (metres):                          | 9.1        |                       |               |
| Special Access:              |              | Special Equipment:                              |            |                       |               |
| Longitude:                   | -118 29 41.1 | Latitude:                                       | 49 11 26.4 |                       |               |
| Superstructure:              |              | Abutments (Left/Right):<br>(looking downstream) |            | # Spans:              | 0             |
| Planned Inspection Comments: |              |                                                 |            |                       |               |

### Structure Name: N6-144

|                              |                                                                                                                                                                                                                                                                                                                        |                                                 |                  |                       |                  |
|------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|------------------|-----------------------|------------------|
| Site #:                      | N6-144                                                                                                                                                                                                                                                                                                                 | Year Superstructure Installed:                  | 2006             | Structure Type/Class: | Permanent Bridge |
| KM:                          | 0.68                                                                                                                                                                                                                                                                                                                   | User km:                                        | 11.50            | Last Inspection Date: | 2019/08/09       |
| Project File ID #:           | 4354                                                                                                                                                                                                                                                                                                                   | Br.                                             | 07               | Next Inspection Date: | 2022/08/09       |
| Road Name:                   | PASS SEVEN                                                                                                                                                                                                                                                                                                             |                                                 |                  |                       |                  |
| Crossing Name:               | PASS Cr                                                                                                                                                                                                                                                                                                                | Total Length (metres):                          | 10.0             |                       |                  |
| Special Access:              |                                                                                                                                                                                                                                                                                                                        | Special Equipment:                              |                  |                       |                  |
| Longitude:                   | -118 34 24.1                                                                                                                                                                                                                                                                                                           | Latitude:                                       | 49 13 43.6       |                       |                  |
| Superstructure:              | Concrete Slab Girders                                                                                                                                                                                                                                                                                                  | Abutments (Left/Right):<br>(looking downstream) | Concrete Precast | # Spans:              | 1                |
| Planned Inspection Comments: | IDIR\JNAUL on 12-MAR-14: JN; 2014-03-12: Settlement of concrete lock blocks supporting concrete sill were identified in 2007 (bridge has not yet been tested for full log hauling loads). Recommend monitoring concrete sill and lock blocks during initial hauling followed by monitoring during routine inspections. |                                                 |                  |                       |                  |

### Structure Name: N6-113

|                              |                  |                                                 |           |                       |               |
|------------------------------|------------------|-------------------------------------------------|-----------|-----------------------|---------------|
| Site #:                      | N6-113           | Year Superstructure Installed:                  | 1990      | Structure Type/Class: | Major Culvert |
| KM:                          | 0.20             | User km:                                        | 0.20      | Last Inspection Date: | 2019/08/09    |
| Project File ID #:           | 8835             | Br.                                             | 01        | Next Inspection Date: | 2022/08/09    |
| Road Name:                   | PROVIDENCE CREEK |                                                 |           |                       |               |
| Crossing Name:               | EHOLT Cr         | Total Length (metres):                          | 11.3      |                       |               |
| Special Access:              |                  | Special Equipment:                              |           |                       |               |
| Longitude:                   | -118 38 57.9     | Latitude:                                       | 49 7 36.2 |                       |               |
| Superstructure:              |                  | Abutments (Left/Right):<br>(looking downstream) |           | # Spans:              | 0             |
| Planned Inspection Comments: |                  |                                                 |           |                       |               |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 22 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-145

|                              |                       |                                                 |                            |                       |                  |
|------------------------------|-----------------------|-------------------------------------------------|----------------------------|-----------------------|------------------|
| Site #:                      | N6-145                | Year Superstructure Installed:                  | 2006                       | Structure Type/Class: | Permanent Bridge |
| KM:                          | 0.15                  | User km:                                        | 0.20                       | Last Inspection Date: | 2019/08/09       |
| Project File ID #:           | 4354                  | Br.                                             | 15                         | Next Inspection Date: | 2022/08/09       |
| Road Name:                   | Pass-Seven 1000       |                                                 |                            |                       |                  |
| Crossing Name:               | Pass Crk Trib         | Total Length (metres):                          | 9.0                        |                       |                  |
| Special Access:              |                       |                                                 | Special Equipment:         |                       |                  |
| Longitude:                   | -118 34 28.9          | Latitude:                                       | 49 13 37.0                 |                       |                  |
| Superstructure:              | Concrete Slab Girders | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans:              | 1                |
| Planned Inspection Comments: |                       |                                                 |                            |                       |                  |

### Structure Name: N6-111A

|                              |               |                                                 |                            |                       |                  |
|------------------------------|---------------|-------------------------------------------------|----------------------------|-----------------------|------------------|
| Site #:                      | N6-111        | Year Superstructure Installed:                  | 2021                       | Structure Type/Class: | Permanent Bridge |
| KM:                          | 9.01          | User km:                                        | 8.80                       | Last Inspection Date: |                  |
| Project File ID #:           | 9267          | Br.                                             | 01                         | Next Inspection Date: | 2022/04/01       |
| Road Name:                   | RENDELL CREEK |                                                 |                            |                       |                  |
| Crossing Name:               | ARTHURS Cr    | Total Length (metres):                          | 18.3                       |                       |                  |
| Special Access:              |               |                                                 | Special Equipment:         |                       |                  |
| Longitude:                   | -118 42 10.9  | Latitude:                                       | 49 41 13.7                 |                       |                  |
| Superstructure:              | Steel I-beam  | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans:              | 1                |
| Planned Inspection Comments: |               |                                                 |                            |                       |                  |

### Structure Name: N6-126

|                              |              |                                                 |                    |                       |               |
|------------------------------|--------------|-------------------------------------------------|--------------------|-----------------------|---------------|
| Site #:                      | N6-126       | Year Superstructure Installed:                  | 1996               | Structure Type/Class: | Major Culvert |
| KM:                          | 0.03         | User km:                                        | 0.00               | Last Inspection Date: | 2019/09/24    |
| Project File ID #:           | 5456         | Br.                                             | 10                 | Next Inspection Date: | 2022/09/24    |
| Road Name:                   | RIVERSIDE    |                                                 |                    |                       |               |
| Crossing Name:               | FIVA Cr      | Total Length (metres):                          | 15.0               |                       |               |
| Special Access:              |              |                                                 | Special Equipment: |                       |               |
| Longitude:                   | -118 53 50.2 | Latitude:                                       | 49 12 30.3         |                       |               |
| Superstructure:              |              | Abutments (Left/Right):<br>(looking downstream) |                    | # Spans:              | 0             |
| Planned Inspection Comments: |              |                                                 |                    |                       |               |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 23 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-091A

|                              |                       |                                                 |                        |                       |                  |
|------------------------------|-----------------------|-------------------------------------------------|------------------------|-----------------------|------------------|
| Site #:                      | N6-091                | Year Superstructure Installed:                  | 2009                   | Structure Type/Class: | Permanent Bridge |
| KM:                          | 6.60                  | User km:                                        | 10.80                  | Last Inspection Date: | 2019/08/10       |
| Project File ID #:           | 4354                  | Br.                                             | 03                     | Next Inspection Date: | 2022/08/10       |
| Road Name:                   | ROCK CANDY EAST       |                                                 |                        |                       |                  |
| Crossing Name:               | KENNEDY Cr            |                                                 | Total Length (metres): | 11.0                  |                  |
| Special Access:              |                       |                                                 | Special Equipment:     |                       |                  |
| Longitude:                   | -118 29 52.9          |                                                 | Latitude:              | 49 15 39.6            |                  |
| Superstructure:              | Concrete Slab Girders | Abutments (Left/Right):<br>(looking downstream) | Concrete Precast       | # Spans:              | 1                |
| Planned Inspection Comments: |                       |                                                 |                        |                       |                  |

### Structure Name: N6-203

|                              |               |                                                 |                        |                       |               |
|------------------------------|---------------|-------------------------------------------------|------------------------|-----------------------|---------------|
| Site #:                      | N6-203        | Year Superstructure Installed:                  | 1900                   | Structure Type/Class: | Major Culvert |
| KM:                          | 1.50          | User km:                                        |                        | Last Inspection Date: |               |
| Project File ID #:           | 8272          | Br.                                             | 01                     | Next Inspection Date: | 2022/08/01    |
| Road Name:                   | ROCK MOUNTAIN |                                                 |                        |                       |               |
| Crossing Name:               | unnamed       |                                                 | Total Length (metres): | 125.0                 |               |
| Special Access:              |               |                                                 | Special Equipment:     |                       |               |
| Longitude:                   | -119 3 29.2   |                                                 | Latitude:              | 49 2 3.6              |               |
| Superstructure:              |               | Abutments (Left/Right):<br>(looking downstream) |                        | # Spans:              | 0             |
| Planned Inspection Comments: |               |                                                 |                        |                       |               |

### Structure Name: N6-092

|                              |                                                                                                                        |                                                 |                        |                       |               |
|------------------------------|------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|------------------------|-----------------------|---------------|
| Site #:                      | N6-092                                                                                                                 | Year Superstructure Installed:                  | 1970                   | Structure Type/Class: | Major Culvert |
| KM:                          | 1.92                                                                                                                   | User km:                                        | 9.00                   | Last Inspection Date: | 2019/08/08    |
| Project File ID #:           | 8272                                                                                                                   | Br.                                             | 01                     | Next Inspection Date: | 2022/08/08    |
| Road Name:                   | ROCK MOUNTAIN                                                                                                          |                                                 |                        |                       |               |
| Crossing Name:               | BUDY Cr                                                                                                                |                                                 | Total Length (metres): | 125.0                 |               |
| Special Access:              |                                                                                                                        |                                                 | Special Equipment:     |                       |               |
| Longitude:                   | -119 5 1.3                                                                                                             |                                                 | Latitude:              | 49 2 22.1             |               |
| Superstructure:              |                                                                                                                        | Abutments (Left/Right):<br>(looking downstream) |                        | # Spans:              | 0             |
| Planned Inspection Comments: | IDIR\JNAUL on 03-MAR-14: JN; 2014-03-03: Check cover depth. Monitor and measure cracks during next routine inspection. |                                                 |                        |                       |               |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 24 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-172

|                              |                            |                                |                                                 |                            |                  |
|------------------------------|----------------------------|--------------------------------|-------------------------------------------------|----------------------------|------------------|
| Site #:                      | N6-172                     | Year Superstructure Installed: | 1997                                            | Structure Type/Class:      | Permanent Bridge |
| KM:                          | 2.40                       | User km:                       |                                                 | Last Inspection Date:      | 2019/09/26       |
| Project File ID #:           | 9267                       | Br.                            | 21                                              | Next Inspection Date:      | 2022/09/26       |
| Road Name:                   | S. GOATSKIN                |                                |                                                 |                            |                  |
| Crossing Name:               | Unnamed Creek              |                                | Total Length (metres):                          | 8.0                        |                  |
| Special Access:              |                            |                                | Special Equipment:                              |                            |                  |
| Longitude:                   | -118 36 29.7               |                                | Latitude:                                       | 49 44 33.7                 |                  |
| Superstructure:              | Steel I-beam               |                                | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans: 1       |
| Planned Inspection Comments: | IDIR\JNAUL on 21-JAN-20: . |                                |                                                 |                            |                  |

### Structure Name: N6-080

|                              |              |                                |                                                 |                       |               |
|------------------------------|--------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-080       | Year Superstructure Installed: | 1993                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 7.75         | User km:                       | 7.80                                            | Last Inspection Date: | 2019/09/26    |
| Project File ID #:           | 0136         | Br.                            | 02                                              | Next Inspection Date: | 2022/09/26    |
| Road Name:                   | THONE LAKE   |                                |                                                 |                       |               |
| Crossing Name:               | PATURAGES Cr |                                | Total Length (metres):                          | 20.0                  |               |
| Special Access:              |              |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -118 49 34.3 |                                | Latitude:                                       | 49 25 44.6            |               |
| Superstructure:              |              |                                | Abutments (Left/Right):<br>(looking downstream) |                       | # Spans: 0    |
| Planned Inspection Comments: |              |                                |                                                 |                       |               |

### Structure Name: N6-137

|                              |                |                                |                                                 |                       |               |
|------------------------------|----------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-137         | Year Superstructure Installed: | 2003                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 2.87           | User km:                       | 0.16                                            | Last Inspection Date: | 2019/09/26    |
| Project File ID #:           | 0136           | Br.                            | 09                                              | Next Inspection Date: | 2022/09/26    |
| Road Name:                   | THONE SPUR 600 |                                |                                                 |                       |               |
| Crossing Name:               | Unnamed        |                                | Total Length (metres):                          | 13.8                  |               |
| Special Access:              |                |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -118 48 3.5    |                                | Latitude:                                       | 49 26 50.4            |               |
| Superstructure:              |                |                                | Abutments (Left/Right):<br>(looking downstream) |                       | # Spans: 0    |
| Planned Inspection Comments: |                |                                |                                                 |                       |               |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 25 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-095

|                              |                |                                |                                                 |                       |               |
|------------------------------|----------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-095         | Year Superstructure Installed: | 1975                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 2.28           | User km:                       | 13.80                                           | Last Inspection Date: | 2019/09/25    |
| Project File ID #:           | 3929           | Br.                            | 01                                              | Next Inspection Date: | 2022/09/25    |
| Road Name:                   | TRAPPING CREEK |                                |                                                 |                       |               |
| Crossing Name:               | Unnamed        |                                | Total Length (metres):                          | 12.2                  |               |
| Special Access:              |                |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -118 57 55.8   |                                | Latitude:                                       | 49 39 7.5             |               |
| Superstructure:              |                |                                | Abutments (Left/Right):<br>(looking downstream) |                       | # Spans: 0    |
| Planned Inspection Comments: |                |                                |                                                 |                       |               |

### Structure Name: N6-096A

|                              |                       |                                |                                                 |                       |                  |
|------------------------------|-----------------------|--------------------------------|-------------------------------------------------|-----------------------|------------------|
| Site #:                      | N6-096                | Year Superstructure Installed: | 2012                                            | Structure Type/Class: | Permanent Bridge |
| KM:                          | 10.49                 | User km:                       | 22.20                                           | Last Inspection Date: | 2019/09/25       |
| Project File ID #:           | 3929                  | Br.                            | 01                                              | Next Inspection Date: | 2022/09/25       |
| Road Name:                   | TRAPPING CREEK        |                                |                                                 |                       |                  |
| Crossing Name:               | Unnamed               |                                | Total Length (metres):                          | 10.6                  |                  |
| Special Access:              |                       |                                | Special Equipment:                              |                       |                  |
| Longitude:                   | -118 55 3.9           |                                | Latitude:                                       | 49 41 43.4            |                  |
| Superstructure:              | Concrete Slab Girders |                                | Abutments (Left/Right):<br>(looking downstream) | Concrete Lock Blocks  | # Spans: 1       |
| Planned Inspection Comments: |                       |                                |                                                 |                       |                  |

### Structure Name: N6-097

|                              |                                                                                                                                                                                                                                                   |                                |                                                 |                       |               |
|------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-097                                                                                                                                                                                                                                            | Year Superstructure Installed: | 1975                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 10.99                                                                                                                                                                                                                                             | User km:                       | 22.70                                           | Last Inspection Date: | 2019/09/25    |
| Project File ID #:           | 3929                                                                                                                                                                                                                                              | Br.                            | 01                                              | Next Inspection Date: | 2022/09/25    |
| Road Name:                   | TRAPPING CREEK                                                                                                                                                                                                                                    |                                |                                                 |                       |               |
| Crossing Name:               | TRAPPING Cr                                                                                                                                                                                                                                       |                                | Total Length (metres):                          | 9.1                   |               |
| Special Access:              |                                                                                                                                                                                                                                                   |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -118 54 40.0                                                                                                                                                                                                                                      |                                | Latitude:                                       | 49 41 45.7            |               |
| Superstructure:              |                                                                                                                                                                                                                                                   |                                | Abutments (Left/Right):<br>(looking downstream) |                       | # Spans: 0    |
| Planned Inspection Comments: | IDIR\JNAUL on 09-MAR-14: JN; 2014-03-09: Added culvert gradient of 3.5% based on as built information on file; confirm as built dimensions during next routine inspection. Fish habitat assessment recommended prior to replacing this structure. |                                |                                                 |                       |               |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 26 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-094

|                              |                |                                |                                                 |                       |               |
|------------------------------|----------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-094         | Year Superstructure Installed: | 1981                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 14.17          | User km:                       | 9.60                                            | Last Inspection Date: | 2019/09/25    |
| Project File ID #:           | 3929           | Br.                            | 01                                              | Next Inspection Date: | 2022/09/25    |
| Road Name:                   | TRAPPING CREEK |                                |                                                 |                       |               |
| Crossing Name:               | LOST Cr        |                                | Total Length (metres):                          | 12.2                  |               |
| Special Access:              |                |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -118 59 17.2   |                                | Latitude:                                       | 49 37 30.8            |               |
| Superstructure:              |                |                                | Abutments (Left/Right):<br>(looking downstream) | # Spans:              | 0             |
| Planned Inspection Comments: |                |                                |                                                 |                       |               |

### Structure Name: N6-051

|                              |                   |                                |                                                 |                       |               |
|------------------------------|-------------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-051            | Year Superstructure Installed: | 1983                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 1.42              | User km:                       | 16.50                                           | Last Inspection Date: | 2019/08/10    |
| Project File ID #:           | 0018              | Br.                            | 09                                              | Next Inspection Date: | 2022/08/10    |
| Road Name:                   | TRAVERSE CREEK    |                                |                                                 |                       |               |
| Crossing Name:               | BEAR (10 MILE) Cr |                                | Total Length (metres):                          | 9.1                   |               |
| Special Access:              |                   |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -118 33 21.1      |                                | Latitude:                                       | 49 28 53.3            |               |
| Superstructure:              |                   |                                | Abutments (Left/Right):<br>(looking downstream) | # Spans:              | 0             |
| Planned Inspection Comments: |                   |                                |                                                 |                       |               |

### Structure Name: N6-153

|                              |                |                                |                                                 |                       |               |
|------------------------------|----------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-153         | Year Superstructure Installed: | 2008                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 12.40          | User km:                       |                                                 | Last Inspection Date: | 2019/08/10    |
| Project File ID #:           | 0018           | Br.                            | 09                                              | Next Inspection Date: | 2022/08/10    |
| Road Name:                   | TRAVERSE CREEK |                                |                                                 |                       |               |
| Crossing Name:               | Traverse Cr.   |                                | Total Length (metres):                          | 25.0                  |               |
| Special Access:              |                |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -118 36 34.0   |                                | Latitude:                                       | 49 31 14.0            |               |
| Superstructure:              |                |                                | Abutments (Left/Right):<br>(looking downstream) | # Spans:              | 0             |
| Planned Inspection Comments: |                |                                |                                                 |                       |               |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 27 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-105

|                              |                   |                                |                                                 |                       |               |
|------------------------------|-------------------|--------------------------------|-------------------------------------------------|-----------------------|---------------|
| Site #:                      | N6-105            | Year Superstructure Installed: | 1990                                            | Structure Type/Class: | Major Culvert |
| KM:                          | 0.65              | User km:                       | 0.80                                            | Last Inspection Date: | 2019/09/25    |
| Project File ID #:           | 4351              | Br.                            | 01                                              | Next Inspection Date: | 2022/09/25    |
| Road Name:                   | TUZO CREEK EUGENE |                                |                                                 |                       |               |
| Crossing Name:               | TUZO Cr           |                                | Total Length (metres):                          | 14.0                  |               |
| Special Access:              |                   |                                | Special Equipment:                              |                       |               |
| Longitude:                   | -119 6 7.5        |                                | Latitude:                                       | 49 22 57.6            |               |
| Superstructure:              |                   |                                | Abutments (Left/Right):<br>(looking downstream) |                       | # Spans: 0    |
| Planned Inspection Comments: |                   |                                |                                                 |                       |               |

### Structure Name: N6-106

|                              |                   |                                |                                                 |                            |                  |
|------------------------------|-------------------|--------------------------------|-------------------------------------------------|----------------------------|------------------|
| Site #:                      | N6-106            | Year Superstructure Installed: | 1999                                            | Structure Type/Class:      | Permanent Bridge |
| KM:                          | 5.90              | User km:                       | 6.00                                            | Last Inspection Date:      | 2019/09/25       |
| Project File ID #:           | 4351              | Br.                            | 01                                              | Next Inspection Date:      | 2022/09/25       |
| Road Name:                   | TUZO CREEK EUGENE |                                |                                                 |                            |                  |
| Crossing Name:               | EUGENE Cr         |                                | Total Length (metres):                          | 12.3                       |                  |
| Special Access:              |                   |                                | Special Equipment:                              |                            |                  |
| Longitude:                   | -119 8 47.8       |                                | Latitude:                                       | 49 24 33.3                 |                  |
| Superstructure:              | Concrete Box Beam |                                | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans: 1       |
| Planned Inspection Comments: |                   |                                |                                                 |                            |                  |

### Structure Name: N6-123

|                              |                            |                                |                                                 |                            |                  |
|------------------------------|----------------------------|--------------------------------|-------------------------------------------------|----------------------------|------------------|
| Site #:                      | N6-123                     | Year Superstructure Installed: | 2000                                            | Structure Type/Class:      | Permanent Bridge |
| KM:                          | 8.56                       | User km:                       | 8.60                                            | Last Inspection Date:      | 2019/08/11       |
| Project File ID #:           | 8973                       | Br.                            | 03                                              | Next Inspection Date:      | 2022/08/11       |
| Road Name:                   | UNION MINE                 |                                |                                                 |                            |                  |
| Crossing Name:               | Unnamed                    |                                | Total Length (metres):                          | 12.2                       |                  |
| Special Access:              |                            |                                | Special Equipment:                              |                            |                  |
| Longitude:                   | -118 25 16.4               |                                | Latitude:                                       | 49 34 5.4                  |                  |
| Superstructure:              | Steel I-beam               |                                | Abutments (Left/Right):<br>(looking downstream) | Concrete Lock Blocks/Steel | # Spans: 1       |
| Planned Inspection Comments: | IDIR\JNAUL on 22-JAN-20: . |                                |                                                 |                            |                  |



# BC Ministry of Forests, Lands, and Natural Resource Operations

## Inspections Due - Detailed Report

Page: 28 of 28  
Date Printed: 2022/05/05  
User Id: IDIR\HABEURSK  
Database: PROD  
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/01/01 Inspection Status:Inspect

### Structure Name: N6-108

|                              |                       |                                                 |                            |                       |                  |
|------------------------------|-----------------------|-------------------------------------------------|----------------------------|-----------------------|------------------|
| Site #:                      | N6-108                | Year Superstructure Installed:                  | 1996                       | Structure Type/Class: | Permanent Bridge |
| KM:                          | 11.68                 | User km:                                        | 2.70                       | Last Inspection Date: | 2019/08/09       |
| Project File ID #:           | 7964                  | Br.                                             | 01                         | Next Inspection Date: | 2022/08/09       |
| Road Name:                   | WALLACE CREEK         |                                                 |                            |                       |                  |
| Crossing Name:               | WALLACE Cr            |                                                 | Total Length (metres):     | 9.6                   |                  |
| Special Access:              |                       |                                                 | Special Equipment:         |                       |                  |
| Longitude:                   | -118 42 38.3          |                                                 | Latitude:                  | 49 8 47.5             |                  |
| Superstructure:              | Concrete Slab Girders | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans:              | 1                |
| Planned Inspection Comments: |                       |                                                 |                            |                       |                  |

### Structure Name: N6-107

|                              |                       |                                                 |                            |                       |                  |
|------------------------------|-----------------------|-------------------------------------------------|----------------------------|-----------------------|------------------|
| Site #:                      | N6-107                | Year Superstructure Installed:                  | 1996                       | Structure Type/Class: | Permanent Bridge |
| KM:                          | 13.06                 | User km:                                        | 1.30                       | Last Inspection Date: | 2019/08/09       |
| Project File ID #:           | 7964                  | Br.                                             | 01                         | Next Inspection Date: | 2022/08/09       |
| Road Name:                   | WALLACE CREEK         |                                                 |                            |                       |                  |
| Crossing Name:               | WALLACE Cr            |                                                 | Total Length (metres):     | 9.6                   |                  |
| Special Access:              |                       |                                                 | Special Equipment:         |                       |                  |
| Longitude:                   | -118 41 49.3          |                                                 | Latitude:                  | 49 8 23.2             |                  |
| Superstructure:              | Concrete Slab Girders | Abutments (Left/Right):<br>(looking downstream) | Steel Pipe and Precast Pad | # Spans:              | 1                |
| Planned Inspection Comments: |                       |                                                 |                            |                       |                  |

### Structure Name: N6-017

|                              |                |                                                 |                        |                       |               |
|------------------------------|----------------|-------------------------------------------------|------------------------|-----------------------|---------------|
| Site #:                      | N6-017         | Year Superstructure Installed:                  | 1983                   | Structure Type/Class: | Major Culvert |
| KM:                          | 0.62           | User km:                                        | 1.10                   | Last Inspection Date: | 2019/08/09    |
| Project File ID #:           | 3719           | Br.                                             | 04                     | Next Inspection Date: | 2022/08/09    |
| Road Name:                   | WINDFALL CREEK |                                                 |                        |                       |               |
| Crossing Name:               | WINDFALL Cr    |                                                 | Total Length (metres): | 9.1                   |               |
| Special Access:              |                |                                                 | Special Equipment:     |                       |               |
| Longitude:                   | -118 42 39.3   |                                                 | Latitude:              | 49 11 32.2            |               |
| Superstructure:              |                | Abutments (Left/Right):<br>(looking downstream) |                        | # Spans:              | 0             |
| Planned Inspection Comments: |                |                                                 |                        |                       |               |

### Structure Type/Class Totals

Permanent Bridge Total: 43  
Temporary Bridge Total: 3

Major Culvert Total: 38  
Woodbox/Log Culvert Total: 0