BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: 64-176

Site #:	64-176	**Year Superstructure Installed:**	2021	**Structure Type/Class:**	Permanent Bridge
KM:	1.00	**User km:**	0.30	**Last Inspection Date:**	
Project File ID #:	7357	**Br.**	01	**Next Inspection Date:**	2023/08/18
Road Name:	7357				
Crossing Name:	Green Lake Outlet			**Total Length (metres):**	18.3
Special Access:				**Special Equipment:**	
Longitude:	-121 4 46.2			**Latitude:**	51 26 20.7
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Steel Pipe and Precast Pad	**# Spans:** 1
Planned Inspection Comments:	IDIR\MRFENNEL on 26-MAY-23: One year post installation inspection				

Structure Name: 64-008

Site #:	64-008	**Year Superstructure Installed:**	1990	**Structure Type/Class:**	Permanent Bridge
KM:	1.90	**User km:**	1.90	**Last Inspection Date:**	2020/07/11
Project File ID #:	6061	**Br.**	06	**Next Inspection Date:**	2023/07/11
Road Name:	BOWERS/CANIMRED				
Crossing Name:	Canimred Cr			**Total Length (metres):**	13.0
Special Access:				**Special Equipment:**	
Longitude:	-120 35 34.0			**Latitude:**	51 48 57.5
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Pile -Permanent Materials	**# Spans:** 1
Planned Inspection Comments:					

Structure Name: 64-158

Site #:	64-158	**Year Superstructure Installed:**	2016	**Structure Type/Class:**	Woodbox/Log Culvert
KM:	1.00	**User km:**	1.00	**Last Inspection Date:**	2021/09/07
Project File ID #:	6061	**Br.**	02	**Next Inspection Date:**	2023/09/07
Road Name:	BOWERS/WINDY				
Crossing Name:	Unnamed			**Total Length (metres):**	6.0
Special Access:				**Special Equipment:**	
Longitude:	-120 40 53.0			**Latitude:**	51 39 54.0
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*			**# Spans:** 0
Planned Inspection Comments:	IDIR\MRFENNEL on 23-JUN-17: Dummy dimension information entered. Inspector to grab measurements and verify information.				

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: 64-054

Site #:	64-054	**Year Superstructure Installed:**	1997	**Structure Type/Class:**	Permanent Bridge
KM:	8.40	**User km:**	1.00	**Last Inspection Date:**	2020/07/16
Project File ID #:	6061	**Br.**	02	**Next Inspection Date:**	2023/07/16
Road Name:	BOWERS/WINDY				
Crossing Name:	Cougar Cr			**Total Length (metres):**	12.0
Special Access:				**Special Equipment:**	
Longitude:	-120 40 43.0			**Latitude:**	51 42 33.6
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Pile -Permanent Materials	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: 64-011

Site #:	64-011	**Year Superstructure Installed:**	2005	**Structure Type/Class:**	Permanent Bridge
KM:	21.20	**User km:**	25.00	**Last Inspection Date:**	2020/07/09
Project File ID #:	5712	**Br.**	01	**Next Inspection Date:**	2023/07/09
Road Name:	CLINTON/LOON				
Crossing Name:	Bonaparte R			**Total Length (metres):**	28.0
Special Access:				**Special Equipment:**	
Longitude:	-121 14 2.3			**Latitude:**	51 12 51.1
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Precast	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: 64-012

Site #:	64-012	**Year Superstructure Installed:**	1991	**Structure Type/Class:**	Major Culvert
KM:	35.80	**User km:**	41.00	**Last Inspection Date:**	2020/07/09
Project File ID #:	5712	**Br.**	01	**Next Inspection Date:**	2023/07/09
Road Name:	CLINTON/LOON				
Crossing Name:	Bakers Cattle Underpass			**Total Length (metres):**	18.0
Special Access:				**Special Equipment:**	
Longitude:	-121 5 23.5			**Latitude:**	51 10 35.0
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:					

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: 64-013

Site #:	64-013	**Year Superstructure Installed:**	1994	**Structure Type/Class:**	Major Culvert
KM:	45.50	**User km:**	50.60	**Last Inspection Date:**	2020/07/09
Project File ID #:	5712	**Br.**	01	**Next Inspection Date:**	2023/07/09
Road Name:	CLINTON/LOON				
Crossing Name:	Brigade Cr	**Total Length (metres):**	20.0		
Special Access:		**Special Equipment:**			
Longitude:	-121 3 42.5	**Latitude:**	51 7 18.7		
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:					

Structure Name: 64-079

Site #:	64-079	**Year Superstructure Installed:**	1994	**Structure Type/Class:**	Major Culvert
KM:	57.50	**User km:**	62.50	**Last Inspection Date:**	2020/07/09
Project File ID #:	5712	**Br.**	01	**Next Inspection Date:**	2023/07/09
Road Name:	CLINTON/LOON				
Crossing Name:	Boulder Cr	**Total Length (metres):**	15.0		
Special Access:		**Special Equipment:**			
Longitude:	-121 4 38.8	**Latitude:**	51 1 46.4		
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:					

Structure Name: PS 64-110

Site #:	64-110	**Year Superstructure Installed:**	2005	**Structure Type/Class:**	Permanent Bridge
KM:	11.43	**User km:**	13.80	**Last Inspection Date:**	2020/07/09
Project File ID #:	5712	**Br.**	07	**Next Inspection Date:**	2023/07/09
Road Name:	CLINTON/TULERIC LAKE				
Crossing Name:	Trib to Deadman Ck	**Total Length (metres):**	10.0		
Special Access:		**Special Equipment:**			
Longitude:	-120 40 9.5	**Latitude:**	51 9 15.0		
Superstructure:	Steel Box Beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:					

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: 64-179

Site #:	64-179	**Year Superstructure Installed:**	2022	**Structure Type/Class:**	Permanent Bridge
KM:	31.00	**User km:**	73.00	**Last Inspection Date:**	
Project File ID #:	6315	**Br.**	01	**Next Inspection Date:**	2023/08/18
Road Name:	EAGAN/BONAPARTE				
Crossing Name:	Unnamed			**Total Length (metres):**	10.6
Special Access:				**Special Equipment:**	
Longitude:	-120 10 42.6			**Latitude:**	51 14 51.3
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*		Steel Pipe and Precast Pad	**# Spans:** 1
Planned Inspection Comments:	IDIR\MRFENNEL on 03-MAY-23: One year post installation inspection				

Structure Name: 64-108

Site #:	64-108	**Year Superstructure Installed:**	2002	**Structure Type/Class:**	Permanent Bridge
KM:	0.10	**User km:**	0.10	**Last Inspection Date:**	2020/07/10
Project File ID #:	10076	**Br.**	01	**Next Inspection Date:**	2023/07/10
Road Name:	GRAHAM CREEK FSR				
Crossing Name:	Graham Cr			**Total Length (metres):**	10.0
Special Access:				**Special Equipment:**	
Longitude:	-120 56 14.6			**Latitude:**	51 23 45.3
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Concrete Precast	**# Spans:** 1
Planned Inspection Comments:					

Structure Name: TKA002

Site #:	64-141	**Year Superstructure Installed:**	2012	**Structure Type/Class:**	Temporary Bridge
KM:	4.00	**User km:**	4.00	**Last Inspection Date:**	2021/09/07
Project File ID #:	8434	**Br.**	10	**Next Inspection Date:**	2023/09/07
Road Name:	MH 8434.10				
Crossing Name:	Unknown			**Total Length (metres):**	6.1
Special Access:				**Special Equipment:**	
Longitude:	-120 33 46.5			**Latitude:**	51 35 54.3
Superstructure:	Timber - untreated stringers	**Abutments (Left/Right):** *(looking downstream)*		Sill -Temporary Materials	**# Spans:** 1
Planned Inspection Comments:					

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: TKA003

Site #:	64-149	**Year Superstructure Installed:**	2012	**Structure Type/Class:**	Temporary Bridge
KM:	5.80	**User km:**	5.80	**Last Inspection Date:**	2021/09/07
Project File ID #:	8434	**Br.**	10	**Next Inspection Date:**	2023/09/07
Road Name:	MH 8434.10				
Crossing Name:	Unknown	**Total Length (metres):**	6.1		
Special Access:		**Special Equipment:**			
Longitude:	-120 34 56.5	**Latitude:**	51 36 20.7		
Superstructure:	Timber - untreated stringers	**Abutments (Left/Right):** *(looking downstream)*	Sill -Temporary Materials	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: TKA005

Site #:	64-150	**Year Superstructure Installed:**	2012	**Structure Type/Class:**	Temporary Bridge
KM:	6.10	**User km:**	6.10	**Last Inspection Date:**	2021/09/07
Project File ID #:	8434	**Br.**	10	**Next Inspection Date:**	2023/09/07
Road Name:	MH 8434.10				
Crossing Name:	Unknown	**Total Length (metres):**	6.1		
Special Access:		**Special Equipment:**			
Longitude:	-120 35 9.5	**Latitude:**	51 36 17.0		
Superstructure:	Timber - untreated stringers	**Abutments (Left/Right):** *(looking downstream)*	Sill -Temporary Materials	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: TKA-019

Site #:	64-154	**Year Superstructure Installed:**	2014	**Structure Type/Class:**	Permanent Bridge
KM:	0.50	**User km:**		**Last Inspection Date:**	2020/07/12
Project File ID #:	5289	**Br.**	24	**Next Inspection Date:**	2023/07/12
Road Name:	MH5289.24				
Crossing Name:	Noname	**Total Length (metres):**	12.0		
Special Access:		**Special Equipment:**			
Longitude:	-120 36 44.6	**Latitude:**	51 37 37.8		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: WO1265

Site #:	64-163	**Year Superstructure Installed:**	2019	**Structure Type/Class:**	Temporary Bridge
KM:	1.40	**User km:**	1.40	**Last Inspection Date:**	2021/09/07
Project File ID #:	5289	**Br.**	26	**Next Inspection Date:**	2023/09/07
Road Name:	MH5289.26				
Crossing Name:	Windy Creek			**Total Length (metres):**	12.2
Special Access:				**Special Equipment:**	
Longitude:	-120 32 38.0			**Latitude:**	51 38 30.0
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Concrete Lock Blocks	**# Spans:** 1
Planned Inspection Comments:	IDIR\MRFENNEL on 26-FEB-21: Post installation inspection CBR_Conversion on 26-FEB-21:				

Structure Name: 64-181

Site #:	64-181	**Year Superstructure Installed:**	1998	**Structure Type/Class:**	Permanent Bridge
KM:	0.90	**User km:**	0.90	**Last Inspection Date:**	
Project File ID #:	6061	**Br.**	40	**Next Inspection Date:**	2023/06/01
Road Name:	MH6061.40				
Crossing Name:	Unknown			**Total Length (metres):**	12.7
Special Access:				**Special Equipment:**	
Longitude:	-120 40 42.5			**Latitude:**	51 42 33.9
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Pile -Permanent Materials	**# Spans:** 1
Planned Inspection Comments:					

Structure Name: TKA026

Site #:	64-175	**Year Superstructure Installed:**	2021	**Structure Type/Class:**	Temporary Bridge
KM:	2.30	**User km:**	2.30	**Last Inspection Date:**	2020/07/13
Project File ID #:	8434	**Br.**	23	**Next Inspection Date:**	2023/07/01
Road Name:	MH8434.23				
Crossing Name:	Unknown			**Total Length (metres):**	12.2
Special Access:				**Special Equipment:**	
Longitude:	-120 26 13.3			**Latitude:**	51 35 10.7
Superstructure:	Steel Box Beam	**Abutments (Left/Right):** *(looking downstream)*		Sill -Temporary Materials	**# Spans:** 1
Planned Inspection Comments:	IDIR\PBLUESCH on 31-JAN-20: PB Jan31.2020 Left bank rock pad oversteepened. Monitor abutment stability during hauling. IDIR\MRFENNEL on 30-JAN-20: One year post installation inspection				

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: WO-1531

Site #:	64-165	**Year Superstructure Installed:**	2020	**Structure Type/Class:**	Temporary Bridge
KM:	0.50	**User km:**	1.80	**Last Inspection Date:**	2021/09/08
Project File ID #:	8611	**Br.**	20	**Next Inspection Date:**	2023/09/08
Road Name:	MH8611.20				
Crossing Name:	Deception Cr			**Total Length (metres):**	9.1
Special Access:				**Special Equipment:**	
Longitude:	-120 35 10.4			**Latitude:**	51 59 43.4
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Sill -Temporary Materials	**# Spans:** 1
Planned Inspection Comments:	IDIR\MRFENNEL on 26-MAR-21: One year post installation inspection				

Structure Name: WO2751

Site #:	64-169	**Year Superstructure Installed:**	2021	**Structure Type/Class:**	Temporary Bridge
KM:	3.70	**User km:**	3.70	**Last Inspection Date:**	
Project File ID #:	8611	**Br.**	21	**Next Inspection Date:**	2023/05/01
Road Name:	MH8611.21				
Crossing Name:	Unknown			**Total Length (metres):**	15.2
Special Access:				**Special Equipment:**	
Longitude:	-120 43 27.0			**Latitude:**	50 1 6.0
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Sill -Temporary Materials	**# Spans:** 1
Planned Inspection Comments:	IDIR\RKEETCH on 25-MAY-22: New Structure installed 2021 CBR_Conversion on 17-FEB-14: Monitor for continued settlement and ensure posted at 2 tonnes. BCTS to remove in 2014, check with them prior to inspection. DA nov 2013.				

Structure Name: TKA030

Site #:	64-170	**Year Superstructure Installed:**		**Structure Type/Class:**	Temporary Bridge
KM:	3.80	**User km:**	3.80	**Last Inspection Date:**	2022/08/29
Project File ID #:	8611	**Br.**	21	**Next Inspection Date:**	2023/06/01
Road Name:	MH8611.21				
Crossing Name:	Unknown			**Total Length (metres):**	12.2
Special Access:				**Special Equipment:**	
Longitude:	-120 43 24.0			**Latitude:**	52 1 3.0
Superstructure:	Steel Box Beam	**Abutments (Left/Right):** *(looking downstream)*		Crib, Log or Untreated	**# Spans:** 1
Planned Inspection Comments:	IDIR\MRFENNEL on 12-MAY-21: One year post installation inspection				

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: TKA031

Site #:	64-171	**Year Superstructure Installed:**	2021	**Structure Type/Class:**	Temporary Bridge
KM:	4.20	**User km:**	4.20	**Last Inspection Date:**	
Project File ID #:	8611	**Br.**	21	**Next Inspection Date:**	2022/05/01
Road Name:	MH8611.21				
Crossing Name:	Unnamed	**Total Length (metres):**	15.2		
Special Access:		**Special Equipment:**			
Longitude:	-120 43 2.0	**Latitude:**	52 0 52.0		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Sill -Temporary Materials	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: PS-054

Site #:	64-172	**Year Superstructure Installed:**	2021	**Structure Type/Class:**	Temporary Bridge
KM:	1.70	**User km:**	1.70	**Last Inspection Date:**	
Project File ID #:	8611	**Br.**	22	**Next Inspection Date:**	2023/05/01
Road Name:	MH8611.22				
Crossing Name:	Unnamed	**Total Length (metres):**	12.2		
Special Access:		**Special Equipment:**			
Longitude:	-120 42 37.0	**Latitude:**	52 1 4.0		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Sill -Temporary Materials	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: TKA015

Site #:	64-173	**Year Superstructure Installed:**	2021	**Structure Type/Class:**	Temporary Bridge
KM:	2.30	**User km:**	2.30	**Last Inspection Date:**	
Project File ID #:	8611	**Br.**	22	**Next Inspection Date:**	2023/05/01
Road Name:	MH8611.22				
Crossing Name:	Unnamed	**Total Length (metres):**	12.4		
Special Access:		**Special Equipment:**			
Longitude:	-120 42 23.0	**Latitude:**	52 0 48.0		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Sill -Temporary Materials	**# Spans:**	1
Planned Inspection Comments:					

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: 64-134

Site #:	64-134	**Year Superstructure Installed:**		2010	**Structure Type/Class:**	Permanent Bridge	
KM:	1.60	**User km:**	1.60	**Last Inspection Date:**		2020/07/10	
Project File ID #:	10650	**Br.**	02	**Next Inspection Date:**		2023/07/10	
Road Name:	MHB 10650.02						
Crossing Name:	Mann Ck Chasm West FSR			**Total Length (metres):**	10.0		
Special Access:				**Special Equipment:**			
Longitude:	-121 45 9.2			**Latitude:**	51 12 8.6		
Superstructure:	Steel Box Beam	**Abutments (Left/Right):** *(looking downstream)*		Concrete Lock Blocks	**# Spans:**	1	
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: inspect 1 year after install. LHS approach may have some settlement due to lack of compaction during construction. Check on US RHS abutment, stream changes direction just above structure but well rip rapped						

Structure Name: 64-129

Site #:	64-129	**Year Superstructure Installed:**			**Structure Type/Class:**	Permanent Bridge	
KM:	18.00	**User km:**	18.00	**Last Inspection Date:**		2020/07/12	
Project File ID #:	8434	**Br.**	06	**Next Inspection Date:**		2023/07/12	
Road Name:	MHD 8434.06						
Crossing Name:	Wavey 01			**Total Length (metres):**	12.0		
Special Access:				**Special Equipment:**			
Longitude:	-120 30 6.9			**Latitude:**	51 35 42.2		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*		Concrete Lock Blocks	**# Spans:**	1	
Planned Inspection Comments:	IDIR\MRFENNEL on 29-MAR-17: Verify bridge details data.						

Structure Name: 64-131

Site #:	64-131	**Year Superstructure Installed:**		1997	**Structure Type/Class:**	Permanent Bridge	
KM:	6.40	**User km:**	6.40	**Last Inspection Date:**		2020/07/10	
Project File ID #:	5956	**Br.**	15	**Next Inspection Date:**		2023/07/10	
Road Name:	MHH 5956.15						
Crossing Name:	614 Road Unnamed Ck Lang Lake			**Total Length (metres):**	15.4		
Special Access:				**Special Equipment:**			
Longitude:	-120 59 29.8			**Latitude:**	51 58 45.0		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Steel Pipe and Precast Pad	**# Spans:**	1	
Planned Inspection Comments:							

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: 64-027

Site #:	64-027	**Year Superstructure Installed:**	1993	**Structure Type/Class:**	Temporary Bridge
KM:	11.64	**User km:**	11.00	**Last Inspection Date:**	2022/08/31
Project File ID #:	8611	**Br.**	01	**Next Inspection Date:**	2023/08/31
Road Name:	SPANISH CREEK				
Crossing Name:	Deception Cr	**Total Length (metres):**	17.0		
Special Access:		**Special Equipment:**			
Longitude:	-120 34 6.1	**Latitude:**	51 58 56.7		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Precast	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: 64-060

Site #:	64-060	**Year Superstructure Installed:**	1998	**Structure Type/Class:**	Permanent Bridge
KM:	32.00	**User km:**	32.00	**Last Inspection Date:**	2020/07/11
Project File ID #:	8611	**Br.**	01	**Next Inspection Date:**	2023/07/11
Road Name:	SPANISH CREEK				
Crossing Name:	Unnamed	**Total Length (metres):**	18.0		
Special Access:		**Special Equipment:**			
Longitude:	-120 21 49.8	**Latitude:**	52 3 45.8		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Precast	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: 64-059

Site #:	64-059	**Year Superstructure Installed:**	1997	**Structure Type/Class:**	Permanent Bridge
KM:	0.12	**User km:**	1.00	**Last Inspection Date:**	2020/07/11
Project File ID #:	8611	**Br.**	13	**Next Inspection Date:**	2023/07/11
Road Name:	SPANISH/BOUNDARY				
Crossing Name:	Spanish Cr	**Total Length (metres):**	21.0		
Special Access:		**Special Equipment:**			
Longitude:	-120 30 28.8	**Latitude:**	51 58 44.8		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Pile -Permanent Materials	**# Spans:**	1
Planned Inspection Comments:					

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: 64-045

Site #:	64-045	**Year Superstructure Installed:**	1992	**Structure Type/Class:**	Permanent Bridge
KM:	16.61	**User km:**	15.00	**Last Inspection Date:**	2020/07/11
Project File ID #:	8611	**Br.**	07	**Next Inspection Date:**	2023/07/11
Road Name:	SPANISH/NO NAME				
Crossing Name:	Ice Cr	**Total Length (metres):**	12.0		
Special Access:		**Special Equipment:**			
Longitude:	-120 29 20.4	**Latitude:**	52 2 58.0		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Pile -Permanent Materials	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: 64-029

Site #:	64-029	**Year Superstructure Installed:**	1992	**Structure Type/Class:**	Temporary Bridge
KM:	0.10	**User km:**	0.00	**Last Inspection Date:**	2022/09/03
Project File ID #:	6411	**Br.**	01	**Next Inspection Date:**	2023/09/03
Road Name:	SPOUT-OIE LAKE				
Crossing Name:	Eagle Cr	**Total Length (metres):**	12.0		
Special Access:		**Special Equipment:**			
Longitude:	-121 27 38.5	**Latitude:**	52 1 8.8		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Pile -Permanent Materials	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: TKA038

Site #:	64-182	**Year Superstructure Installed:**		**Structure Type/Class:**	Temporary Bridge
KM:	4.00	**User km:**		**Last Inspection Date:**	
Project File ID #:	8434	**Br.**	01	**Next Inspection Date:**	2023/08/18
Road Name:	WAVEY LAKE				
Crossing Name:	Wavey Lake	**Total Length (metres):**	12.2		
Special Access:		**Special Equipment:**			
Longitude:	-120 34 4.8	**Latitude:**	51 31 24.6		
Superstructure:	Steel Box Beam	**Abutments (Left/Right):** *(looking downstream)*	Other	**# Spans:**	1
Planned Inspection Comments:					

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: TKA016

Site #:	64-093	**Year Superstructure Installed:**	2019	**Structure Type/Class:**	Permanent Bridge
KM:	17.80	**User km:**	91.50	**Last Inspection Date:**	
Project File ID #:	8434	**Br.**	01	**Next Inspection Date:**	2023/01/07
Road Name:	WAVEY LAKE				
Crossing Name:	Spectacle Cr	**Total Length (metres):**	19.8		
Special Access:		**Special Equipment:**			
Longitude:	-120 29 32.8	**Latitude:**	51 35 21.6		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: 64-164

Site #:	64-164	**Year Superstructure Installed:**	2019	**Structure Type/Class:**	Permanent Bridge
KM:	2.40	**User km:**	6.90	**Last Inspection Date:**	2020/07/10
Project File ID #:	7456	**Br.**	03	**Next Inspection Date:**	2023/07/10
Road Name:	WILCOX/DEMPSEY				
Crossing Name:	Alexandrea Cr	**Total Length (metres):**	11.0		
Special Access:		**Special Equipment:**			
Longitude:	-121 10 6.4	**Latitude:**	51 49 49.7		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	IDIR\MRFENNEL on 26-MAR-20: One year post installation inspection				

Structure Name: 64-112

Site #:	64-112	**Year Superstructure Installed:**	1993	**Structure Type/Class:**	Major Culvert
KM:	3.60	**User km:**	3.60	**Last Inspection Date:**	2020/07/10
Project File ID #:	7456	**Br.**	06	**Next Inspection Date:**	2023/07/10
Road Name:	WILCOX/WESTMAN CK				
Crossing Name:	Boas Creek	**Total Length (metres):**	28.0		
Special Access:		**Special Equipment:**			
Longitude:	-121 9 14.4	**Latitude:**	51 53 0.5		
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:					

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: 64-107

Site #:	64-107	**Year Superstructure Installed:**	2004	**Structure Type/Class:**	Permanent Bridge
KM:	0.10	**User km:**	0.10	**Last Inspection Date:**	2020/07/10
Project File ID #:	7471	**Br.**	05	**Next Inspection Date:**	2023/07/10
Road Name:					
Crossing Name:	Drewy Chris FSR xing Webb Cr	**Total Length (metres):**	10.0		
Special Access:		**Special Equipment:**			
Longitude:	-120 59 8.7	**Latitude:**	51 44 47.4		
Superstructure:	Steel Box Beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:					

Structure Type/Class Totals

Permanent Bridge Total: 18
Temporary Bridge Total: 14
Major Culvert Total: 4
Woodbox/Log Culvert Total: 1