



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 1 of 6
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: 100 Mile House Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required	Special Access Required	Planned Inspection Comment										
1	64-176	64-176		2023/08/18	P	7357-01	18.3	0	7357	1.00	0.30	Green Lake Outlet
			IDIR\MRFENNEL on 26-MAY-23: One year post installation inspection									
2	64-008	64-008	2020/07/11	2023/07/11	P	6061-06	13.0	0	BOWERS/CANIMRED	1.90	1.90	Canimred Cr
3	64-158	64-158	2021/09/07	2023/09/07	W	6061-02	6.0	0	BOWERS/WINDY	1.00	1.00	Unnamed
			IDIR\MRFENNEL on 23-JUN-17: Dummy dimension information entered. Inspector to grab measurements and verify information.									
4	64-054	64-054	2020/07/16	2023/07/16	P	6061-02	12.0	0	BOWERS/WINDY	8.40	1.00	Cougar Cr
5	64-011	64-011	2020/07/09	2023/07/09	P	5712-01	28.0	0	CLINTON/LOON	21.20	25.00	Bonaparte R
6	64-012	64-012	2020/07/09	2023/07/09	MC	5712-01	18.0	0	CLINTON/LOON	35.80	41.00	Bakers Cattle Underpass
7	64-013	64-013	2020/07/09	2023/07/09	MC	5712-01	20.0	0	CLINTON/LOON	45.50	50.60	Brigade Cr
8	64-079	64-079	2020/07/09	2023/07/09	MC	5712-01	15.0	0	CLINTON/LOON	57.50	62.50	Boulder Cr



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 2 of 6
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: 100 Mile House Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required	Special Access Required	Planned Inspection Comment										
9	64-110	PS 64-110	2020/07/09	2023/07/09	P	5712-07	10.0	0	CLINTON/TULERIC LAKE	11.43	13.80	Trib to Deadman Ck
10	64-179	64-179		2023/08/18	P	6315-01	10.6	0	EAGAN/BONAPARTE	31.00	73.00	Unnamed
			IDIR\MRFENNEL on 03-MAY-23: One year post installation inspection									
11	64-108	64-108	2020/07/10	2023/07/10	P	10076-01	10.0	0	GRAHAM CREEK FSR	0.10	0.10	Graham Cr
12	64-141	TKA002	2021/09/07	2023/09/07	T	8434-10	6.1	0	MH 8434.10	4.00	4.00	Unknown
13	64-149	TKA003	2021/09/07	2023/09/07	T	8434-10	6.1	0	MH 8434.10	5.80	5.80	Unknown
14	64-150	TKA005	2021/09/07	2023/09/07	T	8434-10	6.1	0	MH 8434.10	6.10	6.10	Unknown
15	64-154	TKA-019	2020/07/12	2023/07/12	P	5289-24	12.0	0	MH5289.24	0.50		Noname



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 3 of 6
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: 100 Mile House Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required		Special Access Required	Planned Inspection Comment									
16	64-163	WO1265	2021/09/07	2023/09/07	T	5289-26	12.2	0	MH5289.26	1.40	1.40	Windy Creek
			IDIR\MRFENNEL on 26-FEB-21: Post installation inspection CBR_Conversion on 26-FEB-21:									
17	64-181	64-181		2023/06/01	P	6061-40	12.7	0	MH6061.40	0.90	0.90	Unknown
18	64-175	TKA026	2020/07/13	2023/07/01	T	8434-23	12.2	0	MH8434.23	2.30	2.30	Unknown
			IDIR\PBLUESCH on 31-JAN-20: PB Jan31.2020 Left bank rock pad oversteepened. Monitor abutment stability during hauling. IDIR\MRFENNEL on 30-JAN-20: One year post installation inspection									
19	64-165	WO-1531	2021/09/08	2023/09/08	T	8611-20	9.1	0	MH8611.20	0.50	1.80	Deception Cr
			IDIR\MRFENNEL on 26-MAR-21: One year post installation inspection									
20	64-169	WO2751		2023/05/01	T	8611-21	15.2	0	MH8611.21	3.70	3.70	Unknown
			IDIR\RKEETCH on 25-MAY-22: New Structure installed 2021 CBR_Conversion on 17-FEB-14: Monitor for continued settlement and ensure posted at 2 tonnes. BCTS to remove in 2014, check with them prior to									
21	64-170	TKA030	2022/08/29	2023/06/01	T	8611-21	12.2	0	MH8611.21	3.80	3.80	Unknown
			IDIR\MRFENNEL on 12-MAY-21: One year post installation inspection									
22	64-171	TKA031		2022/05/01	T	8611-21	15.2	0	MH8611.21	4.20	4.20	Unnamed



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 4 of 6
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: 100 Mile House Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required		Special Access Required	Planned Inspection Comment									
23	64-172	PS-054		2023/05/01	T	8611-22	12.2	0	MH8611.22	1.70	1.70	Unnamed
24	64-173	TKA015		2023/05/01	T	8611-22	12.4	0	MH8611.22	2.30	2.30	Unnamed
25	64-134	64-134	2020/07/10	2023/07/10	P	10650-02	10.0	0	MHB 10650.02	1.60	1.60	Mann Ck Chasm West
			CBR_Conversion on 17-FEB-14: inspect 1 year after install. LHS approach may have some settlement due to lack of compaction during construction. Check on US RHS abutment, stream changes direction just above structure but well rip rapped									
26	64-129	64-129	2020/07/12	2023/07/12	P	8434-06	12.0	0	MHD 8434.06	18.00	18.00	Wavey 01
			IDIR\MRFENNEL on 29-MAR-17: Verify bridge details data.									
27	64-131	64-131	2020/07/10	2023/07/10	P	5956-15	15.4	0	MHH 5956.15	6.40	6.40	614 Road Unnamed Ck
28	64-027	64-027	2022/08/31	2023/08/31	T	8611-01	17.0	0	SPANISH CREEK	11.64	11.00	Deception Cr
29	64-060	64-060	2020/07/11	2023/07/11	P	8611-01	18.0	0	SPANISH CREEK	32.00	32.00	Unnamed



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 5 of 6
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: 100 Mile House Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required		Special Access Required	Planned Inspection Comment									
30	64-059	64-059	2020/07/11	2023/07/11	P	8611-13	21.0	0	SPANISH/BOUNDARY	0.12	1.00	Spanish Cr
31	64-045	64-045	2020/07/11	2023/07/11	P	8611-07	12.0	0	SPANISH/NO NAME	16.61	15.00	Ice Cr
32	64-029	64-029	2022/09/03	2023/09/03	T	6411-01	12.0	0	SPOUT-OIE LAKE	0.10	0.00	Eagle Cr
33	64-182	TKA038		2023/08/18	T	8434-01	12.2	0	WAVEY LAKE	4.00		Wavey Lake
34	64-093	TKA016		2023/01/07	P	8434-01	19.8	0	WAVEY LAKE	17.80	91.50	Spectacle Cr
35	64-164	64-164	2020/07/10	2023/07/10	P	7456-03	11.0	0	WILCOX/DEMPSEY	2.40	6.90	Alexandrea Cr
			IDIR\MRFENNEL on 26-MAR-20: One year post installation inspection									
36	64-112	64-112	2020/07/10	2023/07/10	MC	7456-06	28.0	0	WILCOX/WESTMAN CK	3.60	3.60	Boas Creek



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 6 of 6
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: 100 Mile House Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required		Special Access Required	Planned Inspection Comment									
37	64-107	64-107	2020/07/10	2023/07/10	P	7471-05	10.0	0		0.10	0.10	Drewy Chris FSR xing

Permanent Bridge Total: 18

Temporary Bridge Total: 14

Major Culvert Total: 4

Woodbox/Log Culvert Total: 1