



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 1 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: K1117

Site #:	K1117	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	2.01	User km:	29.00	Last Inspection Date:	2022/09/06
Project File ID #:	0814	Br.	15	Next Inspection Date:	2023/09/06
Road Name:	-SKUHOST BRANCH 15				
Crossing Name:	Skuhost #2		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-121 2 20.7		Latitude:	50 20 35.0	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:	IDIR\BPelletT on 09-MAR-23: BP Mar 9-23 Monitor deck and abutment conditions, and ensure appropriate signage is posted with every routine inspection IDIR\DMALWAY on 09-MAR-23: BP Feb 25-22 [Measure-up completed in 2018]				

Structure Name: K966

Site #:	K966	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	2.57	User km:	2.70	Last Inspection Date:	2020/07/04
Project File ID #:	8479	Br.	01	Next Inspection Date:	2023/07/04
Road Name:	ARRASTRA CREEK				
Crossing Name:	Blakeburn Cr		Total Length (metres):	18.0	
Special Access:			Special Equipment:		
Longitude:	-120 44 56.4		Latitude:	49 28 51.6	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: K1092

Site #:	K1092	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	5.48	User km:	5.30	Last Inspection Date:	2022/09/10
Project File ID #:	8479	Br.	01	Next Inspection Date:	2023/09/10
Road Name:	ARRASTRA CREEK				
Crossing Name:	Newton Cr		Total Length (metres):	12.6	
Special Access:			Special Equipment:		
Longitude:	-120 44 20.4		Latitude:	49 27 50.4	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 2 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: TKA008

Site #:	K1609	Year Superstructure Installed:	2013	Structure Type/Class:	Permanent Bridge
KM:	19.10	User km:	19.10	Last Inspection Date:	2022/09/10
Project File ID #:	8479	Br.	01	Next Inspection Date:	2023/09/10
Road Name:	ARRASTRA CREEK				
Crossing Name:	Trib to Arrastra Cr		Total Length (metres):	9.6	
Special Access:			Special Equipment:		
Longitude:	-120 49 15.8		Latitude:	49 23 22.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 27-FEB-23: BP Feb 27-23 Inspection required in 2023 to monitor riprap stability and approach conditions. Confirm which slabs have large chips and/or honeycombing requiring repair.				

Structure Name: 930-B007

Site #:	K1577	Year Superstructure Installed:		Structure Type/Class:	Temporary Bridge
KM:	2.30	User km:	2.30	Last Inspection Date:	2022/09/12
Project File ID #:	8529	Br.	62	Next Inspection Date:	2023/09/12
Road Name:	BRANCH 62				
Crossing Name:	Galena Cr		Total Length (metres):	7.6	
Special Access:			Special Equipment:		
Longitude:	-120 15 12.4		Latitude:	49 48 58.1	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Drill timber sill to determine if any rot has occurred. DA.				

Structure Name: K1699

Site #:	K1699	Year Superstructure Installed:		Structure Type/Class:	Permanent Bridge
KM:	0.20	User km:	13.00	Last Inspection Date:	2020/07/03
Project File ID #:	8529	Br.	45	Next Inspection Date:	2023/07/03
Road Name:	DILLARD-RAMPART LAKE				
Crossing Name:	Unknown		Total Length (metres):	14.0	
Special Access:			Special Equipment:		
Longitude:	-120 29 4.6		Latitude:	49 38 47.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 3 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: 930-B006

Site #:	K1575	Year Superstructure Installed:		Structure Type/Class:	Permanent Bridge
KM:	2.90	User km:		Last Inspection Date:	2022/09/12
Project File ID #:	8529	Br.	60	Next Inspection Date:	2023/09/12
Road Name:	ELKHART-GALENA				
Crossing Name:	Galena Cr		Total Length (metres):	11.6	
Special Access:			Special Equipment:		
Longitude:	-120 16 23.5		Latitude:	49 48 27.6	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\BPelletT on 10-MAR-22: BP Mar 10-22 Measure lean in posts and gap between slabs and cap beams with every annual inspection.				

Structure Name: K1301

Site #:	K1301	Year Superstructure Installed:	2004	Structure Type/Class:	Permanent Bridge
KM:	12.35	User km:	11.90	Last Inspection Date:	2020/07/02
Project File ID #:	8529	Br.	04	Next Inspection Date:	2023/07/02
Road Name:	GALENA				
Crossing Name:	Siwash #1		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-120 23 54.0		Latitude:	49 49 1.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1302

Site #:	K1302	Year Superstructure Installed:	2004	Structure Type/Class:	Permanent Bridge
KM:	13.06	User km:	12.30	Last Inspection Date:	2020/07/02
Project File ID #:	8529	Br.	04	Next Inspection Date:	2023/07/02
Road Name:	GALENA				
Crossing Name:	Siwash #2		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-120 23 33.0		Latitude:	49 48 45.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 4 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: K1303

Site #:	K1303	Year Superstructure Installed:	2003	Structure Type/Class:	Permanent Bridge
KM:	15.90	User km:	15.20	Last Inspection Date:	2020/07/02
Project File ID #:	8529	Br.	04	Next Inspection Date:	2023/07/02
Road Name:	GALENA				
Crossing Name:	Siwash #3		Total Length (metres):	17.0	
Special Access:			Special Equipment:		
Longitude:	-120 21 42.0		Latitude:	49 48 9.0	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: remove the old #k628 and install k1303 plate if not already installed. Also check field km's on all Briddges on the Dillard.				

Structure Name: K2042

Site #:	K2042	Year Superstructure Installed:	2000	Structure Type/Class:	Major Culvert
KM:	17.93	User km:	17.80	Last Inspection Date:	2022/09/12
Project File ID #:	8529	Br.	04	Next Inspection Date:	2023/09/12
Road Name:	GALENA				
Crossing Name:	Elusive Cr		Total Length (metres):	18.0	
Special Access:			Special Equipment:		
Longitude:	-120 20 18.3		Latitude:	49 47 30.6	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	IDIR\BPelletT on 26-APR-23: BP Apr 11-23 Measure wall thickness, corrugation profile, bolt pattern, gradient, and cover heights in 2023 inspection.				

Structure Name: K1396

Site #:	K1396	Year Superstructure Installed:	2004	Structure Type/Class:	Temporary Bridge
KM:	0.00	User km:	16.70	Last Inspection Date:	2022/09/12
Project File ID #:	3601	Br.	16	Next Inspection Date:	2023/09/12
Road Name:	HORNET BR 16				
Crossing Name:	Allison Cr		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-120 33 53.2		Latitude:	49 43 35.3	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 09-MAR-23: BP Mar 9-23 Monitor for deck condition and debris buildup, and ensure appropriate signage is posted with every annual inspection.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 5 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: K915

Site #:	K915	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	0.56	User km:	18.00	Last Inspection Date:	2021/10/12
Project File ID #:	6069	Br.	03	Next Inspection Date:	2023/10/12
Road Name:	LOWER MAKA				
Crossing Name:	Maka Cr	Total Length (metres):	21.3		
Special Access:			Special Equipment:		
Longitude:	-121 3 3.0	Latitude:	49 51 25.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1140

Site #:	K1140	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	19.87	User km:	19.50	Last Inspection Date:	2021/10/12
Project File ID #:	6069	Br.	01	Next Inspection Date:	2023/10/12
Road Name:	MAKA-MURRAY				
Crossing Name:	Unnamed	Total Length (metres):	9.6		
Special Access:			Special Equipment:		
Longitude:	-121 2 19.1	Latitude:	49 50 32.5		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: WO101

Site #:	K1756	Year Superstructure Installed:	1990	Structure Type/Class:	Temporary Bridge
KM:	2.40	User km:	2.40	Last Inspection Date:	
Project File ID #:	7573	Br.	08	Next Inspection Date:	2013/03/13
Road Name:	ME7573.08				
Crossing Name:	Unknown	Total Length (metres):	12.3		
Special Access:			Special Equipment:		
Longitude:	-120 35 51.2	Latitude:	49 1 59.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Other	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 6 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: WO4622

Site #:	K1485	Year Superstructure Installed:	2010	Structure Type/Class:	Temporary Bridge
KM:	1.00	User km:	1.00	Last Inspection Date:	2021/08/05
Project File ID #:	8614	Br.	06	Next Inspection Date:	2023/08/05
Road Name:	ME8614.06				
Crossing Name:	Red Cr	Total Length (metres):	9.1		
Special Access:		Special Equipment:			
Longitude:	-120 13 41.1	Latitude:	49 31 27.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 07-MAR-22: BP Mar 7-22 Sound cribs for rot with every routine inspection, and drill to confirm depth if any is found.				

Structure Name: WO3228

Site #:	K1486	Year Superstructure Installed:	2010	Structure Type/Class:	Temporary Bridge
KM:	0.40	User km:	0.40	Last Inspection Date:	2022/09/11
Project File ID #:	8614	Br.	07	Next Inspection Date:	2023/09/11
Road Name:	ME8614.07				
Crossing Name:	Unnamed Cr	Total Length (metres):	7.6		
Special Access:		Special Equipment:			
Longitude:	-120 15 39.3	Latitude:	49 32 34.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 10-MAR-22: BP Mar 10-22 Annual inspection until deck is replaced. Monitor all wooden deck components for rot progression and safety to road users.				

Structure Name: K650

Site #:	K650	Year Superstructure Installed:	2003	Structure Type/Class:	Temporary Bridge
KM:	10.79	User km:	36.40	Last Inspection Date:	2022/09/10
Project File ID #:	3600	Br.	06	Next Inspection Date:	2023/09/10
Road Name:	NICOMEN				
Crossing Name:	Copper Cr Trib	Total Length (metres):	11.3		
Special Access:		Special Equipment:			
Longitude:	-120 48 7.9	Latitude:	49 12 25.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\BPelletT on 27-APR-22: BP Apr 27-22 Inspector to thoroughly search for fabricator markings and photograph any found				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 7 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: K446

Site #:	K446	Year Superstructure Installed:	2006	Structure Type/Class:	Permanent Bridge
KM:	20.39	User km:	21.00	Last Inspection Date:	2021/10/13
Project File ID #:	7573	Br.	01	Next Inspection Date:	2023/10/13
Road Name:	PASAYTEN RIVER				
Crossing Name:	Pasayten R	Total Length (metres):	30.5		
Special Access:			Special Equipment:		
Longitude:	-120 32 42.3	Latitude:	49 1 29.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K447

Site #:	K447	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:	20.79	User km:	21.30	Last Inspection Date:	2021/10/13
Project File ID #:	7573	Br.	01	Next Inspection Date:	2023/10/13
Road Name:	PASAYTEN RIVER				
Crossing Name:	Peeve Cr	Total Length (metres):	15.2		
Special Access:			Special Equipment:		
Longitude:	-120 32 39.6	Latitude:	49 1 18.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1309

Site #:	K1309	Year Superstructure Installed:	2003	Structure Type/Class:	Permanent Bridge
KM:	0.45	User km:	12.60	Last Inspection Date:	2020/07/04
Project File ID #:	0919	Br.	03	Next Inspection Date:	2023/07/04
Road Name:	PLACER CREEK				
Crossing Name:	Watson Cr	Total Length (metres):	8.6		
Special Access:			Special Equipment:		
Longitude:	-120 29 26.6	Latitude:	49 10 14.4		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 8 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: K1310

Site #:	K1310	Year Superstructure Installed:	2003	Structure Type/Class:	Permanent Bridge
KM:	3.00	User km:	15.50	Last Inspection Date:	2020/07/04
Project File ID #:	0919	Br.	03	Next Inspection Date:	2023/07/04
Road Name:	PLACER CREEK				
Crossing Name:	Lynx Cr		Total Length (metres):	9.6	
Special Access:			Special Equipment:		
Longitude:	-120 29 43.8		Latitude:	49 9 26.6	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: WO-1634

Site #:	K1722	Year Superstructure Installed:	2018	Structure Type/Class:	Temporary Bridge
KM:	0.50	User km:	0.50	Last Inspection Date:	2022/09/30
Project File ID #:	10273	Br.	14	Next Inspection Date:	2023/09/30
Road Name:	PLATEAU LAKE				
Crossing Name:	Unknown		Total Length (metres):	9.1	
Special Access:			Special Equipment:		
Longitude:	-120 17 8.6		Latitude:	50 18 39.3	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 17-MAR-22: BP Mar 17-22 Planned for deactivation in 2022 or 2023. Check with BCTS if site has been deactivated before inspecting.				

Structure Name: K682

Site #:	K682	Year Superstructure Installed:	1993	Structure Type/Class:	Permanent Bridge
KM:	29.19	User km:	0.50	Last Inspection Date:	2022/09/06
Project File ID #:	4669	Br.	03	Next Inspection Date:	2023/09/06
Road Name:	PROSPECT BR 03				
Crossing Name:	Spius Cr		Total Length (metres):	16.0	
Special Access:			Special Equipment:		
Longitude:	-121 1 45.7		Latitude:	50 8 9.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Cast in Place	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Do not inspect prior to August 15 so as to allow for lower water levels to assess abutments appropriately. MRF 11/2013				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 9 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: K1438

Site #:	K1438	Year Superstructure Installed:	2008	Structure Type/Class:	Permanent Bridge
KM:	12.24	User km:	25.50	Last Inspection Date:	2021/09/17
Project File ID #:	4669	Br.	02	Next Inspection Date:	2022/09/17
Road Name:	PROSPECT MINER A				
Crossing Name:	Silver Cr	Total Length (metres):	11.6		
Special Access:		Special Equipment:			
Longitude:	-121 10 36.4	Latitude:	49 58 10.6		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\BLUESCH on 23-JAN-19: PB Jan23.2019 Continue to monitor left bank scour at toe of rip rap (upstream). Approaches require fill to ensure safe traffic, slab girder ends are exposed and a hazard to public traffic.				

Structure Name: K1033

Site #:	K1033	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	0.27	User km:	0.20	Last Inspection Date:	2020/07/03
Project File ID #:	8614	Br.	01	Next Inspection Date:	2023/07/03
Road Name:	RED CREEK				
Crossing Name:	Hayes Cr	Total Length (metres):	21.3		
Special Access:		Special Equipment:			
Longitude:	-120 24 34.2	Latitude:	49 34 12.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1567

Site #:	K1567	Year Superstructure Installed:	2013	Structure Type/Class:	Permanent Bridge
KM:	10.40	User km:	10.40	Last Inspection Date:	2020/07/03
Project File ID #:	8614	Br.	01	Next Inspection Date:	2023/07/03
Road Name:	RED CREEK				
Crossing Name:	unamed	Total Length (metres):	11.0		
Special Access:		Special Equipment:			
Longitude:	-120 20 21.7	Latitude:	49 31 16.9		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 13-FEB-18: na				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 10 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: K1499

Site #:	K1499	Year Superstructure Installed:	2010	Structure Type/Class:	Permanent Bridge
KM:	19.00	User km:	19.00	Last Inspection Date:	2020/07/03
Project File ID #:	8614	Br.	01	Next Inspection Date:	2023/07/03
Road Name:	RED CREEK				
Crossing Name:	unkown	Total Length (metres):	8.6		
Special Access:			Special Equipment:		
Longitude:	-120 15 30.6	Latitude:	49 31 59.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K408A

Site #:	K408	Year Superstructure Installed:	2010	Structure Type/Class:	Permanent Bridge
KM:	36.88	User km:	38.60	Last Inspection Date:	2020/07/03
Project File ID #:	8614	Br.	01	Next Inspection Date:	2023/07/03
Road Name:	RED CREEK				
Crossing Name:	Alaric Cr	Total Length (metres):	12.6		
Special Access:			Special Equipment:		
Longitude:	-120 6 30.5	Latitude:	49 35 16.4		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: One year post construction inspection. DA				

Structure Name: K406

Site #:	K406	Year Superstructure Installed:	2001	Structure Type/Class:	Permanent Bridge
KM:	40.59	User km:	42.30	Last Inspection Date:	2022/09/11
Project File ID #:	8614	Br.	01	Next Inspection Date:	2023/09/11
Road Name:	RED CREEK				
Crossing Name:	McNulty Cr	Total Length (metres):	12.6		
Special Access:			Special Equipment:		
Longitude:	-120 5 33.4	Latitude:	49 34 20.2		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 11 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: WO3511

Site #:	K351	Year Superstructure Installed:	2022	Structure Type/Class:	Temporary Bridge
KM:	0.14	User km:	27.60	Last Inspection Date:	2022/08/13
Project File ID #:	7666	Br.	01	Next Inspection Date:	2023/08/13
Road Name:	SALMON RIVER				
Crossing Name:	Salmon R	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-119 57 53.4	Latitude:	50 19 6.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: K351

Site #:	K351	Year Superstructure Installed:	1983	Structure Type/Class:	Permanent Bridge
KM:	0.14	User km:	27.60	Last Inspection Date:	2021/10/07
Project File ID #:	7666	Br.	01	Next Inspection Date:	2022/10/07
Road Name:	SALMON RIVER				
Crossing Name:	Salmon R	Total Length (metres):	6.0		
Special Access:		Special Equipment:			
Longitude:	-119 57 53.4	Latitude:	50 19 6.6		
Superstructure:	Concrete Cast in Place	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 13-FEB-18: na				

Structure Name: K1512

Site #:	K1512	Year Superstructure Installed:	2007	Structure Type/Class:	Major Culvert
KM:	0.20	User km:	14.50	Last Inspection Date:	2022/09/06
Project File ID #:	0814	Br.	40	Next Inspection Date:	2023/09/06
Road Name:	SKUHUN-CALLING LAKE				
Crossing Name:	Calling lake OverFlow	Total Length (metres):	9.8		
Special Access:		Special Equipment:			
Longitude:	-121 6 43.3	Latitude:	50 27 43.1		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 12 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: K626

Site #:	K626	Year Superstructure Installed:	2001	Structure Type/Class:	Permanent Bridge
KM:	3.66	User km:	19.50	Last Inspection Date:	2022/09/07
Project File ID #:	4332	Br.	02	Next Inspection Date:	2023/09/07
Road Name:	SPIUS SOUTH				
Crossing Name:	S Fork Spius		Total Length (metres):	17.4	
Special Access:			Special Equipment:		
Longitude:	-121 7 7.8		Latitude:	49 54 39.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K658

Site #:	K658	Year Superstructure Installed:	1993	Structure Type/Class:	Permanent Bridge
KM:	18.61	User km:	18.00	Last Inspection Date:	2020/07/04
Project File ID #:	9397	Br.	01	Next Inspection Date:	2023/07/04
Road Name:	SUNDAY SUMMIT				
Crossing Name:	Copper Cr #2		Total Length (metres):	18.0	
Special Access:			Special Equipment:		
Longitude:	-120 41 1.5		Latitude:	49 11 34.5	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K671

Site #:	K671	Year Superstructure Installed:	1993	Structure Type/Class:	Major Culvert
KM:	7.59	User km:	6.70	Last Inspection Date:	2019/10/06
Project File ID #:	1045	Br.	02	Next Inspection Date:	2022/10/06
Road Name:	THYNNE-LOWER MCPHAIL				
Crossing Name:	McPhail Cr		Total Length (metres):	18.0	
Special Access:			Special Equipment:		
Longitude:	-120 52 36.3		Latitude:	49 43 38.9	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 13 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: K853

Site #:	K853	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	8.25	User km:	8.30	Last Inspection Date:	2020/07/05
Project File ID #:	8528	Br.	01	Next Inspection Date:	2023/07/05
Road Name:	TULAMEEN				
Crossing Name:	Britton Cr		Total Length (metres):	16.0	
Special Access:			Special Equipment:		
Longitude:	-120 59 2.0		Latitude:	49 35 14.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K873

Site #:	K873	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	12.44	User km:	13.00	Last Inspection Date:	2020/07/05
Project File ID #:	8528	Br.	01	Next Inspection Date:	2023/07/05
Road Name:	TULAMEEN				
Crossing Name:	Eagle Cr		Total Length (metres):	27.4	
Special Access:			Special Equipment:		
Longitude:	-120 57 4.6		Latitude:	49 33 40.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K874

Site #:	K874	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	18.35	User km:	18.50	Last Inspection Date:	2020/07/05
Project File ID #:	8528	Br.	01	Next Inspection Date:	2023/07/05
Road Name:	TULAMEEN				
Crossing Name:	Illal Cr		Total Length (metres):	21.3	
Special Access:			Special Equipment:		
Longitude:	-120 57 43.9		Latitude:	49 31 52.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 14 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: K457

Site #:	K457	Year Superstructure Installed:	1984	Structure Type/Class:	Permanent Bridge
KM:	21.62	User km:	21.60	Last Inspection Date:	2022/09/08
Project File ID #:	8528	Br.	01	Next Inspection Date:	2023/09/08
Road Name:	TULAMEEN				
Crossing Name:	McGee Cr	Total Length (metres):	9.6		
Special Access:		Special Equipment:			
Longitude:	-120 57 13.8	Latitude:	49 30 44.8		
Superstructure:	Concrete Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 21-FEB-20: PB Feb21,2020 assess metal tabs on deck connecting box beam girder				

Structure Name: K459

Site #:	K459	Year Superstructure Installed:	1984	Structure Type/Class:	Permanent Bridge
KM:	31.21	User km:	30.80	Last Inspection Date:	2022/09/09
Project File ID #:	8528	Br.	01	Next Inspection Date:	2023/09/09
Road Name:	TULAMEEN				
Crossing Name:	Railroad Cr	Total Length (metres):	6.1		
Special Access:		Special Equipment:			
Longitude:	-121 0 9.6	Latitude:	49 27 3.0		
Superstructure:	Concrete Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Cast in Place	# Spans:	1
Planned Inspection Comments:					

Structure Name: K465

Site #:	K465	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	50.96	User km:	52.00	Last Inspection Date:	2022/09/09
Project File ID #:	8528	Br.	01	Next Inspection Date:	2023/09/09
Road Name:	TULAMEEN				
Crossing Name:	White Cloud Cr	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-120 59 51.0	Latitude:	49 20 55.2		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 15 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: K466

Site #:	K466	Year Superstructure Installed:	1986	Structure Type/Class:	Permanent Bridge
KM:	0.12	User km:	0.20	Last Inspection Date:	2022/09/08
Project File ID #:	8528	Br.	02	Next Inspection Date:	2023/09/08
Road Name:	TULAMEEN-CHAMPION				
Crossing Name:	Tulameen R		Total Length (metres):	28.0	
Special Access:			Special Equipment:	Peeper Truck	
Longitude:	-120 57 15.0		Latitude:	49 29 5.3	
Superstructure:	Steel I-beam	Abutments (Left/Right): <i>(looking downstream)</i>	Concrete Cast in Place	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 15-FEB-16: Check the monitor item for the wing wall measurements from top girder flange to flat on wing-walls. See the measures and sketch in the attach doc and folders tab from 2013. DA. Peeper inspecton require in 2012 at same time as K636.				

Structure Name: K483

Site #:	K483	Year Superstructure Installed:	1989	Structure Type/Class:	Permanent Bridge
KM:	13.60	User km:	10.00	Last Inspection Date:	2022/09/10
Project File ID #:	8528	Br.	02	Next Inspection Date:	2023/09/10
Road Name:	TULAMEEN-CHAMPION				
Crossing Name:	Champion Cr		Total Length (metres):	22.9	
Special Access:			Special Equipment:		
Longitude:	-120 55 13.8		Latitude:	49 26 56.8	
Superstructure:	Steel I-beam	Abutments (Left/Right): <i>(looking downstream)</i>	Concrete Cast in Place	# Spans:	1
Planned Inspection Comments:					

Structure Name: TKA028

Site #:	K421	Year Superstructure Installed:	2021	Structure Type/Class:	Temporary Bridge
KM:	12.80	User km:	13.00	Last Inspection Date:	2022/09/09
Project File ID #:	0814	Br.	01	Next Inspection Date:	2023/09/09
Road Name:					
Crossing Name:	Skuhost Cr		Total Length (metres):	12.2	
Special Access:	ATV		Special Equipment:		
Longitude:	-121 1 59.5		Latitude:	50 19 13.1	
Superstructure:	Steel Box Beam	Abutments (Left/Right): <i>(looking downstream)</i>	Other	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 16 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: TKO-0037

Site #:	K1770	Year Superstructure Installed:	2021	Structure Type/Class:	Temporary Bridge
KM:	15.10	User km:	18.00	Last Inspection Date:	
Project File ID #:	0814	Br.	01	Next Inspection Date:	2022/08/01
Road Name:					
Crossing Name:	unknown	Total Length (metres):	12.2		
Special Access:			Special Equipment:		
Longitude:	-121 57 3.6	Latitude:	50 19 32.1		
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: K838

Site #:	K838	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	0.05	User km:	0.00	Last Inspection Date:	2022/08/27
Project File ID #:	7649	Br.	02	Next Inspection Date:	2023/08/27
Road Name:	-BURKHOLDER B				
Crossing Name:	Yalakom B	Total Length (metres):	16.0		
Special Access:			Special Equipment:		
Longitude:	-122 25 20.4	Latitude:	51 0 52.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\BPelletT on 01-MAR-23: BP Mar 1-23 Annual inspection required until curbs are replaced				

Structure Name: K882

Site #:	K882	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	1.17	User km:	0.10	Last Inspection Date:	2019/07/10
Project File ID #:	4768	Br.	01	Next Inspection Date:	2022/07/10
Road Name:	4768				
Crossing Name:	Kwoiek #1	Total Length (metres):	24.6		
Special Access:			Special Equipment:		
Longitude:	-121 34 39.8	Latitude:	50 6 16.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 17 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: K544

Site #:	K544	Year Superstructure Installed:	1989	Structure Type/Class:	Temporary Bridge
KM:	2.90	User km:	2.00	Last Inspection Date:	2021/10/12
Project File ID #:	4768	Br.	01	Next Inspection Date:	2023/10/12
Road Name:	4768				
Crossing Name:	Kwoiek #3		Total Length (metres):	19.3	
Special Access:			Special Equipment:		
Longitude:	-121 35 47.1		Latitude:	50 6 54.3	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: K890A

Site #:	K890	Year Superstructure Installed:	2011	Structure Type/Class:	Temporary Bridge
KM:	3.69	User km:	3.80	Last Inspection Date:	2020/06/23
Project File ID #:	4768	Br.	01	Next Inspection Date:	2022/06/23
Road Name:	4768				
Crossing Name:	Kwoiek #4		Total Length (metres):	26.8	
Special Access:			Special Equipment:		
Longitude:	-121 36 20.7		Latitude:	50 7 1.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: K546A

Site #:	K546	Year Superstructure Installed:	2011	Structure Type/Class:	Temporary Bridge
KM:	4.53	User km:	4.70	Last Inspection Date:	2020/06/23
Project File ID #:	4768	Br.	01	Next Inspection Date:	2022/06/23
Road Name:	4768				
Crossing Name:	Kwoiek #5		Total Length (metres):	26.8	
Special Access:			Special Equipment:		
Longitude:	-121 37 1.1		Latitude:	50 6 54.6	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 18 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: K547

Site #:	K547	Year Superstructure Installed:	1989	Structure Type/Class:	Permanent Bridge
KM:	12.29	User km:	12.60	Last Inspection Date:	2020/06/23
Project File ID #:	4768	Br.	01	Next Inspection Date:	2023/06/23
Road Name:	4768				
Crossing Name:	Kwoiek #6		Total Length (metres):	16.3	
Special Access:			Special Equipment:		
Longitude:	-121 42 28.8		Latitude:	50 8 16.8	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:					

Structure Name: K1168

Site #:	K1168	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	0.62	User km:	1.50	Last Inspection Date:	2019/07/09
Project File ID #:	9856	Br.	01	Next Inspection Date:	2022/07/09
Road Name:	9856				
Crossing Name:	Tommy Cr		Total Length (metres):	23.6	
Special Access:	Helicopter		Special Equipment:		
Longitude:	-122 31 24.6		Latitude:	50 50 26.9	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: K1304

Site #:	K1304	Year Superstructure Installed:	2001	Structure Type/Class:	Woodbox/Log Culvert
KM:	6.53	User km:	2.70	Last Inspection Date:	2019/07/09
Project File ID #:	9856	Br.	01	Next Inspection Date:	2021/07/09
Road Name:	9856				
Crossing Name:	Unnamed		Total Length (metres):	10.0	
Special Access:	Helicopter		Special Equipment:		
Longitude:	-122 31 20.4		Latitude:	50 49 3.6	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Heli access required, not to be inspected with Routine inspections. Check with district prior to inspections. DA 2010.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 19 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: K528

Site #:	K528	Year Superstructure Installed:	1987	Structure Type/Class:	Permanent Bridge
KM:	5.11	User km:	5.00	Last Inspection Date:	2020/06/25
Project File ID #:	8490	Br.	01	Next Inspection Date:	2023/06/25
Road Name:	BRIDGE RIVER				
Crossing Name:	Ault Cr		Total Length (metres):	28.5	
Special Access:			Special Equipment:	Peeper Truck	
Longitude:	-122 54 41.3		Latitude:	50 48 49.4	
Superstructure:	Concrete I/T Beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Peep inspection required every 10 years. DA				

Structure Name: K618

Site #:	K618	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	8.00	User km:	7.90	Last Inspection Date:	2020/06/25
Project File ID #:	8490	Br.	01	Next Inspection Date:	2023/06/25
Road Name:	BRIDGE RIVER				
Crossing Name:	Paul Cr		Total Length (metres):	24.9	
Special Access:			Special Equipment:		
Longitude:	-122 56 23.5		Latitude:	50 49 15.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K834

Site #:	K834	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	29.75	User km:	29.40	Last Inspection Date:	2020/06/25
Project File ID #:	8490	Br.	01	Next Inspection Date:	2023/06/25
Road Name:	BRIDGE RIVER				
Crossing Name:	McParlon Cr		Total Length (metres):	36.0	
Special Access:			Special Equipment:	Peeper Truck	
Longitude:	-123 12 25.1		Latitude:	50 48 55.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Next peeper inspection for this bridge will occur in 2017. DA. Feb 2014. On a ten year frequency.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 20 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: 020-07

Site #:	K1588	Year Superstructure Installed:		Structure Type/Class:	Temporary Bridge
KM:	0.10	User km:	0.10	Last Inspection Date:	2021/09/03
Project File ID #:	10806	Br.	01	Next Inspection Date:	2023/09/03
Road Name:	DOWNTON CREEK				
Crossing Name:	Cayoosh Cr	Total Length (metres):	36.6		
Special Access:		Special Equipment:			
Longitude:	-122 5 39.3	Latitude:	50 35 2.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	BCEID\SENTENG on 15-JUL-16: Assess rot in timber deck modules as MOTI only replaced running deck in 2016, sub-deck appeared to be getting rotten based on DA professional follow up in July 2016.				

Structure Name: K1592

Site #:	K1592	Year Superstructure Installed:	2007	Structure Type/Class:	Temporary Bridge
KM:	3.40	User km:		Last Inspection Date:	2021/09/03
Project File ID #:	10806	Br.	01	Next Inspection Date:	2023/09/03
Road Name:	DOWNTON CREEK				
Crossing Name:	Downton Cr	Total Length (metres):	12.5		
Special Access:		Special Equipment:			
Longitude:	-122 7 50.2	Latitude:	50 35 17.6		
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: K534

Site #:	K534	Year Superstructure Installed:	1995	Structure Type/Class:	Temporary Bridge
KM:	0.63	User km:	7.50	Last Inspection Date:	2022/08/26
Project File ID #:	9150	Br.	03	Next Inspection Date:	2023/08/26
Road Name:	EAST HOPE CREEK				
Crossing Name:	Unnamed	Total Length (metres):	12.3		
Special Access:		Special Equipment:			
Longitude:	-122 57 12.4	Latitude:	50 37 20.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\BPelletT on 07-MAR-23: BP Mar 7-23 Carefully assess crib conditions for rot progression and further crushing with every annual inspection				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 21 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: K532

Site #:	K532	Year Superstructure Installed:	2005	Structure Type/Class:	Temporary Bridge
KM:	8.13	User km:	8.50	Last Inspection Date:	2022/08/26
Project File ID #:	9150	Br.	01	Next Inspection Date:	2023/08/26
Road Name:	HOPE CREEK				
Crossing Name:	West Hope Cr		Total Length (metres):	10.7	
Special Access:			Special Equipment:		
Longitude:	-122 57 40.2		Latitude:	50 37 3.0	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 07-MAR-23: .				

Structure Name: K914

Site #:	K914	Year Superstructure Installed:	1995	Structure Type/Class:	Temporary Bridge
KM:	0.59	User km:	9.80	Last Inspection Date:	2022/08/26
Project File ID #:	9150	Br.	05	Next Inspection Date:	2023/08/26
Road Name:	HOPE CREEK BR 05				
Crossing Name:	Hope Cr		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-122 58 1.2		Latitude:	50 36 23.0	
Superstructure:	Log Stringers		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	IDIR\BPellet on 17-MAR-22: BP Mar 17-22 Drill all sills and stringers for rot with every annual inspection. Ensure that bridge is posted closed if it has not been barricaded. IDIR\DMALWAY on 21-FEB-18: Post closed upon next inspection in 2019 if deck components deteriorate and are not replaced.				

Structure Name: K520

Site #:	K520	Year Superstructure Installed:	1987	Structure Type/Class:	Permanent Bridge
KM:	0.00	User km:	0.60	Last Inspection Date:	2020/06/25
Project File ID #:	10194	Br.	01	Next Inspection Date:	2023/06/25
Road Name:	HURLEY RIVER NORTH				
Crossing Name:	Bridge R		Total Length (metres):	38.2	
Special Access:			Special Equipment:	Peeper Truck	
Longitude:	-122 50 57.2		Latitude:	50 50 43.8	
Superstructure:	Concrete I/T Beam		Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 22-JAN-18: peeper inspection in 2017, then in 10 year frequency. DA				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 22 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: K1021

Site #:	K1021	Year Superstructure Installed:	1970	Structure Type/Class:	Temporary Bridge
KM:	0.01	User km:	5.10	Last Inspection Date:	2011/10/19
Project File ID #:	10194	Br.	04	Next Inspection Date:	2013/10/19
Road Name:	HURLEY RIVER SOUTH				
Crossing Name:	Unnamed	Total Length (metres):	15.2		
Special Access:	Helicopter	Special Equipment:			
Longitude:	-123 5 3.6	Latitude:	50 39 19.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Quick inspection, as no vehicular access.				

Structure Name: K535

Site #:	K535	Year Superstructure Installed:	1980	Structure Type/Class:	Temporary Bridge
KM:	0.50	User km:	4.30	Last Inspection Date:	2011/10/19
Project File ID #:	10194	Br.	05	Next Inspection Date:	2013/10/19
Road Name:	HURLEY RVR-SOUTH				
Crossing Name:	Hurley R	Total Length (metres):	15.6		
Special Access:	Helicopter	Special Equipment:			
Longitude:	-123 4 27.6	Latitude:	50 39 48.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Just a quick ocular inspection as no vehicular access.				

Structure Name: K1006

Site #:	K1006	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	25.28	User km:	24.00	Last Inspection Date:	2020/06/25
Project File ID #:	8059	Br.	01	Next Inspection Date:	2023/06/25
Road Name:	KINGDOM LAKE BR 01				
Crossing Name:	Unnamed	Total Length (metres):	18.3		
Special Access:		Special Equipment:			
Longitude:	-122 38 25.5	Latitude:	50 40 52.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 23 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: K1007

Site #:	K1007	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	25.71	User km:	24.40	Last Inspection Date:	2022/08/25
Project File ID #:	8059	Br.	01	Next Inspection Date:	2023/08/25
Road Name:	KINGDOM LAKE BR 01				
Crossing Name:	Cadwallader Cr	Total Length (metres):	15.2		
Special Access:	Bicycle	Special Equipment:			
Longitude:	-122 38 34.6	Latitude:	50 40 39.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\BPellet on 24-FEB-22: BP Feb 24-22 Ensure site is posted closed or barricaded. Note any signs of traffic. Monitor for damage to girders bearing directly on lock blocks. CBR_Conversion on 17-FEB-14: Ensure posted at 20 tonnes load restriction. DA. 2012.				

Structure Name: K639

Site #:	K639	Year Superstructure Installed:	2003	Structure Type/Class:	Permanent Bridge
KM:	1.25	User km:	12.50	Last Inspection Date:	2022/08/25
Project File ID #:	8059	Br.	03	Next Inspection Date:	2023/08/25
Road Name:	KINGDOM LAKE BR 03				
Crossing Name:	Crazy #1	Total Length (metres):	14.0		
Special Access:		Special Equipment:			
Longitude:	-122 44 26.0	Latitude:	50 44 48.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\BPellet on 26-APR-23: BP Apr 26-23 Monitor left ballast wall condition annually until it's repaired.				

Structure Name: K640

Site #:	K640	Year Superstructure Installed:	2003	Structure Type/Class:	Temporary Bridge
KM:	1.43	User km:	12.60	Last Inspection Date:	2021/09/02
Project File ID #:	8059	Br.	03	Next Inspection Date:	2023/09/02
Road Name:	KINGDOM LAKE BR 03				
Crossing Name:	Crazy #2	Total Length (metres):	15.2		
Special Access:		Special Equipment:			
Longitude:	-122 44 19.6	Latitude:	50 44 45.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\BPellet on 25-FEB-22: BP Feb 25-22 Routine inspection in 2023 needs to include the PIC from 2017. IDIR\DMALWAY on 25-JAN-17: Measure up girder depth, flange width etc. Measure C/c span from bearing stiffener to bearing stiffener. As we want to verify we have the right shop drawings on file. Better picture of date stamp on steel required.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 24 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: K1342

Site #:	K1342	Year Superstructure Installed:	2005	Structure Type/Class:	Temporary Bridge
KM:	0.20	User km:	16.00	Last Inspection Date:	2021/09/02
Project File ID #:	8059	Br.	05	Next Inspection Date:	2023/09/02
Road Name:	KINGDON-CHISM BR 05				
Crossing Name:	Cadwallader Cr	Total Length (metres):	24.4		
Special Access:		Special Equipment:			
Longitude:	-122 41 32.3	Latitude:	50 43 59.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\BPellet on 25-FEB-22: BP Feb 25-22 Drill for rot depth in tiebacks and in cribs at ends and under girders with every routine inspection. Determine species if practicable.				

Structure Name: K1345

Site #:	K1345	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:	0.53	User km:	12.60	Last Inspection Date:	2020/06/25
Project File ID #:	8059	Br.	05	Next Inspection Date:	2023/06/25
Road Name:	KINGDON-CHISM BR 05				
Crossing Name:	Chism Cr.	Total Length (metres):	18.3		
Special Access:		Special Equipment:			
Longitude:	-122 41 38.4	Latitude:	50 43 49.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K602

Site #:	K602	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	3.22	User km:	3.20	Last Inspection Date:	2020/06/24
Project File ID #:	5496	Br.	01	Next Inspection Date:	2023/06/24
Road Name:	MUD CREEK BR 01				
Crossing Name:	Jim Cr	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-122 34 54.0	Latitude:	50 55 29.4		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 25 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: K601

Site #:	K601	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	14.01	User km:	14.10	Last Inspection Date:	2020/06/24
Project File ID #:	5496	Br.	01	Next Inspection Date:	2023/06/24
Road Name:	MUD CREEK BR 01				
Crossing Name:	Liza Cr	Total Length (metres):	18.3		
Special Access:			Special Equipment:		
Longitude:	-122 40 41.4	Latitude:	50 57 24.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K503

Site #:	K503	Year Superstructure Installed:	2001	Structure Type/Class:	Permanent Bridge
KM:	24.35	User km:	24.90	Last Inspection Date:	2020/06/24
Project File ID #:	5496	Br.	01	Next Inspection Date:	2023/06/24
Road Name:	MUD CREEK BR 01				
Crossing Name:	Noaxe Cr	Total Length (metres):	13.6		
Special Access:			Special Equipment:		
Longitude:	-122 44 57.0	Latitude:	51 0 52.8		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Monitor items from original construction. DA				

Structure Name: K620

Site #:	K620	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	1.10	User km:	0.90	Last Inspection Date:	2020/06/24
Project File ID #:	5496	Br.	05	Next Inspection Date:	2023/06/24
Road Name:	MUD-PARADISE CREEK				
Crossing Name:	Mud Cr #1	Total Length (metres):	27.5		
Special Access:			Special Equipment:		
Longitude:	-122 46 33.6	Latitude:	51 3 8.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 26 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: K619

Site #:	K619	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	1.64	User km:	1.60	Last Inspection Date:	2020/06/24
Project File ID #:	5496	Br.	05	Next Inspection Date:	2023/06/24
Road Name:	MUD-PARADISE CREEK				
Crossing Name:	Relay Cr	Total Length (metres):	21.4		
Special Access:		Special Equipment:			
Longitude:	-122 46 44.8	Latitude:	51 3 21.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K506

Site #:	K506	Year Superstructure Installed:	2000	Structure Type/Class:	Temporary Bridge
KM:	0.62	User km:	107.50	Last Inspection Date:	2021/09/02
Project File ID #:	5496	Br.	04	Next Inspection Date:	2023/09/02
Road Name:	MUD-TYAUGHTON CRK				
Crossing Name:	Tyaughton Cr	Total Length (metres):	27.8		
Special Access:		Special Equipment:			
Longitude:	-122 45 19.6	Latitude:	51 1 29.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: K563

Site #:	K563	Year Superstructure Installed:	1997	Structure Type/Class:	Temporary Bridge
KM:	5.20	User km:	7.00	Last Inspection Date:	2022/09/05
Project File ID #:	6879	Br.	05	Next Inspection Date:	2023/09/05
Road Name:	MURRAY CREEK N-WEST				
Crossing Name:	Unnamed	Total Length (metres):	6.2		
Special Access:		Special Equipment:			
Longitude:	-121 32 20.2	Latitude:	50 33 0.9		
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 15-FEB-16: annual inspection				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 27 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: K570

Site #:	K570	Year Superstructure Installed:	1970	Structure Type/Class:	Temporary Bridge
KM:	1.70	User km:	18.00	Last Inspection Date:	2022/09/05
Project File ID #:	6879	Br.	04	Next Inspection Date:	2023/09/05
Road Name:	MURRAY CREEK WEST				
Crossing Name:	Murray Cr North	Total Length (metres):	6.2		
Special Access:			Special Equipment:		
Longitude:	-121 31 15.6	Latitude:	50 30 15.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): <i>(looking downstream)</i>	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\BPellet on 25-FEB-22: BP Feb 25-22 Monitor contact between girders and lock blocks, and note any damage to girders. CBR_Conversion on 17-FEB-14:				

Structure Name: K1393

Site #:	K1393	Year Superstructure Installed:	2006	Structure Type/Class:	Temporary Bridge
KM:	5.01	User km:	5.40	Last Inspection Date:	2021/09/01
Project File ID #:	9177	Br.	01	Next Inspection Date:	2023/09/01
Road Name:	NOEL CREEK				
Crossing Name:	Noel Cr	Total Length (metres):	27.4		
Special Access:			Special Equipment:		
Longitude:	-122 48 8.7	Latitude:	50 44 1.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): <i>(looking downstream)</i>	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: K539A

Site #:	K539	Year Superstructure Installed:	2013	Structure Type/Class:	Permanent Bridge
KM:	9.33	User km:	9.30	Last Inspection Date:	2020/06/24
Project File ID #:	8151	Br.	01	Next Inspection Date:	2023/06/24
Road Name:	SLIM CREEK				
Crossing Name:	Roxey Cr	Total Length (metres):	15.6		
Special Access:			Special Equipment:		
Longitude:	-122 56 7.5	Latitude:	50 54 58.5		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): <i>(looking downstream)</i>	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 28 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: K1311

Site #:	K1311	Year Superstructure Installed:	1982	Structure Type/Class:	Major Culvert
KM:	18.71	User km:	18.80	Last Inspection Date:	2020/06/24
Project File ID #:	8151	Br.	01	Next Inspection Date:	2023/06/24
Road Name:	SLIM CREEK				
Crossing Name:	Erin Creek	Total Length (metres):	12.0		
Special Access:		Special Equipment:			
Longitude:	-122 59 16.7	Latitude:	50 56 25.0		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 09-FEB-18: n/a BCEID\SENTENG on 09-FEB-18: n/a				

Structure Name: PS-024

Site #:	K540	Year Superstructure Installed:	2013	Structure Type/Class:	Temporary Bridge
KM:	24.02	User km:	24.30	Last Inspection Date:	2021/09/02
Project File ID #:	8151	Br.	01	Next Inspection Date:	2023/09/02
Road Name:	SLIM CREEK				
Crossing Name:	Slim Cr	Total Length (metres):	21.3		
Special Access:		Special Equipment:			
Longitude:	-123 6 0.2	Latitude:	50 55 5.1		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1587

Site #:	K1587	Year Superstructure Installed:		Structure Type/Class:	Major Culvert
KM:	5.90	User km:		Last Inspection Date:	
Project File ID #:	10808	Br.	01	Next Inspection Date:	2019/06/17
Road Name:	VAN HORLICK				
Crossing Name:	Unnamed	Total Length (metres):	9.0		
Special Access:		Special Equipment:			
Longitude:	-122 18 12.0	Latitude:	50 21 3.9		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Complete one inspection for both culverts at the same time.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 29 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: K918

Site #:	K918	Year Superstructure Installed:	1983	Structure Type/Class:	Temporary Bridge
KM:	7.57	User km:	60.00	Last Inspection Date:	2021/09/03
Project File ID #:	5848	Br.	03	Next Inspection Date:	2023/09/03
Road Name:	W. PAVILION-LEON CRK				
Crossing Name:	Leon Cr	Total Length (metres):	6.0		
Special Access:		Special Equipment:			
Longitude:	-122 0 26.9	Latitude:	50 58 38.6		
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Ensure samples are taken on next inspection due to structure age. DA.				

Structure Name: K564

Site #:	K564	Year Superstructure Installed:	1997	Structure Type/Class:	Temporary Bridge
KM:	6.99	User km:	7.00	Last Inspection Date:	2022/08/27
Project File ID #:	5848	Br.	05	Next Inspection Date:	2023/08/27
Road Name:	W. PAVILION-PONY VLY				
Crossing Name:	Pony Valley Cr	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-122 23 14.4	Latitude:	51 12 28.2		
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\BPellet on 08-MAR-23: BP Mar 8-23 Annual inspection required to check for barricade. Ensure bridge is posted closed with each annual inspection. IDIR\DMALWAY on 19-APR-16: Ensure posted at 10 tonnes, due to deck tie spacing. Do a good job of drilling ties for condition and stringers as it is now 19 years old. The stringers appear in Fair condition from previous inspections.				

Structure Name: K917

Site #:	K917	Year Superstructure Installed:	1991	Structure Type/Class:	Permanent Bridge
KM:	0.00	User km:	83.10	Last Inspection Date:	2020/07/08
Project File ID #:	5848	Br.	01	Next Inspection Date:	2023/07/08
Road Name:	West Pavilion				
Crossing Name:	Watson Bar Cr	Total Length (metres):	8.6		
Special Access:		Special Equipment:			
Longitude:	-122 1 26.5	Latitude:	51 6 28.5		
Superstructure:	Concrete Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Cast in Place	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: On IR#1. High Bar Reserve land. Forward inspection to INAC contacts.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 30 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: K512

Site #:	K512	Year Superstructure Installed:	1988	Structure Type/Class:	Permanent Bridge
KM:	1.67	User km:	0.10	Last Inspection Date:	2020/06/24
Project File ID #:	7649	Br.	01	Next Inspection Date:	2023/06/24
Road Name:	YALAKOM RIVER				
Crossing Name:	Yalakom #1	Total Length (metres):	16.4		
Special Access:		Special Equipment:			
Longitude:	-122 14 21.0	Latitude:	50 54 45.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					

Structure Name: K911

Site #:	K911	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	4.41	User km:	2.80	Last Inspection Date:	2020/07/20
Project File ID #:	7649	Br.	01	Next Inspection Date:	2023/07/20
Road Name:	YALAKOM RIVER				
Crossing Name:	Shulaps Cr	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-122 15 36.3	Latitude:	50 55 40.3		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K514

Site #:	K514	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	9.22	User km:	7.70	Last Inspection Date:	2021/08/31
Project File ID #:	7649	Br.	01	Next Inspection Date:	2023/05/01
Road Name:	YALAKOM RIVER				
Crossing Name:	Yalakom #3	Total Length (metres):	20.0		
Special Access:		Special Equipment:			
Longitude:	-122 17 51.9	Latitude:	50 57 20.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 31 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: K1131

Site #:	K1131	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	9.86	User km:	8.20	Last Inspection Date:	2021/08/31
Project File ID #:	7649	Br.	01	Next Inspection Date:	2023/05/01
Road Name:	YALAKOM RIVER				
Crossing Name:	Junction Cr	Total Length (metres):	10.6		
Special Access:		Special Equipment:			
Longitude:	-122 18 12.9	Latitude:	50 57 32.3		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K880

Site #:	K880	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	16.65	User km:	57.00	Last Inspection Date:	2019/07/11
Project File ID #:	7649	Br.	01	Next Inspection Date:	2023/07/11
Road Name:	YALAKOM RIVER				
Crossing Name:	Beaver Dam	Total Length (metres):	10.6		
Special Access:		Special Equipment:			
Longitude:	-122 22 8.5	Latitude:	50 59 53.3		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K517

Site #:	K517	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	26.04	User km:	24.80	Last Inspection Date:	2020/06/24
Project File ID #:	7649	Br.	01	Next Inspection Date:	2023/06/24
Road Name:	YALAKOM RIVER				
Crossing Name:	Yalakom #6	Total Length (metres):	18.6		
Special Access:		Special Equipment:			
Longitude:	-122 27 45.0	Latitude:	51 1 58.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 32 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: K518

Site #:	K518	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	28.32	User km:	26.90	Last Inspection Date:	2020/06/24
Project File ID #:	7649	Br.	01	Next Inspection Date:	2023/06/24
Road Name:	YALAKOM RIVER				
Crossing Name:	Yalakom #7	Total Length (metres):	20.3		
Special Access:		Special Equipment:			
Longitude:	-122 28 9.5	Latitude:	51 2 39.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Monitor deck panel repair. Please photograph exposed rebar.				

Structure Name: K910

Site #:	K910	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	30.69	User km:	29.50	Last Inspection Date:	2020/06/24
Project File ID #:	7649	Br.	01	Next Inspection Date:	2023/06/24
Road Name:	YALAKOM RIVER				
Crossing Name:	Yalakom Cr	Total Length (metres):	11.0		
Special Access:		Special Equipment:			
Longitude:	-122 29 15.6	Latitude:	51 3 40.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Cast in Place	# Spans:	1
Planned Inspection Comments:					

Structure Name: K519

Site #:	K519	Year Superstructure Installed:	1996	Structure Type/Class:	Temporary Bridge
KM:	38.71	User km:	37.50	Last Inspection Date:	2021/08/31
Project File ID #:	7649	Br.	01	Next Inspection Date:	2023/08/31
Road Name:	YALAKOM RIVER				
Crossing Name:	Yalakom #8	Total Length (metres):	11.0		
Special Access:		Special Equipment:			
Longitude:	-122 33 24.6	Latitude:	51 6 32.4		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 33 of 33
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: WO 3470

Site #:	K1586	Year Superstructure Installed:			Structure Type/Class:	Permanent Bridge	
KM:	1.30	User km:		Last Inspection Date:		2020/06/24	
Project File ID #:	7649	Br.	07	Next Inspection Date:		2023/06/24	
Road Name:		YALAKOM-LAKE LA MARE					
Crossing Name:		Shulaps Cr		Total Length (metres):		15.2	
Special Access:				Special Equipment:			
Longitude:		-122 16 22.4		Latitude:		50 55 39.1	
Superstructure:	Steel I-beam		Abutments (Left/Right): <i>(looking downstream)</i>		Steel Pipe and Precast Pad		# Spans: 1
Planned Inspection Comments:							

Structure Name: K1750

Site #:	K1750	Year Superstructure Installed:		2022	Structure Type/Class:		Permanent Bridge	
KM:	3.20	User km:	3.00	Last Inspection Date:				
Project File ID #:	6069	Br.	01	Next Inspection Date:			2023/08/18	
Road Name:		MAKA-MURRAY						
Crossing Name:		Gillis Creek		Total Length (metres):		18.7		
Special Access:				Special Equipment:				
Longitude:		-120 56 25.0		Latitude:		49 54 33.0		
Superstructure:		Steel I-beam		Abutments (Left/Right): <i>(looking downstream)</i>		Steel Pipe and Precast Pad		# Spans: 1
Planned Inspection Comments:		IDIR\MRFENNEL on 03-MAY-23: One year post installation inspection						

Structure Name: W2124

Site #:	K1771	Year Superstructure Installed:		2020	Structure Type/Class:	Temporary Bridge	
KM:	0.25	User km:	0.25	Last Inspection Date:			
Project File ID #:	10273	Br.	48	Next Inspection Date:		2023/08/19	
Road Name:	ME10273.48						
Crossing Name:	Peter Hope Creek			Total Length (metres):	15.2		
Special Access:				Special Equipment:			
Longitude:	-120 20 36.8			Latitude:	50 19 22.9		
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)		Sill -Temporary Materials		# Spans: 1
Planned Inspection Comments:		IDIR\BPELLETT on 27-FEB-23: BP Feb 27-23 Measure-up structure against fabrication drawings on file to confirm that dimensions match.					

Structure Type/Class Totals

Permanent Bridge Total: 62
Temporary Bridge Total: 31

Major Culvert Total: 5
Woodbox/Log Culvert Total: 1