



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 1 of 15
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: Cascades Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
	Special Equipment Required	Special Access Required	Planned Inspection Comment									
1	K838	K838	2022/08/27	2023/08/27	P	7649-02	16.0	0	-BURKHOLDER B	0.05	0.00	Yalakom B
			IDIR\BPelletT on 01-MAR-23: BP Mar 1-23 Annual inspection required until curbs are replaced									
2	K1117	K1117	2022/09/06	2023/09/06	P	0814-15	15.2	0	-SKUHOST BRANCH 15	2.01	29.00	Skuhost #2
			IDIR\BPelletT on 09-MAR-23: BP Mar 9-23 Monitor deck and abutment conditions, and ensure appropriate signage is posted with every routine inspection									
3	K882	K882	2019/07/10	2022/07/10	P	4768-01	24.6	0	4768	1.17	0.10	Kwoiek #1
4	K544	K544	2021/10/12	2023/10/12	T	4768-01	19.3	0	4768	2.90	2.00	Kwoiek #3
5	K890	K890A	2020/06/23	2022/06/23	T	4768-01	26.8	0	4768	3.69	3.80	Kwoiek #4
6	K546	K546A	2020/06/23	2022/06/23	T	4768-01	26.8	0	4768	4.53	4.70	Kwoiek #5
7	K547	K547	2020/06/23	2023/06/23	P	4768-01	16.3	0	4768	12.29	12.60	Kwoiek #6
8	K1168	K1168	2019/07/09	2022/07/09	P	9856-01	23.6	0	9856	0.62	1.50	Tommy Cr



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 2 of 15
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: Cascades Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required		Special Access Required	Planned Inspection Comment									
		Helicopter										
9	K1304	K1304	2019/07/09	2021/07/09	W	9856-01	10.0	0	9856	6.53	2.70	Unnamed
		Helicopter	CBR_Conversion on 17-FEB-14: Heli access required, not to be inspected with Routine inspections. Check with district prior to inspections. DA 2010.									
10	K966	K966	2020/07/04	2023/07/04	P	8479-01	18.0	0	ARRASTRA CREEK	2.57	2.70	Blakeburn Cr
11	K1092	K1092	2022/09/10	2023/09/10	P	8479-01	12.6	0	ARRASTRA CREEK	5.48	5.30	Newton Cr
12	K1609	TKA008	2022/09/10	2023/09/10	P	8479-01	9.6	0	ARRASTRA CREEK	19.10	19.10	Trib to Arrastra Cr
			CBR_Conversion on 27-FEB-23: BP Feb 27-23 Inspection required in 2023 to monitor riprap stability and approach conditions. Confirm which slabs have large chips and/or honeycombing requiring repair.									
13	K1577	930-B007	2022/09/12	2023/09/12	T	8529-62	7.6	0	BRANCH 62	2.30	2.30	Galena Cr
			CBR_Conversion on 17-FEB-14: Drill timber sill to determine if any rot has occurred. DA.									
14	K528	K528	2020/06/25	2023/06/25	P	8490-01	28.5	0	BRIDGE RIVER	5.11	5.00	Ault Cr
	Peeper Truck		CBR_Conversion on 17-FEB-14: Peeper inspection required every 10 years. DA									
15	K618	K618	2020/06/25	2023/06/25	P	8490-01	24.9	0	BRIDGE RIVER	8.00	7.90	Paul Cr



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 3 of 15
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: Cascades Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required		Special Access Required	Planned Inspection Comment									
16	K834	K834	2020/06/25	2023/06/25	P	8490-01	36.0	0	BRIDGE RIVER	29.75	29.40	McParlon Cr
	Peeper Truck		CBR_Conversion on 17-FEB-14: Next peeper inspection for this bridge will occur in 2017. DA. Feb 2014. On a ten year frequency.									
17	K1699	K1699	2020/07/03	2023/07/03	P	8529-45	14.0	0	DILLARD-RAMPART LAKE	0.20	13.00	Unknown
18	K1588	020-07	2021/09/03	2023/09/03	T	10806-01	36.6	0	DOWNTON CREEK	0.10	0.10	Cayoosh Cr
			BCEID\SENTENG on 15-JUL-16: Assess rot in timber deck modules as MOTI only replaced running deck in 2016, sub-deck appeared to be getting rotten based on DA professional follow up in July 2016.									
19	K1592	K1592	2021/09/03	2023/09/03	T	10806-01	12.5	0	DOWNTON CREEK	3.40		Downton Cr
20	K534	K534	2022/08/26	2023/08/26	T	9150-03	12.3	0	EAST HOPE CREEK	0.63	7.50	Unnamed
			IDIR\BPelletT on 07-MAR-23: BP Mar 7-23 Carefully assess crib conditions for rot progression and further crushing with every annual inspection									
21	K1575	930-B006	2022/09/12	2023/09/12	P	8529-60	11.6	0	ELKHART-GALENA	2.90		Galena Cr
			IDIR\BPelletT on 10-MAR-22: BP Mar 10-22 Measure lean in posts and gap between slabs and cap beams with every annual inspection.									
22	K1301	K1301	2020/07/02	2023/07/02	P	8529-04	18.3	0	GALENA	12.35	11.90	Siwash #1



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 4 of 15
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: Cascades Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required		Special Access Required	Planned Inspection Comment									
23	K1302	K1302	2020/07/02	2023/07/02	P	8529-04	18.3	0	GALENA	13.06	12.30	Siwash #2
24	K1303	K1303	2020/07/02	2023/07/02	P	8529-04	17.0	0	GALENA	15.90	15.20	Siwash #3
			CBR_Conversion on 17-FEB-14: remove the old #k628 and install k1303 plate if not already installed. Also check field km's on all Briddges on the Dillard.									
25	K2042	K2042	2022/09/12	2023/09/12	MC	8529-04	18.0	0	GALENA	17.93	17.80	Elusive Cr
			IDIR\BPelletT on 26-APR-23: BP Apr 11-23 Measure wall thickness, corrugation profile, bolt pattern, gradient, and cover heights in 2023 inspection.									
26	K532	K532	2022/08/26	2023/08/26	T	9150-01	10.7	0	HOPE CREEK	8.13	8.50	West Hope Cr
			CBR_Conversion on 07-MAR-23: .									
27	K914	K914	2022/08/26	2023/08/26	T	9150-05	10.0	0	HOPE CREEK BR 05	0.59	9.80	Hope Cr
			IDIR\BPelletT on 17-MAR-22: BP Mar 17-22 Drill all sills and stringers for rot with every annual inspection. Ensure that bridge is posted closed if it has not been barricaded.									
28	K1396	K1396	2022/09/12	2023/09/12	T	3601-16	12.2	0	HORNET BR 16	0.00	16.70	Allison Cr
			CBR_Conversion on 09-MAR-23: BP Mar 9-23 Monitor for deck condition and debris buildup, and ensure appropriate signage is posted with every annual inspection.									
29	K520	K520	2020/06/25	2023/06/25	P	10194-01	38.2	0	HURLEY RIVER NORTH	0.00	0.60	Bridge R



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 5 of 15
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: Cascades Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
	Special Equipment Required	Special Access Required	Planned Inspection Comment									
	Peeper Truck		CBR_Conversion on 22-JAN-18: peeper inspection in 2017, then in 10 year frequency. DA									
30	K1021	K1021	2011/10/19	2013/10/19	T	10194-04	15.2	0	HURLEY RIVER SOUTH	0.01	5.10	Unnamed
		Helicopter	CBR_Conversion on 17-FEB-14: Quick inspection, as no vehicular access.									
31	K535	K535	2011/10/19	2013/10/19	T	10194-05	15.6	0	HURLEY RVR-SOUTH	0.50	4.30	Hurley R
		Helicopter	CBR_Conversion on 17-FEB-14: Just a quick ocular inspection as no vehicular access.									
32	K1006	K1006	2020/06/25	2023/06/25	P	8059-01	18.3	0	KINGDOM LAKE BR 01	25.28	24.00	Unnamed
33	K1007	K1007	2022/08/25	2023/08/25	P	8059-01	15.2	0	KINGDOM LAKE BR 01	25.71	24.40	Cadwallader Cr
		Bicycle	IDIR\BPelletT on 24-FEB-22: BP Feb 24-22 Ensure site is posted closed or barricaded. Note any signs of traffic. Monitor for damage to girders bearing directly on lock blocks.									
34	K639	K639	2022/08/25	2023/08/25	P	8059-03	14.0	0	KINGDOM LAKE BR 03	1.25	12.50	Crazy #1
			IDIR\BPelletT on 26-APR-23: BP Apr 26-23 Monitor left ballast wall condition annually until it's repaired.									
35	K640	K640	2021/09/02	2023/09/02	T	8059-03	15.2	0	KINGDOM LAKE BR 03	1.43	12.60	Crazy #2
			IDIR\BPelletT on 25-FEB-22: BP Feb 25-22 Routine inspection in 2023 needs to include the PIC from 2017. IDIR\DMALWAY on 25-JAN-17: Measure up girder depth, flange width etc. Measure C/c span from bearing stiffener to bearing stiffener. As we want to									
36	K1342	K1342	2021/09/02	2023/09/02	T	8059-05	24.4	0	KINGDON-CHISM BR 05	0.20	16.00	Cadwallader Cr



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 6 of 15
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: Cascades Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
		Special Equipment Required	Special Access Required	Planned Inspection Comment								
				IDIR\BPELLETT on 25-FEB-22: BP Feb 25-22 Drill for rot depth in tiebacks and in cribs at ends and under girders with every routine inspection. Determine species if practicable.								
37	K1345	K1345	2020/06/25	2023/06/25	P	8059-05	18.3	0	KINGDON-CHISM BR 05	0.53	12.60	Chism Cr.
38	K915	K915	2021/10/12	2023/10/12	P	6069-03	21.3	0	LOWER MAKA	0.56	18.00	Maka Cr
39	K1750	K1750		2023/08/18	P	6069-01	18.7	0	MAKA-MURRAY	3.20	3.00	Gillis Creek
				IDIR\MRFENNEL on 03-MAY-23: One year post installation inspection								
40	K1140	K1140	2021/10/12	2023/10/12	P	6069-01	9.6	0	MAKA-MURRAY	19.87	19.50	Unnamed
41	K1771	W2124		2023/08/19	T	10273-48	15.2	0	ME10273.48	0.25	0.25	Peter Hope Creek
				IDIR\BPELLETT on 27-FEB-23: BP Feb 27-23 Measure-up structure against fabrication drawings on file to confirm that dimensions match.								
42	K1756	WO101		2013/03/13	T	7573-08	12.3	0	ME7573.08	2.40	2.40	Unknown
43	K1485	WO4622	2021/08/05	2023/08/05	T	8614-06	9.1	0	ME8614.06	1.00	1.00	Red Cr



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 7 of 15
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: Cascades Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
			Planned Inspection Comment									
			CBR_Conversion on 07-MAR-22: BP Mar 7-22 Sound cribs for rot with every routine inspection, and drill to confirm depth if any is found.									
44	K1486	WO3228	2022/09/11	2023/09/11	T	8614-07	7.6	0	ME8614.07	0.40	0.40	Unnamed Cr
			CBR_Conversion on 10-MAR-22: BP Mar 10-22 Annual inspection until deck is replaced. Monitor all wooden deck components for rot progression and safety to road users.									
45	K602	K602	2020/06/24	2023/06/24	P	5496-01	12.6	0	MUD CREEK BR 01	3.22	3.20	Jim Cr
46	K601	K601	2020/06/24	2023/06/24	P	5496-01	18.3	0	MUD CREEK BR 01	14.01	14.10	Liza Cr
47	K503	K503	2020/06/24	2023/06/24	P	5496-01	13.6	0	MUD CREEK BR 01	24.35	24.90	Noaxe Cr
			CBR_Conversion on 17-FEB-14: Monitor items from original construction. DA									
48	K620	K620	2020/06/24	2023/06/24	P	5496-05	27.5	0	MUD-PARADISE CREEK	1.10	0.90	Mud Cr #1
49	K619	K619	2020/06/24	2023/06/24	P	5496-05	21.4	0	MUD-PARADISE CREEK	1.64	1.60	Relay Cr
50	K506	K506	2021/09/02	2023/09/02	T	5496-04	27.8	0	MUD-TYAUGHTON CRK	0.62	107.50	Tyaughton Cr



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 8 of 15
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: Cascades Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required		Special Access Required	Planned Inspection Comment									
51	K563	K563	2022/09/05	2023/09/05	T	6879-05	6.2	0	MURRAY CREEK N-WEST	5.20	7.00	Unnamed
			IDIR\DMALWAY on 15-FEB-16: annual inspection									
52	K570	K570	2022/09/05	2023/09/05	T	6879-04	6.2	0	MURRAY CREEK WEST	1.70	18.00	Murray Cr North
			IDIR\BPELLETT on 25-FEB-22: BP Feb 25-22 Monitor contact between girders and lock blocks, and note any damage to girders. CBR_Conversion on 17-FEB-14:									
53	K650	K650	2022/09/10	2023/09/10	T	3600-06	11.3	0	NICOMEN	10.79	36.40	Copper Cr Trib
			IDIR\BPELLETT on 27-APR-22: BP Apr 27-22 Inspector to thoroughly search for fabricator markings and photograph any found									
54	K1393	K1393	2021/09/01	2023/09/01	T	9177-01	27.4	0	NOEL CREEK	5.01	5.40	Noel Cr
55	K446	K446	2021/10/13	2023/10/13	P	7573-01	30.5	0	PASAYTEN RIVER	20.39	21.00	Pasayten R
56	K447	K447	2021/10/13	2023/10/13	P	7573-01	15.2	0	PASAYTEN RIVER	20.79	21.30	Peeve Cr
57	K1309	K1309	2020/07/04	2023/07/04	P	0919-03	8.6	0	PLACER CREEK	0.45	12.60	Watson Cr



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 9 of 15
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: Cascades Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required		Special Access Required	Planned Inspection Comment									
58	K1310	K1310	2020/07/04	2023/07/04	P	0919-03	9.6	0	PLACER CREEK	3.00	15.50	Lynx Cr
59	K1722	WO-1634	2022/09/30	2023/09/30	T	10273-14	9.1	0	PLATEAU LAKE	0.50	0.50	Unknown
			IDIR\MRFENNEL on 17-MAR-22: BP Mar 17-22 Planned for deactivation in 2022 or 2023. Check with BCTS if site has been deactivated before inspecting.									
60	K682	K682	2022/09/06	2023/09/06	P	4669-03	16.0	0	PROSPECT BR 03	29.19	0.50	Spilus Cr
			CBR_Conversion on 17-FEB-14: Do not inspect prior to August 15 so as to allow for lower water levels to assess abutments appropriately. MRF 11/2013									
61	K1438	K1438	2021/09/17	2022/09/17	P	4669-02	11.6	0	PROSPECT MINER A	12.24	25.50	Silver Cr
			IDIR\PBLUESCH on 23-JAN-19: PB Jan23.2019 Continue to monitor left bank scour at toe of rip rap (upstream). Approaches require fill to ensure safe traffic, slab girder ends are exposed and a hazard to public traffic.									
62	K1033	K1033	2020/07/03	2023/07/03	P	8614-01	21.3	0	RED CREEK	0.27	0.20	Hayes Cr
63	K1567	K1567	2020/07/03	2023/07/03	P	8614-01	11.0	0	RED CREEK	10.40	10.40	unamed
			CBR_Conversion on 13-FEB-18: na									
64	K1499	K1499	2020/07/03	2023/07/03	P	8614-01	8.6	0	RED CREEK	19.00	19.00	unkown



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 10 of 15
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: Cascades Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required		Special Access Required	Planned Inspection Comment									
65	K408	K408A	2020/07/03	2023/07/03	P	8614-01	12.6	0	RED CREEK	36.88	38.60	Alaric Cr
			CBR_Conversion on 17-FEB-14: One year post construction inspection. DA									
66	K406	K406	2022/09/11	2023/09/11	P	8614-01	12.6	0	RED CREEK	40.59	42.30	McNulty Cr
67	K351	WO3511	2022/08/13	2023/08/13	T	7666-01	12.2	0	SALMON RIVER	0.14	27.60	Salmon R
68	K351	K351	2021/10/07	2022/10/07	P	7666-01	6.0	0	SALMON RIVER	0.14	27.60	Salmon R
			CBR_Conversion on 13-FEB-18: na									
69	K1512	K1512	2022/09/06	2023/09/06	MC	0814-40	9.8	0	SKUHUN-CALLING LAKE	0.20	14.50	Calling lake OverFlow
70	K539	K539A	2020/06/24	2023/06/24	P	8151-01	15.6	0	SLIM CREEK	9.33	9.30	Roxey Cr
71	K1311	K1311	2020/06/24	2023/06/24	MC	8151-01	12.0	0	SLIM CREEK	18.71	18.80	Erin Creek



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 11 of 15
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: Cascades Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required		Special Access Required	Planned Inspection Comment									
			CBR_Conversion on 09-FEB-18: n/a BCEID\SENTENG on 09-FEB-18: n/a									
72	K540	PS-024	2021/09/02	2023/09/02	T	8151-01	21.3	0	SLIM CREEK	24.02	24.30	Slim Cr
73	K626	K626	2022/09/07	2023/09/07	P	4332-02	17.4	0	SPIUS SOUTH	3.66	19.50	S Fork Spius
74	K658	K658	2020/07/04	2023/07/04	P	9397-01	18.0	0	SUNDAY SUMMIT	18.61	18.00	Copper Cr #2
75	K671	K671	2019/10/06	2022/10/06	MC	1045-02	18.0	0	THYNNE-LOWER MCPHAIL	7.59	6.70	McPhail Cr
76	K853	K853	2020/07/05	2023/07/05	P	8528-01	16.0	0	TULAMEEN	8.25	8.30	Britton Cr
77	K873	K873	2020/07/05	2023/07/05	P	8528-01	27.4	0	TULAMEEN	12.44	13.00	Eagle Cr
78	K874	K874	2020/07/05	2023/07/05	P	8528-01	21.3	0	TULAMEEN	18.35	18.50	Illal Cr



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 12 of 15
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: Cascades Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required		Special Access Required	Planned Inspection Comment									
79	K457	K457	2022/09/08	2023/09/08	P	8528-01	9.6	0	TULAMEEN	21.62	21.60	McGee Cr
			IDIR\PBLUESCH on 21-FEB-20: PB Feb21,2020 assess metal tabs on deck connecting box beam girder									
80	K459	K459	2022/09/09	2023/09/09	P	8528-01	6.1	0	TULAMEEN	31.21	30.80	Railroad Cr
81	K465	K465	2022/09/09	2023/09/09	P	8528-01	12.6	0	TULAMEEN	50.96	52.00	White Cloud Cr
82	K466	K466	2022/09/08	2023/09/08	P	8528-02	28.0	0	TULAMEEN-CHAMPION	0.12	0.20	Tulameen R
	Peeper Truck		CBR_Conversion on 15-FEB-16: Check the monitor item for the wing wall measurements from top girder flange to flat on wing-walls. See the measures and sketch in the attach doc and folders tab from 2013. DA.									
83	K483	K483	2022/09/10	2023/09/10	P	8528-02	22.9	0	TULAMEEN-CHAMPION	13.60	10.00	Champion Cr
84	K1587	K1587		2019/06/17	MC	10808-01	9.0	0	VAN HORLICK	5.90		Unnamed
			CBR_Conversion on 17-FEB-14: Complete one inspection for both culverts at the same time.									
85	K918	K918	2021/09/03	2023/09/03	T	5848-03	6.0	0	W. PAVILION-LEON CRK	7.57	60.00	Leon Cr



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 13 of 15
Date Printed: 2023/06/19
User Id: IDIR\IMRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: Cascades Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
			Planned Inspection Comment									
			CBR_Conversion on 17-FEB-14: Ensure samples are taken on next inspection due to structure age. DA.									
86	K564	K564	2022/08/27	2023/08/27	T	5848-05	10.0	0	W. PAVILION-PONY VLY	6.99	7.00	Pony Valley Cr
			IDIR\BPelletT on 08-MAR-23: BP Mar 8-23 Annual inspection required to check for barricade. Ensure bridge is posted closed with each annual inspection.									
87	K917	K917	2020/07/08	2023/07/08	P	5848-01	8.6	0	West Pavilion	0.00	83.10	Watson Bar Cr
			CBR_Conversion on 17-FEB-14: On IR#1. High Bar Reserve land. Forward inspection to INAC contacts.									
88	K512	K512	2020/06/24	2023/06/24	P	7649-01	16.4	0	YALAKOM RIVER	1.67	0.10	Yalakom #1
89	K911	K911	2020/07/20	2023/07/20	P	7649-01	12.6	0	YALAKOM RIVER	4.41	2.80	Shulaps Cr
90	K514	K514	2021/08/31	2023/05/01	P	7649-01	20.0	0	YALAKOM RIVER	9.22	7.70	Yalakom #3
91	K1131	K1131	2021/08/31	2023/05/01	P	7649-01	10.6	0	YALAKOM RIVER	9.86	8.20	Junction Cr
92	K880	K880	2019/07/11	2023/07/11	P	7649-01	10.6	0	YALAKOM RIVER	16.65	57.00	Beaver Dam



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 14 of 15
Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: Cascades Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required		Special Access Required	Planned Inspection Comment									
93	K517	K517	2020/06/24	2023/06/24	P	7649-01	18.6	0	YALAKOM RIVER	26.04	24.80	Yalakom #6
94	K518	K518	2020/06/24	2023/06/24	P	7649-01	20.3	0	YALAKOM RIVER	28.32	26.90	Yalakom #7
			CBR_Conversion on 17-FEB-14: Monitor deck panel repair. Please photograph exposed rebar.									
95	K910	K910	2020/06/24	2023/06/24	P	7649-01	11.0	0	YALAKOM RIVER	30.69	29.50	Yalakom Cr
96	K519	K519	2021/08/31	2023/08/31	T	7649-01	11.0	0	YALAKOM RIVER	38.71	37.50	Yalakom #8
97	K1586	WO 3470	2020/06/24	2023/06/24	P	7649-07	15.2	0	YALAKOM-LAKE LA MARE	1.30		Shulaps Cr
98	K421	TKA028	2022/09/09	2023/09/09	T	0814-01	12.2	0		12.80	13.00	Skuhost Cr
		ATV										
99	K1770	TKO-0037		2022/08/01	T	0814-01	12.2	0		15.10	18.00	unknown



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Summary

Page: 15 of 15
Date Printed: 2023/06/19
User Id: IDIR\IMRFENNEL
Database: PROD
Report Id: CBR004

Forest District: Cascades Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: Forest Service Road Site Status:Active

Forest District: Cascades Natural Resource District

No.	Site #	Structure Name	Last Inspection Date	Next Inspection Date	Structure Type/Class	Project File ID# / Br.	Total Length (metres)	# Piers	Road Name	KM	User KM	Crossing Name
Special Equipment Required		Special Access Required	Planned Inspection Comment									

Permanent Bridge Total: 62

Temporary Bridge Total: 31

Major Culvert Total: 5

Woodbox/Log Culvert Total: 1