BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K131

Site #:	K131	**Year Superstructure Installed:**	2000	**Structure Type/Class:**	Permanent Bridge
KM:	6.88	**User km:**	6.80	**Last Inspection Date:**	2020/10/02
Project File ID #:	7458	**Br.**	12	**Next Inspection Date:**	2023/10/02
Road Name:	ADAMS EAST				
Crossing Name:	Michel Cr	**Total Length (metres):**	15.0		
Special Access:		**Special Equipment:**			
Longitude:	-119 25 37.2	**Latitude:**	51 24 8.4		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Jan 21,2013 Inspect mounting blocks for performance.				

Structure Name: K801

Site #:	K801	**Year Superstructure Installed:**	1995	**Structure Type/Class:**	Permanent Bridge
KM:	8.12	**User km:**	8.10	**Last Inspection Date:**	2022/09/20
Project File ID #:	7458	**Br.**	12	**Next Inspection Date:**	2023/09/20
Road Name:	ADAMS EAST				
Crossing Name:	Rock Cr	**Total Length (metres):**	16.0		
Special Access:		**Special Equipment:**			
Longitude:	-119 25 29.2	**Latitude:**	51 23 21.8		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	IDIR\PBLUESCH on 24-JAN-17: PB Jan24.2017 Close inspection of bracing bolts and rip rap. CBR_Conversion on 17-FEB-14: PB Mar 10/11. Have a good look at rip rap and any abutment erosion.				

Structure Name: K166

Site #:	K166	**Year Superstructure Installed:**	1987	**Structure Type/Class:**	Permanent Bridge
KM:	17.92	**User km:**	17.60	**Last Inspection Date:**	2020/10/10
Project File ID #:	7458	**Br.**	01	**Next Inspection Date:**	2023/10/10
Road Name:	ADAMS WEST				
Crossing Name:	Sinmax	**Total Length (metres):**	25.0		
Special Access:		**Special Equipment:**			
Longitude:	-119 47 37.9	**Latitude:**	51 4 44.0		
Superstructure:	Concrete Box Beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Precast	**# Spans:**	1
Planned Inspection Comments:					

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1775

Site #:	K1775	**Year Superstructure Installed:**	2022	**Structure Type/Class:**	Permanent Bridge
KM:	8.40	**User km:**	8.40	**Last Inspection Date:**	
Project File ID #:	5072	**Br.**	04	**Next Inspection Date:**	2023/08/18
Road Name:	ADAMS-TUM TUM				
Crossing Name:	Unnamed	**Total Length (metres):**	7.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 21 34.0	**Latitude:**	51 31 37.0		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	IDIR\MRFENNEL on 11-APR-23: One year post installation inspection				

Structure Name: K1780

Site #:	K1780	**Year Superstructure Installed:**	2022	**Structure Type/Class:**	Permanent Bridge
KM:	15.10	**User km:**	15.10	**Last Inspection Date:**	
Project File ID #:	5072	**Br.**	04	**Next Inspection Date:**	2023/08/18
Road Name:	ADAMS-TUM TUM				
Crossing Name:	Unnamed	**Total Length (metres):**	12.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 17 19.0	**Latitude:**	51 33 31.0		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	IDIR\MRFENNEL on 11-APR-23: One year post installation inspection				

Structure Name: K1776

Site #:	K1776	**Year Superstructure Installed:**	2022	**Structure Type/Class:**	Permanent Bridge
KM:	21.10	**User km:**	21.10	**Last Inspection Date:**	
Project File ID #:	5072	**Br.**	04	**Next Inspection Date:**	2023/08/18
Road Name:	ADAMS-TUM TUM				
Crossing Name:	Unnamed	**Total Length (metres):**	7.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 14 58.0	**Latitude:**	51 36 10.0		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	IDIR\MRFENNEL on 11-APR-23: One year post installation inspection				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K964A

Site #:	K964	**Year Superstructure Installed:**	2018	**Structure Type/Class:**	Temporary Bridge
KM:	0.19	**User km:**	8.90	**Last Inspection Date:**	2022/09/27
Project File ID #:	8410	**Br.**	01	**Next Inspection Date:**	2023/09/27
Road Name:	BERRY CR FSR				
Crossing Name:	Unnamed	**Total Length (metres):**	5.3		
Special Access:		**Special Equipment:**			
Longitude:	-119 23 38.0	**Latitude:**	52 0 31.0		
Superstructure:	Log Stringers	**Abutments (Left/Right):** *(looking downstream)*	Crib, Log or Untreated	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K698

Site #:	K698	**Year Superstructure Installed:**	1987	**Structure Type/Class:**	Permanent Bridge
KM:	0.00	**User km:**	0.10	**Last Inspection Date:**	2022/09/25
Project File ID #:	0731	**Br.**	01	**Next Inspection Date:**	2023/09/25
Road Name:	BONE CREEK				
Crossing Name:	North Thompson R	**Total Length (metres):**	80.0		
Special Access:		**Special Equipment:**	Peeper Truck		
Longitude:	-119 11 16.3	**Latitude:**	52 15 58.5		
Superstructure:	Glulam Girder	**Abutments (Left/Right):** *(looking downstream)*	Pile -Permanent Materials	**# Spans:**	4
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Mar 28/11. Complete routine condition inspection in 2012. Scheduled for peeper in 2011. PB Jan23.2013. Planned for peeper inspection in 2013 following MOT rip rap hauling.				

Structure Name: 5004

Site #:	5004	**Year Superstructure Installed:**	1991	**Structure Type/Class:**	Temporary Bridge
KM:	0.48	**User km:**	0.30	**Last Inspection Date:**	2022/09/25
Project File ID #:	R10870	**Br.**	BR1883	**Next Inspection Date:**	2023/09/25
Road Name:	BR1883				
Crossing Name:	Unknown	**Total Length (metres):**	16.9		
Special Access:		**Special Equipment:**			
Longitude:	-118 58 55.5	**Latitude:**	52 17 2.9		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Crib, Log or Untreated	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 26-MAR-14: PB Jan 15,2013 Monitor cribs for failure and condition of ties....some are failing.				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K817

Site #:	K817	**Year Superstructure Installed:**		1999	**Structure Type/Class:**	Major Culvert	
KM:	4.60	**User km:**	4.50	**Last Inspection Date:**		2020/09/30	
Project File ID #:	9137	**Br.**	01	**Next Inspection Date:**		2023/09/30	
Road Name:	CARIBOU MTN-MAINLINE						
Crossing Name:	Cedar Cr			**Total Length (metres):**	27.0		
Special Access:				**Special Equipment:**			
Longitude:	-119 38 37.3			**Latitude:**	51 35 41.4		
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*			**# Spans:**	0	
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Mar11,2011 The structure reviewed in 2009 & 2010 appears to be K818 Caribou-Homestead km 0.6. K817 is at km 4.6 on Caribou Mtn (Cedar Creek).Confirm GPS coordinates and structure location relative to K818. Verify correct structure with exisitng file information.						

Structure Name: K1596

Site #:	K1596	**Year Superstructure Installed:**			**Structure Type/Class:**	Temporary Bridge	
KM:	0.40	**User km:**	0.40	**Last Inspection Date:**		2021/09/14	
Project File ID #:	8412	**Br.**	11	**Next Inspection Date:**		2023/09/14	
Road Name:	CL8412.11						
Crossing Name:	Unknown			**Total Length (metres):**	10.6		
Special Access:				**Special Equipment:**			
Longitude:	-119 50 1.1			**Latitude:**	51 34 20.9		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*		Concrete Lock Blocks	**# Spans:**	1	
Planned Inspection Comments:	CBR_Conversion on 31-JAN-19: PB Jan23,2012 Monitor right abutment for performance. IDIR\PBLUESCH on 20-JAN-17: .						

Structure Name: K1597

Site #:	K1597	**Year Superstructure Installed:**		2001	**Structure Type/Class:**	Temporary Bridge	
KM:	1.70	**User km:**	1.70	**Last Inspection Date:**		2021/09/14	
Project File ID #:	8412	**Br.**	11	**Next Inspection Date:**		2023/09/14	
Road Name:	CL8412.11						
Crossing Name:	Unknown			**Total Length (metres):**	15.3		
Special Access:				**Special Equipment:**			
Longitude:	-119 51 4.2			**Latitude:**	51 34 15.7		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Concrete Lock Blocks	**# Spans:**	1	
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Gather as built information. MRF 2012						

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1598

Site #:	K1598	**Year Superstructure Installed:**		2001	**Structure Type/Class:**	Temporary Bridge	
KM:	2.00	**User km:**	2.00	**Last Inspection Date:**		2021/09/14	
Project File ID #:	8412	**Br.**	11	**Next Inspection Date:**		2023/09/14	
Road Name:	CL8412.11						
Crossing Name:	Unknown			**Total Length (metres):**	12.2		
Special Access:				**Special Equipment:**			
Longitude:	-119 51 16.5			**Latitude:**	51 34 16.0		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Concrete Lock Blocks	**# Spans:**	1	
Planned Inspection Comments:	CBR_Conversion on 20-JAN-17: PB Jan20.2017 Appears wrong photos uploaded in 2015. Should be WO2643 12m length.						

Structure Name: K1563

Site #:	K1563	**Year Superstructure Installed:**			**Structure Type/Class:**	Temporary Bridge	
KM:	1.30	**User km:**		**Last Inspection Date:**		2021/07/07	
Project File ID #:	8412	**Br.**	25	**Next Inspection Date:**		2023/07/07	
Road Name:	CL8412.25						
Crossing Name:	No Name S3			**Total Length (metres):**	10.0		
Special Access:				**Special Equipment:**			
Longitude:	-119 58 41.6			**Latitude:**	51 30 46.4		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*		Concrete Lock Blocks	**# Spans:**	1	
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Mar7.2012 There are issues with the abutment sills and likely with the shear connectors (may not be connected).						

Structure Name: K1795

Site #:	K1795	**Year Superstructure Installed:**			**Structure Type/Class:**	Permanent Bridge	
KM:	4.80	**User km:**		**Last Inspection Date:**			
Project File ID #:	8420	**Br.**	01	**Next Inspection Date:**		2023/08/19	
Road Name:	CL8420.01						
Crossing Name:	Clemina Creek			**Total Length (metres):**	21.3		
Special Access:				**Special Equipment:**			
Longitude:	-119 5 17.1			**Latitude:**	52 34 15.0		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Steel Pipe and Precast Pad	**# Spans:**	1	
Planned Inspection Comments:							

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K109

Site #:	K109	**Year Superstructure Installed:**	2000	**Structure Type/Class:**	Permanent Bridge
KM:	18.94	**User km:**	25.70	**Last Inspection Date:**	2020/07/12
Project File ID #:	7669	**Br.**	01	**Next Inspection Date:**	2023/07/12
Road Name:	CLEARWATER-100 MILE				
Crossing Name:	Mann Cr	**Total Length (metres):**	9.8		
Special Access:		**Special Equipment:**			
Longitude:	-120 21 2.4	**Latitude:**	51 41 51.6		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Concrete Cast in Place	**# Spans:**	1
Planned Inspection Comments:	IDIR\PBLUESCH on 14-FEB-18: PB Feb14.2018 Inspect cast in place abutments for scour.				

Structure Name: K1507A

Site #:	K1507	**Year Superstructure Installed:**	2010	**Structure Type/Class:**	Permanent Bridge
KM:	0.75	**User km:**		**Last Inspection Date:**	2020/09/16
Project File ID #:	8256	**Br.**	03	**Next Inspection Date:**	2023/09/16
Road Name:	DOMINION CR MAINLINE				
Crossing Name:	Dominion Creek	**Total Length (metres):**	24.4		
Special Access:		**Special Equipment:**			
Longitude:	-119 6 28.7	**Latitude:**	52 29 35.7		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB June29/11 Inspect stability of rip rap at downstream rightbank corner. Rip rap armouring was also required at the time of final inspection on the left bank (low chain) approx 75m upstream from the abutmtent. Please confirm completed. Also confirm user km and GPS coordinates.				

Structure Name: K869

Site #:	K869	**Year Superstructure Installed:**	1998	**Structure Type/Class:**	Permanent Bridge
KM:	0.01	**User km:**	1.70	**Last Inspection Date:**	2022/09/24
Project File ID #:	0565	**Br.**	03	**Next Inspection Date:**	2023/09/24
Road Name:	FINN-TUM				
Crossing Name:	Unnamed	**Total Length (metres):**	22.0		
Special Access:		**Special Equipment:**			
Longitude:	-119 5 12.1	**Latitude:**	51 59 11.4		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K749

Site #:	K749	**Year Superstructure Installed:**	1994	**Structure Type/Class:**	Permanent Bridge
KM:	0.64	**User km:**	8.10	**Last Inspection Date:**	2020/09/28
Project File ID #:	8425	**Br.**	01	**Next Inspection Date:**	2023/09/28
Road Name:	HASCHEAK CREEK				
Crossing Name:	McDougall Cr	**Total Length (metres):**	24.0		
Special Access:	Gate Key	**Special Equipment:**			
Longitude:	-119 59 26.4	**Latitude:**	51 35 57.9		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Cast in Place	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K699

Site #:	K699	**Year Superstructure Installed:**	1988	**Structure Type/Class:**	Permanent Bridge
KM:	0.02	**User km:**	0.10	**Last Inspection Date:**	2020/09/16
Project File ID #:	0590	**Br.**	02	**Next Inspection Date:**	2023/09/16
Road Name:	LEMPRIERE CREEK				
Crossing Name:	North Thompson R	**Total Length (metres):**	45.0		
Special Access:		**Special Equipment:**	Peeper Truck		
Longitude:	-119 12 33.0	**Latitude:**	52 28 52.9		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Pile -Permanent Materials	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Jan23,2013. Confirm crossties replaced. If not ensure posted to 5 tonnes.				

Structure Name: K796

Site #:	K796	**Year Superstructure Installed:**	1998	**Structure Type/Class:**	Permanent Bridge
KM:	19.27	**User km:**	19.30	**Last Inspection Date:**	2020/09/19
Project File ID #:	4771	**Br.**	01	**Next Inspection Date:**	2023/09/19
Road Name:	MAD RIVER				
Crossing Name:	Mad R	**Total Length (metres):**	20.4		
Special Access:		**Special Equipment:**			
Longitude:	-119 29 19.2	**Latitude:**	51 46 28.2		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Mar8.2012 Monitor abutment fills and oversteepend rip rap.				

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1181

Site #:	K1181	**Year Superstructure Installed:**	2001	**Structure Type/Class:**	Permanent Bridge
KM:	6.98	**User km:**	6.80	**Last Inspection Date:**	2020/07/12
Project File ID #:	9968	**Br.**	01	**Next Inspection Date:**	2023/07/12
Road Name:	MAHOOD-WEST MAINLINE				
Crossing Name:	Unnamed	**Total Length (metres):**	15.2		
Special Access:		**Special Equipment:**			
Longitude:	-120 25 7.8	**Latitude:**	51 52 33.0		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Precast	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K823

Site #:	K823	**Year Superstructure Installed:**	1993	**Structure Type/Class:**	Permanent Bridge
KM:	9.30	**User km:**	2.90	**Last Inspection Date:**	2022/09/26
Project File ID #:	0590	**Br.**	03	**Next Inspection Date:**	2023/09/26
Road Name:	MANTEAU-CANVAS CREEK				
Crossing Name:	Unnamed	**Total Length (metres):**	9.3		
Special Access:	ATV	**Special Equipment:**			
Longitude:	-119 16 50.9	**Latitude:**	52 27 30.9		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:	IDIR\PBLUESCH on 09-APR-14: PB Apr9,2014 Inpsect lock block abutments for stability and scour.				

Structure Name: K1455A

Site #:	K1455	**Year Superstructure Installed:**	1991	**Structure Type/Class:**	Major Culvert
KM:	12.00	**User km:**		**Last Inspection Date:**	2020/09/30
Project File ID #:	8414	**Br.**	01	**Next Inspection Date:**	2023/09/30
Road Name:	MCCORVIE LAKES				
Crossing Name:	Slake Creek	**Total Length (metres):**	27.0		
Special Access:		**Special Equipment:**			
Longitude:	-119 48 40.8	**Latitude:**	51 36 43.4		
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Mar6.2012 Location to be confirmed to ensure inspecting correct structure.				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K2010A

Site #:	K2010	**Year Superstructure Installed:**	2019	**Structure Type/Class:**	Permanent Bridge
KM:	17.10	**User km:**	17.10	**Last Inspection Date:**	2020/09/16
Project File ID #:	0590	**Br.**	01	**Next Inspection Date:**	2023/09/16
Road Name:	NORTH THOMPSON				
Crossing Name:	Unnamed	**Total Length (metres):**	10.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 20 19.8	**Latitude:**	52 29 58.5		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	IDIR\PBLUESCH on 16-JAN-20: PB Jan16.2020 Monitor rip rap for scour. Shallow keyway, channel may scour as this was a culvert replacement. IDIR\MRFENNEL on 16-JAN-20: One year post installation inspection				

Structure Name: K006

Site #:	K006	**Year Superstructure Installed:**	1998	**Structure Type/Class:**	Permanent Bridge
KM:	19.60	**User km:**	20.30	**Last Inspection Date:**	2022/09/26
Project File ID #:	0590	**Br.**	01	**Next Inspection Date:**	2023/09/26
Road Name:	NORTH THOMPSON				
Crossing Name:	Adolph Cr	**Total Length (metres):**	22.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 22 11.6	**Latitude:**	52 30 21.9		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	IDIR\PBLUESCH on 27-FEB-18: PB Feb 27.2018 Assess upstream channel and stability of left bank road approach.				

Structure Name: PS-026

Site #:	K821	**Year Superstructure Installed:**	2013	**Structure Type/Class:**	Temporary Bridge
KM:	36.60	**User km:**	35.90	**Last Inspection Date:**	2022/09/26
Project File ID #:	0590	**Br.**	01	**Next Inspection Date:**	2023/09/26
Road Name:	NORTH THOMPSON				
Crossing Name:	#5	**Total Length (metres):**	12.2		
Special Access:		**Special Equipment:**			
Longitude:	-119 32 3.0	**Latitude:**	52 34 25.2		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Sill -Temporary Materials	**# Spans:**	1
Planned Inspection Comments:	IDIR\PBLUESCH on 27-FEB-18: PB Jan25.2017 Evaluate log crib condition for stability as per SNT as-built dwg# K821-1/1 (5 year design life).				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1503

Site #:	K1503	**Year Superstructure Installed:**	2008	**Structure Type/Class:**	Temporary Bridge
KM:	17.60	**User km:**		**Last Inspection Date:**	2022/09/22
Project File ID #:	5072	**Br.**	10	**Next Inspection Date:**	2023/09/22
Road Name:	OLIVER CREEK				
Crossing Name:	Unknown			**Total Length (metres):**	15.2
Special Access:				**Special Equipment:**	
Longitude:	-118 57 43.2			**Latitude:**	51 46 21.6
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Concrete Lock Blocks	**# Spans:** 1
Planned Inspection Comments:	CBR_Conversion on 20-JAN-17: PB Jan20,2017 Monitor abutment rip rap for stability and scour.				

Structure Name: K1504A

Site #:	K1504	**Year Superstructure Installed:**	2012	**Structure Type/Class:**	Temporary Bridge
KM:	20.50	**User km:**	19.50	**Last Inspection Date:**	2022/09/22
Project File ID #:	5072	**Br.**	10	**Next Inspection Date:**	2023/09/22
Road Name:	OLIVER CREEK				
Crossing Name:	Unknown			**Total Length (metres):**	24.4
Special Access:				**Special Equipment:**	
Longitude:	-118 57 19.5			**Latitude:**	51 45 16.2
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Steel Pipe and Precast Pad	**# Spans:** 1
Planned Inspection Comments:	IDIR\PBLUESCH on 01-FEB-19: PB Feb01.2019 Assess clearance to girders and channel aggradation.				

Structure Name: K045

Site #:	K045	**Year Superstructure Installed:**	2011	**Structure Type/Class:**	Major Culvert
KM:	1.50	**User km:**		**Last Inspection Date:**	2020/09/19
Project File ID #:	0564	**Br.**	05	**Next Inspection Date:**	2023/09/19
Road Name:	OTTER-CARIBOU				
Crossing Name:	Unnamed crossing			**Total Length (metres):**	18.0
Special Access:				**Special Equipment:**	
Longitude:	-119 25 17.3			**Latitude:**	51 40 14.9
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*			**# Spans:** 0
Planned Inspection Comments:					

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K040A

Site #:	K040	**Year Superstructure Installed:**	2022	**Structure Type/Class:**	Temporary Bridge
KM:	0.91	**User km:**	0.70	**Last Inspection Date:**	2022/09/23
Project File ID #:	8398	**Br.**	04	**Next Inspection Date:**	2023/09/23
Road Name:	PARK ROAD				
Crossing Name:	Lion Cr	**Total Length (metres):**	12.2		
Special Access:		**Special Equipment:**			
Longitude:	-119 24 14.9	**Latitude:**	51 53 56.8		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Jan 15, 2013 Inspect abutments for failure / erosion.				

Structure Name: K042

Site #:	K042	**Year Superstructure Installed:**	1993	**Structure Type/Class:**	Permanent Bridge
KM:	13.48	**User km:**	17.90	**Last Inspection Date:**	2022/09/27
Project File ID #:	8398	**Br.**	04	**Next Inspection Date:**	2022/08/20
Road Name:	PARK ROAD				
Crossing Name:	Upper Raft R	**Total Length (metres):**	9.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 28 53.5	**Latitude:**	51 59 0.4		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Mar 01/11 Confirm correct GPS coords.				

Structure Name: K820

Site #:	K820	**Year Superstructure Installed:**	1987	**Structure Type/Class:**	Permanent Bridge
KM:	15.45	**User km:**	0.20	**Last Inspection Date:**	2022/09/28
Project File ID #:	8397	**Br.**	03	**Next Inspection Date:**	2023/09/28
Road Name:	RAFT-MARTIN				
Crossing Name:	Raft R	**Total Length (metres):**	30.5		
Special Access:		**Special Equipment:**			
Longitude:	-119 49 47.0	**Latitude:**	51 39 55.4		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Precast	**# Spans:**	1
Planned Inspection Comments:					

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K969

Site #:	K969	**Year Superstructure Installed:**	1992	**Structure Type/Class:**	Major Culvert
KM:	0.45	**User km:**	4.50	**Last Inspection Date:**	2022/09/28
Project File ID #:	8397	**Br.**	02	**Next Inspection Date:**	2023/09/28
Road Name:	RAFT-RAFT PEAK				
Crossing Name:	Candle Cr	**Total Length (metres):**	16.0		
Special Access:		**Special Equipment:**			
Longitude:	-119 57 8.9	**Latitude:**	51 41 35.1		
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:	IDIR\PBLUESCH on 11-APR-14: PB Apr11.2014 Monitor outlet rip rap for stability in 2015. CBR_Conversion on 17-FEB-14: PB Mar11/11. Annual inspection to monitor outlet rip rap. GMc Mar30/09 Inspect annually ubntil we are sure the the outlet rip rap is stable. Take extensive photos of the outlet rip rap so that comparisons can be made with earlier inspections				

Structure Name: K968

Site #:	K968	**Year Superstructure Installed:**	1992	**Structure Type/Class:**	Major Culvert
KM:	2.79	**User km:**	8.50	**Last Inspection Date:**	2022/09/28
Project File ID #:	8397	**Br.**	02	**Next Inspection Date:**	2023/09/28
Road Name:	RAFT-RAFT PEAK				
Crossing Name:	Candle #2	**Total Length (metres):**	19.0		
Special Access:		**Special Equipment:**			
Longitude:	-119 56 45.6	**Latitude:**	51 41 45.6		
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:	IDIR\PBLUESCH on 14-FEB-18: PB Feb14.2018 Inspect annually and after any significant flow event along with K969. IDIR\PBLUESCH on 11-APR-14: PB Apr11.2014 Inspect in 2015. CBR_Conversion on 17-FEB-14: GMc Mar 31/09 Inspect this annually seeing that K969 should be inspected annually				

Structure Name: K1079

Site #:	K1079	**Year Superstructure Installed:**	2003	**Structure Type/Class:**	Permanent Bridge
KM:	15.25	**User km:**	11.70	**Last Inspection Date:**	2020/09/20
Project File ID #:	8397	**Br.**	01	**Next Inspection Date:**	2023/09/20
Road Name:	RAFT-RAFT RIVER				
Crossing Name:	Willis Cr	**Total Length (metres):**	12.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 52 53.0	**Latitude:**	51 40 17.3		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K098

Site #:	K098	**Year Superstructure Installed:**	1989	**Structure Type/Class:**	Permanent Bridge
KM:	23.50	**User km:**	23.60	**Last Inspection Date:**	2020/09/20
Project File ID #:	8397	**Br.**	01	**Next Inspection Date:**	2023/09/20
Road Name:	RAFT-RAFT RIVER				
Crossing Name:	Molliet Cr	**Total Length (metres):**	11.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 44 40.3	**Latitude:**	51 42 13.6		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K056

Site #:	K056	**Year Superstructure Installed:**	1998	**Structure Type/Class:**	Permanent Bridge
KM:	39.08	**User km:**	39.50	**Last Inspection Date:**	2020/09/19
Project File ID #:	8397	**Br.**	01	**Next Inspection Date:**	2023/09/19
Road Name:	RAFT-RAFT RIVER				
Crossing Name:	#5	**Total Length (metres):**	15.0		
Special Access:		**Special Equipment:**			
Longitude:	-119 39 32.4	**Latitude:**	51 49 14.4		
Superstructure:	Concrete I/T Beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K1536

Site #:	K1536	**Year Superstructure Installed:**	2009	**Structure Type/Class:**	Temporary Bridge
KM:	48.00	**User km:**		**Last Inspection Date:**	2022/09/27
Project File ID #:	8397	**Br.**	01	**Next Inspection Date:**	2023/09/27
Road Name:	RAFT-RAFT RIVER				
Crossing Name:	Unnamed	**Total Length (metres):**	5.0		
Special Access:		**Special Equipment:**			
Longitude:	-119 35 40.2	**Latitude:**	51 51 51.0		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:	IDIR\PBLUESCH on 26-JAN-15: PB Jan26,2015 Have a close assessment of deck to girder connection.				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K854

Site #:	K854	**Year Superstructure Installed:**	1996	**Structure Type/Class:**	Permanent Bridge
KM:	51.46	**User km:**	52.30	**Last Inspection Date:**	2020/09/19
Project File ID #:	8397	**Br.**	01	**Next Inspection Date:**	2023/09/19
Road Name:	RAFT-RAFT RIVER				
Crossing Name:	Raft R	**Total Length (metres):**	24.0		
Special Access:		**Special Equipment:**			
Longitude:	-119 34 19.2	**Latitude:**	51 53 46.8		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K1020

Site #:	K1020	**Year Superstructure Installed:**	1996	**Structure Type/Class:**	Permanent Bridge
KM:	1.75	**User km:**	5.00	**Last Inspection Date:**	2022/09/27
Project File ID #:	8397	**Br.**	09	**Next Inspection Date:**	2023/09/27
Road Name:	RAFT-WEST RAFT				
Crossing Name:	Unnamed	**Total Length (metres):**	15.2		
Special Access:		**Special Equipment:**			
Longitude:	-119 46 10.2	**Latitude:**	51 48 34.2		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K1612A

Site #:	K1612	**Year Superstructure Installed:**	2013	**Structure Type/Class:**	Permanent Bridge
KM:	5.00	**User km:**		**Last Inspection Date:**	2022/09/25
Project File ID #:	7468	**Br.**	20	**Next Inspection Date:**	2023/09/25
Road Name:	REDSANDS				
Crossing Name:	Unknown	**Total Length (metres):**	12.2		
Special Access:		**Special Equipment:**			
Longitude:	-119 13 1.4	**Latitude:**	52 11 17.1		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 26-FEB-18: PB Feb26.2018 Voids in grout seams in deck joints should be fully assessed in 2018.				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K818

Site #:	K818	**Year Superstructure Installed:**	1999	**Structure Type/Class:**	Major Culvert
KM:	0.51	**User km:**	0.60	**Last Inspection Date:**	2020/09/30
Project File ID #:	9137	**Br.**	02	**Next Inspection Date:**	2023/09/30
Road Name:	ROAD 30				
Crossing Name:	Reg Christie Cr			**Total Length (metres):**	18.0
Special Access:				**Special Equipment:**	
Longitude:	-119 37 27.7			**Latitude:**	51 36 27.2
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:	IDIR\PBLUESCH on 13-FEB-18: PB Feb13.2018 The culvert invert is wearing through; closely inspect for condition and pipe performance with detailed photos. CBR_Conversion on 17-FEB-14: PB Mar 11,2011. It appears this structure has been confused with K817 for a number of years. Recently inspected as K817 in 2009 & 2010. Confirm location, GPS coordinates and structure details relative to K817.				

Structure Name: K1194A

Site #:	K1194	**Year Superstructure Installed:**	2014	**Structure Type/Class:**	Major Culvert
KM:	0.36	**User km:**	12.50	**Last Inspection Date:**	2020/10/02
Project File ID #:	7458	**Br.**	16	**Next Inspection Date:**	2023/10/02
Road Name:	ROCK CREEK				
Crossing Name:	Unnamed			**Total Length (metres):**	25.0
Special Access:				**Special Equipment:**	
Longitude:	-119 20 47.4			**Latitude:**	51 24 15.0
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:					

Structure Name: K697

Site #:	K697	**Year Superstructure Installed:**	1985	**Structure Type/Class:**	Temporary Bridge
KM:	4.33	**User km:**	5.00	**Last Inspection Date:**	2022/09/25
Project File ID #:	8256	**Br.**	01	**Next Inspection Date:**	2023/09/25
Road Name:	SERPENTINE CREEK				
Crossing Name:	Unnamed			**Total Length (metres):**	15.2
Special Access:				**Special Equipment:**	
Longitude:	-119 8 45.4			**Latitude:**	52 25 24.3
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Sill -Temporary Materials	**# Spans:**	1
Planned Inspection Comments:	IDIR\PBLUESCH on 01-FEB-19: PB Feb01.2019 WRONG STRUCTURE INSPECTED IN 2018 ON RP ROAD JUST DOWNSTREAM. K697 IS UPSTREAM APPROX 100M ON FSR. IDIR\PBLUESCH on 07-DEC-16: PB Dec 7,2016. Structure downrated from 10 tonnes to 5 tonnes. Ensure posted. IDIR\PBLUESCH on 27-JAN-15: PB Jan 27,2015 Ensure posted to 10 tonnes. Inspect timber deck condition.				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort: CBR_Conversion on 27-JAN-15: .

Structure Name: K696A

Site #:	K696	**Year Superstructure Installed:**	2011	**Structure Type/Class:**	Permanent Bridge
KM:	8.86	**User km:**	0.20	**Last Inspection Date:**	2020/09/16
Project File ID #:	8256	**Br.**	01	**Next Inspection Date:**	2023/09/16
Road Name:	SERPENTINE CREEK				
Crossing Name:	Moonbeam Cr	**Total Length (metres):**	18.3		
Special Access:		**Special Equipment:**			
Longitude:	-119 7 49.2	**Latitude:**	52 27 39.0		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K1445

Site #:	K1445	**Year Superstructure Installed:**	1990	**Structure Type/Class:**	Temporary Bridge
KM:	0.00	**User km:**	0.10	**Last Inspection Date:**	2022/09/23
Project File ID #:	9959	**Br.**	01	**Next Inspection Date:**	2023/09/23
Road Name:	SHANNON CREEK				
Crossing Name:	Shannon Cr	**Total Length (metres):**	15.4		
Special Access:		**Special Equipment:**			
Longitude:	-119 18 55.2	**Latitude:**	51 47 11.4		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Sill -Temporary Materials	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 11-APR-14: PB Feb 20,2012. New treated timber sills are only 3.7m long, girder to girder spacing is 3.3m. Monitor abutments for performance.				

Structure Name: K1466

Site #:	K1466	**Year Superstructure Installed:**	2000	**Structure Type/Class:**	Permanent Bridge
KM:	11.50	**User km:**		**Last Inspection Date:**	2020/09/17
Project File ID #:	10593	**Br.**	01	**Next Inspection Date:**	2023/09/17
Road Name:	THE LOOKOUT				
Crossing Name:	Unknown	**Total Length (metres):**	14.0		
Special Access:		**Special Equipment:**			
Longitude:	-119 25 37.1	**Latitude:**	52 4 10.6		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K816

Site #:	K816	**Year Superstructure Installed:**	1988	**Structure Type/Class:**	Permanent Bridge
KM:	6.35	**User km:**	31.50	**Last Inspection Date:**	2022/09/20
Project File ID #:	5072	**Br.**	01	**Next Inspection Date:**	2023/09/20
Road Name:	VAVENBY-ADAMS				
Crossing Name:	Roberts Cr	**Total Length (metres):**	12.0		
Special Access:		**Special Equipment:**			
Longitude:	-119 29 29.2	**Latitude:**	51 31 43.1		
Superstructure:	Concrete Box Beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Precast	**# Spans:**	1
Planned Inspection Comments:	IDIR\PBLUESCH on 01-NOV-17: PB Nov01.2017 Requires mounting block Burrard coupler replacement (grouted or mechanical), existing retrofit connections are stripping out of the concrete. Requires assessment and engineered procedure.				

Structure Name: K734

Site #:	K734	**Year Superstructure Installed:**	1978	**Structure Type/Class:**	Permanent Bridge
KM:	1.64	**User km:**	1.20	**Last Inspection Date:**	2022/09/20
Project File ID #:	7458	**Br.**	12	**Next Inspection Date:**	2023/09/20
Road Name:	ADAMS EAST				
Crossing Name:	Upper Adams R	**Total Length (metres):**	53.0		
Special Access:		**Special Equipment:**	Peeper Truck		
Longitude:	-119 27 17.5	**Latitude:**	51 26 3.9		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Pile -Permanent Materials	**# Spans:**	3
Planned Inspection Comments:	IDIR\PBLUESCH on 12-MAR-14: PB Mar12,2014 Drill pier piling for rot during 2014 peeper inspection. CBR_Conversion on 17-FEB-14: GMc Jan 21/10. The main pier may be subject to scour. The channel bottom around it should be sounded. Conduct routine inspection in 2012.				

Structure Name: K126

Site #:	K126	**Year Superstructure Installed:**	1995	**Structure Type/Class:**	Permanent Bridge
KM:	6.43	**User km:**	6.30	**Last Inspection Date:**	2022/09/20
Project File ID #:	7458	**Br.**	12	**Next Inspection Date:**	2023/09/20
Road Name:	ADAMS EAST				
Crossing Name:	Gannett Cr	**Total Length (metres):**	16.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 25 38.7	**Latitude:**	51 24 25.8		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	IDIR\PBLUESCH on 12-MAR-14: PB Mar12.2014 Assess damaged deck panel.				

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1032

Site #:	K1032	**Year Superstructure Installed:**	1999	**Structure Type/Class:**	Permanent Bridge
KM:	15.36	**User km:**	14.90	**Last Inspection Date:**	2020/10/03
Project File ID #:	7458	**Br.**	12	**Next Inspection Date:**	2023/10/03
Road Name:	ADAMS EAST				
Crossing Name:	Momich R			**Total Length (metres):**	30.5
Special Access:				**Special Equipment:**	
Longitude:	-119 25 9.7			**Latitude:**	51 20 5.8
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Steel Pipe and Precast Pad	**# Spans:** 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Jan 16,2013 Check curb mounting blocks for repair/replacement.				

Structure Name: K1734

Site #:	K1734	**Year Superstructure Installed:**		**Structure Type/Class:**	Temporary Bridge
KM:	2.00	**User km:**	2.00	**Last Inspection Date:**	2022/09/19
Project File ID #:	7458	**Br.**	05	**Next Inspection Date:**	2023/09/19
Road Name:	ADAMS W/BARRIEREPASS				
Crossing Name:	Unknown			**Total Length (metres):**	6.0
Special Access:				**Special Equipment:**	
Longitude:	-119 30 18.7			**Latitude:**	51 18 43.2
Superstructure:	Log Stringers	**Abutments (Left/Right):** *(looking downstream)*		Crib, Log or Untreated	**# Spans:** 1
Planned Inspection Comments:	IDIR\MRFENNEL on 06-FEB-19: Yearly inspections required.				

Structure Name: K059

Site #:	K059	**Year Superstructure Installed:**	1988	**Structure Type/Class:**	Permanent Bridge
KM:	4.67	**User km:**	4.70	**Last Inspection Date:**	2020/09/30
Project File ID #:	5072	**Br.**	04	**Next Inspection Date:**	2023/09/30
Road Name:	ADAMS-TUM TUM				
Crossing Name:	#2 Goat Cr			**Total Length (metres):**	15.0
Special Access:				**Special Equipment:**	
Longitude:	-119 24 20.4			**Latitude:**	51 30 57.0
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Sill - Permanent Materials	**# Spans:** 1
Planned Inspection Comments:					

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K810

Site #:	K810	**Year Superstructure Installed:**	1989	**Structure Type/Class:**	Permanent Bridge
KM:	11.02	**User km:**	11.00	**Last Inspection Date:**	2020/09/30
Project File ID #:	5072	**Br.**	04	**Next Inspection Date:**	2023/09/30
Road Name:	ADAMS-TUM TUM				
Crossing Name:	#3 Anderson Cr			**Total Length (metres):**	6.6
Special Access:				**Special Equipment:**	
Longitude:	-119 19 43.3			**Latitude:**	51 32 10.7
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K621

Site #:	K621	**Year Superstructure Installed:**	1999	**Structure Type/Class:**	Permanent Bridge
KM:	20.84	**User km:**	20.80	**Last Inspection Date:**	2022/09/21
Project File ID #:	5072	**Br.**	04	**Next Inspection Date:**	2023/09/21
Road Name:	ADAMS-TUM TUM				
Crossing Name:	McConnel Cr			**Total Length (metres):**	12.6
Special Access:				**Special Equipment:**	
Longitude:	-119 15 21.7			**Latitude:**	51 36 1.3
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	IDIR\PBLUESCH on 05-NOV-15: PB Nov 5, 2015. This structure was impacted by an event in Sept 2015 and the channel was heavily scoured exposing the pre-existing log crib mud sills and tie backs. This structure should be monitored for rip rap stability and additional scour. CBR_Conversion on 17-FEB-14:				

Structure Name: K1145A

Site #:	K1145	**Year Superstructure Installed:**	2019	**Structure Type/Class:**	Permanent Bridge
KM:	35.34	**User km:**	35.50	**Last Inspection Date:**	2020/09/30
Project File ID #:	5072	**Br.**	04	**Next Inspection Date:**	2023/09/30
Road Name:	ADAMS-TUM TUM				
Crossing Name:	Unnamed			**Total Length (metres):**	15.6
Special Access:				**Special Equipment:**	
Longitude:	-119 10 36.2			**Latitude:**	51 41 59.1
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	IDIR\MRFENNEL on 30-MAR-20: One year post installation inspection				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K063

Site #:	K063	**Year Superstructure Installed:**	1999	**Structure Type/Class:**	Permanent Bridge
KM:	37.80	**User km:**	22.74	**Last Inspection Date:**	2020/10/04
Project File ID #:	5072	**Br.**	04	**Next Inspection Date:**	2023/10/04
Road Name:	ADAMS-TUM TUM				
Crossing Name:	Lyost Cr	**Total Length (metres):**	10.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 10 37.7	**Latitude:**	51 43 19.7		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB June3/11 Curbs damaged winter 2010/11. Scheduled for replacement in 2011. Verify GPS coordinates MRF 2012/01/19				

Structure Name: K883

Site #:	K883	**Year Superstructure Installed:**	1999	**Structure Type/Class:**	Permanent Bridge
KM:	39.79	**User km:**	40.00	**Last Inspection Date:**	2020/09/30
Project File ID #:	5072	**Br.**	04	**Next Inspection Date:**	2023/09/30
Road Name:	ADAMS-TUM TUM				
Crossing Name:	Camp Six Cr	**Total Length (metres):**	15.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 10 0.0	**Latitude:**	51 44 7.2		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB June3/11 Curbs damaged winter 2010/11. Scheduled for replacement in 2011.				

Structure Name: K064

Site #:	K064	**Year Superstructure Installed:**	1996	**Structure Type/Class:**	Permanent Bridge
KM:	51.84	**User km:**	52.30	**Last Inspection Date:**	2020/09/30
Project File ID #:	5072	**Br.**	04	**Next Inspection Date:**	2023/09/30
Road Name:	ADAMS-TUM TUM				
Crossing Name:	#12	**Total Length (metres):**	11.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 8 26.4	**Latitude:**	51 49 45.6		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:	IDIR\PBLUESCH on 21-FEB-18: PB Feb21.2018 Continue to monitor tension cracks underside of girder slabs. CBR_Conversion on 17-FEB-14: PB June3/11 Curbs damaged winter 2010/11. Scheduled for replacement in 2011.				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K176

Site #:	K176	**Year Superstructure Installed:**	1991	**Structure Type/Class:**	Permanent Bridge
KM:	0.34	**User km:**	0.40	**Last Inspection Date:**	2020/07/14
Project File ID #:	9086	**Br.**	01	**Next Inspection Date:**	2023/07/14
Road Name:	BARLETT CREEK				
Crossing Name:	Louis Cr	**Total Length (metres):**	18.4		
Special Access:		**Special Equipment:**			
Longitude:	-120 2 45.6	**Latitude:**	51 4 47.6		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K1685

Site #:	K1685	**Year Superstructure Installed:**	2016	**Structure Type/Class:**	Permanent Bridge
KM:	7.40	**User km:**	7.40	**Last Inspection Date:**	2020/10/03
Project File ID #:	7458	**Br.**	21	**Next Inspection Date:**	2023/10/03
Road Name:	BATES ROAD				
Crossing Name:	Unnamed	**Total Length (metres):**	11.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 15 21.0	**Latitude:**	51 21 11.0		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K1028

Site #:	K1028	**Year Superstructure Installed:**	1997	**Structure Type/Class:**	Permanent Bridge
KM:	7.25	**User km:**	6.80	**Last Inspection Date:**	2020/09/18
Project File ID #:	8410	**Br.**	02	**Next Inspection Date:**	2023/09/18
Road Name:	BERRY-MESSITER				
Crossing Name:	Snowball Cr	**Total Length (metres):**	15.2		
Special Access:		**Special Equipment:**			
Longitude:	-119 21 9.4	**Latitude:**	51 57 50.8		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:					

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K829

Site #:	K829	**Year Superstructure Installed:**	1986	**Structure Type/Class:**	Major Culvert
KM:	9.00	**User km:**	5.37	**Last Inspection Date:**	2022/09/24
Project File ID #:	8410	**Br.**	02	**Next Inspection Date:**	2023/09/24
Road Name:	BERRY-MESSITER				
Crossing Name:	Unnamed			**Total Length (metres):**	22.0
Special Access:				**Special Equipment:**	
Longitude:	-119 21 3.6			**Latitude:**	51 56 53.9
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:	IDIR\PBLUESCH on 25-MAR-14: PB Mar 25.2014 Continue to monitor piping at inlet and condition of failing invert at the outlet. Use caution near the outlet.				

Structure Name: K1062

Site #:	K1062	**Year Superstructure Installed:**	1998	**Structure Type/Class:**	Permanent Bridge
KM:	12.92	**User km:**	0.10	**Last Inspection Date:**	2020/07/14
Project File ID #:	8553	**Br.**	02	**Next Inspection Date:**	2023/07/14
Road Name:	BLACK PINES				
Crossing Name:	Jamieson Cr			**Total Length (metres):**	12.6
Special Access:				**Special Equipment:**	
Longitude:	-120 18 44.6			**Latitude:**	50 59 14.2
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: 5009

Site #:	5009	**Year Superstructure Installed:**	1970	**Structure Type/Class:**	Temporary Bridge
KM:	2.33	**User km:**	4.80	**Last Inspection Date:**	2022/09/25
Project File ID #:	0731	**Br.**	14	**Next Inspection Date:**	2023/09/25
Road Name:	BR1850A				
Crossing Name:	unknown			**Total Length (metres):**	7.5
Special Access:	ATV			**Special Equipment:**	
Longitude:	-119 8 59.4			**Latitude:**	52 14 0.2
Superstructure:	Log Stringers	**Abutments (Left/Right):** *(looking downstream)*	Sill -Temporary Materials	**# Spans:**	1
Planned Inspection Comments:	IDIR\PBLUESCH on 26-FEB-18: PB Feb 26.2018 District to confirm access to site prior to mobilizing for inspection. Structure may be a hazard to traffic if/when road system is opened up due to the age of this log structure. This crossing has not been inspected since 2009 due to lack of access. CBR_Conversion on 17-FEB-14: GMC Apr 7/09 Pick up as built info and post to 5 T ATV access required due to slide across road MRF 2012/01/18				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: PS-020

Site #:	K1541	**Year Superstructure Installed:**	2015	**Structure Type/Class:**	Permanent Bridge
KM:	16.10	**User km:**	16.10	**Last Inspection Date:**	2020/07/14
Project File ID #:	4482	**Br.**	01	**Next Inspection Date:**	2023/07/14
Road Name:	CAHILITY CREEK FSR				
Crossing Name:	unknown	**Total Length (metres):**	9.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 53 46.7	**Latitude:**	50 55 11.4		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 23-FEB-18: n/a				

Structure Name: K1619A

Site #:	K1619	**Year Superstructure Installed:**	2022	**Structure Type/Class:**	Permanent Bridge
KM:	3.20	**User km:**		**Last Inspection Date:**	
Project File ID #:	1422	**Br.**	46	**Next Inspection Date:**	2023/06/01
Road Name:	CL1422.46				
Crossing Name:	unnamed	**Total Length (metres):**	9.6		
Special Access:		**Special Equipment:**			
Longitude:	-120 23 8.7	**Latitude:**	51 34 7.2		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K1620A

Site #:	K1620	**Year Superstructure Installed:**	2022	**Structure Type/Class:**	Permanent Bridge
KM:	3.60	**User km:**		**Last Inspection Date:**	
Project File ID #:	1422	**Br.**	46	**Next Inspection Date:**	2023/06/01
Road Name:	CL1422.46				
Crossing Name:	unnamed	**Total Length (metres):**	10.6		
Special Access:		**Special Equipment:**			
Longitude:	-120 23 13.8	**Latitude:**	51 34 20.1		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1762

Site #:	K1762	**Year Superstructure Installed:**	2022	**Structure Type/Class:**	Major Culvert
KM:	1.50	**User km:**	1.50	**Last Inspection Date:**	
Project File ID #:	8398	**Br.**	14	**Next Inspection Date:**	2023/08/19
Road Name:	CL8398.14				
Crossing Name:	Unnamed	**Total Length (metres):**	31.0		
Special Access:		**Special Equipment:**			
Longitude:	-119 19 49.0	**Latitude:**	51 48 22.0		
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:					

Structure Name: TKA-022

Site #:	K1712	**Year Superstructure Installed:**	2018	**Structure Type/Class:**	Temporary Bridge
KM:	2.50	**User km:**	2.50	**Last Inspection Date:**	2021/09/14
Project File ID #:	8412	**Br.**	31	**Next Inspection Date:**	2023/09/14
Road Name:	CL8412.31				
Crossing Name:	Unknown	**Total Length (metres):**	12.2		
Special Access:		**Special Equipment:**			
Longitude:	-119 52 1.5	**Latitude:**	51 32 50.0		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:	IDIR\MRFENNEL on 07-FEB-19: One year post installation inspection				

Structure Name: K1419

Site #:	K1419	**Year Superstructure Installed:**	1985	**Structure Type/Class:**	Permanent Bridge
KM:	1.00	**User km:**	0.00	**Last Inspection Date:**	2020/09/28
Project File ID #:	7669	**Br.**	01	**Next Inspection Date:**	2023/09/28
Road Name:	CLEARWATER-100 MILE				
Crossing Name:	Brookfield Cr	**Total Length (metres):**	9.3		
Special Access:		**Special Equipment:**	Peeper Truck		
Longitude:	-120 5 24.0	**Latitude:**	51 39 15.0		
Superstructure:	Steel Box Beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Cast in Place	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Mar 09/11. Confirm and provide updated GPS coords. Structure appears to be incorrectly mapped. Confirm bridge length.				

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1519

Site #:	K1519	**Year Superstructure Installed:**	2013	**Structure Type/Class:**	Permanent Bridge
KM:	35.00	**User km:**		**Last Inspection Date:**	2020/07/11
Project File ID #:	7669	**Br.**	01	**Next Inspection Date:**	2023/07/11
Road Name:	CLEARWATER-100 MILE				
Crossing Name:	Unnamed			**Total Length (metres):**	15.4
Special Access:				**Special Equipment:**	
Longitude:	-120 29 22.0			**Latitude:**	51 44 32.0
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K1658

Site #:	K1658	**Year Superstructure Installed:**	2002	**Structure Type/Class:**	Temporary Bridge
KM:	14.40	**User km:**	14.40	**Last Inspection Date:**	2022/09/04
Project File ID #:	8502	**Br.**	01	**Next Inspection Date:**	2023/09/04
Road Name:	CORNWALL CREEK				
Crossing Name:	maclaren creek			**Total Length (metres):**	6.2
Special Access:				**Special Equipment:**	
Longitude:	-121 25 8.0			**Latitude:**	50 46 48.1
Superstructure:	Log Stringers	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:	IDIR\PBLUESCH on 05-FEB-19: PB Feb05.2019 Closely inspect stringers at sills for rot. Drill and record rot values at bearing locations. IDIR\DMALWAY on 06-JUL-15: Annual inspection due to age				

Structure Name: K1432

Site #:	K1432	**Year Superstructure Installed:**	2007	**Structure Type/Class:**	Major Culvert
KM:	12.50	**User km:**	0.00	**Last Inspection Date:**	2020/07/12
Project File ID #:	1422	**Br.**	10	**Next Inspection Date:**	2023/07/12
Road Name:	CP 879				
Crossing Name:	Blowdown Cr.			**Total Length (metres):**	14.9
Special Access:				**Special Equipment:**	
Longitude:	-120 28 21.0			**Latitude:**	51 32 37.0
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: note that the culvert is not actually on branch one. GPS Coordinates should be used to locate structure.				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: PS002

Site #:	K1727	**Year Superstructure Installed:**	2018	**Structure Type/Class:**	Temporary Bridge
KM:	0.14	**User km:**	0.14	**Last Inspection Date:**	2021/09/06
Project File ID #:	8544	**Br.**	11	**Next Inspection Date:**	2023/09/06
Road Name:	CP 887				
Crossing Name:	Unknown	**Total Length (metres):**	12.0		
Special Access:		**Special Equipment:**			
Longitude:	-120 18 41.4	**Latitude:**	51 34 2.3		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 28-FEB-20: na IDIR\PBLUESCH on 28-FEB-20: na				

Structure Name: WO3459

Site #:	K1728	**Year Superstructure Installed:**	2018	**Structure Type/Class:**	Temporary Bridge
KM:	0.50	**User km:**	0.50	**Last Inspection Date:**	2021/09/06
Project File ID #:	8544	**Br.**	11	**Next Inspection Date:**	2023/09/06
Road Name:	CP 887				
Crossing Name:	Unknown	**Total Length (metres):**	7.6		
Special Access:		**Special Equipment:**			
Longitude:	-120 18 24.6	**Latitude:**	51 34 5.2		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Other	**# Spans:**	1
Planned Inspection Comments:	IDIR\MRFENNEL on 07-FEB-19: One year post construction inspection CBR_Conversion on 17-FEB-14: One year post construction inspection, bring and install site ID plate. DA. 2011.				

Structure Name: K863

Site #:	K863	**Year Superstructure Installed:**	1995	**Structure Type/Class:**	Permanent Bridge
KM:	0.61	**User km:**	0.70	**Last Inspection Date:**	2022/09/04
Project File ID #:	7529	**Br.**	01	**Next Inspection Date:**	2023/09/04
Road Name:	CRISS CREEK				
Crossing Name:	Criss Cr	**Total Length (metres):**	22.7		
Special Access:		**Special Equipment:**	Peeper Truck		
Longitude:	-120 57 34.4	**Latitude:**	50 53 16.2		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Structure to be downgraded at next inspection if concrete repair is not completed. DA Jan 2014				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1063

Site #:	K1063	**Year Superstructure Installed:**	1998	**Structure Type/Class:**	Permanent Bridge
KM:	7.98	**User km:**	37.00	**Last Inspection Date:**	2020/07/13
Project File ID #:	0690	**Br.**	01	**Next Inspection Date:**	2023/07/13
Road Name:	DARLINGTON				
Crossing Name:	Machete Cr	**Total Length (metres):**	15.8		
Special Access:		**Special Equipment:**			
Longitude:	-120 29 34.8	**Latitude:**	51 23 11.7		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	IDIR\DMALWAY on 26-FEB-18: na				

Structure Name: K864

Site #:	K864	**Year Superstructure Installed:**	1997	**Structure Type/Class:**	Permanent Bridge
KM:	34.14	**User km:**	10.90	**Last Inspection Date:**	2022/09/29
Project File ID #:	0690	**Br.**	01	**Next Inspection Date:**	2023/09/29
Road Name:	DARLINGTON				
Crossing Name:	Lindquist Cr	**Total Length (metres):**	24.0		
Special Access:		**Special Equipment:**	Peeper Truck		
Longitude:	-120 15 58.8	**Latitude:**	51 17 53.4		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Significant cracking has been noted and evaulated professionally, continue to monitor. DA				

Structure Name: K866

Site #:	K866	**Year Superstructure Installed:**	1998	**Structure Type/Class:**	Permanent Bridge
KM:	39.60	**User km:**	4.70	**Last Inspection Date:**	2022/09/29
Project File ID #:	0690	**Br.**	01	**Next Inspection Date:**	2023/09/29
Road Name:	DARLINGTON				
Crossing Name:	Darlington Cr	**Total Length (metres):**	9.6		
Special Access:		**Special Equipment:**			
Longitude:	-120 13 12.6	**Latitude:**	51 18 56.7		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K655

Site #:	K655	**Year Superstructure Installed:**	1992	**Structure Type/Class:**	Permanent Bridge
KM:	0.01	**User km:**	0.10	**Last Inspection Date:**	2022/10/06
Project File ID #:	0562	**Br.**	04	**Next Inspection Date:**	2023/10/06
Road Name:	DUNN PEAK				
Crossing Name:	Harper Cr	**Total Length (metres):**	14.0		
Special Access:		**Special Equipment:**			
Longitude:	-119 51 11.9	**Latitude:**	51 28 27.4		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Precast	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K647A

Site #:	K647	**Year Superstructure Installed:**	2014	**Structure Type/Class:**	Permanent Bridge
KM:	2.03	**User km:**	1.90	**Last Inspection Date:**	2022/09/23
Project File ID #:	8398	**Br.**	06	**Next Inspection Date:**	2023/09/23
Road Name:	E AVOLA-LION CREEK				
Crossing Name:	Unnamed	**Total Length (metres):**	18.3		
Special Access:		**Special Equipment:**			
Longitude:	-119 20 53.5	**Latitude:**	51 52 15.5		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	IDIR\MRFENNEL on 19-FEB-16: PB Feb19,2016 Complete detailed inspection of panel joints from below deck. Review all comments from 2015 routine inspection.				

Structure Name: K792A

Site #:	K792	**Year Superstructure Installed:**	2021	**Structure Type/Class:**	Major Culvert
KM:	10.22	**User km:**	10.10	**Last Inspection Date:**	2022/09/28
Project File ID #:	8422	**Br.**	01	**Next Inspection Date:**	2023/09/28
Road Name:	EAST BLACKPOOL				
Crossing Name:	McClennon Cr	**Total Length (metres):**	18.0		
Special Access:	Gate Key	**Special Equipment:**			
Longitude:	-120 5 25.2	**Latitude:**	51 33 35.0		
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:					

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1411

Site #:	K1411	**Year Superstructure Installed:**	2008	**Structure Type/Class:**	Permanent Bridge
KM:	0.00	**User km:**	17.00	**Last Inspection Date:**	2020/07/14
Project File ID #:	9232	**Br.**	01	**Next Inspection Date:**	2023/07/14
Road Name:	EILEEN LAKE				
Crossing Name:	Niskonlith Cr	**Total Length (metres):**	9.5		
Special Access:		**Special Equipment:**			
Longitude:	-119 49 53.9	**Latitude:**	50 48 7.9		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K1187

Site #:	K1187	**Year Superstructure Installed:**	2001	**Structure Type/Class:**	Permanent Bridge
KM:	10.60	**User km:**	12.30	**Last Inspection Date:**	2020/07/14
Project File ID #:	9232	**Br.**	01	**Next Inspection Date:**	2023/07/14
Road Name:	EILEEN LAKE				
Crossing Name:	Louis Cr	**Total Length (metres):**	12.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 55 46.4	**Latitude:**	50 48 42.7		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K1034

Site #:	K1034	**Year Superstructure Installed:**	1999	**Structure Type/Class:**	Permanent Bridge
KM:	13.36	**User km:**	14.50	**Last Inspection Date:**	2020/07/14
Project File ID #:	9232	**Br.**	01	**Next Inspection Date:**	2023/07/14
Road Name:	EILEEN LAKE				
Crossing Name:	Dominion Cr	**Total Length (metres):**	11.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 56 37.8	**Latitude:**	50 49 39.6		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	IDIR\DMALWAY on 28-FEB-18: upon next inspection confirm out to out length of slabs. As WCP dwg on file note 11.6 m o/o.				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1583

Site #:	K1583	**Year Superstructure Installed:**		**Structure Type/Class:**	Permanent Bridge
KM:	13.40	**User km:**	68.60	**Last Inspection Date:**	2022/10/04
Project File ID #:	8591	**Br.**	35	**Next Inspection Date:**	2023/10/04
Road Name:	FATOX LAKE				
Crossing Name:	Deadman R			**Total Length (metres):**	11.6
Special Access:				**Special Equipment:**	
Longitude:	-120 47 43.3			**Latitude:**	51 7 12.6
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*		Steel Pipe and Precast Pad	**# Spans:** 1
Planned Inspection Comments:	IDIR\PBLUESCH on 06-FEB-19: PB Feb06.2019 Repairs called for by D.Alway in 2013 not yet complete. Footings, towers and cap beams are rotating. Continue to monitor abutment condition.				

Structure Name: K830

Site #:	K830	**Year Superstructure Installed:**	1994	**Structure Type/Class:**	Permanent Bridge
KM:	0.14	**User km:**	14.00	**Last Inspection Date:**	2020/09/18
Project File ID #:	0565	**Br.**	04	**Next Inspection Date:**	2023/09/18
Road Name:	FINN-BRANCH 1				
Crossing Name:	Finn Cr			**Total Length (metres):**	16.0
Special Access:				**Special Equipment:**	
Longitude:	-119 10 19.8			**Latitude:**	51 58 23.6
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Concrete Precast	**# Spans:** 1
Planned Inspection Comments:	IDIR\MRFENNEL on 07-FEB-17: Bridge is located less than 200m off of the Finn Cr FSR				

Structure Name: K692A

Site #:	K692	**Year Superstructure Installed:**	2016	**Structure Type/Class:**	Permanent Bridge
KM:	28.54	**User km:**	27.70	**Last Inspection Date:**	2020/09/18
Project File ID #:	0565	**Br.**	01	**Next Inspection Date:**	2023/09/18
Road Name:	FINN-FINN CREEK				
Crossing Name:	Adams R			**Total Length (metres):**	39.6
Special Access:				**Special Equipment:**	
Longitude:	-119 5 54.6			**Latitude:**	52 0 3.3
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Steel Pipe and Precast Pad	**# Spans:** 1
Planned Inspection Comments:	IDIR\MRFENNEL on 21-FEB-18: PB Feb21.2018 Monitor rip rap for stability and scour at both abutments.				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K066

Site #:	K066	**Year Superstructure Installed:**	1998	**Structure Type/Class:**	Permanent Bridge
KM:	3.98	**User km:**	15.90	**Last Inspection Date:**	2022/09/21
Project File ID #:	0565	**Br.**	03	**Next Inspection Date:**	2023/09/21
Road Name:	FINN-TUM				
Crossing Name:	Unnamed	**Total Length (metres):**	13.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 8 17.7	**Latitude:**	51 52 44.9		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	IDIR\PBLUESCH on 05-FEB-20: PB Feb05.2020 Abutment cap beam requires concrete repair; a full or complete repair may not be feasible as the spalling concrete cap appears to be in contact with slabs. This indicates footings may be rotating.				

Structure Name: K1027

Site #:	K1027	**Year Superstructure Installed:**	1998	**Structure Type/Class:**	Permanent Bridge
KM:	8.33	**User km:**	11.20	**Last Inspection Date:**	2022/09/21
Project File ID #:	0565	**Br.**	03	**Next Inspection Date:**	2023/09/21
Road Name:	FINN-TUM				
Crossing Name:	Unnamed	**Total Length (metres):**	18.3		
Special Access:		**Special Equipment:**			
Longitude:	-119 6 28.3	**Latitude:**	51 54 41.2		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K807

Site #:	K807	**Year Superstructure Installed:**	1995	**Structure Type/Class:**	Permanent Bridge
KM:	16.63	**User km:**	3.80	**Last Inspection Date:**	2022/09/24
Project File ID #:	0565	**Br.**	03	**Next Inspection Date:**	2023/09/24
Road Name:	FINN-TUM				
Crossing Name:	Adams R	**Total Length (metres):**	43.2		
Special Access:		**Special Equipment:**	Peeper Truck		
Longitude:	-119 5 27.5	**Latitude:**	51 58 57.3		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Pile -Permanent Materials	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Mar 10/11 Confirm GPS coords. Those collected in 2010 look incorrect.				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K088

Site #:	K088	**Year Superstructure Installed:**	1998	**Structure Type/Class:**	Permanent Bridge
KM:	8.92	**User km:**	9.30	**Last Inspection Date:**	2022/09/20
Project File ID #:	7458	**Br.**	14	**Next Inspection Date:**	2023/09/20
Road Name:	GANNETT LAKE				
Crossing Name:	Gannett Cr	**Total Length (metres):**	10.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 24 9.0	**Latitude:**	51 25 59.5		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 06-FEB-19: PB Feb13,2012 Monitor sills and bearing pads. Right Bank footings appear to have been hooked at install and pulled out of plumb. IDIR\PBLUESCH on 06-FEB-19: #				

Structure Name: K811A

Site #:	K811	**Year Superstructure Installed:**	2020	**Structure Type/Class:**	Permanent Bridge
KM:	5.52	**User km:**	4.00	**Last Inspection Date:**	2022/09/20
Project File ID #:	7458	**Br.**	09	**Next Inspection Date:**	2023/09/20
Road Name:	GOLLEN CREEK				
Crossing Name:	Gollen Cr	**Total Length (metres):**	24.4		
Special Access:		**Special Equipment:**			
Longitude:	-119 31 22.6	**Latitude:**	51 27 59.2		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K1758

Site #:	K1758	**Year Superstructure Installed:**	2020	**Structure Type/Class:**	Major Culvert
KM:	3.50	**User km:**	3.50	**Last Inspection Date:**	2022/09/20
Project File ID #:	7458	**Br.**	13	**Next Inspection Date:**	2023/09/20
Road Name:	HARBOUR LAKE				
Crossing Name:	Marjorie Cr	**Total Length (metres):**	16.0		
Special Access:		**Special Equipment:**			
Longitude:	-119 27 11.0	**Latitude:**	51 27 44.0		
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:					

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K145

Site #:	K145	**Year Superstructure Installed:**	1992	**Structure Type/Class:**	Permanent Bridge
KM:	17.20	**User km:**	17.60	**Last Inspection Date:**	2020/07/13
Project File ID #:	0562	**Br.**	02	**Next Inspection Date:**	2023/07/13
Road Name:	HARPER CREEK				
Crossing Name:	Unnamed	**Total Length (metres):**	8.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 51 1.8	**Latitude:**	51 27 59.4		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Moved to annual inspection to monitor scour and lack of riprap issues closer. DA Jan 2014.				

Structure Name: K1418

Site #:	K1418	**Year Superstructure Installed:**	2007	**Structure Type/Class:**	Major Culvert
KM:	37.81	**User km:**	21.50	**Last Inspection Date:**	2020/07/14
Project File ID #:	8553	**Br.**	01	**Next Inspection Date:**	2023/07/14
Road Name:	JAMIESON CREEK				
Crossing Name:	Unnamed	**Total Length (metres):**	17.0		
Special Access:		**Special Equipment:**			
Longitude:	-120 18 17.1	**Latitude:**	51 2 11.9		
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:					

Structure Name: K933

Site #:	K933	**Year Superstructure Installed:**	1968	**Structure Type/Class:**	Permanent Bridge
KM:	51.69	**User km:**	6.70	**Last Inspection Date:**	2022/10/04
Project File ID #:	8553	**Br.**	01	**Next Inspection Date:**	2023/10/04
Road Name:	JAMIESON CREEK				
Crossing Name:	Jamieson Cr #5	**Total Length (metres):**	8.7		
Special Access:		**Special Equipment:**			
Longitude:	-120 19 17.4	**Latitude:**	50 55 19.4		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Cast in Place	**# Spans:**	1
Planned Inspection Comments:	IDIR\PBLUESCH on 06-FEB-19: PB Feb06,2019 Structure is planned for replacement.				

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: TKA012

Site #:	K1644	**Year Superstructure Installed:**	2015	**Structure Type/Class:**	Temporary Bridge
KM:	3.50	**User km:**	3.50	**Last Inspection Date:**	2021/07/05
Project File ID #:	10043	**Br.**	05	**Next Inspection Date:**	2023/07/05
Road Name:	KA10043.05				
Crossing Name:	Cowell Cr	**Total Length (metres):**	15.2		
Special Access:		**Special Equipment:**			
Longitude:	-120 6 1.1	**Latitude:**	51 24 20.9		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K1611

Site #:	K1611	**Year Superstructure Installed:**	2008	**Structure Type/Class:**	Permanent Bridge
KM:	1.30	**User km:**	1.30	**Last Inspection Date:**	2020/07/13
Project File ID #:	10873	**Br.**	01	**Next Inspection Date:**	2023/07/13
Road Name:	KA10873.01				
Crossing Name:	Demers Creek	**Total Length (metres):**	8.6		
Special Access:		**Special Equipment:**			
Longitude:	-120 13 57.1	**Latitude:**	51 28 53.7		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: WO 2324

Site #:	K1760	**Year Superstructure Installed:**	2020	**Structure Type/Class:**	Temporary Bridge
KM:	0.80	**User km:**	0.80	**Last Inspection Date:**	2021/07/03
Project File ID #:	5451	**Br.**	19	**Next Inspection Date:**	2023/07/03
Road Name:	KA5451.19				
Crossing Name:	Scottie Creek	**Total Length (metres):**	20.0		
Special Access:		**Special Equipment:**			
Longitude:	-121 21 50.9	**Latitude:**	50 58 37.6		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks/Sill -	**# Spans:**	1
Planned Inspection Comments:					

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: 65232389

Site #:	K1599	**Year Superstructure Installed:**	2012	**Structure Type/Class:**	Temporary Bridge
KM:	0.25	**User km:**	46.75	**Last Inspection Date:**	2021/07/02
Project File ID #:	8553	**Br.**	87	**Next Inspection Date:**	2023/07/02
Road Name:	KA8553.87				
Crossing Name:	Criss Creek			**Total Length (metres):**	12.2
Special Access:				**Special Equipment:**	
Longitude:	-120 33 10.0			**Latitude:**	51 2 50.0
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Concrete Lock Blocks	**# Spans:** 1
Planned Inspection Comments:					

Structure Name: WO-2750

Site #:	K1600	**Year Superstructure Installed:**	2012	**Structure Type/Class:**	Temporary Bridge
KM:	2.50	**User km:**	49.00	**Last Inspection Date:**	2021/07/02
Project File ID #:	8553	**Br.**	87	**Next Inspection Date:**	2023/07/02
Road Name:	KA8553.87				
Crossing Name:	unnamed			**Total Length (metres):**	12.2
Special Access:				**Special Equipment:**	
Longitude:	-120 32 37.0			**Latitude:**	51 2 10.0
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Concrete Lock Blocks	**# Spans:** 1
Planned Inspection Comments:	IDIR\PBLUESCH on 05-FEB-20: PB Feb05.2020 Check clearance between abutment armouring and underside of girders next inspection.				

Structure Name: TKA011

Site #:	K1624	**Year Superstructure Installed:**	2013	**Structure Type/Class:**	Temporary Bridge
KM:	1.00	**User km:**	1.00	**Last Inspection Date:**	2021/07/02
Project File ID #:	8553	**Br.**	88	**Next Inspection Date:**	2023/07/02
Road Name:	KA8553.88				
Crossing Name:	Unknown Creek			**Total Length (metres):**	12.2
Special Access:				**Special Equipment:**	
Longitude:	-120 31 33.4			**Latitude:**	51 1 59.5
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Sill - Permanent Materials	**# Spans:** 1
Planned Inspection Comments:	IDIR\DMALWAY on 23-FEB-18: na				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1010

Site #:	K1010	**Year Superstructure Installed:**	1997	**Structure Type/Class:**	Permanent Bridge
KM:	2.50	**User km:**	4.00	**Last Inspection Date:**	2022/09/29
Project File ID #:	1422	**Br.**	02	**Next Inspection Date:**	2023/09/29
Road Name:	LOST HORSE LAKE				
Crossing Name:	Lost Horse Cr	**Total Length (metres):**	4.5		
Special Access:		**Special Equipment:**			
Longitude:	-120 24 25.2	**Latitude:**	51 34 11.6		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K053

Site #:	K053	**Year Superstructure Installed:**	1998	**Structure Type/Class:**	Permanent Bridge
KM:	20.73	**User km:**	21.30	**Last Inspection Date:**	2020/09/19
Project File ID #:	4771	**Br.**	01	**Next Inspection Date:**	2023/09/19
Road Name:	MAD RIVER				
Crossing Name:	Unnamed	**Total Length (metres):**	11.6		
Special Access:		**Special Equipment:**			
Longitude:	-119 28 27.0	**Latitude:**	51 46 56.4		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K1156

Site #:	K1156	**Year Superstructure Installed:**	2001	**Structure Type/Class:**	Permanent Bridge
KM:	0.87	**User km:**	5.50	**Last Inspection Date:**	2020/07/12
Project File ID #:	9968	**Br.**	01	**Next Inspection Date:**	2023/07/12
Road Name:	MAHOOD-WEST MAINLINE				
Crossing Name:	Unnamed	**Total Length (metres):**	17.0		
Special Access:		**Special Equipment:**			
Longitude:	-120 25 15.9	**Latitude:**	51 51 56.9		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1095

Site #:	K1095	**Year Superstructure Installed:**	2001	**Structure Type/Class:**	Permanent Bridge
KM:	5.19	**User km:**	5.20	**Last Inspection Date:**	2020/07/12
Project File ID #:	9968	**Br.**	01	**Next Inspection Date:**	2023/07/12
Road Name:	MAHOOD-WEST MAINLINE				
Crossing Name:	Unnamed	**Total Length (metres):**	18.3		
Special Access:		**Special Equipment:**			
Longitude:	-120 25 24.0	**Latitude:**	51 51 53.8		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K822

Site #:	K822	**Year Superstructure Installed:**	1993	**Structure Type/Class:**	Permanent Bridge
KM:	9.40	**User km:**	3.30	**Last Inspection Date:**	2022/09/26
Project File ID #:	0590	**Br.**	03	**Next Inspection Date:**	2023/07/01
Road Name:	MANTEAU-CANVAS CREEK				
Crossing Name:	Canvas Cr	**Total Length (metres):**	15.3		
Special Access:		**Special Equipment:**			
Longitude:	-119 16 40.5	**Latitude:**	52 27 28.7		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Jan25,2013 Monitor abutments for stability and erosion. Post to 10 tonnes. MRF 01/2012 Bridge is located on Canvas Creek FSR. Wrong site identified and inspected last inspection. Site is still active. PB Mar11/11. Structure inspected in 2010 does not appear to be K822. Locate and inspect K822 in 2011, confirm location and GPS coords. Check with District. (Structure inspected in 2010 has been posted to 5 tonnes by BCTS and is scheduled for removal in spring 2011.)				

Structure Name: K162A

Site #:	K162	**Year Superstructure Installed:**	2019	**Structure Type/Class:**	Permanent Bridge
KM:	9.13	**User km:**	19.10	**Last Inspection Date:**	2020/07/14
Project File ID #:	4337	**Br.**	01	**Next Inspection Date:**	2023/07/14
Road Name:	MCGILLVRAY LAKE				
Crossing Name:	McGillvray Cr	**Total Length (metres):**	21.2		
Special Access:		**Special Equipment:**			
Longitude:	-119 50 38.6	**Latitude:**	50 51 22.1		
Superstructure:	Glulam Girder	**Abutments (Left/Right):** *(looking downstream)*	Other	**# Spans:**	1
Planned Inspection Comments:	IDIR\MRFENNEL on 30-MAR-20: One year post installation inspection.				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K693

Site #:	K693	**Year Superstructure Installed:**	1983	**Structure Type/Class:**	Permanent Bridge
KM:	2.80	**User km:**	0.10	**Last Inspection Date:**	2022/09/24
Project File ID #:	7468	**Br.**	01	**Next Inspection Date:**	2023/09/24
Road Name:	MUD LAKE				
Crossing Name:	Red Sands Bridge	**Total Length (metres):**	60.8		
Special Access:		**Special Equipment:**	Peeper Truck		
Longitude:	-119 17 6.0	**Latitude:**	52 7 55.8		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Pile -Permanent	**# Spans:**	3

Planned Inspection Comments:
IDIR\PBLUESCH on 26-FEB-18: PB Feb 26.2018 Assess lean of primary pier for further movement.
IDIR\PBLUESCH on 23-JAN-17: PB Jan23.2017 Structure to be posted Max GVW 63.5 T.
CBR_Conversion on 17-FEB-14: PB Mar 28/11. Complete routine condition inspection in 2012. Assess condition of town side timber retaining wall (untreated cedar installed in 1982/1983). Structure may also be peeper inspected in 2012. Girder connections at piers to be assessed by peeper.

Structure Name: 5011

Site #:	5011	**Year Superstructure Installed:**	1998	**Structure Type/Class:**	Temporary Bridge
KM:	8.23	**User km:**	26.50	**Last Inspection Date:**	2022/09/24
Project File ID #:	7468	**Br.**	01	**Next Inspection Date:**	2023/09/24
Road Name:	MUD LAKE				
Crossing Name:	Mud River	**Total Length (metres):**	36.7		
Special Access:	ATV	**Special Equipment:**			
Longitude:	-119 6 56.0	**Latitude:**	52 7 16.2		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Sill -Temporary Materials	**# Spans:**	2

Planned Inspection Comments:
IDIR\PBLUESCH on 06-FEB-19: Walking access only for 3.5km.
CBR_Conversion on 17-FEB-14: Quad access required MRF 2012/01/18

Structure Name: K142A

Site #:	K142	**Year Superstructure Installed:**	2013	**Structure Type/Class:**	Permanent Bridge
KM:	13.00	**User km:**	13.30	**Last Inspection Date:**	2020/07/13
Project File ID #:	0562	**Br.**	01	**Next Inspection Date:**	2023/07/13
Road Name:	NORTH BARRIERE LAKE				
Crossing Name:	Barriere River	**Total Length (metres):**	24.4		
Special Access:		**Special Equipment:**			
Longitude:	-119 43 12.7	**Latitude:**	51 21 12.4		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1

Planned Inspection Comments: IDIR\DMALWAY on 26-FEB-18: na

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1467

Site #:	K1467	**Year Superstructure Installed:**		2002	**Structure Type/Class:**	Temporary Bridge	
KM:	9.90	**User km:**	8.40	**Last Inspection Date:**		2021/09/12	
Project File ID #:	8090	**Br.**	02	**Next Inspection Date:**		2023/09/12	
Road Name:	NORTH FROTH						
Crossing Name:	Wilkins Creek			**Total Length (metres):**	12.2		
Special Access:	Four Wheel Drive			**Special Equipment:**			
Longitude:	-119 16 36.3			**Latitude:**	52 3 11.8		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Crib, Log or Untreated	**# Spans:**	1	
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Mar7.2012 Check for deck connection during 2012 inspection. PB Mar11/11 Check deck to girder connection, should be lagged.						

Structure Name: K1601

Site #:	K1601	**Year Superstructure Installed:**			**Structure Type/Class:**	Permanent Bridge	
KM:	38.80	**User km:**	37.60	**Last Inspection Date:**		2022/09/26	
Project File ID #:	0590	**Br.**	01	**Next Inspection Date:**		2023/09/26	
Road Name:	NORTH THOMPSON						
Crossing Name:	Lehber Creek			**Total Length (metres):**	18.0		
Special Access:				**Special Equipment:**			
Longitude:	-119 33 38.9			**Latitude:**	52 35 3.9		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Steel Pipe and Precast Pad	**# Spans:**	1	
Planned Inspection Comments:	IDIR\PBLUESCH on 20-JAN-17: PB Jan20.2017 Inspect LB footings for scour, measure scour depth. IDIR\PBLUESCH on 29-JAN-15: PB Jan 29,2015 User KM to be confirmed and updated. CBR_Conversion on 17-FEB-14: Gather as built information and verify coordinates. MRF 01/2013						

Structure Name: K770

Site #:	K770	**Year Superstructure Installed:**		1982	**Structure Type/Class:**	Permanent Bridge	
KM:	0.00	**User km:**	0.10	**Last Inspection Date:**		2020/09/19	
Project File ID #:	0564	**Br.**	03	**Next Inspection Date:**		2023/09/19	
Road Name:	OTTER MAIN						
Crossing Name:	N Thompson R			**Total Length (metres):**	80.0		
Special Access:				**Special Equipment:**	Peeper Truck		
Longitude:	-119 25 44.8			**Latitude:**	51 40 42.4		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Other	**# Spans:**	3	
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Mar03,2010. Measure up span lengths next inspection.						

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K832

Site #:	K832	**Year Superstructure Installed:**		1999	**Structure Type/Class:**	Permanent Bridge	
KM:	0.60	**User km:**	0.70	**Last Inspection Date:**		2020/09/19	
Project File ID #:	0564	**Br.**	03	**Next Inspection Date:**		2023/09/19	
Road Name:	OTTER MAIN						
Crossing Name:	Otter Cr			**Total Length (metres):**	30.4		
Special Access:				**Special Equipment:**			
Longitude:	-119 25 23.2			**Latitude:**	51 40 47.9		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Steel Pipe and Precast Pad	**# Spans:**	1	
Planned Inspection Comments:							

Structure Name: K1407

Site #:	K1407	**Year Superstructure Installed:**		2008	**Structure Type/Class:**	Permanent Bridge	
KM:	0.00	**User km:**	16.30	**Last Inspection Date:**		2020/07/07	
Project File ID #:	0705	**Br.**	02	**Next Inspection Date:**		2023/07/07	
Road Name:	RABBIT FLATS						
Crossing Name:	Unnamed			**Total Length (metres):**	6.4		
Special Access:				**Special Equipment:**			
Longitude:	-120 35 58.0			**Latitude:**	50 35 11.0		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*		Steel Pipe and Precast Pad	**# Spans:**	1	
Planned Inspection Comments:							

Structure Name: K1408

Site #:	K1408	**Year Superstructure Installed:**		2007	**Structure Type/Class:**	Permanent Bridge	
KM:	0.00	**User km:**	16.40	**Last Inspection Date:**		2020/07/07	
Project File ID #:	0705	**Br.**	02	**Next Inspection Date:**		2023/07/07	
Road Name:	RABBIT FLATS						
Crossing Name:	Unnamed			**Total Length (metres):**	7.4		
Special Access:				**Special Equipment:**			
Longitude:	-120 35 54.0			**Latitude:**	50 35 11.0		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*		Steel Pipe and Precast Pad	**# Spans:**	1	
Planned Inspection Comments:							

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K795

Site #:	K795	**Year Superstructure Installed:**		1992	**Structure Type/Class:**	Permanent Bridge	
KM:	6.59	**User km:**	6.60	**Last Inspection Date:**		2020/09/19	
Project File ID #:	8397	**Br.**	06	**Next Inspection Date:**		2023/09/19	
Road Name:	RAFT-KOWALSKI						
Crossing Name:	Richie Cr			**Total Length (metres):**	10.0		
Special Access:				**Special Equipment:**			
Longitude:	-119 37 26.0			**Latitude:**	51 53 37.4		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*		Concrete Lock Blocks	**# Spans:**	1	
Planned Inspection Comments:							

Structure Name: K097

Site #:	K097	**Year Superstructure Installed:**			**Structure Type/Class:**	Permanent Bridge	
KM:	16.10	**User km:**	16.10	**Last Inspection Date:**		2022/09/28	
Project File ID #:	8397	**Br.**	01	**Next Inspection Date:**		2023/09/28	
Road Name:	RAFT-RAFT RIVER						
Crossing Name:	Unknown			**Total Length (metres):**	12.0		
Special Access:				**Special Equipment:**			
Longitude:	-119 49 31.7			**Latitude:**	51 40 6.8		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*		Steel Pipe and Precast Pad	**# Spans:**	1	
Planned Inspection Comments:	IDIR\PBLUESCH on 12-FEB-20: PB Feb12.2020 Inspect deck for fabrication numbers.						

Structure Name: K1709

Site #:	K1709	**Year Superstructure Installed:**		2018	**Structure Type/Class:**	Permanent Bridge	
KM:	6.20	**User km:**	21.00	**Last Inspection Date:**		2022/09/27	
Project File ID #:	8397	**Br.**	07	**Next Inspection Date:**		2023/09/27	
Road Name:	RAFT-RAFT RIVER EAST						
Crossing Name:	Stratton Creek			**Total Length (metres):**	15.6		
Special Access:				**Special Equipment:**			
Longitude:	-119 36 37.3			**Latitude:**	51 50 52.0		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*		Steel Pipe and Precast Pad	**# Spans:**	1	
Planned Inspection Comments:	IDIR\MRFENNEL on 19-APR-23: PB April 19.2023 Re-inspect in 2023 at Interfor request. Assess slab girders for signs of overstress and assess all shear key welds for failure.						

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1633

Site #:	K1633	**Year Superstructure Installed:**			**Structure Type/Class:**	Permanent Bridge	
KM:	4.25	**User km:**	4.25	**Last Inspection Date:**		2020/07/11	
Project File ID #:	7669	**Br.**	06	**Next Inspection Date:**		2023/07/11	
Road Name:	ROAD 6 AND ROAD 20						
Crossing Name:	Unknown			**Total Length (metres):**	15.2		
Special Access:				**Special Equipment:**			
Longitude:	-120 26 29.7			**Latitude:**	51 45 18.2		
Superstructure:	Compo Girders	**Abutments (Left/Right):** *(looking downstream)*		Steel Pipe and Precast Pad	**# Spans:**	1	
Planned Inspection Comments:							

Structure Name: K1621

Site #:	K1621	**Year Superstructure Installed:**	2006		**Structure Type/Class:**	Permanent Bridge	
KM:	8.90	**User km:**	8.50	**Last Inspection Date:**		2020/07/11	
Project File ID #:	7669	**Br.**	06	**Next Inspection Date:**		2023/07/11	
Road Name:	ROAD 6 AND ROAD 20						
Crossing Name:	Unknown			**Total Length (metres):**	10.6		
Special Access:				**Special Equipment:**			
Longitude:	-120 26 25.7			**Latitude:**	51 47 7.8		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*		Steel Pipe and Precast Pad	**# Spans:**	1	
Planned Inspection Comments:							

Structure Name: K1632

Site #:	K1632	**Year Superstructure Installed:**	2006		**Structure Type/Class:**	Permanent Bridge	
KM:	10.10	**User km:**	10.10	**Last Inspection Date:**		2020/07/11	
Project File ID #:	7669	**Br.**	06	**Next Inspection Date:**		2023/07/11	
Road Name:	ROAD 6 AND ROAD 20						
Crossing Name:	Unknown			**Total Length (metres):**	10.6		
Special Access:				**Special Equipment:**			
Longitude:	-120 25 52.9			**Latitude:**	51 47 36.2		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*		Steel Pipe and Precast Pad	**# Spans:**	1	
Planned Inspection Comments:							

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1622

Site #:	K1622	**Year Superstructure Installed:**	2007	**Structure Type/Class:**	Major Culvert
KM:	11.10	**User km:**	11.50	**Last Inspection Date:**	2020/07/11
Project File ID #:	7669	**Br.**	06	**Next Inspection Date:**	2023/07/11
Road Name:	ROAD 6 AND ROAD 20				
Crossing Name:	Unknown			**Total Length (metres):**	11.5
Special Access:				**Special Equipment:**	
Longitude:	-120 24 52.7			**Latitude:**	51 47 50.0
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:					

Structure Name: K1652

Site #:	K1652	**Year Superstructure Installed:**	2005	**Structure Type/Class:**	Permanent Bridge
KM:	0.10	**User km:**	0.10	**Last Inspection Date:**	2020/07/12
Project File ID #:	7669	**Br.**	15	**Next Inspection Date:**	2023/07/12
Road Name:	ROAD 7B TFL				
Crossing Name:	Unknown			**Total Length (metres):**	12.0
Special Access:				**Special Equipment:**	
Longitude:	-120 32 53.4			**Latitude:**	51 43 57.6
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	IDIR\MRFENNEL on 23-JAN-17: PB Jan23,2017 Inspect deck surface for Rapid Span WO #.				

Structure Name: K1681

Site #:	K1681	**Year Superstructure Installed:**	2017	**Structure Type/Class:**	Temporary Bridge
KM:	2.40	**User km:**	2.40	**Last Inspection Date:**	2022/09/22
Project File ID #:	5072	**Br.**	20	**Next Inspection Date:**	2023/09/22
Road Name:	ROBERTS CREEK				
Crossing Name:	Lecelerc Cr			**Total Length (metres):**	7.5
Special Access:				**Special Equipment:**	
Longitude:	-119 31 7.3			**Latitude:**	51 35 31.6
Superstructure:	Log Stringers	**Abutments (Left/Right):** *(looking downstream)*	Sill -Temporary Materials	**# Spans:**	1
Planned Inspection Comments:	IDIR\RKEETCH on 04-MAY-22: RBK May4,2022 Inspect foundation for extent of scour and support of structure. IDIR\PBLUESCH on 12-JAN-17: PB Jan12,2017 Measure up all stringer info, species etc.				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1691

Site #:	K1691	**Year Superstructure Installed:**	2004	**Structure Type/Class:**	Major Culvert
KM:	2.00	**User km:**	2.00	**Last Inspection Date:**	2020/10/02
Project File ID #:	5072	**Br.**	25	**Next Inspection Date:**	2023/10/02
Road Name:	S. DUDGEON BR25				
Crossing Name:	Unknown	**Total Length (metres):**	17.8		
Special Access:		**Special Equipment:**			
Longitude:	-119 15 16.9	**Latitude:**	51 32 49.1		
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:	IDIR\MRFENNEL on 26-SEP-16: Verify depth of fill at inlet and outlet				

Structure Name: K1088

Site #:	K1088	**Year Superstructure Installed:**	2001	**Structure Type/Class:**	Permanent Bridge
KM:	0.18	**User km:**	37.80	**Last Inspection Date:**	2022/09/22
Project File ID #:	0562	**Br.**	12	**Next Inspection Date:**	2023/09/22
Road Name:	SASKUM WEST				
Crossing Name:	North Barriere R	**Total Length (metres):**	18.3		
Special Access:		**Special Equipment:**			
Longitude:	-119 43 7.5	**Latitude:**	51 27 23.2		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K183

Site #:	K183	**Year Superstructure Installed:**	1986	**Structure Type/Class:**	Permanent Bridge
KM:	21.01	**User km:**	39.90	**Last Inspection Date:**	2020/07/14
Project File ID #:	8591	**Br.**	01	**Next Inspection Date:**	2023/07/14
Road Name:	SAWMILL LAKE				
Crossing Name:	Tranquille Cr	**Total Length (metres):**	18.2		
Special Access:		**Special Equipment:**			
Longitude:	-120 40 35.4	**Latitude:**	50 56 41.7		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Pile -Permanent Materials	**# Spans:**	1
Planned Inspection Comments:					

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K190

Site #:	K190	**Year Superstructure Installed:**	1989	**Structure Type/Class:**	Permanent Bridge
KM:	28.59	**User km:**	46.60	**Last Inspection Date:**	2022/10/04
Project File ID #:	8591	**Br.**	01	**Next Inspection Date:**	2023/10/04
Road Name:	SAWMILL LAKE				
Crossing Name:	Heller Cr	**Total Length (metres):**	8.6		
Special Access:		**Special Equipment:**			
Longitude:	-120 41 35.1	**Latitude:**	50 59 53.0		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: WO1263

Site #:	K113	**Year Superstructure Installed:**	2011	**Structure Type/Class:**	Temporary Bridge
KM:	11.60	**User km:**		**Last Inspection Date:**	2021/09/06
Project File ID #:	7669	**Br.**	02	**Next Inspection Date:**	2023/09/06
Road Name:	SOCK LAKE-ROAD 1				
Crossing Name:	Unnamed	**Total Length (metres):**	12.2		
Special Access:		**Special Equipment:**			
Longitude:	-120 4 26.1	**Latitude:**	51 43 0.2		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:	IDIR\PBLUESCH on 25-JAN-17: PB Jan25.2017 Clearance from underside of girders to armouring should be measured to ensure no risk to structure.				

Structure Name: K107A

Site #:	K107	**Year Superstructure Installed:**	2010	**Structure Type/Class:**	Permanent Bridge
KM:	7.07	**User km:**	10.80	**Last Inspection Date:**	2020/09/29
Project File ID #:	7524	**Br.**	03	**Next Inspection Date:**	2023/09/29
Road Name:	SPAHATS CREEK				
Crossing Name:	#1	**Total Length (metres):**	18.3		
Special Access:		**Special Equipment:**			
Longitude:	-119 51 54.4	**Latitude:**	51 45 29.1		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB May25/11 Inspect grout pockets. Poured in marginal conditions.				

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1143

Site #:	K1143	**Year Superstructure Installed:**	2001	**Structure Type/Class:**	Permanent Bridge
KM:	2.00	**User km:**	0.30	**Last Inspection Date:**	2020/10/01
Project File ID #:	5072	**Br.**	08	**Next Inspection Date:**	2023/10/01
Road Name:	SUNSET-MAMMOTH				
Crossing Name:	Sunset	**Total Length (metres):**	27.4		
Special Access:	ATV	**Special Equipment:**			
Longitude:	-119 9 10.2	**Latitude:**	51 38 38.5		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: PS-044

Site #:	K1679	**Year Superstructure Installed:**	2016	**Structure Type/Class:**	Temporary Bridge
KM:	6.10	**User km:**	6.10	**Last Inspection Date:**	2021/09/04
Project File ID #:	5072	**Br.**	08	**Next Inspection Date:**	2023/09/04
Road Name:	SUNSET-MAMMOTH				
Crossing Name:	Unnamed	**Total Length (metres):**	7.3		
Special Access:		**Special Equipment:**			
Longitude:	-119 9 39.0	**Latitude:**	51 41 38.5		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Concrete Lock Blocks	**# Spans:**	1
Planned Inspection Comments:	IDIR\MRFENNEL on 21-NOV-16: One year post installation inspection				

Structure Name: K1123

Site #:	K1123	**Year Superstructure Installed:**	1999	**Structure Type/Class:**	Major Culvert
KM:	3.26	**User km:**	17.00	**Last Inspection Date:**	2022/09/29
Project File ID #:	1422	**Br.**	01	**Next Inspection Date:**	2023/09/29
Road Name:	TAWEEL LAKE				
Crossing Name:	Unnamed	**Total Length (metres):**	14.0		
Special Access:		**Special Equipment:**			
Longitude:	-120 21 55.2	**Latitude:**	51 36 46.7		
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:					

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1404

Site #:	K1404	**Year Superstructure Installed:**	2007	**Structure Type/Class:**	Permanent Bridge
KM:	6.86	**User km:**	13.40	**Last Inspection Date:**	2020/07/13
Project File ID #:	1422	**Br.**	01	**Next Inspection Date:**	2023/07/13
Road Name:	TAWEEL LAKE				
Crossing Name:	Stiger Cr	**Total Length (metres):**	15.2		
Special Access:		**Special Equipment:**			
Longitude:	-120 20 28.2	**Latitude:**	51 35 17.4		
Superstructure:	Compo Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K741

Site #:	K741	**Year Superstructure Installed:**	1985	**Structure Type/Class:**	Permanent Bridge
KM:	0.86	**User km:**	0.80	**Last Inspection Date:**	2020/10/01
Project File ID #:	5072	**Br.**	07	**Next Inspection Date:**	2023/10/01
Road Name:	TUM TUM-HARBOUR				
Crossing Name:	Adams R	**Total Length (metres):**	54.7		
Special Access:		**Special Equipment:**	Peeper Truck		
Longitude:	-119 9 56.4	**Latitude:**	51 38 38.1		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Pile -Permanent Materials	**# Spans:**	3
Planned Inspection Comments:					

Structure Name: K1706

Site #:	K1706	**Year Superstructure Installed:**	2019	**Structure Type/Class:**	Major Culvert
KM:	7.25	**User km:**	7.25	**Last Inspection Date:**	2020/10/02
Project File ID #:	5072	**Br.**	07	**Next Inspection Date:**	2023/10/02
Road Name:	TUM TUM-HARBOUR				
Crossing Name:	Unnamed	**Total Length (metres):**	14.7		
Special Access:		**Special Equipment:**			
Longitude:	-119 8 2.1	**Latitude:**	51 36 40.6		
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:					

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1458

Site #:	K1458	**Year Superstructure Installed:**	2001	**Structure Type/Class:**	Major Culvert
KM:	0.10	**User km:**		**Last Inspection Date:**	2020/09/17
Project File ID #:	8418	**Br.**	02	**Next Inspection Date:**	2023/09/17
Road Name:	WHITE WATER CRK-BR 1				
Crossing Name:	Deet Creek	**Total Length (metres):**	15.0		
Special Access:		**Special Equipment:**			
Longitude:	-119 16 27.4	**Latitude:**	52 11 0.5		
Superstructure:		**Abutments (Left/Right):** *(looking downstream)*		**# Spans:**	0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: GMc Apr 6/09 Pick up Culvert diameter and length next inspection				

Structure Name: K1409

Site #:	K1409	**Year Superstructure Installed:**	2007	**Structure Type/Class:**	Permanent Bridge
KM:	0.00	**User km:**	15.90	**Last Inspection Date:**	2020/07/07
Project File ID #:	0705	**Br.**	01	**Next Inspection Date:**	2023/07/07
Road Name:					
Crossing Name:	Unnamed	**Total Length (metres):**	8.4		
Special Access:		**Special Equipment:**			
Longitude:	-120 36 4.0	**Latitude:**	50 35 23.0		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

Structure Name: K1402

Site #:	K1402	**Year Superstructure Installed:**	2007	**Structure Type/Class:**	Permanent Bridge
KM:	1.80	**User km:**	1.60	**Last Inspection Date:**	2020/07/07
Project File ID #:	3714	**Br.**	01	**Next Inspection Date:**	2023/07/07
Road Name:					
Crossing Name:	Meadow Cr	**Total Length (metres):**	8.6		
Special Access:		**Special Equipment:**			
Longitude:	-120 31 28.0	**Latitude:**	50 28 11.0		
Superstructure:	Concrete Slab Girders	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:					

BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Date Printed: 2023/06/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Thompson Rivers Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1165

Site #:	K1165	**Year Superstructure Installed:**	1998	**Structure Type/Class:**	Permanent Bridge
KM:	6.42	**User km:**	13.00	**Last Inspection Date:**	2020/10/03
Project File ID #:	9865	**Br.**	01	**Next Inspection Date:**	2023/10/03
Road Name:					
Crossing Name:	Spillman Cr	**Total Length (metres):**	16.0		
Special Access:		**Special Equipment:**			
Longitude:	-119 36 38.8	**Latitude:**	51 8 23.2		
Superstructure:	Steel I-beam	**Abutments (Left/Right):** *(looking downstream)*	Steel Pipe and Precast Pad	**# Spans:**	1
Planned Inspection Comments:	CBR_Conversion on 23-FEB-18: Need to document WO # and steel girder labels. Clear deck at corners to document WO #.				

Structure Type/Class Totals

Permanent Bridge Total: 98
Temporary Bridge Total: 29
Major Culvert Total: 18
Woodbox/Log Culvert Total: 0