



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 1 of 17
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N5-214

Site #:	N5-214	Year Superstructure Installed:	2011	Structure Type/Class:	Major Culvert
KM:	2.30	User km:	2.30	Last Inspection Date:	2020/08/31
Project File ID #:	0221	Br.	06	Next Inspection Date:	2023/08/31
Road Name:	AR0221.06 WOODCHUCK				
Crossing Name:	Woodchuck Creek	Total Length (metres):	20.8		
Special Access:		Special Equipment:			
Longitude:	-117 14 8.5	Latitude:	49 9 36.8		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: N5-208

Site #:	N5-208	Year Superstructure Installed:	2010	Structure Type/Class:	Permanent Bridge
KM:	2.00	User km:		Last Inspection Date:	2020/09/02
Project File ID #:	10633	Br.	01	Next Inspection Date:	2023/09/02
Road Name:	AR10633.01NINEMILE				
Crossing Name:	Unnamed	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-117 46 36.3	Latitude:	49 17 38.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-001A

Site #:	N5-001	Year Superstructure Installed:	2014	Structure Type/Class:	Temporary Bridge
KM:	2.00	User km:	2.90	Last Inspection Date:	2021/08/11
Project File ID #:	0006	Br.	01	Next Inspection Date:	2023/08/11
Road Name:	ARCHIBALD				
Crossing Name:	ARCHIBALD Cr	Total Length (metres):	15.2		
Special Access:		Special Equipment:			
Longitude:	-117 23 36.3	Latitude:	49 9 39.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 2 of 17
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N5-228

Site #:	N5-228	Year Superstructure Installed:	1995	Structure Type/Class:	Temporary Bridge
KM:	2.00	User km:	2.00	Last Inspection Date:	2021/08/07
Project File ID #:	9003	Br.	02	Next Inspection Date:	2023/08/07
Road Name:	BIGGER				
Crossing Name:	Asher Cr		Total Length (metres):	23.0	
Special Access:			Special Equipment:		
Longitude:	-117 29 34.0		Latitude:	50 36 34.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-008

Site #:	N5-008	Year Superstructure Installed:	1987	Structure Type/Class:	Permanent Bridge
KM:	0.43	User km:	5.40	Last Inspection Date:	2020/08/24
Project File ID #:	0319	Br.	02	Next Inspection Date:	2023/08/24
Road Name:	BURTON-SNOW				
Crossing Name:	SNOW Cr		Total Length (metres):	16.4	
Special Access:			Special Equipment:		
Longitude:	-117 51 23.3		Latitude:	49 56 37.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-280

Site #:	N5-280	Year Superstructure Installed:		Structure Type/Class:	Major Culvert
KM:	6.70	User km:	6.70	Last Inspection Date:	
Project File ID #:	9780	Br.	01	Next Inspection Date:	2023/08/01
Road Name:	CAMERON LAKE-ONE				
Crossing Name:	unknown		Total Length (metres):	14.0	
Special Access:			Special Equipment:		
Longitude:	-117 59 30.1		Latitude:	50 18 34.2	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 3 of 17
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N5-027

Site #:	N5-027	Year Superstructure Installed:	1992	Structure Type/Class:	Temporary Bridge
KM:	3.35	User km:	17.30	Last Inspection Date:	2021/08/11
Project File ID #:	0040	Br.	03	Next Inspection Date:	2023/08/11
Road Name:	ERIE CR. GRASSY ONE				
Crossing Name:	Unnamed		Total Length (metres):	8.3	
Special Access:			Special Equipment:		
Longitude:	-117 27 30.2		Latitude:	49 15 47.5	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-240A

Site #:	N5-240	Year Superstructure Installed:	2021	Structure Type/Class:	Major Culvert
KM:	2.10	User km:		Last Inspection Date:	
Project File ID #:	9568	Br.	27	Next Inspection Date:	2023/06/01
Road Name:	EUREKA FSR				
Crossing Name:	unknown		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-118 18 52.2		Latitude:	50 4 41.8	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\RKEETCH on 05-APR-23: Confirm length of pipe, measure inlet and outlet cover at site. Document any scour at upstream armour or in the road grade.				

Structure Name: N5-252

Site #:	N5-252	Year Superstructure Installed:	2017	Structure Type/Class:	Permanent Bridge
KM:	7.50	User km:	7.50	Last Inspection Date:	2020/09/08
Project File ID #:	6288	Br.	01	Next Inspection Date:	2023/09/08
Road Name:	GOOSE CREEK				
Crossing Name:	goose creek trib		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-117 40 43.7		Latitude:	49 27 47.1	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 4 of 17
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N5-028

Site #:	N5-028	Year Superstructure Installed:	2003	Structure Type/Class:	Permanent Bridge
KM:	14.26	User km:	1.60	Last Inspection Date:	2020/09/02
Project File ID #:	6288	Br.	01	Next Inspection Date:	2023/09/02
Road Name:	GOOSE CREEK				
Crossing Name:	GOOSE Cr	Total Length (metres):	18.3		
Special Access:			Special Equipment:		
Longitude:	-117 39 14.0	Latitude:	49 25 5.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Perform routine visual condition assessment in 2014 (after freshet) to assess foundation repairs (completed in 2013), deck joints and road end fills.				

Structure Name: N5-062

Site #:	N5-062	Year Superstructure Installed:	1986	Structure Type/Class:	Permanent Bridge
KM:	0.02	User km:	22.50	Last Inspection Date:	2021/08/13
Project File ID #:	4518	Br.	01	Next Inspection Date:	2020/08/17
Road Name:	GRIZZLY CREEK				
Crossing Name:	KOCH Cr	Total Length (metres):	22.0		
Special Access:			Special Equipment:		
Longitude:	-117 51 33.6	Latitude:	49 38 21.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 04-JAN-17: Please provide photos of wing walls/cribs.				

Structure Name: N5-029

Site #:	N5-029	Year Superstructure Installed:	1992	Structure Type/Class:	Temporary Bridge
KM:	0.02	User km:	0.00	Last Inspection Date:	2022/08/29
Project File ID #:	0330	Br.	01	Next Inspection Date:	2023/08/29
Road Name:	HADOW CREEK				
Crossing Name:	INCOMAPPLEUX R	Total Length (metres):	30.4		
Special Access:			Special Equipment:	Peeper Truck	
Longitude:	-117 41 39.5	Latitude:	50 45 26.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\BPELLETT on 20-MAY-22: BP May 20-22 Annual inspection required & peeper inspection in 2023 recommended IDIR\BPELLETT on 02-MAY-22: BP May 2-22 Inspector to thoroughly search for fabricator markings and photograph any found IDIR\JNAUL on 13-MAY-19: Hire Ron Peace and peeper to inspect cribs in 2021 IDIR\JNAUL on 16-MAR-15: Bridge has a new deck including ties, planks and curbs. Rot has been detected in cribs and sills and sills may require replacement in 2 to 3 years according to SNT report in 2013.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 5 of 17
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status: Inspect

JN; 2015-03-16: Re-inspect cribs and voids annually and after every major storm event. Bridge should be surveyed in 2015 for replacement in 2016. For replacement design Ga, I would prefer to have concrete abutments tied into the bed rock.

CBR_Conversion on 17-FEB-14: Inspect rot in sill logs.

Structure Name: N5-159A

Site #:	N5-159	Year Superstructure Installed:	2013	Structure Type/Class:	Permanent Bridge
KM:	5.65	User km:	5.60	Last Inspection Date:	2020/08/26
Project File ID #:	0330	Br.	01	Next Inspection Date:	2023/08/26
Road Name:	HADOW CREEK				
Crossing Name:	TOWN Cr	Total Length (metres):	18.3		
Special Access:		Special Equipment:			
Longitude:	-117 44 47.1	Latitude:	50 45 49.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-109A

Site #:	N5-109	Year Superstructure Installed:	2012	Structure Type/Class:	Permanent Bridge
KM:	9.24	User km:	9.20	Last Inspection Date:	2020/08/26
Project File ID #:	0330	Br.	01	Next Inspection Date:	2023/08/26
Road Name:	HADOW CREEK				
Crossing Name:	COMAPLIX Cr	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-117 47 11.0	Latitude:	50 45 13.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-031

Site #:	N5-031	Year Superstructure Installed:	1989	Structure Type/Class:	Permanent Bridge
KM:	15.20	User km:	15.20	Last Inspection Date:	2020/08/25
Project File ID #:	0176	Br.	02	Next Inspection Date:	2023/08/25
Road Name:	HALFWAY-DEEP				
Crossing Name:	Unnamed	Total Length (metres):	7.7		
Special Access:		Special Equipment:			
Longitude:	-117 44 42.4	Latitude:	50 29 45.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 16-MAR-15: JN; 2015-03-16: monitor lock blocks for settlement and rip rap for scour. Girder tag indicates L-75 girders instead of L60 in the CBR.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 6 of 17
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N5-066A

Site #:	N5-066	Year Superstructure Installed:	2014	Structure Type/Class:	Permanent Bridge
KM:	12.90	User km:	30.70	Last Inspection Date:	2020/09/02
Project File ID #:	0145	Br.	01	Next Inspection Date:	2023/09/02
Road Name:	KOCH CREEK				
Crossing Name:	WATSON Cr		Total Length (metres):	18.7	
Special Access:			Special Equipment:		
Longitude:	-117 54 44.9		Latitude:	49 42 0.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-184

Site #:	N5-184	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:	25.80	User km:	25.80	Last Inspection Date:	2020/09/02
Project File ID #:	0145	Br.	01	Next Inspection Date:	2023/09/02
Road Name:	KOCH CREEK				
Crossing Name:	Unnamed		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-117 51 57.0		Latitude:	49 46 0.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-185

Site #:	N5-185	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:	27.10	User km:	27.10	Last Inspection Date:	2020/09/03
Project File ID #:	0145	Br.	01	Next Inspection Date:	2023/09/03
Road Name:	KOCH CREEK				
Crossing Name:	Unnamed		Total Length (metres):	9.3	
Special Access:			Special Equipment:		
Longitude:	-117 51 36.3		Latitude:	49 46 39.4	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 7 of 17
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N5-186

Site #:	N5-186	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:	27.60	User km:	27.60	Last Inspection Date:	2020/09/03
Project File ID #:	0145	Br.	01	Next Inspection Date:	2023/09/03
Road Name:	KOCH CREEK				
Crossing Name:	Unnamed	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-117 51 26.6	Latitude:	49 46 52.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-187

Site #:	N5-187	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:	29.90	User km:	29.90	Last Inspection Date:	2020/09/03
Project File ID #:	0145	Br.	01	Next Inspection Date:	2023/09/03
Road Name:	KOCH CREEK				
Crossing Name:	Unnamed	Total Length (metres):	15.2		
Special Access:		Special Equipment:			
Longitude:	-117 50 56.3	Latitude:	49 48 2.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-045

Site #:	N5-045	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	5.77	User km:	9.30	Last Inspection Date:	2020/09/02
Project File ID #:	4172	Br.	01	Next Inspection Date:	2023/09/02
Road Name:	LADYBIRD CREEK				
Crossing Name:	NORNS Cr	Total Length (metres):	15.5		
Special Access:		Special Equipment:			
Longitude:	-117 45 53.2	Latitude:	49 26 7.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 14-MAR-14: JN; 2014-3-14: Re-inspect bin walls annually for scour.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 8 of 17
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N5-234

Site #:	N5-234	Year Superstructure Installed:		Structure Type/Class:	Woodbox/Log Culvert
KM:	5.10	User km:		Last Inspection Date:	2022/08/29
Project File ID #:	0322	Br.	01	Next Inspection Date:	2023/08/01
Road Name:	LARDEAU CREEK				
Crossing Name:	unknown		Total Length (metres):	20.0	
Special Access:			Special Equipment:		
Longitude:	-117 26 10.3		Latitude:	50 39 46.8	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	IDIR\JNAUL on 13-DEC-16: Monitor for failure after every freshet, after major rain on snow events, and after major rain storm events. IDIR\HABEURSK on 25-APR-16: take back structure. Inspect and record information to update CBR.				

Structure Name: N5-248

Site #:	N5-248	Year Superstructure Installed:	2017	Structure Type/Class:	Permanent Bridge
KM:	1.50	User km:	1.50	Last Inspection Date:	2022/08/25
Project File ID #:	0209	Br.	01	Next Inspection Date:	2023/08/25
Road Name:	LEMON CREEK-MAIN				
Crossing Name:	South Lemon		Total Length (metres):	13.5	
Special Access:			Special Equipment:		
Longitude:	-117 27 43.5		Latitude:	49 41 52.0	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\BPellett on 21-APR-22: BP Apr 21-22 Monitor effects of Lemon Creek on left approach and left downstream corner				

Structure Name: N5-169

Site #:	N5-169	Year Superstructure Installed:	2005	Structure Type/Class:	Temporary Bridge
KM:	2.88	User km:	4.00	Last Inspection Date:	2021/08/12
Project File ID #:	9468	Br.	02	Next Inspection Date:	2023/08/12
Road Name:	LIMPID-TWO				
Crossing Name:	Unnamed		Total Length (metres):	7.3	
Special Access:			Special Equipment:		
Longitude:	-117 24 16.3		Latitude:	49 3 40.6	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 9 of 17
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N5-057A

Site #:	N5-057	Year Superstructure Installed:	2019	Structure Type/Class:	Permanent Bridge
KM:	0.64	User km:	12.80	Last Inspection Date:	2021/08/13
Project File ID #:	7777	Br.	01	Next Inspection Date:	2023/09/02
Road Name:	LITTLE SLOCAN MAIN				
Crossing Name:	KOCH Cr	Total Length (metres):	31.9		
Special Access:			Special Equipment:		
Longitude:	-117 45 38.8	Latitude:	49 36 14.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-111A

Site #:	N5-111	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	0.46	User km:	0.50	Last Inspection Date:	2020/09/02
Project File ID #:	9464	Br.	05	Next Inspection Date:	2023/09/02
Road Name:	MUD LAKE-FIVE				
Crossing Name:	BIG SHEEP Cr	Total Length (metres):	10.7		
Special Access:			Special Equipment:		
Longitude:	-118 0 7.1	Latitude:	49 14 36.5		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 02-APR-14: JN; 2014-04-02: Need professional inspection to determine cause of crack in the bulkhead wall - is the bearing block settled and load redistributed to the outer blocks through ballastwall? Inspector to check for settlement of bearing blocks.				

Structure Name: N5-069

Site #:	N5-069	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	0.00	User km:	0.00	Last Inspection Date:	2020/08/23
Project File ID #:	8683	Br.	01	Next Inspection Date:	2023/08/23
Road Name:	OCTOPUS CREEK				
Crossing Name:	TAITE Cr	Total Length (metres):	18.3		
Special Access:			Special Equipment:		
Longitude:	-118 4 44.8	Latitude:	49 47 45.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 10 of 17
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N5-267

Site #:	N5-267	Year Superstructure Installed:		Structure Type/Class:	Permanent Bridge
KM:	0.30	User km:	0.30	Last Inspection Date:	
Project File ID #:	8391	Br.	4	Next Inspection Date:	2023/08/01
Road Name:	OSCAR 5000				
Crossing Name:	oscar creek		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-117 8 58.0		Latitude:	49 16 48.6	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-073

Site #:	N5-073	Year Superstructure Installed:	1996	Structure Type/Class:	Major Culvert
KM:	6.30	User km:	6.30	Last Inspection Date:	2020/09/03
Project File ID #:	7700	Br.	01	Next Inspection Date:	2023/09/03
Road Name:	PEDRO				
Crossing Name:	PEDRO Cr-S.FORK		Total Length (metres):	18.0	
Special Access:			Special Equipment:		
Longitude:	-117 33 54.7		Latitude:	49 33 36.7	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: N5-237

Site #:	N5-237	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	0.30	User km:	15.90	Last Inspection Date:	2020/08/26
Project File ID #:	0322	Br.	05	Next Inspection Date:	2023/08/26
Road Name:	SECTION_ONE_A				
Crossing Name:	lardeau cr		Total Length (metres):	22.4	
Special Access:			Special Equipment:		
Longitude:	-117 21 18.2		Latitude:	50 39 42.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\HABEURSK on 16-MAR-16: Confirm Structure details and location				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 11 of 17
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N5-245

Site #:	N5-245	Year Superstructure Installed:	2000	Structure Type/Class:	Major Culvert
KM:	3.50	User km:	3.50	Last Inspection Date:	2020/08/26
Project File ID #:	0322	Br.	20	Next Inspection Date:	2023/08/26
Road Name:	SECTION_THREE_G				
Crossing Name:	Copper Queen Cr		Total Length (metres):	20.0	
Special Access:			Special Equipment:		
Longitude:	-117 25 28.7		Latitude:	50 36 35.4	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					

Structure Name: N5-089A

Site #:	N5-089	Year Superstructure Installed:	2013	Structure Type/Class:	Temporary Bridge
KM:	3.07	User km:	15.00	Last Inspection Date:	2021/08/11
Project File ID #:	0221	Br.	01	Next Inspection Date:	2023/08/11
Road Name:	SHEEP CREEK				
Crossing Name:	SHEEP Cr		Total Length (metres):	12.1	
Special Access:			Special Equipment:		
Longitude:	-117 5 20.8		Latitude:	49 10 3.9	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:	IDIR\BPellet on 22-APR-22: BP Apr 22-22 Inspector to thoroughly search structure for fabricator markings and take high-quality photographs of all found				

Structure Name: N5-172

Site #:	N5-172	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	16.27	User km:	5.60	Last Inspection Date:	2020/09/03
Project File ID #:	0179	Br.	01	Next Inspection Date:	2023/09/03
Road Name:	SLEWISKIN ONE				
Crossing Name:	Unnamed		Total Length (metres):	3.6	
Special Access:			Special Equipment:		
Longitude:	-117 44 31.5		Latitude:	50 6 59.4	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:	IDIR\JNAUL on 15-MAR-14: It appears that the rip rap protecting the footings has washed out. Inspector to measure depth of inverted T footings and look for signs of settlement in walls.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 12 of 17
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N5-118

Site #:	N5-118	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	0.00	User km:	8.90	Last Inspection Date:	2020/08/24
Project File ID #:	9564	Br.	01	Next Inspection Date:	2023/08/24
Road Name:	SOUTH FIFE ONE				
Crossing Name:	SOUTH FIFE Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-118 7 46.0		Latitude:	50 7 52.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-116

Site #:	N5-116	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	7.00	User km:	7.00	Last Inspection Date:	2020/08/24
Project File ID #:	9564	Br.	01	Next Inspection Date:	2023/08/24
Road Name:	SOUTH FIFE ONE				
Crossing Name:	NORTH FIFE Cr		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-118 8 6.3		Latitude:	50 8 23.1	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-115A

Site #:	N5-115	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	8.96	User km:	4.40	Last Inspection Date:	2020/08/24
Project File ID #:	9564	Br.	01	Next Inspection Date:	2019/08/05
Road Name:	SOUTH FIFE ONE				
Crossing Name:	FIFE Cr		Total Length (metres):	21.8	
Special Access:			Special Equipment:		
Longitude:	-118 6 26.3		Latitude:	50 7 32.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 13 of 17
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N5-119

Site #:	N5-119	Year Superstructure Installed:	1992	Structure Type/Class:	Temporary Bridge
KM:	0.18	User km:	13.10	Last Inspection Date:	2022/09/01
Project File ID #:	9564	Br.	02	Next Inspection Date:	2023/09/01
Road Name:	SOUTH FIFE TWO				
Crossing Name:	SOUTH FIFE Cr		Total Length (metres):	8.3	
Special Access:			Special Equipment:		
Longitude:	-118 10 42.0		Latitude:	50 7 13.7	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	IDIR\BPELLETT on 22-APR-22: BP Apr 22-22 Inspector to photograph fabricator markings on girders IDIR\JNAUL on 01-APR-14: JN; 2014-04-01: reinspect cribs for scour and rot.				

Structure Name: N1-214

Site #:	N5-207	Year Superstructure Installed:	2012	Structure Type/Class:	Permanent Bridge
KM:	0.00	User km:	9.00	Last Inspection Date:	2020/08/31
Project File ID #:	0010	Br.	01	Next Inspection Date:	2023/08/31
Road Name:	SOUTH SALMO RIVER				
Crossing Name:	Wallack Creek		Total Length (metres):	10.6	
Special Access:			Special Equipment:		
Longitude:	-117 19 48.4		Latitude:	49 2 21.2	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: N5-151

Site #:	N5-151	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	6.44	User km:	6.70	Last Inspection Date:	2021/08/13
Project File ID #:	7609	Br.	01	Next Inspection Date:	2022/08/13
Road Name:	TROZZO CREEK				
Crossing Name:	TROZZO Cr		Total Length (metres):	12.3	
Special Access:			Special Equipment:		
Longitude:	-117 27 20.9		Latitude:	49 38 12.6	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\BPELLETT on 26-APR-22: BP Apr 26-22 Monitor curb conditions and post bridge appropriately				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 14 of 17
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N5-266

Site #:	N5-266	Year Superstructure Installed:	2022	Structure Type/Class:	Major Culvert
KM:	1.90	User km:	1.90	Last Inspection Date:	
Project File ID #:	9536	Br.	12	Next Inspection Date:	2023/08/01
Road Name:	TWIN CREEKS				
Crossing Name:	Twin Creeks		Total Length (metres):	16.0	
Special Access:			Special Equipment:		
Longitude:	-117 11 3.3		Latitude:	49 4 39.3	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					

Structure Name: N5-229

Site #:	N5-229	Year Superstructure Installed:	2017	Structure Type/Class:	Permanent Bridge
KM:	1.10	User km:	1.10	Last Inspection Date:	2020/09/01
Project File ID #:	0011	Br.	02	Next Inspection Date:	2023/09/01
Road Name:	WEST BIG SHEEP FSR				
Crossing Name:	St Thomas Creek		Total Length (metres):	10.6	
Special Access:			Special Equipment:		
Longitude:	-117 58 31.1		Latitude:	49 7 23.0	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: N5-253

Site #:	N5-253	Year Superstructure Installed:	2019	Structure Type/Class:	Permanent Bridge
KM:	5.00	User km:	5.00	Last Inspection Date:	2020/09/01
Project File ID #:	0011	Br.	02	Next Inspection Date:	2023/09/01
Road Name:	WEST BIG SHEEP FSR				
Crossing Name:	Diana Creek		Total Length (metres):	8.0	
Special Access:			Special Equipment:		
Longitude:	-117 57 36.2		Latitude:	49 5 53.5	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 15 of 17
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N5-196

Site #:	N5-196	Year Superstructure Installed:	2007	Structure Type/Class:	Permanent Bridge
KM:	0.17	User km:	0.20	Last Inspection Date:	2020/08/24
Project File ID #:	9564	Br.	05	Next Inspection Date:	2023/08/24
Road Name:	WEST WHATSHAN				
Crossing Name:	Whatshan River	Total Length (metres):	24.4		
Special Access:		Special Equipment:			
Longitude:	-118 6 3.5	Latitude:	50 6 36.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-129

Site #:	N5-129	Year Superstructure Installed:	2003	Structure Type/Class:	Permanent Bridge
KM:	7.90	User km:	19.00	Last Inspection Date:	2020/08/24
Project File ID #:	2010	Br.	01	Next Inspection Date:	2023/08/24
Road Name:	WHATSHAN FSR				
Crossing Name:	WHITE-GROUSE Cr	Total Length (metres):	12.4		
Special Access:		Special Equipment:			
Longitude:	-118 4 44.8	Latitude:	50 0 4.6		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-249

Site #:	N5-249	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	22.90	User km:	30.40	Last Inspection Date:	2022/09/01
Project File ID #:	2010	Br.	01	Next Inspection Date:	2020/08/19
Road Name:	WHATSHAN FSR				
Crossing Name:	Stevens Cr	Total Length (metres):	10.4		
Special Access:		Special Equipment:			
Longitude:	-118 2 53.8	Latitude:	50 6 4.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 29-SEP-16: Fill out inventory sheet as found structure with no shop drawings and values entered in Details are estimates.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 16 of 17
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N5-133A

Site #:	N5-133	Year Superstructure Installed:	2019	Structure Type/Class:	Permanent Bridge
KM:	54.72	User km:	61.70	Last Inspection Date:	2020/08/24
Project File ID #:	2010	Br.	01	Next Inspection Date:	2023/08/24
Road Name:	WHATSHAN FSR				
Crossing Name:	RIOULX Cr		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-118 2 42.2		Latitude:	50 17 10.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-135

Site #:	N5-135	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	66.60	User km:	71.30	Last Inspection Date:	2020/08/24
Project File ID #:	2010	Br.	01	Next Inspection Date:	2023/08/24
Road Name:	WHATSHAN FSR				
Crossing Name:	SOUTH FOSTHALL Cr		Total Length (metres):	23.0	
Special Access:			Special Equipment:		
Longitude:	-118 2 2.8		Latitude:	50 22 6.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N5-136

Site #:	N5-136	Year Superstructure Installed:	1982	Structure Type/Class:	Temporary Bridge
KM:	70.53	User km:	77.20	Last Inspection Date:	2021/08/03
Project File ID #:	2010	Br.	01	Next Inspection Date:	2023/08/03
Road Name:	WHATSHAN FSR				
Crossing Name:	FOSTHALL Cr		Total Length (metres):	14.3	
Special Access:			Special Equipment:		
Longitude:	-118 0 55.9		Latitude:	50 23 25.6	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: licensee noted rot in the cribs 2010.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 17 of 17
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status: Inspect

Structure Name: TKO-0026

Site #:	N5-225	Year Superstructure Installed:	2015	Structure Type/Class:	Temporary Bridge
KM:	1.50	User km:	1.50	Last Inspection Date:	2021/08/06
Project File ID #:	0330	Br.	05	Next Inspection Date:	2023/08/06
Road Name:	WHISKEY3000				
Crossing Name:	Katie Cr	Total Length (metres):	20.3		
Special Access:			Special Equipment:		
Longitude:	-117 49 20.6		Latitude:	50 43 19.3	
Superstructure:	Steel I-beam	Abutments (Left/Right): <i>(looking downstream)</i>	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 26-JAN-16: JN; 2016-01-26: Added load rating of 55 tonnes (L60) based on SNT GA drawings and certification on file. No responsibility taken for design. Bridge has flares and the actual load rating may be less than L60 due to different distribution factors. Professional engineer of record Les T. from SNT is responsible for checking flare as well as crib design and foundations. IDIR\MRFENNEL on 06-OCT-15: One year post installation inspection				

Structure Name: N5-122

Site #:	N5-122	Year Superstructure Installed:	2007	Structure Type/Class:	Major Culvert
KM:	37.75	User km:	4.70	Last Inspection Date:	2020/09/03
Project File ID #:	0035	Br.	01	Next Inspection Date:	2023/09/03
Road Name:	WILSON CREEK				
Crossing Name:	HICKS Cr	Total Length (metres):	25.0		
Special Access:			Special Equipment:		
Longitude:	-117 23 19.5		Latitude:	50 3 54.6	
Superstructure:		Abutments (Left/Right): <i>(looking downstream)</i>		# Spans:	0
Planned Inspection Comments:					

Structure Type/Class Totals

Permanent Bridge Total: 33	Major Culvert Total: 7
Temporary Bridge Total: 9	Woodbox/Log Culvert Total: 1