



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 1 of 15
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N6-004

Site #:	N6-004	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:	12.13	User km:	11.10	Last Inspection Date:	2020/08/22
Project File ID #:	6333	Br.	01	Next Inspection Date:	2023/08/22
Road Name:	ALMOND CREEK				
Crossing Name:	ALMOND Cr #3		Total Length (metres):	14.5	
Special Access:			Special Equipment:		
Longitude:	-118 30 16.9		Latitude:	49 18 17.1	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N6-002

Site #:	N6-002	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:	14.48	User km:	8.70	Last Inspection Date:	2020/08/22
Project File ID #:	6333	Br.	01	Next Inspection Date:	2023/08/22
Road Name:	ALMOND CREEK				
Crossing Name:	ALMOND Cr #1		Total Length (metres):	14.5	
Special Access:			Special Equipment:		
Longitude:	-118 29 2.4		Latitude:	49 17 45.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N6-189

Site #:	N6-189	Year Superstructure Installed:	2000	Structure Type/Class:	Temporary Bridge
KM:	2.20	User km:		Last Inspection Date:	2021/09/15
Project File ID #:	9267	Br.	20	Next Inspection Date:	2023/09/15
Road Name:	ARTHURS 100				
Crossing Name:	UNKNOWN		Total Length (metres):	8.0	
Special Access:			Special Equipment:		
Longitude:	-118 40 20.7		Latitude:	49 42 30.7	
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\HABEURSK on 07-JAN-20: .				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 2 of 15
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N6-190

Site #:	N6-190	Year Superstructure Installed:	2007	Structure Type/Class:	Temporary Bridge
KM:	4.40	User km:		Last Inspection Date:	2021/09/15
Project File ID #:	9267	Br.	20	Next Inspection Date:	2023/09/15
Road Name:	ARTHURS 100				
Crossing Name:	UNKNOWN		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-118 39 42.4		Latitude:	49 43 32.2	
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\HABEURSK on 07-JAN-20: .				

Structure Name: N6-039

Site #:	N6-039	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	4.57	User km:	9.50	Last Inspection Date:	2020/08/19
Project File ID #:	3994	Br.	01	Next Inspection Date:	2023/08/19
Road Name:	BARTH CREEK				
Crossing Name:	COPPERKETTLE Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-118 49 7.5		Latitude:	49 37 23.6	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: JN, 2013-12-09: Professional inspection required in spring of 2014 to assess surface preparation for deck soffit patch repair (wood end downstream side). At this time, also inspect crack in the upstream deck and issue repair prescription if required.				

Structure Name: N6-160

Site #:	N6-160	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	3.30	User km:		Last Inspection Date:	2022/08/03
Project File ID #:	0018	Br.	13	Next Inspection Date:	2023/08/03
Road Name:	BD0018.13HOWE CREEK				
Crossing Name:	Howe Creek		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-118 29 7.6		Latitude:	49 30 42.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 07-JAN-20: JRG Jan 7, 2020 Monitor abutments for settlement and monitor gap between and sill at lock blocks at right abutment. Record gap at location on blue arrow.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 3 of 15
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N6-065

Site #:	N6-065	Year Superstructure Installed:	2001	Structure Type/Class:	Permanent Bridge
KM:	24.10	User km:	29.10	Last Inspection Date:	2022/08/03
Project File ID #:	0018	Br.	27	Next Inspection Date:	2023/08/03
Road Name:	BD0018.27NORTH BOULD				
Crossing Name:	Traverse Cr.		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-118 39 43.4		Latitude:	49 29 37.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 07-JAN-20: . IDIR\JNAUL on 07-JAN-20: . IDIR\JNAUL on 07-JAN-20: .				

Structure Name: N6-165

Site #:	N6-165	Year Superstructure Installed:		Structure Type/Class:	Permanent Bridge
KM:	2.40	User km:	2.40	Last Inspection Date:	2020/08/22
Project File ID #:	0018	Br.	52	Next Inspection Date:	2023/08/22
Road Name:	BD0018.52GABLE 16600				
Crossing Name:	Unnamed Cr.		Total Length (metres):	8.0	
Special Access:			Special Equipment:		
Longitude:	-118 40 22.6		Latitude:	49 25 27.6	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 22-JAN-16: Re-inspect in 2016 to assess deck planks and monitor scour. Bridge may be down rated in future if not re-decked. CBR_Conversion on 17-FEB-14: need good photo of girder id to obtain verification of load rating				

Structure Name: N6-163

Site #:	N6-163	Year Superstructure Installed:		Structure Type/Class:	Temporary Bridge
KM:	0.10	User km:	0.10	Last Inspection Date:	2021/09/10
Project File ID #:	0018	Br.	58	Next Inspection Date:	2023/09/10
Road Name:	BD0018.58LITTLE CREE				
Crossing Name:	Little Cr.		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-118 35 26.2		Latitude:	49 25 22.8	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 08-JAN-20: JRG Jan 8, 2020 Record all the information on the structure ID plate.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 4 of 15
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status: Inspect

Structure Name: N6-170

Site #:	N6-170	Year Superstructure Installed:		Structure Type/Class:	Permanent Bridge
KM:	1.00	User km:		Last Inspection Date:	2020/08/22
Project File ID #:	0018	Br.	69	Next Inspection Date:	2023/08/22
Road Name:	BD0018.69DMBOULDER13				
Crossing Name:	Boulder Creek		Total Length (metres):	8.0	
Special Access:			Special Equipment:		
Longitude:	-118 39 30.7		Latitude:	49 29 5.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 22-JAN-16: JN; Re-inspect in 2016 and collect repair information. CBR_Conversion on 17-FEB-14: JNaul; 2014-01-30: Need professional inspection in 2014 to assess bearing block settlement issues. Location coordinates are dummy. Inspector to collect accurate location coordinates. Correct coordinates collected in 2010				

Structure Name: TKO-0031

Site #:	N6-192	Year Superstructure Installed:		Structure Type/Class:	Temporary Bridge
KM:	2.80	User km:	2.80	Last Inspection Date:	2021/09/09
Project File ID #:	8973	Br.	08	Next Inspection Date:	2023/09/09
Road Name:	BD8973.08UNION2200				
Crossing Name:	Dane Creek		Total Length (metres):	9.1	
Special Access:			Special Equipment:		
Longitude:	-118 21 20.0		Latitude:	49 32 38.1	
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: N6-176

Site #:	N6-176	Year Superstructure Installed:	2003	Structure Type/Class:	Permanent Bridge
KM:	0.60	User km:		Last Inspection Date:	2020/08/22
Project File ID #:	10849	Br.	02	Next Inspection Date:	2023/08/22
Road Name:	BLUEJOINT1100				
Crossing Name:	Bluejoint Creek		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-118 26 1.0		Latitude:	49 30 6.8	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 16-JAN-17: Inspector to re-inspect bridge in 2017 and down rate the bridge to 5 tonnes if deck is not replaced. Please send us photos for our records.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 5 of 15
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N6-008A

Site #:	N6-008	Year Superstructure Installed:		Structure Type/Class:	Major Culvert
KM:	2.49	User km:	2.80	Last Inspection Date:	2020/08/21
Project File ID #:	3719	Br.	01	Next Inspection Date:	2023/08/21
Road Name:	BOUNDARY CREEK				
Crossing Name:	HENDERSON Cr		Total Length (metres):	16.0	
Special Access:			Special Equipment:		
Longitude:	-118 42 16.2		Latitude:	49 12 34.9	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	IDIR\JNAUL on 08-APR-15: Reinspect in 2016 to check for no post barriers. IDIR\JNAUL on 27-FEB-14: JN; 2014-02-27: No as built information on file. Professional inspection required in 2014.				

Structure Name: N6-136

Site #:	N6-136	Year Superstructure Installed:	2002	Structure Type/Class:	Permanent Bridge
KM:	10.34	User km:	10.50	Last Inspection Date:	2020/08/23
Project File ID #:	0099	Br.	01	Next Inspection Date:	2023/08/23
Road Name:	BURRELL CREEK				
Crossing Name:	DEADEYE CRK		Total Length (metres):	9.0	
Special Access:			Special Equipment:		
Longitude:	-118 24 29.8		Latitude:	49 26 50.0	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:					

Structure Name: TKO-0030

Site #:	N6-181	Year Superstructure Installed:	2019	Structure Type/Class:	Temporary Bridge
KM:	1.70	User km:	28.80	Last Inspection Date:	2021/09/10
Project File ID #:	0018	Br.	106	Next Inspection Date:	2023/09/10
Road Name:	Boulder 13100				
Crossing Name:	unknown		Total Length (metres):	9.1	
Special Access:			Special Equipment:		
Longitude:	-118 39 35.4		Latitude:	49 29 2.5	
Superstructure:	Steel Box Beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:	IDIR\MRFENNEL on 26-MAR-20: .				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 6 of 15
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N6-078A

Site #:	N6-078	Year Superstructure Installed:	2018	Structure Type/Class:	Permanent Bridge
KM:	8.53	User km:	8.50	Last Inspection Date:	2020/08/18
Project File ID #:	0060	Br.	06	Next Inspection Date:	2023/08/18
Road Name:	CENTRE MOUNTAIN				
Crossing Name:	RENDELL Cr #2	Total Length (metres):	18.3		
Special Access:		Special Equipment:			
Longitude:	-118 38 53.5	Latitude:	49 47 49.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N6-041

Site #:	N6-041	Year Superstructure Installed:	1992	Structure Type/Class:	Major Culvert
KM:	19.33	User km:	17.20	Last Inspection Date:	2020/08/21
Project File ID #:	0161	Br.	01	Next Inspection Date:	2023/08/21
Road Name:	CONKLE JOHSTON CREEK				
Crossing Name:	CONKLE Cr	Total Length (metres):	15.0		
Special Access:		Special Equipment:			
Longitude:	-119 5 16.2	Latitude:	49 11 16.7		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\JNAUL on 27-FEB-14: JN; 2014-02-27: Monitor debris upstream and bedload inside the culverts.				

Structure Name: N6-044A

Site #:	N6-044	Year Superstructure Installed:		Structure Type/Class:	Major Culvert
KM:	0.26	User km:	21.70	Last Inspection Date:	2020/08/21
Project File ID #:	0282	Br.	01	Next Inspection Date:	2023/08/21
Road Name:	CROUSE CREEK				
Crossing Name:	BEAVERDELL Cr	Total Length (metres):	16.6		
Special Access:		Special Equipment:			
Longitude:	-118 58 19.9	Latitude:	49 28 46.4		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\JNAUL on 27-FEB-14: JN; 2014-02-27: There are no drawings or as built information on file. Professional inspection required.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 7 of 15
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N6-114

Site #:	N6-114	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	0.32	User km:	0.30	Last Inspection Date:	2020/08/23
Project File ID #:	8973	Br.	02	Next Inspection Date:	2023/08/23
Road Name:	FRANKLIN MOUNTAIN				
Crossing Name:	GLOUCESTER Cr		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-118 20 53.1		Latitude:	49 34 36.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N6-046

Site #:	N6-046	Year Superstructure Installed:	1978	Structure Type/Class:	Major Culvert
KM:	4.83	User km:	22.00	Last Inspection Date:	2020/08/21
Project File ID #:	6316	Br.	04	Next Inspection Date:	2023/08/21
Road Name:	GILPIN-STEWART CREEK				
Crossing Name:	TREADMILL Cr		Total Length (metres):	21.9	
Special Access:			Special Equipment:		
Longitude:	-118 19 8.2		Latitude:	49 8 59.7	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: N6-174

Site #:	N6-174	Year Superstructure Installed:	2011	Structure Type/Class:	Temporary Bridge
KM:	0.50	User km:		Last Inspection Date:	2021/09/15
Project File ID #:	9267	Br.	36	Next Inspection Date:	2023/09/15
Road Name:	GOAT850				
Crossing Name:	Unknown		Total Length (metres):	8.0	
Special Access:			Special Equipment:		
Longitude:	-118 32 5.8		Latitude:	49 46 13.3	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 8 of 15
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N6-121

Site #:	N6-121	Year Superstructure Installed:	1995	Structure Type/Class:	Temporary Bridge
KM:	11.45	User km:	10.50	Last Inspection Date:	2021/09/15
Project File ID #:	9267	Br.	02	Next Inspection Date:	2023/09/15
Road Name:	GOATSKIN CREEK				
Crossing Name:	GOATSKIN Cr	Total Length (metres):	16.3		
Special Access:			Special Equipment:		
Longitude:	-118 35 52.8	Latitude:	49 45 39.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 16-JAN-20: JRG Jan 16, 2020 Monitor condition of cribs. IDIR\JNAUL on 08-MAR-14: JN; 2014-03-08: Professional inspection required in 2014 to determine condition of bearing sills, bulkheads, sills and road fill, and to assess bent wind brace. Full log haul replacement date on file is 2015. Depending upon the findings from 2014 inspection, this structure may be down rated in future.				

Structure Name: N6-117

Site #:	N6-117	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	0.00	User km:	12.70	Last Inspection Date:	2020/08/18
Project File ID #:	5412	Br.	01	Next Inspection Date:	2023/08/18
Road Name:	GRANO CREEK				
Crossing Name:	HELLROARER #1	Total Length (metres):	14.0		
Special Access:			Special Equipment:		
Longitude:	-118 42 30.9	Latitude:	49 35 10.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\HABEURSK on 19-FEB-21: .				

Structure Name: N6-118

Site #:	N6-118	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	0.24	User km:	19.40	Last Inspection Date:	2019/09/26
Project File ID #:	5412	Br.	01	Next Inspection Date:	2022/09/26
Road Name:	GRANO CREEK				
Crossing Name:	COCHRANE Cr	Total Length (metres):	15.3		
Special Access:	Gate Key	Special Equipment:			
Longitude:	-118 40 36.9	Latitude:	49 39 1.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 9 of 15
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status: Inspect

Structure Name: N6-071A

Site #:	N6-071	Year Superstructure Installed:	2008	Structure Type/Class:	Permanent Bridge
KM:	16.70	User km:	16.70	Last Inspection Date:	2020/08/18
Project File ID #:	0060	Br.	01	Next Inspection Date:	2023/08/18
Road Name:	KETTLE RIVER				
Crossing Name:	SPLIT Cr		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-118 44 0.9		Latitude:	49 46 10.9	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: N6-076

Site #:	N6-076	Year Superstructure Installed:	1985	Structure Type/Class:	Permanent Bridge
KM:	19.63	User km:	0.00	Last Inspection Date:	2020/08/19
Project File ID #:	0136	Br.	01	Next Inspection Date:	2023/08/19
Road Name:	LOSTHORSE CREEK				
Crossing Name:	Kettle R		Total Length (metres):	36.6	
Special Access:			Special Equipment:	Peeper Truck	
Longitude:	-118 52 34.7		Latitude:	49 22 55.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	2
Planned Inspection Comments:	IDIR\JNAUL on 03-MAR-14: JN; 2014-03-03: Need professional inspection in 2014 to assess cracks in wing walls, tension in dywidag bars, adequacy of repairs done to abutments in 1996, and measure gaps in concrete panels.				

Structure Name: N6-162

Site #:	N6-162	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	1.20	User km:	1.20	Last Inspection Date:	2021/09/10
Project File ID #:	0285	Br.	01	Next Inspection Date:	2023/08/06
Road Name:	LYNCH CREEK FSR				
Crossing Name:	Lynch Cr.		Total Length (metres):	16.0	
Special Access:			Special Equipment:		
Longitude:	-118 25 7.3		Latitude:	49 14 43.3	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 10 of 15
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N6-035

Site #:	N6-035	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	6.25	User km:	40.30	Last Inspection Date:	2020/08/23
Project File ID #:	0099	Br.	03	Next Inspection Date:	2023/08/23
Road Name:	MCFARLANE CREEK				
Crossing Name:	MCFARLANE Cr	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-118 20 5.3	Latitude:	49 40 9.7		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 26-FEB-14: JN; 2014-02-26: Need photos of cracks and curb offset. Professional engineers should inspect this structure in 2014.				

Structure Name: N6-033A

Site #:	N6-033	Year Superstructure Installed:	2021	Structure Type/Class:	Permanent Bridge
KM:	10.39	User km:	36.10	Last Inspection Date:	
Project File ID #:	0099	Br.	03	Next Inspection Date:	2023/08/01
Road Name:	MCFARLANE CREEK				
Crossing Name:	WALTER Cr	Total Length (metres):	15.6		
Special Access:		Special Equipment:			
Longitude:	-118 20 28.4	Latitude:	49 38 6.1		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N6-082A

Site #:	N6-082	Year Superstructure Installed:	2013	Structure Type/Class:	Permanent Bridge
KM:	2.30	User km:	11.20	Last Inspection Date:	2022/09/26
Project File ID #:	5457	Br.	01	Next Inspection Date:	2023/09/26
Road Name:	MCKINNEY CREEK				
Crossing Name:	MCKINNEY Cr	Total Length (metres):	7.0		
Special Access:		Special Equipment:			
Longitude:	-119 12 47.2	Latitude:	49 5 9.5		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 18-FEB-21: JRG 18, 2021 Monitor two tier lock blocks for scour.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 11 of 15
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N6-086A

Site #:	N6-086	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	2.16	User km:	2.40	Last Inspection Date:	2020/08/22
Project File ID #:	5595	Br.	01	Next Inspection Date:	2023/08/22
Road Name:	MILLER CREEK				
Crossing Name:	MILLER Cr		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-118 23 59.6		Latitude:	49 12 29.8	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: N6-090C

Site #:	N6-090	Year Superstructure Installed:	2022	Structure Type/Class:	Permanent Bridge
KM:	9.65	User km:	17.20	Last Inspection Date:	
Project File ID #:	4354	Br.	01	Next Inspection Date:	2023/08/01
Road Name:	PASS				
Crossing Name:	KENNEDY Cr		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-118 32 57.8		Latitude:	49 16 15.9	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N6-088

Site #:	N6-088	Year Superstructure Installed:	1984	Structure Type/Class:	Major Culvert
KM:	24.28	User km:	2.80	Last Inspection Date:	2019/08/09
Project File ID #:	4354	Br.	01	Next Inspection Date:	2022/08/09
Road Name:	PASS				
Crossing Name:	PASS Cr #1		Total Length (metres):	9.1	
Special Access:			Special Equipment:		
Longitude:	-118 29 41.1		Latitude:	49 11 26.4	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 12 of 15
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N6-205

Site #:	N6-205	Year Superstructure Installed:	2021	Structure Type/Class:	Major Culvert
KM:	25.46	User km:	25.00	Last Inspection Date:	
Project File ID #:	4354	Br.	01	Next Inspection Date:	2023/07/14
Road Name:	PASS				
Crossing Name:	Unnamed Creek		Total Length (metres):	24.0	
Special Access:			Special Equipment:		
Longitude:	-118 34 33.9		Latitude:	49 19 6.4	
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:	IDIR\DMALWAY on 01-FEB-23: Measure inlet and outlet coverage. One culvert section appears installed steeper than design.				

Structure Name: N6-079A

Site #:	N6-079	Year Superstructure Installed:	2016	Structure Type/Class:	Permanent Bridge
KM:	0.09	User km:	0.10	Last Inspection Date:	2020/08/18
Project File ID #:	9267	Br.	01	Next Inspection Date:	2023/08/18
Road Name:	RENDELL CREEK				
Crossing Name:	Kettle R		Total Length (metres):	40.0	
Special Access:			Special Equipment:		
Longitude:	-118 46 30.7		Latitude:	49 37 54.7	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: N6-135A

Site #:	N6-135	Year Superstructure Installed:	2008	Structure Type/Class:	Permanent Bridge
KM:	2.50	User km:	3.50	Last Inspection Date:	2020/08/18
Project File ID #:	0060	Br.	04	Next Inspection Date:	2023/08/18
Road Name:	SPLIT CREEK				
Crossing Name:	SPLIT Cr		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-118 44 14.6		Latitude:	49 49 49.3	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 13 of 15
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N6-086

Site #:	N6-183	Year Superstructure Installed:	2016	Structure Type/Class:	Temporary Bridge
KM:	0.20	User km:	0.20	Last Inspection Date:	2021/09/14
Project File ID #:	0073	Br.	10	Next Inspection Date:	2023/09/14
Road Name:	STATE18000				
Crossing Name:	unknown		Total Length (metres):	6.2	
Special Access:			Special Equipment:		
Longitude:	-118 52 3.1		Latitude:	49 32 28.2	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	IDIR\JNAUL on 21-JAN-20: JRG Jan 21, 2020 Confirm girder geometry. Shop drawings show: 6100 mm o/o length, 5500 mm c/c of bearing stiffeners, diaphragm spacing 2750 mm, top and bottom flange 178 mm x 16 mm, total girder height 515 mm.				

Structure Name: N6-138

Site #:	N6-138	Year Superstructure Installed:	2003	Structure Type/Class:	Permanent Bridge
KM:	3.34	User km:	0.70	Last Inspection Date:	2020/08/19
Project File ID #:	0136	Br.	09	Next Inspection Date:	2023/08/19
Road Name:	THONE SPUR 600				
Crossing Name:	Unnamed		Total Length (metres):	6.4	
Special Access:			Special Equipment:		
Longitude:	-118 47 53.1		Latitude:	49 26 42.7	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:					

Structure Name: N6-093

Site #:	N6-093	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	4.95	User km:	0.70	Last Inspection Date:	2020/08/21
Project File ID #:	3929	Br.	01	Next Inspection Date:	2023/08/21
Road Name:	TRAPPING CREEK				
Crossing Name:	WEST KETTLE R		Total Length (metres):	27.5	
Special Access:			Special Equipment:		
Longitude:	-119 3 18.8		Latitude:	49 33 50.5	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:	IDIR\JNAUL on 21-JAN-16: JN: According to inspector Downstream Right Bank (DS RB) sill should be monitored for settlement. Inspector measured following s gaps between bottom flange and blocks: Left gap upstream is 35 mm. Downstream is 30 mm. Right upstream gap is 65 mm, downstream 36 mm. Downstream right bank may be settling. IDIR\JNAUL on 09-MAR-14: JN; 2014-03-09: Changed abutments from precast to concrete lock block - Dura block retaining walls and concrete sills on fill. Cracks in dura blocks observed as early as 2001 (a year after bridge installation.) Professional inspection of abutments required (2014).				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 14 of 15
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status: Inspect

Structure Name: N6-052

Site #:	N6-052	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	3.71	User km:	18.70	Last Inspection Date:	2020/08/22
Project File ID #:	0018	Br.	09	Next Inspection Date:	2023/08/22
Road Name:	TRAVERSE CREEK				
Crossing Name:	BOULDER (12M) Cr		Total Length (metres):	13.0	
Special Access:			Special Equipment:		
Longitude:	-118 33 55.9		Latitude:	49 30 2.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Monitoring and Inspection: Rip rap, cracks, and settlement under blocks should be monitored every 2 years, and before and after industrial use.				

Structure Name: N6-053

Site #:	N6-053	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	5.00	User km:	20.00	Last Inspection Date:	2020/08/22
Project File ID #:	0018	Br.	09	Next Inspection Date:	2023/08/22
Road Name:	TRAVERSE CREEK				
Crossing Name:	TRAVERSE Cr		Total Length (metres):	14.5	
Special Access:			Special Equipment:		
Longitude:	-118 33 55.8		Latitude:	49 30 43.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Monitoring and Inspection: Rip rap, cracks, and settlement under blocks should be monitored every year, and before and after each industrial use. Monitor the through crack in the concrete block (RB 4th row from the top) for settlement and deterioration annually.				

Structure Name: N6-054

Site #:	N6-054	Year Superstructure Installed:	2004	Structure Type/Class:	Permanent Bridge
KM:	8.69	User km:	23.90	Last Inspection Date:	2020/08/22
Project File ID #:	0018	Br.	09	Next Inspection Date:	2023/08/22
Road Name:	TRAVERSE CREEK				
Crossing Name:	N FORK TRAVERSE Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-118 35 16.0		Latitude:	49 31 52.8	
Superstructure:	Compo Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 15 of 15
Date Printed: 2023/07/11
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2023/12/30 Inspection Status:Inspect

Structure Name: N6-119

Site #:	N6-119	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	0.07	User km:	0.10	Last Inspection Date:	2020/08/23
Project File ID #:	8973	Br.	03	Next Inspection Date:	2023/08/23
Road Name:	UNION MINE				
Crossing Name:	GLOUCESTER Cr	Total Length (metres):	12.5		
Special Access:		Special Equipment:			
Longitude:	-118 20 48.6	Latitude:	49 33 30.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 11-FEB-21: . IDIR\JNAUL on 11-FEB-21: .				

Structure Name: N6-120

Site #:	N6-120	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	4.37	User km:	4.40	Last Inspection Date:	2020/08/23
Project File ID #:	8973	Br.	03	Next Inspection Date:	2023/08/23
Road Name:	UNION MINE				
Crossing Name:	FRANKLIN Cr	Total Length (metres):	12.5		
Special Access:		Special Equipment:			
Longitude:	-118 23 18.9	Latitude:	49 33 7.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 17-FEB-21: .				

Structure Type/Class Totals

Permanent Bridge Total: 30
Temporary Bridge Total: 8

Major Culvert Total: 6
Woodbox/Log Culvert Total: 0