



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 1 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K877

Site #:	K877	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	4.31	User km:	23.50	Last Inspection Date:	2022/08/10
Project File ID #:	0724	Br.	01	Next Inspection Date:	2023/08/10
Road Name:	1020 (TEN TWENTY)				
Crossing Name:	Humamilt #2		Total Length (metres):	10.6	
Special Access:			Special Equipment:		
Longitude:	-119 7 54.0		Latitude:	51 16 54.6	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: MC Dec 2012, Monitor rip rap after freshet				

Structure Name: K769

Site #:	K769	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	23.17	User km:	4.90	Last Inspection Date:	2022/08/11
Project File ID #:	0724	Br.	01	Next Inspection Date:	2023/08/11
Road Name:	1020 (TEN TWENTY)				
Crossing Name:	Celista Main		Total Length (metres):	24.4	
Special Access:			Special Equipment:		
Longitude:	-119 0 49.5		Latitude:	51 13 0.5	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 08-JAN-19: PB Jan08.2019 Concrete deck requires repair at various pockets and joints. Areas of grout failure and bearing locations to be closely inspected.				

Structure Name: K803

Site #:	K803	Year Superstructure Installed:	1992	Structure Type/Class:	Woodbox/Log Culvert
KM:	25.25	User km:	30.10	Last Inspection Date:	2022/08/10
Project File ID #:	0724	Br.	01	Next Inspection Date:	2023/08/10
Road Name:	1020 (TEN TWENTY)				
Crossing Name:	Unnamed		Total Length (metres):	6.0	
Special Access:			Special Equipment:		
Longitude:	-119 11 41.4		Latitude:	51 18 51.1	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\PBLUESCH on 09-FEB-16: PB Feb25,2015 Annual inspection. Crib tie backs are crushing.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 2 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1429

Site #:	K1429	Year Superstructure Installed:	2012	Structure Type/Class:	Temporary Bridge
KM:	6.38	User km:	25.10	Last Inspection Date:	2022/08/11
Project File ID #:	4852	Br.	01	Next Inspection Date:	2023/08/11
Road Name:	ADAMS PLATEAU				
Crossing Name:	Gold Cr	Total Length (metres):	7.2		
Special Access:		Special Equipment:			
Longitude:	-119 32 20.4	Latitude:	51 3 20.6		
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: K859

Site #:	K859	Year Superstructure Installed:	1995	Structure Type/Class:	Temporary Bridge
KM:	6.10	User km:	23.80	Last Inspection Date:	2021/09/20
Project File ID #:	3982	Br.	08	Next Inspection Date:	2023/09/20
Road Name:	ANSTEY				
Crossing Name:	Wilson # 2	Total Length (metres):	13.0		
Special Access:		Special Equipment:			
Longitude:	-118 58 13.2	Latitude:	50 57 45.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 21-FEB-17: PB Feb21,2017 Structure requires measure up of cross tie dimensions. IDIR\PBLUESCH on 15-FEB-16: PB Feb15,2016 Record manufactures Job# and complete full measure up of steel girders and crossties for load rating. CBR_Conversion on 24-FEB-14: PB Feb24/11. Record girder identifiers including Rapidsan WO# on web.				

Structure Name: K1602

Site #:	K1602	Year Superstructure Installed:	2002	Structure Type/Class:	Temporary Bridge
KM:	2.70	User km:		Last Inspection Date:	2022/08/10
Project File ID #:	9108	Br.	01	Next Inspection Date:	2023/08/10
Road Name:	ANSTEY BEACH				
Crossing Name:	unknown	Total Length (metres):	7.9		
Special Access:		Special Equipment:			
Longitude:	-118 58 54.0	Latitude:	51 2 52.0		
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Jan 30,2014 Confirm user KM, full measure of bridge dimensions, stringers to be drilled for rot. Ensure structure is posted to 20 tonnes.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 3 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K654

Site #:	K654	Year Superstructure Installed:	1990	Structure Type/Class:	Permanent Bridge
KM:	0.76	User km:	7.40	Last Inspection Date:	2022/06/30
Project File ID #:	5143	Br.	05	Next Inspection Date:	2023/06/30
Road Name:	ASHTON MARA EAST				
Crossing Name:	Johnson Cr		Total Length (metres):	14.4	
Special Access:			Special Equipment:		
Longitude:	-119 0 10.8		Latitude:	50 41 37.2	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Feb23.2013 Monitor rip rap for scour.				

Structure Name: K653

Site #:	K653	Year Superstructure Installed:	1991	Structure Type/Class:	Permanent Bridge
KM:	4.95	User km:	13.90	Last Inspection Date:	2022/06/30
Project File ID #:	5143	Br.	05	Next Inspection Date:	2023/06/30
Road Name:	ASHTON MARA EAST				
Crossing Name:	Mara Cr		Total Length (metres):	14.3	
Special Access:			Special Equipment:		
Longitude:	-118 58 29.9		Latitude:	50 44 30.4	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Feb32.2013 Monitor abutments and rip rap for scour.				

Structure Name: K778

Site #:	K778	Year Superstructure Installed:	1980	Structure Type/Class:	Major Culvert
KM:	6.71	User km:	6.50	Last Inspection Date:	2022/06/30
Project File ID #:	5143	Br.	05	Next Inspection Date:	2023/06/30
Road Name:	ASHTON MARA EAST				
Crossing Name:	Unnamed		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-119 0 21.0		Latitude:	50 41 27.0	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Inspect annually				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 4 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K777

Site #:	K777	Year Superstructure Installed:	1972	Structure Type/Class:	Major Culvert
KM:	12.11	User km:	11.50	Last Inspection Date:	2022/06/30
Project File ID #:	5143	Br.	05	Next Inspection Date:	2023/06/30
Road Name:	ASHTON MARA EAST				
Crossing Name:	Ashton Cr	Total Length (metres):	8.0		
Special Access:			Special Equipment:		
Longitude:	-118 59 29.5	Latitude:	50 43 31.4		
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Feb25.2013. Monitor annually. Incorrect structure was inspected in 2012.				

Structure Name: K652

Site #:	K652	Year Superstructure Installed:	1991	Structure Type/Class:	Permanent Bridge
KM:	19.68	User km:	19.70	Last Inspection Date:	2022/06/30
Project File ID #:	5143	Br.	05	Next Inspection Date:	2023/06/30
Road Name:	ASHTON MARA EAST				
Crossing Name:	Hummingbird Cr	Total Length (metres):	11.3		
Special Access:			Special Equipment:		
Longitude:	-118 56 57.6	Latitude:	50 46 51.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 21-FEB-14: PB Feb21.2014 Planned inspection comment and monitor item re: undermined shallow footings not addressed in 2013. Fill supporting the footings is being eroded. Continue to monitor undermined footings and scoured rip rap. Scheduled for re-inspection in 2014. Detailed photos of the footing condition should be taken and comments recorded. CBR_Conversion on 17-FEB-14: PB Feb23.2013 Monitor undermined precast footings and scoured rip rap.				

Structure Name: K775

Site #:	K775	Year Superstructure Installed:	1992	Structure Type/Class:	Major Culvert
KM:	24.24	User km:	24.40	Last Inspection Date:	2022/06/30
Project File ID #:	5143	Br.	05	Next Inspection Date:	2023/06/30
Road Name:	ASHTON MARA EAST				
Crossing Name:	Sicamous Cr	Total Length (metres):	11.0		
Special Access:			Special Equipment:		
Longitude:	-118 54 14.7	Latitude:	50 47 48.5		
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 5 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K651

Site #:	K651	Year Superstructure Installed:	1992	Structure Type/Class:	Permanent Bridge
KM:	27.35	User km:	26.70	Last Inspection Date:	2022/06/30
Project File ID #:	5143	Br.	05	Next Inspection Date:	2023/06/30
Road Name:	ASHTON MARA EAST				
Crossing Name:	Sicamous Cr		Total Length (metres):	9.0	
Special Access:			Special Equipment:		
Longitude:	-118 52 53.1		Latitude:	50 47 18.7	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\BPELLETT on 02-MAY-22: BP May 2-22 Take representative photographs of right abutment shape with every annual inspection. Use a long level, stringline, or similar device as a visual aid. IDIR\PBLUESCH on 20-FEB-14: PB Feb 20,2014 Continue to monitor rip rap for stability and lock block abutments for scour.				

Structure Name: K1573

Site #:	K1573	Year Superstructure Installed:		Structure Type/Class:	Temporary Bridge
KM:	2.38	User km:		Last Inspection Date:	2021/08/22
Project File ID #:	7271	Br.	07	Next Inspection Date:	2023/08/22
Road Name:	BLAIS SOUTH				
Crossing Name:	Blais Creek		Total Length (metres):	16.8	
Special Access:	Pedestrian		Special Equipment:		
Longitude:	-118 51 5.7		Latitude:	51 28 42.5	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:	IDIR\BPELLETT on 05-APR-22: BP Apr 5-22 Annual inspection no longer required. Riprap not moving and road access will only be re-established for deck and substructure replacement project, currently scheduled for 2022. IDIR\PBLUESCH on 26-FEB-15: PB Feb26.2015 Measure up crosstie dimensions and spacing, they look undersized. Assess deck/girder connection and photograph. CBR_Conversion on 17-FEB-14: PB Feb22,2013 Monitor sill logs for rot/settlement.				

Structure Name: K1025

Site #:	K1025	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	2.00	User km:	1.90	Last Inspection Date:	2020/10/09
Project File ID #:	0724	Br.	05	Next Inspection Date:	2023/10/09
Road Name:	CELISTA HUMAMILT				
Crossing Name:	Unnamed		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-118 59 56.8		Latitude:	51 17 13.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 6 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K738A

Site #:	K738	Year Superstructure Installed:	2008	Structure Type/Class:	Permanent Bridge
KM:	0.50	User km:	16.20	Last Inspection Date:	2022/10/06
Project File ID #:	6019	Br.	01	Next Inspection Date:	2023/10/06
Road Name:	CHARCOAL CREEK				
Crossing Name:	Blanc #1	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-119 31 46.8	Latitude:	50 41 32.7		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Other	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 05-FEB-16: PB Feb5.2016 Monitor for aggradation, channel was dredged in 2013.				

Structure Name: K762

Site #:	K762	Year Superstructure Installed:	1998	Structure Type/Class:	Temporary Bridge
KM:	10.32	User km:	29.50	Last Inspection Date:	2022/08/09
Project File ID #:	R07629	Br.	18-7	Next Inspection Date:	2023/08/09
Road Name:	CP 888				
Crossing Name:	Unnamed	Total Length (metres):	8.0		
Special Access:	Helicopter	Special Equipment:			
Longitude:	-118 54 14.4	Latitude:	51 27 33.4		
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Jan 30, 2014 Bridge across the Seymour River has been pulled. Confirm access (if any) with District or Engineering Branch prior to mobilizing to site; alternate access from Smokey House pending. Quad required.PB mar11/11 Ensure posted to 2 tonnes. Requires ATV for access. GMC June 23/09 LC D/S crib undermined. Should be OK for light traffic. Inspect and assess annually				

Structure Name: K280

Site #:	K280	Year Superstructure Installed:	1987	Structure Type/Class:	Temporary Bridge
KM:	13.63	User km:	14.10	Last Inspection Date:	2022/07/30
Project File ID #:	6320	Br.	01	Next Inspection Date:	2023/07/30
Road Name:	CRAZY CREEK				
Crossing Name:	Crazy Cr #4	Total Length (metres):	16.4		
Special Access:		Special Equipment:			
Longitude:	-118 31 0.2	Latitude:	51 2 10.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 14-JAN-19: PB Jan14.2019 Post to 5 tonnes. Annual inspection. Cross-ties are undersized 150mmx200mm section .PB feb23/11 needs number plate.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 7 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K281

Site #:	K281	Year Superstructure Installed:	1990	Structure Type/Class:	Temporary Bridge
KM:	15.96	User km:	16.40	Last Inspection Date:	2021/08/01
Project File ID #:	6320	Br.	01	Next Inspection Date:	2023/08/01
Road Name:	CRAZY CREEK				
Crossing Name:	Crazy Cr #5		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-118 29 15.6		Latitude:	51 1 43.5	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 03-MAR-15: PB Mar03,2015 Assess log crib condition. IDIR\PBLUESCH on 20-FEB-14: PB Feb 20,2014 This structure has a non standard deck upgrade with additional ties installed between the pre-exisiting rotten deck ties. It appears these crossties have been decked over with a new running deck, but possibly the old subdeck. Re-inspect in 2014 and take detailed photos of the deck condition. Structure should be posted to 5 tonnes until proper repairs completed. Deck is attached to girders with rotten ties, please confirm. CBR_Conversion on 17-FEB-14: PB Feb06,2012 Load rating set to 5 tonnes (from 20 tonnes) until required deck repairs completed. Ensure structure is posted. GMC Apr Jan27/10 Poste to 5 T in 2009				

Structure Name: K272A

Site #:	K272	Year Superstructure Installed:	2010	Structure Type/Class:	Major Culvert
KM:	3.70	User km:		Last Inspection Date:	2022/07/30
Project File ID #:	4848	Br.	05	Next Inspection Date:	2023/07/30
Road Name:	EAGLE RIVER				
Crossing Name:	Unknown		Total Length (metres):	9.7	
Special Access:			Special Equipment:		
Longitude:	-118 43 35.0		Latitude:	50 57 32.0	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\BPELLETT on 26-APR-22: BP Apr 26-22 Measure exposure and undermining of footings, and potential build-up of large bedload above inlet CBR_Conversion on 17-FEB-14: PB May3/12. Collect as built info during 2012 inspection.				

Structure Name: K736A

Site #:	K736	Year Superstructure Installed:	2013	Structure Type/Class:	Permanent Bridge
KM:	0.52	User km:	64.50	Last Inspection Date:	2020/10/08
Project File ID #:	0839	Br.	01	Next Inspection Date:	2023/10/08
Road Name:	GORGE				
Crossing Name:	Ratchford #2		Total Length (metres):	36.9	
Special Access:			Special Equipment:		
Longitude:	-118 51 59.4		Latitude:	51 21 30.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 8 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Planned Inspection Comments:

Structure Name: K1517

Site #:	K1517	Year Superstructure Installed:	2009	Structure Type/Class:	Major Culvert
KM:	11.90	User km:	11.90	Last Inspection Date:	2020/10/07
Project File ID #:	0839	Br.	01	Next Inspection Date:	2023/10/07
Road Name:	GORGE				
Crossing Name:	Unnamed		Total Length (metres):	26.0	
Special Access:			Special Equipment:		
Longitude:	-118 47 0.5		Latitude:	51 1 47.6	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0

Planned Inspection Comments:

Structure Name: K902

Site #:	K902	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	16.03	User km:	20.40	Last Inspection Date:	2020/10/07
Project File ID #:	0839	Br.	01	Next Inspection Date:	2023/10/07
Road Name:	GORGE				
Crossing Name:	Four Mile		Total Length (metres):	14.0	
Special Access:			Special Equipment:		
Longitude:	-118 48 43.2		Latitude:	51 4 31.2	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1

Planned Inspection Comments:

Structure Name: K901

Site #:	K901	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	28.41	User km:	33.20	Last Inspection Date:	2020/10/07
Project File ID #:	0839	Br.	01	Next Inspection Date:	2023/10/07
Road Name:	GORGE				
Crossing Name:	First Cr		Total Length (metres):	17.0	
Special Access:			Special Equipment:		
Longitude:	-118 50 18.5		Latitude:	51 7 43.3	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1

Planned Inspection Comments:



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 9 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1049

Site #:	K1049	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	42.89	User km:	48.40	Last Inspection Date:	2020/10/07
Project File ID #:	0839	Br.	01	Next Inspection Date:	2023/10/07
Road Name:	GORGE				
Crossing Name:	Anstey R	Total Length (metres):	26.0		
Special Access:		Special Equipment:	Peeper Truck		
Longitude:	-118 49 7.8	Latitude:	51 13 31.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 09-MAR-15: .				

Structure Name: K271

Site #:	K271	Year Superstructure Installed:	1994	Structure Type/Class:	Major Culvert
KM:	5.94	User km:	12.90	Last Inspection Date:	2020/10/06
Project File ID #:	4848	Br.	06	Next Inspection Date:	2023/10/06
Road Name:	GRIFFIN BR. 1				
Crossing Name:	Third	Total Length (metres):	18.0		
Special Access:		Special Equipment:			
Longitude:	-118 39 50.7	Latitude:	50 57 15.2		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: GMc Oct 21/08 Requires ATV or Fly in Access. Do not include in unit rate routine conditional inspections. Should be done hourly or by in house personnel				

Structure Name: K1149

Site #:	K1149	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	6.04	User km:	6.30	Last Inspection Date:	2022/07/06
Project File ID #:	6524	Br.	05	Next Inspection Date:	2023/07/06
Road Name:	HUNTER				
Crossing Name:	Unnamed	Total Length (metres):	16.8		
Special Access:		Special Equipment:			
Longitude:	-118 52 27.2	Latitude:	50 39 33.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 25-FEB-20: PB Feb 25.2020 Cross ties look original. Monitor tie condition for rot and performance.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 10 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1643

Site #:	K1643	Year Superstructure Installed:	2016	Structure Type/Class:	Permanent Bridge
KM:	4.40	User km:	4.40	Last Inspection Date:	2021/07/16
Project File ID #:	6524	Br.	03	Next Inspection Date:	2023/07/16
Road Name:	KINGFISHER				
Crossing Name:	Unnamed		Total Length (metres):	5.5	
Special Access:			Special Equipment:		
Longitude:	-118 47 23.0		Latitude:	50 40 28.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: K260A

Site #:	K260	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	0.08	User km:	0.40	Last Inspection Date:	2020/10/07
Project File ID #:	3982	Br.	07	Next Inspection Date:	2023/10/07
Road Name:	LEGERWOOD				
Crossing Name:	Legerwood Cr		Total Length (metres):	12.0	
Special Access:	Gate Key		Special Equipment:		
Longitude:	-118 46 24.5		Latitude:	50 57 54.3	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 10-MAY-19: PB May10.2019 Exterior slabs cracked during 2018/2019 winter due to tracked equipment loading. Monitor hairline cracks in slabs.				

Structure Name: K988

Site #:	K988	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	4.77	User km:	25.40	Last Inspection Date:	2020/09/25
Project File ID #:	0835	Br.	04	Next Inspection Date:	2023/09/25
Road Name:	MABEL NOISY				
Crossing Name:	Noisy Cr		Total Length (metres):	17.0	
Special Access:			Special Equipment:		
Longitude:	-118 39 22.8		Latitude:	50 42 30.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 25-FEB-20: PB Feb 25.2020 Recent abutment repairs completed in 2019. Scoured foundation lock block grouted to ensure full bearing on supporting soil. Rock armouring added.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 11 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K239

Site #:	K239	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	0.22	User km:	0.20	Last Inspection Date:	2022/10/07
Project File ID #:	0825	Br.	04	Next Inspection Date:	2023/10/07
Road Name:	MOUNTIDA HAINES CR N				
Crossing Name:	Haines Cr	Total Length (metres):	9.6		
Special Access:			Special Equipment:		
Longitude:	-119 20 50.1		Latitude:	50 33 56.9	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 25-FEB-20: PB Feb25.2020 Continue to monitor right bank footings for scour. Additional cobble armouring may have been added over rip rap toe based on 2019 photos which is covering the exposed precast footings. CBR_Conversion on 17-FEB-14: PB Feb06,2012 Assess right bank exposed footings for scour.				

Structure Name: K218A

Site #:	K218	Year Superstructure Installed:	2010	Structure Type/Class:	Permanent Bridge
KM:	6.23	User km:	12.00	Last Inspection Date:	2022/08/09
Project File ID #:	0762	Br.	01	Next Inspection Date:	2023/08/09
Road Name:	NORTH FORK				
Crossing Name:	Perry Main #2	Total Length (metres):	18.3		
Special Access:			Special Equipment:		
Longitude:	-118 41 9.5		Latitude:	51 5 30.8	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 15-JAN-19: PB Jan15.2019 Inspect panels from underside for concrete damage and performance of repaired areas.				

Structure Name: K219A

Site #:	K219	Year Superstructure Installed:	2010	Structure Type/Class:	Permanent Bridge
KM:	6.70	User km:	12.50	Last Inspection Date:	2020/10/07
Project File ID #:	0762	Br.	01	Next Inspection Date:	2023/10/07
Road Name:	NORTH FORK				
Crossing Name:	Perry Main #3	Total Length (metres):	15.2		
Special Access:			Special Equipment:		
Longitude:	-118 41 13.3		Latitude:	51 5 47.7	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 12 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1581

Site #:	K1581	Year Superstructure Installed:	2012	Structure Type/Class:	Major Culvert
KM:	21.10	User km:	28.50	Last Inspection Date:	2020/10/07
Project File ID #:	0762	Br.	01	Next Inspection Date:	2023/10/07
Road Name:	NORTH FORK				
Crossing Name:	Unknown Cr		Total Length (metres):	12.8	
Special Access:			Special Equipment:		
Longitude:	-118 40 37.0		Latitude:	51 13 15.0	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	CBR_Conversion on 04-NOV-20: PB Nov04.2020 Continue to monitor arch footing for scour at outlet.				

Structure Name: K1116A

Site #:	K1116	Year Superstructure Installed:	2011	Structure Type/Class:	Permanent Bridge
KM:	22.35	User km:	27.10	Last Inspection Date:	2022/08/09
Project File ID #:	0762	Br.	01	Next Inspection Date:	2023/08/09
Road Name:	NORTH FORK				
Crossing Name:	Perry Main #6		Total Length (metres):	27.4	
Special Access:			Special Equipment:		
Longitude:	-118 40 34.7		Latitude:	51 12 41.5	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\PBLUESCH on 15-JAN-19: PB Jan 15.2019 Upstream girder and bracing repaired / heat straightened in 2017. Channel dredged in 2018. Most of the original rip rap is buried under dredged fill; some of the original rip rap on LB may have been lost during 2015 event. Monitor abutments for scour and armour performance.				

Structure Name: K912

Site #:	K912	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	26.24	User km:	23.00	Last Inspection Date:	2020/10/14
Project File ID #:	0762	Br.	01	Next Inspection Date:	2023/10/14
Road Name:	NORTH FORK				
Crossing Name:	Perry Main #4		Total Length (metres):	8.6	
Special Access:			Special Equipment:		
Longitude:	-118 40 40.4		Latitude:	51 11 31.6	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 13 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K913A

Site #:	K913	Year Superstructure Installed:	2012	Structure Type/Class:	Permanent Bridge
KM:	7.17	User km:	48.40	Last Inspection Date:	2020/10/08
Project File ID #:	0762	Br.	07	Next Inspection Date:	2023/10/08
Road Name:	NORTH FORK 7000 FSR				
Crossing Name:	Myoff #2	Total Length (metres):	27.4		
Special Access:		Special Equipment:			
Longitude:	-118 42 42.1	Latitude:	51 22 35.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1167

Site #:	K1167	Year Superstructure Installed:	2002	Structure Type/Class:	Major Culvert
KM:	23.15	User km:	23.50	Last Inspection Date:	2022/07/30
Project File ID #:	6865	Br.	01	Next Inspection Date:	2023/07/30
Road Name:	OWLHEAD CREEK				
Crossing Name:	Unnamed	Total Length (metres):	12.3		
Special Access:		Special Equipment:			
Longitude:	-118 48 39.9	Latitude:	50 49 5.2		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: PS-034

Site #:	K878	Year Superstructure Installed:	2015	Structure Type/Class:	Temporary Bridge
KM:	6.46	User km:	20.70	Last Inspection Date:	2022/08/09
Project File ID #:	7271	Br.	02	Next Inspection Date:	2023/08/09
Road Name:	RATCHFORD				
Crossing Name:	Cotton Cr	Total Length (metres):	26.2		
Special Access:		Special Equipment:			
Longitude:	-118 50 36.2	Latitude:	51 21 57.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\PBUESCH on 09-FEB-16: PB Feb09.2016 Temp install in 2015.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 14 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1068

Site #:	K1068	Year Superstructure Installed:	1997	Structure Type/Class:	Major Culvert
KM:	6.04	User km:	6.10	Last Inspection Date:	2022/08/04
Project File ID #:	4609	Br.	04	Next Inspection Date:	2023/08/04
Road Name:	ROSEMOND				
Crossing Name:	Larch Hills Cr		Total Length (metres):	12.1	
Special Access:			Special Equipment:		
Longitude:	-119 5 27.3		Latitude:	50 43 26.2	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					

Structure Name: K229B

Site #:	K229	Year Superstructure Installed:	2014	Structure Type/Class:	Permanent Bridge
KM:	11.43	User km:	11.20	Last Inspection Date:	2020/10/03
Project File ID #:	0771	Br.	01	Next Inspection Date:	2023/10/03
Road Name:	SCOTCH CREEK				
Crossing Name:	Sparkle Cr		Total Length (metres):	8.0	
Special Access:			Special Equipment:		
Longitude:	-119 27 15.8		Latitude:	51 1 17.6	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: K231

Site #:	K231	Year Superstructure Installed:	2003	Structure Type/Class:	Major Culvert
KM:	21.89	User km:	7.50	Last Inspection Date:	2020/10/03
Project File ID #:	0771	Br.	01	Next Inspection Date:	2023/10/03
Road Name:	SCOTCH CREEK				
Crossing Name:	Little Snuff Box		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-119 21 55.4		Latitude:	51 3 41.7	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 15 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K232

Site #:	K232	Year Superstructure Installed:	1990	Structure Type/Class:	Temporary Bridge
KM:	40.56	User km:	40.20	Last Inspection Date:	2022/08/11
Project File ID #:	0771	Br.	01	Next Inspection Date:	2023/08/11
Road Name:	SCOTCH CREEK				
Crossing Name:	Scotch Cr #4	Total Length (metres):	18.3		
Special Access:		Special Equipment:			
Longitude:	-119 11 6.6	Latitude:	51 9 8.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Feb23.2013 Monitor old crib for failure. The crib supports foundation fill.				

Structure Name: K868

Site #:	K868	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	46.21	User km:	12.00	Last Inspection Date:	2020/10/09
Project File ID #:	0771	Br.	01	Next Inspection Date:	2023/10/09
Road Name:	SCOTCH CREEK				
Crossing Name:	Unnamed	Total Length (metres):	8.6		
Special Access:		Special Equipment:			
Longitude:	-119 8 44.4	Latitude:	51 11 13.7		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 12-JAN-21: . IDIR\PBLUESCH on 12-JAN-21: .				

Structure Name: K957A

Site #:	K957	Year Superstructure Installed:	2008	Structure Type/Class:	Major Culvert
KM:	0.07	User km:	35.50	Last Inspection Date:	2022/08/11
Project File ID #:	0771	Br.	02	Next Inspection Date:	2023/08/11
Road Name:	SCOTCH-KWIKWOIT				
Crossing Name:	Kwikoit CMP	Total Length (metres):	14.0		
Special Access:		Special Equipment:			
Longitude:	-119 24 36.6	Latitude:	51 10 31.7		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\PBLUESCH on 31-JAN-18: PB Jan31.2018 Continue to monitor footing scour. CBR_Conversion on 17-FEB-14: Confirm asbuilt data and enter missing data				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 16 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K233

Site #:	K233	Year Superstructure Installed:	1989	Structure Type/Class:	Permanent Bridge
KM:	10.84	User km:	24.90	Last Inspection Date:	2020/10/03
Project File ID #:	0771	Br.	02	Next Inspection Date:	2023/10/03
Road Name:	SCOTCH-KWIKWOIT				
Crossing Name:	Kwikoit #2		Total Length (metres):	19.4	
Special Access:			Special Equipment:		
Longitude:	-119 26 35.1		Latitude:	51 6 29.9	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Feb 22/11. Inspect timber sills and rip rap.				

Structure Name: K951

Site #:	K951	Year Superstructure Installed:	1982	Structure Type/Class:	Major Culvert
KM:	19.67	User km:	32.50	Last Inspection Date:	2022/08/11
Project File ID #:	0771	Br.	02	Next Inspection Date:	2023/08/11
Road Name:	SCOTCH-KWIKWOIT				
Crossing Name:	Unnamed		Total Length (metres):	0.0	
Special Access:			Special Equipment:		
Longitude:	-119 25 19.8		Latitude:	51 9 30.0	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	CBR_Conversion on 08-FEB-23: .				

Structure Name: K237

Site #:	K237	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	1.35	User km:	1.50	Last Inspection Date:	2020/10/03
Project File ID #:	0771	Br.	05	Next Inspection Date:	2023/10/03
Road Name:	SCOTCH-ONYX				
Crossing Name:	Onyx #2		Total Length (metres):	8.6	
Special Access:			Special Equipment:		
Longitude:	-119 18 51.0		Latitude:	51 0 0.6	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 17 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K275

Site #:	K275	Year Superstructure Installed:	1992	Structure Type/Class:	Temporary Bridge
KM:	2.55	User km:	0.60	Last Inspection Date:	2021/08/24
Project File ID #:	0771	Br.	05	Next Inspection Date:	2023/08/24
Road Name:	SCOTCH-ONYX				
Crossing Name:	Onyx #1	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-119 19 5.0	Latitude:	50 59 49.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: K294

Site #:	K294	Year Superstructure Installed:	1991	Structure Type/Class:	Permanent Bridge
KM:	0.48	User km:	12.20	Last Inspection Date:	2022/08/11
Project File ID #:	0771	Br.	06	Next Inspection Date:	2023/08/11
Road Name:	SCOTCH-SOUTH				
Crossing Name:	Scotch Cr #1	Total Length (metres):	19.7		
Special Access:		Special Equipment:			
Longitude:	-119 27 0.0	Latitude:	51 1 15.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Cast in Place	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 16-JAN-19: PB Jan31.2018 Monitor cast-in-place abutments for scour. Measure horizontal extent of scour annually.				

Structure Name: K1014

Site #:	K1014	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	1.03	User km:	41.50	Last Inspection Date:	2022/08/09
Project File ID #:	0839	Br.	08	Next Inspection Date:	2023/08/09
Road Name:	SECOND CREEK				
Crossing Name:	Second Cr	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-118 47 15.6	Latitude:	51 8 33.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 27-FEB-20: PB Jan31.2018 Deck slabs require concrete repair where rebar is exposed. Re-inspect concrete deck damage and cap beam in 2020. CBR_Conversion on 17-FEB-14: PB Jan 29,2014 Monitor tension cracks in slabs. Not assessed in 2013. Re-inspect in 2014.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 18 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1015

Site #:	K1015	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	2.30	User km:	43.50	Last Inspection Date:	2022/08/09
Project File ID #:	0839	Br.	08	Next Inspection Date:	2023/08/09
Road Name:	SECOND CREEK				
Crossing Name:	Second Cr	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-118 46 17.4	Latitude:	51 7 49.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 16-MAR-15: PB Jan 24,2013 Monitor settlement of lock block footings and measure vertical displacement from skid plate.				

Structure Name: K283

Site #:	K283	Year Superstructure Installed:	1989	Structure Type/Class:	Permanent Bridge
KM:	11.43	User km:	11.30	Last Inspection Date:	2022/08/10
Project File ID #:	7271	Br.	01	Next Inspection Date:	2023/08/10
Road Name:	SEYMOUR RIVER				
Crossing Name:	Ratchford	Total Length (metres):	30.3		
Special Access:		Special Equipment:	Peeper Truck		
Longitude:	-118 54 4.2	Latitude:	51 18 39.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast/Pile -	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 16-JAN-19: PB Jan16.2019 Closely inspect fill supporting bearing locations at left bank abutment. CBR_Conversion on 17-FEB-14: March 15,2012. Have a close look at low chain footing stability as noted below and photographed/measured extensively in 2009 by Ron Peace. May 13/09 GMc take photographs of the fill in front of the U/S LC footings to monitor for any ravelling				

Structure Name: PS-053

Site #:	K764	Year Superstructure Installed:	1993	Structure Type/Class:	Permanent Bridge
KM:	28.93	User km:	37.40	Last Inspection Date:	2022/08/10
Project File ID #:	7271	Br.	01	Next Inspection Date:	2023/08/10
Road Name:	SEYMOUR RIVER				
Crossing Name:	Seymour #2	Total Length (metres):	20.0		
Special Access:		Special Equipment:			
Longitude:	-118 52 41.8	Latitude:	51 26 32.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 22-FEB-19: One year post installation inspection				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 19 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K730

Site #:	K730	Year Superstructure Installed:	1990	Structure Type/Class:	Permanent Bridge
KM:	43.01	User km:	51.50	Last Inspection Date:	2022/08/10
Project File ID #:	7271	Br.	01	Next Inspection Date:	2023/08/10
Road Name:	SEYMOUR RIVER				
Crossing Name:	Canyon Cr	Total Length (metres):	17.2		
Special Access:	ATV	Special Equipment:			
Longitude:	-118 54 21.0	Latitude:	51 33 36.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Other	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 31-JAN-18: PB Jan 30, 2014 Confirm access (if any) with District or Engineering Branch prior to mobilizing to site; road is brushed in. Quad required. Pick up girder as built info in 2013.				

Structure Name: K740

Site #:	K740	Year Superstructure Installed:	1998	Structure Type/Class:	Temporary Bridge
KM:	1.95	User km:	26.10	Last Inspection Date:	2022/08/09
Project File ID #:	7271	Br.	03	Next Inspection Date:	2023/08/09
Road Name:	SEYMOUR WEST				
Crossing Name:	Unnamed	Total Length (metres):	8.0		
Special Access:	Helicopter	Special Equipment:			
Longitude:	-118 54 22.9	Latitude:	51 25 22.3		
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Jan 30, 2014 Bridge across the Seymour River has been pulled. Confirm access (if any) with District or Engineering Branch prior to mobilizing to site; alternate access from Smokey House pending. Quad may be required. PB Feb06,2012 Ensure posted to 5 tonnes in 2012; Structure scheduled to be removed in 2012 (check with district on status). GMC Oct 13/09Post to 5 Tonnes in 2010. ATV may be required for access				

Structure Name: K1134A

Site #:	K1134	Year Superstructure Installed:	2019	Structure Type/Class:	Temporary Bridge
KM:	5.52	User km:	5.50	Last Inspection Date:	2021/08/21
Project File ID #:	7271	Br.	08	Next Inspection Date:	2023/08/21
Road Name:	SMOKEYHOUSE				
Crossing Name:	Unnamed	Total Length (metres):	9.1		
Special Access:		Special Equipment:			
Longitude:	-118 56 27.5	Latitude:	51 23 11.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 28-NOV-19: One year post installation inspection.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 20 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1238

Site #:	K1238	Year Superstructure Installed:		1999	Structure Type/Class:	Major Culvert	
KM:	5.56	User km:	5.51	Last Inspection Date:		2022/08/09	
Project File ID #:	7271	Br.	08	Next Inspection Date:		2023/08/09	
Road Name:		SMOKEYHOUSE					
Crossing Name:		Unnamed		Total Length (metres):		8.4	
Special Access:				Special Equipment:			
Longitude:		-118 56 25.2		Latitude:		51 23 12.4	
Superstructure:				Abutments (Left/Right): <i>(looking downstream)</i>		# Spans: 0	
Planned Inspection Comments:		IDIR\BPellett on 09-MAY-23: BP May 8-23 Inspector to measure fill depths and culvert length, gradient, span & rise, wall thickness, and corrugation profile in 2023 routine inspection.					

Structure Name: K1308

Site #:	K1308	Year Superstructure Installed:	2004	Structure Type/Class:	Permanent Bridge
KM:	0.00	User km:	3.00	Last Inspection Date:	2020/06/30
Project File ID #:	4123	Br.	06	Next Inspection Date:	2023/06/30
Road Name:	SPA CREEK				
Crossing Name:	Spa Cr		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-119 24 30.0		Latitude:	50 33 3.6	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: K760

Site #:	K760	Year Superstructure Installed:	1986	Structure Type/Class:	Permanent Bridge
KM:	0.14	User km:	11.70	Last Inspection Date:	2020/09/25
Project File ID #:	0835	Br.	01	Next Inspection Date:	2023/09/25
Road Name:	THREE VALLEY-MABEL				
Crossing Name:	Kingfisher Cr		Total Length (metres):	14.4	
Special Access:			Special Equipment:		
Longitude:	-118 44 57.2		Latitude:	50 41 50.2	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:	IDIR\BPBLUESCH on 01-FEB-18: PB Feb 01.2018 Timber crossies are showing obvious signs of rot. Annual inspection. Closely inspect and assess tie condition and performance. Drill ties for rot. CBR_Conversion on 17-FEB-14: PB Feb23/11 Needs number plate. Confirm GPS coordinates.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 21 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K242A

Site #:	K242	Year Superstructure Installed:	2013	Structure Type/Class:	Permanent Bridge
KM:	19.58	User km:	19.10	Last Inspection Date:	2020/09/25
Project File ID #:	0835	Br.	01	Next Inspection Date:	2023/09/25
Road Name:	THREE VALLEY-MABEL				
Crossing Name:	Danforth Cr	Total Length (metres):	15.6		
Special Access:		Special Equipment:			
Longitude:	-118 41 14.3	Latitude:	50 44 38.6		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K243

Site #:	K243	Year Superstructure Installed:	1989	Structure Type/Class:	Permanent Bridge
KM:	24.72	User km:	24.10	Last Inspection Date:	2022/07/06
Project File ID #:	0835	Br.	01	Next Inspection Date:	2023/07/06
Road Name:	THREE VALLEY-MABEL				
Crossing Name:	Hatt Cr	Total Length (metres):	12.0		
Special Access:		Special Equipment:			
Longitude:	-118 39 56.8	Latitude:	50 46 13.4		
Superstructure:	Concrete Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 17-JAN-19: PB Jan17.2019 Assess closely for scour at abutments.				

Structure Name: K771

Site #:	K771	Year Superstructure Installed:	1986	Structure Type/Class:	Major Culvert
KM:	34.43	User km:	34.00	Last Inspection Date:	2022/07/06
Project File ID #:	0835	Br.	01	Next Inspection Date:	2023/07/06
Road Name:	THREE VALLEY-MABEL				
Crossing Name:	Struthers	Total Length (metres):	9.5		
Special Access:		Special Equipment:			
Longitude:	-118 35 30.6	Latitude:	50 47 25.2		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 22 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1076

Site #:	K1076	Year Superstructure Installed:	2001	Structure Type/Class:	Temporary Bridge
KM:	51.55	User km:	4.50	Last Inspection Date:	2022/07/06
Project File ID #:	0835	Br.	01	Next Inspection Date:	2023/07/06
Road Name:	THREE VALLEY-MABEL				
Crossing Name:	East Fork Wap		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-118 29 11.4		Latitude:	50 53 42.0	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans: 1
Planned Inspection Comments:	IDIR\PBLUESCH on 26-JAN-16: PB Jan26,2016 Assess bearing of girders which are cantilevered on old crib; currently the girders are resting on untreated log sills.				

Structure Name: K249

Site #:	K249	Year Superstructure Installed:	1991	Structure Type/Class:	Temporary Bridge
KM:	54.69	User km:	1.60	Last Inspection Date:	2021/07/16
Project File ID #:	0835	Br.	01	Next Inspection Date:	2023/07/16
Road Name:	THREE VALLEY-MABEL				
Crossing Name:	South Pass #2		Total Length (metres):	22.0	
Special Access:			Special Equipment:		
Longitude:	-118 28 47.4		Latitude:	50 55 7.2	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 20-FEB-14: PB Feb23,2013 Inspect bearing and precast footing condition.Check for interference b/w girders and old crib logs.				

Structure Name: K1417

Site #:	K1417	Year Superstructure Installed:	1990	Structure Type/Class:	Permanent Bridge
KM:	0.00	User km:	8.50	Last Inspection Date:	2022/07/06
Project File ID #:	0835	Br.	06	Next Inspection Date:	2023/07/06
Road Name:	VICTOR				
Crossing Name:	Unnamed		Total Length (metres):	10.4	
Special Access:			Special Equipment:		
Longitude:	-118 25 56.0		Latitude:	50 54 7.9	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:	IDIR\PBLUESCH on 09-MAR-15: PB Mar 09,2015 Assess treated timber sill condition and cross-time dimensions in 2015. Cross-ties may be undersized.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 23 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1163

Site #:	K1163	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	4.02	User km:	4.80	Last Inspection Date:	2022/07/06
Project File ID #:	0835	Br.	06	Next Inspection Date:	2023/07/06
Road Name:	VICTOR				
Crossing Name:	Unnamed		Total Length (metres):	17.8	
Special Access:			Special Equipment:		
Longitude:	-118 26 45.0		Latitude:	50 52 43.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Feb22.2013 The outside corner of the flared deck (roadway end) is supported on a beam extending out from the main bridge beams. The outside end is supported by a small timber block. That block should be checked for rot prior to industrial hall. If it is rotten it should be replaced by a permanent concrete or steel block				

Structure Name: K369

Site #:	K369	Year Superstructure Installed:	1993	Structure Type/Class:	Permanent Bridge
KM:	125.96	User km:	125.80	Last Inspection Date:	2022/07/01
Project File ID #:	7654	Br.	01	Next Inspection Date:	2023/07/01
Road Name:	201				
Crossing Name:	Haggart Cr		Total Length (metres):	11.0	
Special Access:			Special Equipment:		
Longitude:	-118 42 21.6		Latitude:	49 53 59.3	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 10-FEB-20: JRG Feb 10, 2020 Monitor abutment scour. Measure depth and extent of scour at each inspection.				

Structure Name: K370

Site #:	K370	Year Superstructure Installed:	1986	Structure Type/Class:	Temporary Bridge
KM:	130.58	User km:	130.40	Last Inspection Date:	2022/07/01
Project File ID #:	7654	Br.	01	Next Inspection Date:	2023/07/01
Road Name:	201				
Crossing Name:	Kettle R		Total Length (metres):	18.9	
Special Access:			Special Equipment:		
Longitude:	-118 41 32.5		Latitude:	49 56 18.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 24 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1562

Site #:	K1562	Year Superstructure Installed:	2010	Structure Type/Class:	Permanent Bridge
KM:	23.00	User km:	23.00	Last Inspection Date:	2020/08/12
Project File ID #:	4038	Br.	01	Next Inspection Date:	2023/08/12
Road Name:	ABERDEEN				
Crossing Name:	Unnamed		Total Length (metres):	9.1	
Special Access:			Special Equipment:		
Longitude:	-119 5 19.8		Latitude:	50 5 4.6	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB June 6,2013 Structure is short for the site. Installed in 2010. Monitor rip rap stability and footings for scour.				

Structure Name: K1634

Site #:	K1634	Year Superstructure Installed:		Structure Type/Class:	Woodbox/Log Culvert
KM:	0.30	User km:	27.00	Last Inspection Date:	2022/07/09
Project File ID #:	4038	Br.	11	Next Inspection Date:	2023/07/09
Road Name:	B2				
Crossing Name:	Heart Cr Trib		Total Length (metres):	5.0	
Special Access:			Special Equipment:		
Longitude:	-119 1 16.2		Latitude:	50 5 27.4	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\PBLUESCH on 12-MAR-15: PB Mar12,2015 Ensure posted to 5 tonnes.				

Structure Name: K1178

Site #:	K1178	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	24.28	User km:	3.40	Last Inspection Date:	2020/09/24
Project File ID #:	7217	Br.	01	Next Inspection Date:	2023/09/24
Road Name:	BAKER				
Crossing Name:	Vlem Cr		Total Length (metres):	9.6	
Special Access:			Special Equipment:		
Longitude:	-119 0 12.0		Latitude:	50 26 53.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 25 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1177

Site #:	K1177	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	0.63	User km:	0.60	Last Inspection Date:	2022/07/06
Project File ID #:	7217	Br.	02	Next Inspection Date:	2023/07/06
Road Name:	BAKER-VLEM				
Crossing Name:	Vlem Cr	Total Length (metres):	6.7		
Special Access:		Special Equipment:			
Longitude:	-118 58 44.0	Latitude:	50 27 0.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 04-JAN-16: PB Jan04,2016 Monitor downstream right footing. It has become exposed. Inspect for any scour or undermining. IDIR\PBLUESCH on 10-FEB-15: PB Feb10,2015 Monitor failing rip rap armouring.				

Structure Name: K1744

Site #:	K1744	Year Superstructure Installed:		Structure Type/Class:	Permanent Bridge
KM:	85.20	User km:	85.20	Last Inspection Date:	2022/07/01
Project File ID #:	10924	Br.	07	Next Inspection Date:	2023/07/01
Road Name:	BANTING CREEK				
Crossing Name:	Banting Creek	Total Length (metres):	9.0		
Special Access:		Special Equipment:			
Longitude:	-118 21 12.9	Latitude:	50 0 11.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\BPelletT on 16-MAY-23: BP May 16-23 [PIC completed in 2022] IDIR\MRFENNEL on 10-FEB-20: JRG Feb 10, 2020 Measure depth and extent of scour under right abutment lock blocks at every inspection.				

Structure Name: K347

Site #:	K347	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	0.55	User km:	3.50	Last Inspection Date:	2020/08/09
Project File ID #:	7657	Br.	02	Next Inspection Date:	2023/08/09
Road Name:	BARDOLPH				
Crossing Name:	Coldstream Cr	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-119 5 8.9	Latitude:	50 16 13.8		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Jan25.2012. Inspect underside of slab #8 for rust and loss of section.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 26 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1073

Site #:	K1073	Year Superstructure Installed:		1999	Structure Type/Class:	Major Culvert	
KM:	0.82	User km:	18.50	Last Inspection Date:		2022/07/07	
Project File ID #:	1030	Br.	12	Next Inspection Date:		2023/07/07	
Road Name:		BELFIELD					
Crossing Name:		Unnamed		Total Length (metres):		23.0	
Special Access:				Special Equipment:			
Longitude:		-118 35 54.5		Latitude:		50 24 42.2	
Superstructure:				Abutments (Left/Right): <i>(looking downstream)</i>		# Spans: 0	
Planned Inspection Comments:		IDIR\BPellett on 09-MAY-23: BP May 9-23 Inspector to measure fill depths and culvert length, gradient, span & rise, wall thickness, and corrugation profile in 2023 routine inspection.					

Structure Name: K368

Site #:	K368	Year Superstructure Installed:	1993	Structure Type/Class:	Permanent Bridge
KM:	0.39	User km:	29.80	Last Inspection Date:	2022/07/06
Project File ID #:	8400	Br.	02	Next Inspection Date:	2023/07/06
Road Name:	BOBBIE BURNS-SOWSAP				
Crossing Name:	Sowsap Cr		Total Length (metres):	9.0	
Special Access:			Special Equipment:		
Longitude:	-118 50 27.4		Latitude:	50 27 26.1	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\BLUESCH on 10-FEB-20: . IDIR\JRUPAR on 16-JAN-19: JRG Jan 16, 2019 Monitor left bank downstream footing for scour.				

Structure Name: K1571

Site #:	K1571	Year Superstructure Installed:		Structure Type/Class:	Permanent Bridge
KM:	4.30	User km:	19.00	Last Inspection Date:	2020/08/10
Project File ID #:	8215	Br.	09	Next Inspection Date:	2023/08/10
Road Name:	BOLTON				
Crossing Name:	Cherry Creek		Total Length (metres):	12.4	
Special Access:			Special Equipment:		
Longitude:	-118 19 11.9		Latitude:	50 18 18.2	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 19-JAN-18: .				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 27 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K320A

Site #:	K320	Year Superstructure Installed:	2013	Structure Type/Class:	Permanent Bridge
KM:	1.38	User km:	1.30	Last Inspection Date:	2020/08/09
Project File ID #:	8214	Br.	01	Next Inspection Date:	2023/08/09
Road Name:	CURRIE CREEK				
Crossing Name:	Cherry Cr	Total Length (metres):	24.4		
Special Access:		Special Equipment:			
Longitude:	-118 29 51.9	Latitude:	50 14 49.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: 935A

Site #:	K935	Year Superstructure Installed:	2010	Structure Type/Class:	Permanent Bridge
KM:	6.97	User km:	24.10	Last Inspection Date:	2020/08/12
Project File ID #:	4038	Br.	10	Next Inspection Date:	2023/08/12
Road Name:	CURTIS LAKE				
Crossing Name:	Curtis Cr	Total Length (metres):	9.0		
Special Access:		Special Equipment:			
Longitude:	-119 1 51.0	Latitude:	50 6 32.4		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1561

Site #:	K1561	Year Superstructure Installed:	2005	Structure Type/Class:	Temporary Bridge
KM:	2.52	User km:		Last Inspection Date:	2022/07/08
Project File ID #:	1031	Br.	23	Next Inspection Date:	2023/07/08
Road Name:	DUSTIN				
Crossing Name:	Trib. to Harris Creek	Total Length (metres):	2.1		
Special Access:		Special Equipment:			
Longitude:	-118 52 4.5	Latitude:	50 7 54.0		
Superstructure:	Other	Abutments (Left/Right): (looking downstream)	Other	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 16-JAN-19: JRG Jan 16, 2019 Measure up extent of scour and monitor during future inspections.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 28 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K363 OS

Site #:	K363	Year Superstructure Installed:	2022	Structure Type/Class:	Temporary Bridge
KM:	0.11	User km:	8.90	Last Inspection Date:	2022/07/02
Project File ID #:	8216	Br.	01	Next Inspection Date:	2023/07/02
Road Name:	FERRY CREEK				
Crossing Name:	Ferry Cr	Total Length (metres):	18.3		
Special Access:		Special Equipment:			
Longitude:	-118 40 16.8	Latitude:	50 8 18.0		
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: K363

Site #:	K363	Year Superstructure Installed:	1987	Structure Type/Class:	Temporary Bridge
KM:	0.11	User km:	8.90	Last Inspection Date:	2021/08/18
Project File ID #:	8216	Br.	01	Next Inspection Date:	2022/08/18
Road Name:	FERRY CREEK				
Crossing Name:	Ferry Cr	Total Length (metres):	13.0		
Special Access:		Special Equipment:			
Longitude:	-118 40 16.8	Latitude:	50 8 18.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 11-FEB-20: JRG Feb 11, 2020 Ensure closed signs are posted and road is barricaded. IDIR\PBLUESCH on 21-JAN-16: PB Jan21.2016 Assess cross ties and log crib abutments for continued deterioration.				

Structure Name: K1555A

Site #:	K1555	Year Superstructure Installed:	2016	Structure Type/Class:	Major Culvert
KM:	20.60	User km:		Last Inspection Date:	2022/07/08
Project File ID #:	4038	Br.	07	Next Inspection Date:	2023/07/08
Road Name:	GOAT				
Crossing Name:	McAuley Creek	Total Length (metres):	14.0		
Special Access:		Special Equipment:			
Longitude:	-118 55 15.3	Latitude:	50 5 23.2		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\JRUPAR on 11-FEB-20: JRG Feb 11, 2020 Record gap at coupler during every inspection.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 29 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: WO 2733

Site #:	K1660	Year Superstructure Installed:	2016	Structure Type/Class:	Permanent Bridge
KM:	3.10	User km:	30.60	Last Inspection Date:	2020/08/11
Project File ID #:	1031	Br.	35	Next Inspection Date:	2023/08/11
Road Name:	H300				
Crossing Name:	Unknown		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-118 48 16.2		Latitude:	50 6 14.8	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\MRFENNEL on 14-NOV-16: One year post installation inspection				

Structure Name: K1664

Site #:	K1664	Year Superstructure Installed:	2016	Structure Type/Class:	Temporary Bridge
KM:	4.80	User km:	4.80	Last Inspection Date:	2021/08/20
Project File ID #:	1031	Br.	35	Next Inspection Date:	2023/08/20
Road Name:	H300				
Crossing Name:	Harris Creek		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-118 49 5.0		Latitude:	50 5 48.0	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans: 1
Planned Inspection Comments:	IDIR\MRFENNEL on 27-APR-22: BP Apr 27-22 Inspector to search thoroughly for fabricator markings and photograph any found IDIR\PBLUESCH on 13-DEC-16: PB Dec13.2016 Confirm crossing is posted 15 km/hr.				

Structure Name: TOC0015

Site #:	K1675	Year Superstructure Installed:	2016	Structure Type/Class:	Temporary Bridge
KM:	5.20	User km:	5.20	Last Inspection Date:	2021/08/20
Project File ID #:	1031	Br.	35	Next Inspection Date:	2023/08/20
Road Name:	H300				
Crossing Name:	Unnamed		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-118 49 20.0		Latitude:	50 5 53.0	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans: 1
Planned Inspection Comments:	IDIR\MRFENNEL on 12-FEB-20: .				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 30 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1537

Site #:	K1537	Year Superstructure Installed:	2000	Structure Type/Class:	Temporary Bridge
KM:	1.26	User km:	80.80	Last Inspection Date:	2021/09/15
Project File ID #:	8435	Br.	20	Next Inspection Date:	2023/09/15
Road Name:	HAGGART WEST				
Crossing Name:	Unnamed		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-118 46 24.1		Latitude:	49 55 45.5	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 05-JAN-16: .				

Structure Name: K1489

Site #:	K1489	Year Superstructure Installed:	2008	Structure Type/Class:	Woodbox/Log Culvert
KM:	25.00	User km:	25.00	Last Inspection Date:	2022/07/08
Project File ID #:	4038	Br.	15	Next Inspection Date:	2023/07/08
Road Name:	HEART				
Crossing Name:	Unnamed		Total Length (metres):	5.0	
Special Access:			Special Equipment:		
Longitude:	-118 58 48.0		Latitude:	50 7 34.0	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	CBR_Conversion on 17-JAN-19: JRG Jan 17, 2019 Ensure posted for 20 tonnes.				

Structure Name: K1490

Site #:	K1490	Year Superstructure Installed:		Structure Type/Class:	Woodbox/Log Culvert
KM:	28.00	User km:	28.00	Last Inspection Date:	2022/07/08
Project File ID #:	4038	Br.	15	Next Inspection Date:	2023/07/08
Road Name:	HEART				
Crossing Name:	Unnamed		Total Length (metres):	5.0	
Special Access:			Special Equipment:		
Longitude:	-118 59 49.0		Latitude:	50 6 58.0	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	IDIR\JRUPAR on 17-JAN-19: JRG Jan 17, 2019 Ensure bridge is posted for 20 tonnes. IDIR\PBLUESCH on 16-FEB-15: PB Feb16.2015 Collect all stringer data for load rating. CBR_Conversion on 17-FEB-14: Gmc Apr 29/09 New to register, structure scheduled to be replaced. collect asbuilt data at inspection.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 31 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K361

Site #:	K361	Year Superstructure Installed:	1989	Structure Type/Class:	Temporary Bridge
KM:	2.67	User km:	9.70	Last Inspection Date:	2022/07/02
Project File ID #:	1108	Br.	01	Next Inspection Date:	2023/07/02
Road Name:	HECKMAN-CREEK				
Crossing Name:	Heckman Cr	Total Length (metres):	5.9		
Special Access:		Special Equipment:			
Longitude:	-118 37 3.4	Latitude:	50 7 35.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 19-JAN-21: JRG Jan 19, 2021 Close the bridge if the curbs are not replaced.				

Structure Name: K1614

Site #:	K1614	Year Superstructure Installed:	2014	Structure Type/Class:	Temporary Bridge
KM:	1.30	User km:	1.30	Last Inspection Date:	2021/08/17
Project File ID #:	4038	Br.	21	Next Inspection Date:	2023/08/17
Road Name:	HILDA				
Crossing Name:	Unknown	Total Length (metres):	6.0		
Special Access:		Special Equipment:			
Longitude:	-119 3 37.0	Latitude:	50 1 29.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 07-JAN-16: .				

Structure Name: K884

Site #:	K884	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	0.89	User km:	53.60	Last Inspection Date:	2020/08/17
Project File ID #:	8435	Br.	02	Next Inspection Date:	2023/08/17
Road Name:	K10				
Crossing Name:	McIntyre Cr	Total Length (metres):	17.0		
Special Access:		Special Equipment:			
Longitude:	-118 33 21.2	Latitude:	50 2 10.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 32 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K885

Site #:	K885	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	0.93	User km:	53.70	Last Inspection Date:	2020/08/17
Project File ID #:	8435	Br.	02	Next Inspection Date:	2023/08/17
Road Name:	K10				
Crossing Name:	Kettle R		Total Length (metres):	27.4	
Special Access:			Special Equipment:		
Longitude:	-118 33 20.3		Latitude:	50 2 9.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K886

Site #:	K886	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	1.47	User km:	54.30	Last Inspection Date:	2020/08/17
Project File ID #:	8435	Br.	02	Next Inspection Date:	2023/08/17
Road Name:	K10				
Crossing Name:	Strutell Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-118 33 26.4		Latitude:	50 1 52.8	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K375

Site #:	K375	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	20.04	User km:	62.10	Last Inspection Date:	2020/08/17
Project File ID #:	8435	Br.	05	Next Inspection Date:	2023/08/17
Road Name:	K50				
Crossing Name:	Kettle R		Total Length (metres):	22.0	
Special Access:			Special Equipment:		
Longitude:	-118 38 2.1		Latitude:	49 58 49.3	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 16-FEB-15: PB Feb16.2015 pick up fabricator identifiers (Rapid span WO#)next inspection				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 33 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K301

Site #:	K301	Year Superstructure Installed:	2008	Structure Type/Class:	Permanent Bridge
KM:	20.47	User km:	1.90	Last Inspection Date:	2020/08/10
Project File ID #:	0951	Br.	01	Next Inspection Date:	2023/08/10
Road Name:	KATE CREEK				
Crossing Name:	Outlet Cr	Total Length (metres):	13.0		
Special Access:		Special Equipment:			
Longitude:	-118 30 59.3	Latitude:	50 20 54.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Jan 13/12 Monitor for scour and take photos of rip rap				

Structure Name: K331

Site #:	K331	Year Superstructure Installed:	1989	Structure Type/Class:	Permanent Bridge
KM:	10.37	User km:	10.30	Last Inspection Date:	2020/08/17
Project File ID #:	0335	Br.	01	Next Inspection Date:	2023/08/17
Road Name:	KEEFER LAKE				
Crossing Name:	Kettle R	Total Length (metres):	17.3		
Special Access:		Special Equipment:			
Longitude:	-118 24 26.4	Latitude:	50 7 16.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					

Structure Name: K332

Site #:	K332	Year Superstructure Installed:	1989	Structure Type/Class:	Permanent Bridge
KM:	14.01	User km:	13.40	Last Inspection Date:	2020/08/17
Project File ID #:	0335	Br.	01	Next Inspection Date:	2023/08/01
Road Name:	KEEFER LAKE				
Crossing Name:	Kettle R	Total Length (metres):	14.3		
Special Access:		Special Equipment:			
Longitude:	-118 21 45.1	Latitude:	50 7 48.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 22-JAN-21: .				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 34 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K372

Site #:	K372	Year Superstructure Installed:	1963	Structure Type/Class:	Temporary Bridge
KM:	14.98	User km:	66.90	Last Inspection Date:	2021/09/15
Project File ID #:	8435	Br.	01	Next Inspection Date:	2023/09/15
Road Name:	KETTLE RIVER				
Crossing Name:	Kettle R	Total Length (metres):	18.5		
Special Access:		Special Equipment:			
Longitude:	-118 40 41.7	Latitude:	49 57 14.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile - Temporary Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: K373

Site #:	K373	Year Superstructure Installed:	2002	Structure Type/Class:	Temporary Bridge
KM:	15.24	User km:	66.40	Last Inspection Date:	2021/09/15
Project File ID #:	8435	Br.	01	Next Inspection Date:	2023/09/15
Road Name:	KETTLE RIVER				
Crossing Name:	Bruer Cr	Total Length (metres):	11.0		
Special Access:		Special Equipment:			
Longitude:	-118 40 38.1	Latitude:	49 57 24.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile - Temporary Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: K313

Site #:	K313	Year Superstructure Installed:	1986	Structure Type/Class:	Temporary Bridge
KM:	0.03	User km:	58.80	Last Inspection Date:	2021/07/16
Project File ID #:	1111	Br.	01	Next Inspection Date:	2023/07/16
Road Name:	MABLE LAKE				
Crossing Name:	Wap R	Total Length (metres):	16.3		
Special Access:		Special Equipment:			
Longitude:	-118 34 6.6	Latitude:	50 48 11.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile - Temporary Materials	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 12-FEB-20: JRG Feb 12, 2020 Monitor pile decay. Professional inspection Jun 16, 2019 identified 30 mm sap rot in RB pile 4 and 35 mm sap rot in LB pile 3.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 35 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1017

Site #:	K1017	Year Superstructure Installed:	1995	Structure Type/Class:	Major Culvert
KM:	8.45	User km:	53.00	Last Inspection Date:	2020/09/25
Project File ID #:	1111	Br.	01	Next Inspection Date:	2023/09/25
Road Name:	MABLE LAKE				
Crossing Name:	Dale Cr		Total Length (metres):	14.3	
Special Access:			Special Equipment:		
Longitude:	-118 34 6.0		Latitude:	50 45 26.3	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	CBR_Conversion on 08-DEC-20: JRG Dec 8, 2020 Confirm coordinates and inlet and outlet cover during next inspection.				

Structure Name: K1109

Site #:	K1109	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	33.46	User km:	17.20	Last Inspection Date:	2020/09/25
Project File ID #:	1111	Br.	01	Next Inspection Date:	2023/09/25
Road Name:	MABLE LAKE				
Crossing Name:	Appelles Cr		Total Length (metres):	9.6	
Special Access:			Special Equipment:		
Longitude:	-118 43 8.5		Latitude:	50 31 6.3	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 19-JAN-21: .				

Structure Name: K309

Site #:	K309	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	37.92	User km:	21.90	Last Inspection Date:	2022/07/07
Project File ID #:	1111	Br.	01	Next Inspection Date:	2023/07/07
Road Name:	MABLE LAKE				
Crossing Name:	Torrent Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-118 43 2.4		Latitude:	50 33 31.2	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Jan 13,2012. Inspect flanges for section loss.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 36 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K308A

Site #:	K308	Year Superstructure Installed:	2013	Structure Type/Class:	Permanent Bridge
KM:	40.83	User km:	19.00	Last Inspection Date:	2020/09/25
Project File ID #:	1111	Br.	01	Next Inspection Date:	2023/09/25
Road Name:	MABLE LAKE				
Crossing Name:	Smythe Cr		Total Length (metres):	24.4	
Special Access:			Special Equipment:		
Longitude:	-118 43 9.0		Latitude:	50 32 1.2	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-15: .				

Structure Name: K781

Site #:	K781	Year Superstructure Installed:	1991	Structure Type/Class:	Permanent Bridge
KM:	49.61	User km:	10.40	Last Inspection Date:	2022/07/07
Project File ID #:	1111	Br.	01	Next Inspection Date:	2023/07/07
Road Name:	MABLE LAKE				
Crossing Name:	Latewhos Cr		Total Length (metres):	14.0	
Special Access:			Special Equipment:		
Longitude:	-118 43 18.0		Latitude:	50 27 42.6	
Superstructure:	Concrete Box Beam		Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 13-FEB-20: .				

Structure Name: K1016

Site #:	K1016	Year Superstructure Installed:	1996	Structure Type/Class:	Temporary Bridge
KM:	0.19	User km:	49.30	Last Inspection Date:	2022/07/07
Project File ID #:	1111	Br.	05	Next Inspection Date:	2023/07/07
Road Name:	MABLE-COTTON				
Crossing Name:	Tsuius Cr		Total Length (metres):	12.1	
Special Access:	ATV		Special Equipment:		
Longitude:	-118 29 43.9		Latitude:	50 41 44.2	
Superstructure:	Log Stringers		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 18-JAN-19: JRG Jan 18, 2019 Access on foot. Monitor deterioration of timber components and notify when bridge closure required. Ensure posted for 5 tonnes.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 37 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K348

Site #:	K348	Year Superstructure Installed:	1990	Structure Type/Class:	Temporary Bridge
KM:	14.30	User km:	44.30	Last Inspection Date:	2022/07/07
Project File ID #:	1111	Br.	05	Next Inspection Date:	2023/07/07
Road Name:	MABLE-COTTON				
Crossing Name:	Ohashi Cr		Total Length (metres):	9.0	
Special Access:	ATV		Special Equipment:		
Longitude:	-118 31 47.7		Latitude:	50 39 32.2	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 13-FEB-20: JRG Feb 13, 2020 Only accessible on foot.				

Structure Name: K317

Site #:	K317	Year Superstructure Installed:	1996	Structure Type/Class:	Temporary Bridge
KM:	14.80	User km:	44.80	Last Inspection Date:	2022/07/07
Project File ID #:	1111	Br.	05	Next Inspection Date:	2023/07/07
Road Name:	MABLE-COTTON				
Crossing Name:	Tsuius Cr		Total Length (metres):	11.2	
Special Access:	ATV		Special Equipment:		
Longitude:	-118 31 21.7		Latitude:	50 39 49.4	
Superstructure:	Log Stringers		Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans: 1
Planned Inspection Comments:	IDIR\JRUPAR on 21-JAN-19: JRG Jan 21, 2019 Only accessible on foot. IDIR\PBLUESCH on 12-JAN-16: PB Jan 12,2016 Load rating set to 5 tonnes based on age and multiple rotten components. Ensure posted once accessible. CBR_Conversion on 17-FEB-14: PB Jan 30, 2014 Quad required. Confirm GPS coordinates. Drill in 2014 and ensure posted to 10 tonnes. PB Mar04,2010. Inspect in 2010 and post to 10 tonnes. MC- Missed in 2011 - inspect in 2012				

Structure Name: K1603

Site #:	K1603	Year Superstructure Installed:	2012	Structure Type/Class:	Permanent Bridge
KM:	15.10	User km:	15.10	Last Inspection Date:	2020/09/25
Project File ID #:	1111	Br.	02	Next Inspection Date:	2023/09/25
Road Name:	MABLE-TAYLOR				
Crossing Name:	unknown		Total Length (metres):	9.1	
Special Access:			Special Equipment:		
Longitude:	-118 38 30.5		Latitude:	50 28 33.9	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 38 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K328

Site #:	K328	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	2.59	User km:	9.80	Last Inspection Date:	2022/08/12
Project File ID #:	8569	Br.	04	Next Inspection Date:	2023/08/12
Road Name:	MAW MAIN				
Crossing Name:	Whiteman Cr	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-119 31 54.3	Latitude:	50 12 56.4		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Cast in Place	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 18-JAN-19: JRG Jan 18, 2019 Monitor aggradation and condition of approaches.				

Structure Name: K977

Site #:	K977	Year Superstructure Installed:	1987	Structure Type/Class:	Major Culvert
KM:	0.00	User km:	0.20	Last Inspection Date:	2022/08/12
Project File ID #:	7596	Br.	01	Next Inspection Date:	2023/08/12
Road Name:	MCGREGOR CREEK				
Crossing Name:	McGregor Cr	Total Length (metres):	11.0		
Special Access:		Special Equipment:			
Longitude:	-119 28 47.1	Latitude:	50 21 8.5		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: K984

Site #:	K984	Year Superstructure Installed:	1993	Structure Type/Class:	Permanent Bridge
KM:	0.95	User km:	28.00	Last Inspection Date:	2022/08/12
Project File ID #:	8561	Br.	08	Next Inspection Date:	2023/08/12
Road Name:	MONTE-PRATT				
Crossing Name:	Spruce Cr	Total Length (metres):	6.0		
Special Access:		Special Equipment:			
Longitude:	-119 59 58.5	Latitude:	50 22 42.7		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR Conversion on 13-FEB-20: JRG Feb 13, 2020 Measure scour under footings and take photos during every inspection. 2019 field measurements: RB DS footing exposed with up to 1000 mm of scour under footing. RB US footing exposed but not accessible. LB DS footing exposed with up to 450 mm of scour under footing. LB US footing not exposed.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 39 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1653

Site #:	K1653	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	6.40	User km:	6.40	Last Inspection Date:	2020/08/10
Project File ID #:	8215	Br.	01	Next Inspection Date:	2023/08/10
Road Name:	NORTH FORK				
Crossing Name:	Unnamed Cr		Total Length (metres):	9.0	
Special Access:			Special Equipment:		
Longitude:	-118 28 52.5		Latitude:	50 16 12.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 23-JAN-18: .				

Structure Name: K1654

Site #:	K1654	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	6.70	User km:	6.70	Last Inspection Date:	2020/08/10
Project File ID #:	8215	Br.	01	Next Inspection Date:	2023/08/10
Road Name:	NORTH FORK				
Crossing Name:	Unknown		Total Length (metres):	11.0	
Special Access:			Special Equipment:		
Longitude:	-118 28 44.6		Latitude:	50 16 19.8	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 23-JAN-18: PB Jan23.2018. Monitor rip rap scour.				

Structure Name: K1655

Site #:	K1655	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	7.30	User km:	7.30	Last Inspection Date:	2020/08/10
Project File ID #:	8215	Br.	01	Next Inspection Date:	2023/08/10
Road Name:	NORTH FORK				
Crossing Name:	Unnamed Cr		Total Length (metres):	14.0	
Special Access:			Special Equipment:		
Longitude:	-118 27 56.5		Latitude:	50 16 27.6	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 23-JAN-18: PB Jan23.2018. Monitor rip rap scour.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 40 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1108

Site #:	K1108	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	5.30	User km:	5.30	Last Inspection Date:	2020/08/10
Project File ID #:	8215	Br.	02	Next Inspection Date:	2023/08/10
Road Name:	NORTH FORK-OTTESON				
Crossing Name:	Unnamed	Total Length (metres):	8.6		
Special Access:		Special Equipment:			
Longitude:	-118 28 9.3	Latitude:	50 16 35.8		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K613

Site #:	K613	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	3.98	User km:	10.00	Last Inspection Date:	2020/08/14
Project File ID #:	7023	Br.	01	Next Inspection Date:	2023/08/14
Road Name:	OYAMA LAKE				
Crossing Name:	Oyama Cr	Total Length (metres):	11.6		
Special Access:		Special Equipment:			
Longitude:	-119 17 50.8	Latitude:	50 7 21.6		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K641

Site #:	K641	Year Superstructure Installed:	2004	Structure Type/Class:	Permanent Bridge
KM:	9.13	User km:	14.90	Last Inspection Date:	2020/08/14
Project File ID #:	7023	Br.	01	Next Inspection Date:	2023/08/14
Road Name:	OYAMA LAKE				
Crossing Name:	Damer Cr	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-119 15 13.7	Latitude:	50 8 55.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 41 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K979A

Site #:	K979	Year Superstructure Installed:	2011	Structure Type/Class:	Major Culvert
KM:	0.13	User km:	10.80	Last Inspection Date:	2020/06/30
Project File ID #:	6020	Br.	01	Next Inspection Date:	2023/06/30
Road Name:	PINAUS LAKE				
Crossing Name:	Equesis Cr		Total Length (metres):	10.9	
Special Access:			Special Equipment:		
Longitude:	-119 31 28.3		Latitude:	50 24 59.2	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					

Structure Name: K980

Site #:	K980	Year Superstructure Installed:	1986	Structure Type/Class:	Major Culvert
KM:	3.65	User km:	10.50	Last Inspection Date:	2020/06/30
Project File ID #:	6020	Br.	01	Next Inspection Date:	2023/06/30
Road Name:	PINAUS LAKE				
Crossing Name:	Equesis Cr		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-119 31 13.8		Latitude:	50 24 57.0	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	IDIR\JRUPAR on 18-JAN-19: JRG Jan 18, 2019 Monitor the crossing for indications of performance following future high flow event. CBR_Conversion on 17-FEB-14: PB Feb16,2010. Monitor clearance at outlet.				

Structure Name: K1638

Site #:	K1638	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	1.05	User km:	84.30	Last Inspection Date:	2020/08/18
Project File ID #:	8435	Br.	22	Next Inspection Date:	2023/08/18
Road Name:	RANGER				
Crossing Name:	Winnifred Cr Trib		Total Length (metres):	8.6	
Special Access:			Special Equipment:		
Longitude:	-118 26 33.8		Latitude:	49 57 55.2	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\PBLUESCH on 16-MAR-15: PB Mar16.2015 Look for any manufacturer's identifiers. IDIR\KEHODDER on 29-APR-14: Inherited structure...confirm details on 1st Inspection				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 42 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: TOC0019

Site #:	K1637	Year Superstructure Installed:	2019	Structure Type/Class:	Temporary Bridge
KM:	2.50	User km:	85.70	Last Inspection Date:	2021/08/19
Project File ID #:	8435	Br.	22	Next Inspection Date:	2023/08/19
Road Name:	RANGER				
Crossing Name:	Winnifred Creek Trib		Total Length (metres):	9.1	
Special Access:			Special Equipment:		
Longitude:	-118 25 30.1		Latitude:	49 58 4.5	
Superstructure:	Steel Box Beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:					

Structure Name: K1636

Site #:	K1636	Year Superstructure Installed:	2001	Structure Type/Class:	Woodbox/Log Culvert
KM:	0.60	User km:	85.40	Last Inspection Date:	2022/07/01
Project File ID #:	8435	Br.	25	Next Inspection Date:	2023/07/01
Road Name:	RAZOR				
Crossing Name:	Unknown		Total Length (metres):	6.0	
Special Access:			Special Equipment:		
Longitude:	-118 26 16.6		Latitude:	49 58 11.4	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	IDIR\PBLUESCH on 16-MAR-15: PB Mar 16.2015 No access for stringer assesement. Rated to 5 tonnes. Ensure posted. IDIR\KEHODDER on 29-APR-14: Inherited..confirm details at 1st inspection				

Structure Name: TOC0011

Site #:	K367	Year Superstructure Installed:	2016	Structure Type/Class:	Permanent Bridge
KM:	0.14	User km:	8.80	Last Inspection Date:	2020/09/24
Project File ID #:	1030	Br.	03	Next Inspection Date:	2023/09/24
Road Name:	SILVER PARK MTN.				
Crossing Name:	Ireland Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-118 42 15.4		Latitude:	50 25 7.2	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 43 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K366

Site #:	K366	Year Superstructure Installed:	1987	Structure Type/Class:	Permanent Bridge
KM:	5.26	User km:	14.30	Last Inspection Date:	2022/07/07
Project File ID #:	1030	Br.	03	Next Inspection Date:	2023/07/07
Road Name:	SILVER PARK MTN.				
Crossing Name:	Ireland Cr	Total Length (metres):	6.2		
Special Access:		Special Equipment:			
Longitude:	-118 38 38.5	Latitude:	50 25 0.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Mar7,2013 Monitor wing walls for movement. Confirm GPS coords. Structure appears to be mapped incorrectly.				

Structure Name: TOC0016

Site #:	K1665	Year Superstructure Installed:	2016	Structure Type/Class:	Permanent Bridge
KM:	6.70	User km:	14.50	Last Inspection Date:	2020/09/25
Project File ID #:	1030	Br.	03	Next Inspection Date:	2023/09/25
Road Name:	SILVER PARK MTN.				
Crossing Name:	Unnamed	Total Length (metres):	8.8		
Special Access:		Special Equipment:			
Longitude:	-118 37 35.7	Latitude:	50 24 54.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 14-DEC-16: PB Dec14,2016 Confirm exact cross-tie dimensions at next inspection.				

Structure Name: K359A

Site #:	K359	Year Superstructure Installed:	2016	Structure Type/Class:	Permanent Bridge
KM:	16.32	User km:	15.90	Last Inspection Date:	2020/08/09
Project File ID #:	0993	Br.	01	Next Inspection Date:	2023/08/09
Road Name:	SOUTH FORK				
Crossing Name:	Monashee trib.	Total Length (metres):	15.6		
Special Access:		Special Equipment:			
Longitude:	-118 21 4.0	Latitude:	50 12 23.6		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 04-APR-17: PB Apr04.2017 Assess slab girder concrete repairs. Assess road approaches, ditches and any drainage issues.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 44 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K687

Site #:	K687	Year Superstructure Installed:	1991	Structure Type/Class:	Permanent Bridge
KM:	2.10	User km:	11.10	Last Inspection Date:	2022/08/12
Project File ID #:	8569	Br.	05	Next Inspection Date:	2023/08/12
Road Name:	SOUTH FORK				
Crossing Name:	Whiteman Cr		Total Length (metres):	9.0	
Special Access:			Special Equipment:		
Longitude:	-119 32 33.7		Latitude:	50 12 44.8	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:	IDIR\JRUPAR on 22-JAN-19: JRG Jan 22, 2019 Monitor abutment scour.				

Structure Name: K975

Site #:	K975	Year Superstructure Installed:	1985	Structure Type/Class:	Major Culvert
KM:	8.91	User km:	14.10	Last Inspection Date:	2022/08/12
Project File ID #:	8569	Br.	05	Next Inspection Date:	2023/08/12
Road Name:	SOUTH FORK				
Crossing Name:	South Whiteman Cr		Total Length (metres):	18.0	
Special Access:			Special Equipment:		
Longitude:	-119 34 4.2		Latitude:	50 11 27.5	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	CBR_Conversion on 22-JAN-19: JRG Jan 22, 2019 Monitor crossing location for potential embankment scour or debris accumulation.				

Structure Name: K358

Site #:	K358	Year Superstructure Installed:	1987	Structure Type/Class:	Permanent Bridge
KM:	0.13	User km:	14.80	Last Inspection Date:	2022/07/02
Project File ID #:	0993	Br.	03	Next Inspection Date:	2023/07/02
Road Name:	SOUTH FORK-RAILROAD				
Crossing Name:	Monashee Cr		Total Length (metres):	10.4	
Special Access:			Special Equipment:		
Longitude:	-118 21 32.3		Latitude:	50 11 51.5	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 45 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K357

Site #:	K357	Year Superstructure Installed:	1987	Structure Type/Class:	Permanent Bridge
KM:	3.94	User km:	18.50	Last Inspection Date:	2020/08/09
Project File ID #:	0993	Br.	03	Next Inspection Date:	2023/08/09
Road Name:	SOUTH FORK-RAILROAD				
Crossing Name:	Railroad Cr Trib		Total Length (metres):	8.5	
Special Access:			Special Equipment:		
Longitude:	-118 19 7.4		Latitude:	50 10 38.9	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:	IDIR\BLUESCH on 12-MAY-22: PB may12.2022 Tolko upgraded timber decking in 2021; likely new wear deck over failing subdeck. Confirm decking condition and repairs completed. CBR_Conversion on 17-FEB-14: PB Jan 22,2013 Wrong site inspected or photos mixed up with K359. Rescheduled for 2014.				

Structure Name: K1018

Site #:	K1018	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	3.66	User km:	3.60	Last Inspection Date:	2022/07/01
Project File ID #:	8770	Br.	01	Next Inspection Date:	2023/07/01
Road Name:	STRUTELL CREEK				
Crossing Name:	Strutell Cr		Total Length (metres):	11.6	
Special Access:			Special Equipment:		
Longitude:	-118 30 37.5		Latitude:	50 2 13.9	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\JRUPAR on 22-JAN-19: JRG Jan 22, 2019 Monitor aggradation. Record height from creek bed to underside of girders.				

Structure Name: K338

Site #:	K338	Year Superstructure Installed:	1988	Structure Type/Class:	Temporary Bridge
KM:	6.02	User km:	50.40	Last Inspection Date:	2022/07/03
Project File ID #:	0905	Br.	01	Next Inspection Date:	2023/07/03
Road Name:	SUGAR LAKE				
Crossing Name:	Unnamed		Total Length (metres):	12.1	
Special Access:			Special Equipment:		
Longitude:	-118 21 57.6		Latitude:	50 44 17.4	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	IDIR\JRUPAR on 14-FEB-20: JRG Feb 14, 2020 Carefully measure decay in cedar crib logs. Identify depth of sap rot and heart rot. 2019 inspection notes 50 mm to 200 mm rot under girders, confirm if this is correct.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 46 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K337

Site #:	K337	Year Superstructure Installed:	1987	Structure Type/Class:	Temporary Bridge
KM:	12.58	User km:	43.90	Last Inspection Date:	2022/07/03
Project File ID #:	0905	Br.	01	Next Inspection Date:	2023/07/03
Road Name:	SUGAR LAKE				
Crossing Name:	Gagne Cr	Total Length (metres):	13.4		
Special Access:		Special Equipment:			
Longitude:	-118 21 11.8	Latitude:	50 41 18.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 14-FEB-20: JRG Feb 14, 2020 Carefully measure decay in cedar crib logs. Identify depth of sap rot and heart rot.				

Structure Name: K335A

Site #:	K335	Year Superstructure Installed:	2011	Structure Type/Class:	Permanent Bridge
KM:	21.20	User km:	21.20	Last Inspection Date:	2022/07/03
Project File ID #:	0905	Br.	01	Next Inspection Date:	2023/07/03
Road Name:	SUGAR LAKE				
Crossing Name:	Star Cr	Total Length (metres):	24.4		
Special Access:		Special Equipment:			
Longitude:	-118 27 24.7	Latitude:	50 30 58.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 14-FEB-20: JRG Feb 14, 2020 Top of ballast wall has 20 mm and 40 mm chamfer. Record which chamfer is next to deck panels at each abutment. IDIR\PBLUESCH on 14-DEC-17: PB Dec14.2017 Annual inspection due to proposed off-highway haul. Inspect deck panels and bearings for any signs of distress. CBR_Conversion on 17-FEB-14: PB Jan26.2012. Inspect deck drainage and comment. PB Mar5.2013 Debris flow in 2012 has reduced clearance significantly. Monitor until channel works completed. PB Jan 20,2013 No photos submitted from 2013 inspection. Re-inspect in 2014.				

Structure Name: K994

Site #:	K994	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	44.85	User km:	12.00	Last Inspection Date:	2020/08/10
Project File ID #:	0905	Br.	01	Next Inspection Date:	2023/08/10
Road Name:	SUGAR LAKE				
Crossing Name:	Unnamed	Total Length (metres):	8.6		
Special Access:		Special Equipment:			
Longitude:	-118 30 50.4	Latitude:	50 26 48.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 47 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1680 CUL

Site #:	K1680	Year Superstructure Installed:	2020	Structure Type/Class:	Major Culvert
KM:	47.70	User km:	47.70	Last Inspection Date:	
Project File ID #:	0905	Br.	01	Next Inspection Date:	2022/11/22
Road Name:	SUGAR LAKE				
Crossing Name:	Unnamed		Total Length (metres):	9.0	
Special Access:			Special Equipment:		
Longitude:	-118 20 54.0		Latitude:	50 43 30.0	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					

Structure Name: K339

Site #:	K339	Year Superstructure Installed:	1988	Structure Type/Class:	Temporary Bridge
KM:	50.80	User km:	50.80	Last Inspection Date:	2022/07/03
Project File ID #:	0905	Br.	01	Next Inspection Date:	2022/09/08
Road Name:	SUGAR LAKE				
Crossing Name:	Valerian Cr		Total Length (metres):	13.1	
Special Access:			Special Equipment:		
Longitude:	-118 22 19.2		Latitude:	50 44 43.8	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	IDIR\JRUPAR on 14-FEB-20: JRG Feb 14, 2020 Carefully measure decay in cedar crib logs. Identify depth of sap rot and heart rot. CBR_Conversion on 17-FEB-14: Monitor for scour at next inspection. PB Feb 15/10.				

Structure Name: K340

Site #:	K340	Year Superstructure Installed:	1988	Structure Type/Class:	Temporary Bridge
KM:	51.90	User km:	51.90	Last Inspection Date:	2022/07/03
Project File ID #:	0905	Br.	01	Next Inspection Date:	2022/09/08
Road Name:	SUGAR LAKE				
Crossing Name:	West Fork Shuswap R		Total Length (metres):	14.0	
Special Access:			Special Equipment:		
Longitude:	-118 22 0.0		Latitude:	50 45 16.5	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	IDIR\JRUPAR on 14-FEB-20: JRG Feb 14, 2020 Carefully measure decay in cedar crib logs. Identify depth of sap rot and heart rot.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 48 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K341

Site #:	K341	Year Superstructure Installed:	1988	Structure Type/Class:	Temporary Bridge
KM:	3.73	User km:	52.90	Last Inspection Date:	2022/07/03
Project File ID #:	0905	Br.	12	Next Inspection Date:	2023/07/03
Road Name:	SUGAR-BLANKET				
Crossing Name:	East Fork Shuswap R		Total Length (metres):	15.1	
Special Access:			Special Equipment:		
Longitude:	-118 21 41.1		Latitude:	50 45 23.4	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	IDIR\JRUPAR on 18-FEB-20: JRG Feb 18, 2020 Carefully measure decay in cedar crib logs. Identify depth of sap rot and heart rot.				

Structure Name: K342

Site #:	K342	Year Superstructure Installed:	1989	Structure Type/Class:	Permanent Bridge
KM:	0.09	User km:	22.60	Last Inspection Date:	2022/07/03
Project File ID #:	0905	Br.	05	Next Inspection Date:	2023/07/03
Road Name:	SUGAR-SPECTRUM				
Crossing Name:	Shuswap R		Total Length (metres):	42.7	
Special Access:			Special Equipment:	Peeper Truck	
Longitude:	-118 26 42.5		Latitude:	50 30 47.3	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans: 1
Planned Inspection Comments:	IDIR\PBLUESCH on 14-DEC-17: PB Dec14.2017 Annual inspection due to proposed off-highway haul. Inspect deck panels and bearings for any signs of distress. IDIR\PBLUESCH on 13-JAN-16: PB Jan 13.2016 Assess rotten log crib at south abutment.				

Structure Name: K343

Site #:	K343	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	4.66	User km:	26.40	Last Inspection Date:	2020/08/11
Project File ID #:	0905	Br.	05	Next Inspection Date:	2023/08/11
Road Name:	SUGAR-SPECTRUM				
Crossing Name:	Spectrum Cr		Total Length (metres):	20.4	
Special Access:			Special Equipment:		
Longitude:	-118 27 13.6		Latitude:	50 28 59.1	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\PBLUESCH on 23-JAN-19: JRG Jan 23, 2019 Clearly document each deck joint location requiring repair. E.g. joint between panels 1 & 2, 25% of joint requires repair. IDIR\PBLUESCH on 14-DEC-17: PB Dec14.2017 Annual inspection due to proposed off-highway haul. Inspect deck panels and bearings for any signs of distress.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 49 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: WO 2934

Site #:	K1661	Year Superstructure Installed:	2016	Structure Type/Class:	Permanent Bridge
KM:	2.80	User km:	34.30	Last Inspection Date:	2020/08/12
Project File ID #:	1031	Br.	52	Next Inspection Date:	2023/08/12
Road Name:	THELMA				
Crossing Name:	Unknown		Total Length (metres):	9.1	
Special Access:			Special Equipment:		
Longitude:	-118 47 50.7		Latitude:	50 5 8.1	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:	IDIR\MRFENNEL on 14-NOV-16: One year post installation inspection				

Structure Name: WO 2545

Site #:	K1662	Year Superstructure Installed:	2016	Structure Type/Class:	Temporary Bridge
KM:	4.60	User km:	36.10	Last Inspection Date:	2021/08/20
Project File ID #:	1031	Br.	52	Next Inspection Date:	2023/08/20
Road Name:	THELMA				
Crossing Name:	Unknown		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-118 48 31.8		Latitude:	50 4 28.4	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\MRFENNEL on 18-FEB-20: .				

Structure Name: K1694

Site #:	K1694	Year Superstructure Installed:		Structure Type/Class:	Temporary Bridge
KM:	6.10	User km:	37.50	Last Inspection Date:	2022/07/08
Project File ID #:	1031	Br.	52	Next Inspection Date:	2023/07/08
Road Name:	THELMA				
Crossing Name:	Unnamed		Total Length (metres):	7.6	
Special Access:	Pedestrian		Special Equipment:		
Longitude:	-118 49 23.0		Latitude:	50 4 3.0	
Superstructure:	Log Stringers		Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans: 1
Planned Inspection Comments:	IDIR\PBLUESCH on 28-MAR-17: PB Mar 28,2017 Structure should be closed to traffic or deactivated unless repairs are made.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 50 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1641A

Site #:	K1641	Year Superstructure Installed:	2019	Structure Type/Class:	Permanent Bridge
KM:	17.36	User km:	79.20	Last Inspection Date:	2020/08/18
Project File ID #:	8435	Br.	06	Next Inspection Date:	2023/08/18
Road Name:	WINNIFRED				
Crossing Name:	Winnifred Cr		Total Length (metres):	15.6	
Special Access:			Special Equipment:		
Longitude:	-118 29 57.9		Latitude:	49 56 57.1	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\MRFENNEL on 12-JAN-21: JRG Jan 12, 2021 Inspect deck and take photos of deck panel damage at joint between panels one and two.				

Structure Name: TOC0008

Site #:	K1640	Year Superstructure Installed:	2021	Structure Type/Class:	Temporary Bridge
KM:	21.44	User km:	83.30	Last Inspection Date:	2021/08/19
Project File ID #:	8435	Br.	06	Next Inspection Date:	2023/08/19
Road Name:	WINNIFRED				
Crossing Name:	Winnifred Creek Trib		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-118 28 21.1		Latitude:	49 56 58.6	
Superstructure:	Steel Box Beam		Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 28-APR-22: .				

Structure Name: K1640

Site #:	K1640	Year Superstructure Installed:	2002	Structure Type/Class:	Permanent Bridge
KM:	21.44	User km:	83.30	Last Inspection Date:	2020/08/18
Project File ID #:	8435	Br.	06	Next Inspection Date:	2023/08/18
Road Name:	WINNIFRED				
Crossing Name:	Winnifred Creek Trib		Total Length (metres):	8.6	
Special Access:			Special Equipment:		
Longitude:	-118 28 21.1		Latitude:	49 56 58.6	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\PBLUESCH on 07-MAR-19: JRG Mar 7, 2019 Monitor caps for possible rotation at every inspection.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 51 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: TOC0018

Site #:	K1741	Year Superstructure Installed:	2019	Structure Type/Class:	Temporary Bridge
KM:	84.50	User km:	84.50	Last Inspection Date:	2020/08/18
Project File ID #:	8435	Br.	06	Next Inspection Date:	2023/08/01
Road Name:	WINNIFRED				
Crossing Name:	Winnifred Cr Trib		Total Length (metres):	9.1	
Special Access:			Special Equipment:		
Longitude:	-118 25 30.1		Latitude:	49 58 4.5	
Superstructure:	Steel Box Beam		Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans: 1
Planned Inspection Comments:	IDIR\MRFENNEL on 07-JAN-20: One year post installation inspection				

Structure Name: K576

Site #:	K576	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	6.45	User km:	26.00	Last Inspection Date:	2022/07/09
Project File ID #:	4038	Br.	05	Next Inspection Date:	2023/07/09
Road Name:	WOLLASTON				
Crossing Name:	Unnamed		Total Length (metres):	9.0	
Special Access:			Special Equipment:		
Longitude:	-119 6 58.0		Latitude:	50 3 40.5	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\JRUPAR on 12-JAN-21: JRG Jan 12, 2021 Close the bridge if the curbs are not replaced.				

Structure Name: K384

Site #:	K384	Year Superstructure Installed:	1976	Structure Type/Class:	Permanent Bridge
KM:	43.83	User km:	58.50	Last Inspection Date:	2022/07/10
Project File ID #:	7654	Br.	01	Next Inspection Date:	2023/07/10
Road Name:	201				
Crossing Name:	Wilkinson Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:	Peeper Truck	
Longitude:	-119 16 48.6		Latitude:	49 38 21.0	
Superstructure:	Glulam Girder		Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Aug10/11 Inspect downstream/right bank pile and cap for failure below number plate. Take detailed photo for monitoring purposes.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 52 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K681

Site #:	K681	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	54.99	User km:	105.00	Last Inspection Date:	2022/07/09
Project File ID #:	7654	Br.	01	Next Inspection Date:	2023/07/09
Road Name:	201				
Crossing Name:	Damfino Cr		Total Length (metres):	13.6	
Special Access:			Special Equipment:		
Longitude:	-118 51 57.3		Latitude:	49 51 9.1	
Superstructure:	Concrete Box Beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K1566

Site #:	K1566	Year Superstructure Installed:	2010	Structure Type/Class:	Major Culvert
KM:	67.50	User km:	67.50	Last Inspection Date:	2020/08/13
Project File ID #:	7654	Br.	01	Next Inspection Date:	2023/08/13
Road Name:	201				
Crossing Name:	Parker Stirling		Total Length (metres):	15.0	
Special Access:			Special Equipment:		
Longitude:	-119 12 55.1		Latitude:	49 41 42.3	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: K1312

Site #:	K1312	Year Superstructure Installed:	2003	Structure Type/Class:	Permanent Bridge
KM:	91.30	User km:	91.30	Last Inspection Date:	2020/08/13
Project File ID #:	7654	Br.	01	Next Inspection Date:	2023/08/13
Road Name:	201				
Crossing Name:	West Kettle River		Total Length (metres):	22.0	
Special Access:			Special Equipment:		
Longitude:	-119 0 10.6		Latitude:	49 47 47.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 53 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1530

Site #:	K1530	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	120.30	User km:	120.30	Last Inspection Date:	2020/08/18
Project File ID #:	7654	Br.	01	Next Inspection Date:	2023/08/18
Road Name:	201				
Crossing Name:	Unknown		Total Length (metres):	11.3	
Special Access:			Special Equipment:		
Longitude:	-118 44 11.6		Latitude:	49 51 46.5	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K388A

Site #:	K388	Year Superstructure Installed:	2012	Structure Type/Class:	Permanent Bridge
KM:	1.03	User km:	39.10	Last Inspection Date:	2020/07/04
Project File ID #:	6296	Br.	01	Next Inspection Date:	2023/07/04
Road Name:	ASHNOLA				
Crossing Name:	Duruissseau Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-120 20 28.9		Latitude:	49 3 24.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB May 30.2013 New install in 2012.				

Structure Name: K405A

Site #:	K405	Year Superstructure Installed:	2019	Structure Type/Class:	Permanent Bridge
KM:	15.57	User km:	18.50	Last Inspection Date:	2020/07/02
Project File ID #:	7720	Br.	01	Next Inspection Date:	2023/07/02
Road Name:	BEAR				
Crossing Name:	Unnamed		Total Length (metres):	15.6	
Special Access:			Special Equipment:		
Longitude:	-120 0 28.2		Latitude:	49 57 53.4	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 54 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K705

Site #:	K705	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	1.14	User km:	1.10	Last Inspection Date:	2022/09/13
Project File ID #:	9555	Br.	01	Next Inspection Date:	2023/09/13
Road Name:	BOULDER				
Crossing Name:	ELLIN CR	Total Length (metres):	6.6		
Special Access:			Special Equipment:		
Longitude:	-120 0 9.7	Latitude:	49 57 21.2		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\BPELLETT on 27-APR-22: BP Mar 17-22 Measure undermining and cap beam rotation with every annual inspection. Compare new values to previous inspections when reporting on bridge condition. Ensure 5T load rating sign is still posted unless bridge should be closed. Search thoroughly for fabricator markings and photograph any found. IDIR\BLUE SCH on 22-DEC-15: PPB Dec 22.2015. Measure extent of footing undermining for all 4 footings. Ensure posted to 20 tonnes. CBR_Conversion on 17-FEB-14: PB Jan 10/12. Continue to monitor footings for undermining and settlement.				

Structure Name: K1688

Site #:	K1688	Year Superstructure Installed:	2018	Structure Type/Class:	Permanent Bridge
KM:	0.30	User km:	0.30	Last Inspection Date:	2022/07/10
Project File ID #:	8700	Br.	01	Next Inspection Date:	2023/07/10
Road Name:	BROWNE LAKE				
Crossing Name:	unnamed	Total Length (metres):	8.0		
Special Access:			Special Equipment:		
Longitude:	-119 11 28.0	Latitude:	49 47 46.5		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 07-JAN-20: Post installation inspection				

Structure Name: K849

Site #:	K849	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	0.46	User km:	59.80	Last Inspection Date:	2022/07/10
Project File ID #:	6413	Br.	02	Next Inspection Date:	2023/07/10
Road Name:	CANYON LAKES				
Crossing Name:	WILKINSON Cr	Total Length (metres):	18.0		
Special Access:			Special Equipment:		
Longitude:	-119 18 32.8	Latitude:	49 38 59.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 08-JAN-19: JRG Jan 8 2019 Monitor deck panel joints and honeycombing with exposed rebar on underside of deck.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 55 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1171

Site #:	K1171	Year Superstructure Installed:	2001	Structure Type/Class:	Major Culvert
KM:	1.63	User km:	34.90	Last Inspection Date:	2022/07/10
Project File ID #:	7654	Br.	15	Next Inspection Date:	2023/07/10
Road Name:	CULPER				
Crossing Name:	South Ellis Cr Tributary		Total Length (metres):	20.0	
Special Access:			Special Equipment:		
Longitude:	-119 26 25.2		Latitude:	49 24 52.6	
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:	IDIR\BPellet on 08-MAY-23: BP May 8-23 Inspector to measure fill depths and culvert length, gradient, diameter, wall thickness, and corrugation profile in 2023 routine inspection.				

Structure Name: K1170

Site #:	K1170	Year Superstructure Installed:	1999	Structure Type/Class:	Major Culvert
KM:	4.53	User km:	32.70	Last Inspection Date:	2022/07/10
Project File ID #:	7654	Br.	02	Next Inspection Date:	2023/07/10
Road Name:	DERENZY				
Crossing Name:	Unnamed		Total Length (metres):	0.0	
Special Access:			Special Equipment:		
Longitude:	-119 25 13.1		Latitude:	49 25 30.9	
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 08-MAY-23: BP May 8-23 Inspector to measure fill depths and culvert length, gradient, span & rise, wall thickness, and corrugation profile in 2023 routine inspection. Note: [PB Jan7,2013 Pick up culvert length and cover depths next inspection.] - this PIC was never completed.				

Structure Name: K1629

Site #:	K1629	Year Superstructure Installed:		Structure Type/Class:	Permanent Bridge
KM:	7.55	User km:	110.20	Last Inspection Date:	2020/08/14
Project File ID #:	7654	Br.	32	Next Inspection Date:	2023/08/14
Road Name:	EDGE				
Crossing Name:	Damfino Cr Tributary		Total Length (metres):	9.6	
Special Access:			Special Equipment:		
Longitude:	-118 49 13.5		Latitude:	49 49 31.3	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\BPBUESCH on 04-FEB-15: PB Feb 3,2015 Inspect high chain abutment for failure and tower lean. Assess slabs for damage. CBR_Conversion on 17-FEB-14: PB Jan21,2014 BCTS reallocation. Measure-up and confirm all structure details at first inspection in 2014.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 56 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1568

Site #:	K1568	Year Superstructure Installed:	2003	Structure Type/Class:	Major Culvert
KM:	0.63	User km:	26.50	Last Inspection Date:	2022/09/13
Project File ID #:	7720	Br.	20	Next Inspection Date:	2023/09/13
Road Name:	ESPERON 150				
Crossing Name:	Esperon Creek	Total Length (metres):	9.7		
Special Access:		Special Equipment:			
Longitude:	-119 41 35.0	Latitude:	50 4 29.2		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\BPellett on 15-FEB-22: BP Feb 15-22 Annual inspection to be completed in low water conditions and length of footing exposure and undermining on each side measured.				

Structure Name: K841

Site #:	K841	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	0.93	User km:	39.80	Last Inspection Date:	2020/08/13
Project File ID #:	8692	Br.	01	Next Inspection Date:	2023/08/13
Road Name:	GRAYSTOKES				
Crossing Name:	Mission Cr	Total Length (metres):	30.5		
Special Access:		Special Equipment:			
Longitude:	-119 3 48.8	Latitude:	49 53 15.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: PB Jan10,2013 Monitor rubber bearing pads.				

Structure Name: K848

Site #:	K848	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	1.68	User km:	19.50	Last Inspection Date:	2020/07/02
Project File ID #:	7720	Br.	14	Next Inspection Date:	2023/07/02
Road Name:	HATHEUME LAKE				
Crossing Name:	Hatheume Cr	Total Length (metres):	10.6		
Special Access:		Special Equipment:			
Longitude:	-120 1 49.4	Latitude:	49 57 36.5		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 57 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K586

Site #:	K586	Year Superstructure Installed:	1990	Structure Type/Class:	Permanent Bridge
KM:	12.94	User km:	1.00	Last Inspection Date:	2022/09/13
Project File ID #:	9556	Br.	01	Next Inspection Date:	2023/09/13
Road Name:	HIDDEN CREEK				
Crossing Name:	Lambly Cr		Total Length (metres):	17.0	
Special Access:			Special Equipment:		
Longitude:	-119 38 4.3		Latitude:	49 59 58.6	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Cast in Place	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 08-JAN-19: JRG Jan 8, 2019 Continue to monitor footings for stability and any scour issues (no rip rap).				

Structure Name: TOC0013

Site #:	K1687	Year Superstructure Installed:	2016	Structure Type/Class:	Temporary Bridge
KM:	1.08	User km:	114.30	Last Inspection Date:	2021/07/22
Project File ID #:	7654	Br.	135	Next Inspection Date:	2023/07/22
Road Name:	HOOK				
Crossing Name:	Damfino Trib		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-118 47 14.7		Latitude:	49 51 34.1	
Superstructure:	Steel Box Beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:					

Structure Name: K01

Site #:	K01	Year Superstructure Installed:	1985	Structure Type/Class:	Permanent Bridge
KM:	2.77	User km:	2.50	Last Inspection Date:	2020/08/12
Project File ID #:	0959	Br.	03	Next Inspection Date:	2023/08/12
Road Name:	IDEAL LAKE FSR				
Crossing Name:	BELGO DAM		Total Length (metres):	2.8	
Special Access:			Special Equipment:		
Longitude:	-119 5 43.2		Latitude:	50 0 36.6	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Cast in Place	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 09-JAN-19: JRG Jan 9, 2019 Measure bridge o/o length and clear width. IDIR\PBLUESCH on 09-JAN-19: JRG Jan 9, 2019 Ensure posted to 5 tonnes.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 58 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K387

Site #:	K387	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	12.05	User km:	18.00	Last Inspection Date:	2020/07/03
Project File ID #:	6988	Br.	01	Next Inspection Date:	2023/07/03
Road Name:	ISINTOK-MCNULTY				
Crossing Name:	Isintok Cr		Total Length (metres):	12.4	
Special Access:			Special Equipment:		
Longitude:	-119 54 41.4		Latitude:	49 34 34.2	
Superstructure:	Concrete Box Beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K702

Site #:	K702	Year Superstructure Installed:	1990	Structure Type/Class:	Major Culvert
KM:	9.88	User km:	9.70	Last Inspection Date:	2022/09/13
Project File ID #:	7720	Br.	04	Next Inspection Date:	2023/09/13
Road Name:	JACKPINE				
Crossing Name:	JACKPINE Cr		Total Length (metres):	15.3	
Special Access:			Special Equipment:		
Longitude:	-119 44 52.0		Latitude:	49 55 47.0	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 09-JAN-19: JRG Jan 9, 2019 Large gaps at coupled connections. Monitor for scour and settlement of road.				

Structure Name: K703

Site #:	K703	Year Superstructure Installed:	1990	Structure Type/Class:	Major Culvert
KM:	12.05	User km:	11.90	Last Inspection Date:	2022/09/13
Project File ID #:	7720	Br.	04	Next Inspection Date:	2023/09/13
Road Name:	JACKPINE				
Crossing Name:	POWERS CR		Total Length (metres):	15.0	
Special Access:			Special Equipment:		
Longitude:	-119 44 35.7		Latitude:	49 56 40.4	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	IDIR\JRUPAR on 09-JAN-19: JRG Jan 9, 2019 Monitor culvert for scour, settlement, or further deformation.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 59 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1702

Site #:	K1702	Year Superstructure Installed:	2017	Structure Type/Class:	Major Culvert
KM:	0.30	User km:	0.30	Last Inspection Date:	2022/07/10
Project File ID #:	7654	Br.	62	Next Inspection Date:	2023/07/10
Road Name:	KILMER				
Crossing Name:	Shuttleworth Creek		Total Length (metres):	25.3	
Special Access:			Special Equipment:		
Longitude:	-119 20 42.3		Latitude:	49 21 38.5	
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:	IDIR\BPellet on 16-FEB-22: BP Feb 15-22 Annual inspection to be completed in low water conditions and length of footing exposure and undermining on each side measured. IDIR\JRUPAR on 09-JAN-19: JRG Jan 9, 2019 Monitor extent of exposed footings, and geometry of scour if it occurs.				

Structure Name: K1657

Site #:	K1657	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	6.30	User km:	54.40	Last Inspection Date:	2020/08/13
Project File ID #:	8692	Br.	18	Next Inspection Date:	2023/08/13
Road Name:	KOOCHIN				
Crossing Name:	Koochin Cr		Total Length (metres):	11.0	
Special Access:			Special Equipment:		
Longitude:	-118 57 41.9		Latitude:	49 56 58.6	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\MRFENNEL on 25-APR-16: One year post installation inspection				

Structure Name: K1667

Site #:	K1667	Year Superstructure Installed:	2016	Structure Type/Class:	Permanent Bridge
KM:	9.13	User km:	57.20	Last Inspection Date:	2020/08/13
Project File ID #:	8692	Br.	18	Next Inspection Date:	2023/08/13
Road Name:	KOOCHIN				
Crossing Name:	Unnamed		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-118 56 22.8		Latitude:	49 57 23.4	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 60 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K412

Site #:	K412	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	14.91	User km:	0.20	Last Inspection Date:	2020/07/03
Project File ID #:	R06638	Br.	23H	Next Inspection Date:	2023/07/03
Road Name:	LOST CHAIN ROAD				
Crossing Name:	Lost Chain Cr	Total Length (metres):	11.6		
Special Access:		Special Equipment:			
Longitude:	-119 58 1.8	Latitude:	49 40 14.4		
Superstructure:	Concrete Box Beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Dec 21,2010. Assess tension cracks underside of slabs.				

Structure Name: K1666

Site #:	K1666	Year Superstructure Installed:	2016	Structure Type/Class:	Permanent Bridge
KM:	0.93	User km:	59.10	Last Inspection Date:	2020/08/13
Project File ID #:	8692	Br.	19	Next Inspection Date:	2023/08/13
Road Name:	LOST LOCH				
Crossing Name:	Unnamed	Total Length (metres):	12.0		
Special Access:		Special Equipment:			
Longitude:	-118 55 3.4	Latitude:	49 56 47.9		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: K729

Site #:	K729	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	2.16	User km:	2.00	Last Inspection Date:	2022/09/13
Project File ID #:	9396	Br.	01	Next Inspection Date:	2023/09/13
Road Name:	MELLIN LAKE				
Crossing Name:	Unnamed	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-119 59 11.4	Latitude:	49 59 39.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 21-FEB-20: JRG Feb 20, 2020 Measure angle of right abutment steel pipe columns at every inspection.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 61 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K395

Site #:	K395	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	0.04	User km:	5.00	Last Inspection Date:	2022/07/26
Project File ID #:	1071	Br.	02	Next Inspection Date:	2023/07/26
Road Name:	MT. SWITE				
Crossing Name:	McDougall Cr	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-119 35 35.6	Latitude:	49 54 5.1		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Jan 30,2014 Provide detailed driving directions.				

Structure Name: K397

Site #:	K397	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	6.15	User km:	76.40	Last Inspection Date:	2022/07/10
Project File ID #:	6428	Br.	01	Next Inspection Date:	2023/07/10
Road Name:	MYRA				
Crossing Name:	Stirling Cr	Total Length (metres):	14.0		
Special Access:		Special Equipment:			
Longitude:	-119 13 7.7	Latitude:	49 45 25.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 20-APR-22: PB april20.2022 Structure is composite. Requires concrete deck repairs. Contact RBE for prescription. IDIR\PBLUESCH on 09-JAN-19: JRG Jan 9, 2019 Inspect deck panel grout joints from underside of deck. Record number of deck panel grout joints covered with form work and number of joints not fully grouted. Record geometry of any damage to deck panels at joints.				

Structure Name: K1306

Site #:	K1306	Year Superstructure Installed:	2004	Structure Type/Class:	Permanent Bridge
KM:	2.77	User km:	47.30	Last Inspection Date:	2022/09/13
Project File ID #:	7720	Br.	05	Next Inspection Date:	2023/09/13
Road Name:	NICOLA RIVER				
Crossing Name:	Nicola R	Total Length (metres):	20.0		
Special Access:		Special Equipment:			
Longitude:	-119 55 32.7	Latitude:	50 1 32.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 08-JAN-21: JRG Jan 8, 2021 Close bridge if the approaches have not been repaired with fill added at bridge corners to achieve design road width. CBR_Conversion on 10-JAN-19: JRG Jan 10, 2019 Confirm if maintenance items completed in next inspection.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 62 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K856

Site #:	K856	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	2.31	User km:	6.30	Last Inspection Date:	2022/09/13
Project File ID #:	9578	Br.	01	Next Inspection Date:	2023/09/13
Road Name:	OLD DAVE				
Crossing Name:	Unnamed		Total Length (metres):	12.6	
Special Access:			Special Equipment:		
Longitude:	-119 53 38.7		Latitude:	50 1 46.9	
Superstructure:	Concrete Box Beam		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:	IDIR\BLUE SCH on 06-FEB-15: PB Feb6,2015 Monitor both abutments for erosion. Left bank upstream footing previously exposed 2008/2009 and subsequently armoured.				

Structure Name: K843

Site #:	K843	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	3.13	User km:	9.90	Last Inspection Date:	2020/07/02
Project File ID #:	9578	Br.	03	Next Inspection Date:	2023/07/02
Road Name:	OLD DAVE EAST				
Crossing Name:	Unnamed		Total Length (metres):	9.6	
Special Access:			Special Equipment:		
Longitude:	-119 51 10.9		Latitude:	50 2 5.9	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: K1735

Site #:	K1735	Year Superstructure Installed:	2019	Structure Type/Class:	Major Culvert
KM:	0.60	User km:	3.10	Last Inspection Date:	2022/07/10
Project File ID #:	7654	Br.	10	Next Inspection Date:	2023/07/10
Road Name:	SAUNIER NORTH				
Crossing Name:	Saunier Cr		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-119 20 15.0		Latitude:	49 26 39.6	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	IDIR\BPELLETT on 16-FEB-22: BP Feb 16-22 Annual inspections to be completed in low water conditions to monitor streambed degradation and footing exposure. Measure depth of cover with every inspection. IDIR\MRFENNEL on 07-JAN-21: JRG Jan 7, 2021 Lock blocks reported to be on 12 degree slope. Arch design specified slope to be 9 degrees. Right/Town lock block slope confirmed to be 9 degrees during construction. Monitor lock blocks for possible rotation during future inspections.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 63 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: TOC0010

Site #:	K1531	Year Superstructure Installed:	2014	Structure Type/Class:	Temporary Bridge
KM:	2.97	User km:	2.90	Last Inspection Date:	2021/09/15
Project File ID #:	7654	Br.	49	Next Inspection Date:	2023/09/15
Road Name:	SPLIT				
Crossing Name:	Split Creek		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-118 45 9.6		Latitude:	49 52 55.2	
Superstructure:	Other	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\PBLUESCH on 18-JAN-18: Jan 18.2018. Multiple lag bolts installed below bottom ballast wall timber are not visible. Timbers set slightly too far apart therefore creekside bolt holes in bearing plates are inside of the timber sill. IDIR\PBLUESCH on 03-APR-17: PB May02,2016 BCTS install 2014.				

Structure Name: K410

Site #:	K410	Year Superstructure Installed:	1993	Structure Type/Class:	Temporary Bridge
KM:	11.10	User km:	10.80	Last Inspection Date:	2021/07/24
Project File ID #:	8694	Br.	03	Next Inspection Date:	2023/07/24
Road Name:	TROUT CREEK				
Crossing Name:	Trout Cr		Total Length (metres):	12.1	
Special Access:			Special Equipment:		
Longitude:	-120 7 52.8		Latitude:	49 46 35.8	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 11-JAN-19: JRG Jan 11, 2019 AE dwg VW63-SK-301 to 305 BCFS L100 show bearing stiffeners positioned 140 mm from centreline of steel pipe columns. As-Built condition reflects shop drawings.				

Structure Name: K1199A

Site #:	K1199	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	0.09	User km:	0.10	Last Inspection Date:	2020/07/02
Project File ID #:	8694	Br.	06	Next Inspection Date:	2023/07/02
Road Name:	WHITEHEAD EAST				
Crossing Name:	Unnamed		Total Length (metres):	10.6	
Special Access:			Special Equipment:		
Longitude:	-120 10 44.5		Latitude:	49 48 4.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 64 of 65
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Okanagan Shuswap Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Sort:

Structure Name: K1197

Site #:	K1197	Year Superstructure Installed:	1999	Structure Type/Class:	Major Culvert
KM:	3.03	User km:	42.50	Last Inspection Date:	2022/07/12
Project File ID #:	8694	Br.	07	Next Inspection Date:	2023/07/12
Road Name:	WHITEHEAD WEST				
Crossing Name:	Unnamed		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-120 11 19.3		Latitude:	49 47 0.7	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	IDIR\BPellet on 08-MAY-23: BP May 8-23 Measure culvert span, rise, wall thickness, and corrugation profile during 2023 routine inspection. Also take measurements and photographs of coupler gap.				

Structure Name: K1548

Site #:	K1548	Year Superstructure Installed:	2009	Structure Type/Class:	Temporary Bridge
KM:	10.00	User km:	10.00	Last Inspection Date:	2021/07/26
Project File ID #:	S25268	Br.	1	Next Inspection Date:	2023/07/26
Road Name:					
Crossing Name:	Bald Range Creek		Total Length (metres):	12.6	
Special Access:	ATV		Special Equipment:		
Longitude:	-119 33 57.4		Latitude:	49 59 43.3	
Superstructure:	Log Stringers		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 18-JAN-18: .				

Structure Name: PS-045

Site #:	K1788	Year Superstructure Installed:	2018	Structure Type/Class:	Temporary Bridge
KM:	13.90	User km:	13.90	Last Inspection Date:	
Project File ID #:	0993	Br.	01	Next Inspection Date:	2023/08/18
Road Name:	SOUTH FORK				
Crossing Name:	Unnamed		Total Length (metres):	21.3	
Special Access:			Special Equipment:		
Longitude:	-118 22 29.9		Latitude:	50 11 40.9	
Superstructure:	Steel Box Beam		Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans: 1
Planned Inspection Comments:	IDIR\MRFENNEL on 03-MAY-23: Temporary installation after road washout. One year post installation inspection				

Structure Type/Class Totals

Permanent Bridge Total: 112
Temporary Bridge Total: 44

Major Culvert Total: 31
Woodbox/Log Culvert Total: 5