



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 1 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Management Area:

Structure Name: N4-068

Site #:	N4-068	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	0.33	User km:	36.10	Last Inspection Date:	2020/09/08
Project File ID #:	9984	Br.	01	Next Inspection Date:	2023/09/08
Road Name:	ADAMANTS FSR				
Crossing Name:	GOLDSTREAM R		Total Length (metres):	21.3	
Special Access:			Special Equipment:		
Longitude:	-118 8 19.8		Latitude:	51 37 3.7	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Sill - Permanent	# Spans: 1
Planned Inspection Comments:					

Structure Name: N4-050A

Site #:	N4-050	Year Superstructure Installed:	2009	Structure Type/Class:	Temporary Bridge
KM:	17.58	User km:	29.90	Last Inspection Date:	2021/07/31
Project File ID #:	5384	Br.	02	Next Inspection Date:	2023/07/31
Road Name:	AKOLKOLEX - CRAWFORD				
Crossing Name:	CRAWFORD Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-117 58 37.6		Latitude:	50 45 25.6	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14:				

Structure Name: N4-006

Site #:	N4-006	Year Superstructure Installed:	1992	Structure Type/Class:	Permanent Bridge
KM:	0.31	User km:	18.60	Last Inspection Date:	2022/07/29
Project File ID #:	5384	Br.	03	Next Inspection Date:	2023/07/21
Road Name:	AKOLKOLEX - HOLYK				
Crossing Name:	AKOLKOLEX R		Total Length (metres):	20.0	
Special Access:			Special Equipment:		
Longitude:	-117 54 59.5		Latitude:	50 53 0.7	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans: 1
Planned Inspection Comments:	IDIR\MIPENNER on 23-FEB-19: JRG Feb 23, 2019 Detailed inspection of accessible sections of left abutment retaining wall. Monitor for potential movement and signs of instability.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 2 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Management Area:

Structure Name: N4-007

Site #:	N4-007	Year Superstructure Installed:	1993	Structure Type/Class:	Temporary Bridge
KM:	7.86	User km:	24.50	Last Inspection Date:	2021/08/01
Project File ID #:	5384	Br.	03	Next Inspection Date:	2023/08/01
Road Name:	AKOLKOLEX - HOLYK				
Crossing Name:	HOLYK Cr	Total Length (metres):	14.3		
Special Access:		Special Equipment:			
Longitude:	-117 50 47.1	Latitude:	50 51 30.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 04-FEB-20: .				

Structure Name: N4-004

Site #:	N4-004	Year Superstructure Installed:	1990	Structure Type/Class:	Temporary Bridge
KM:	0.48	User km:	27.80	Last Inspection Date:	2022/07/29
Project File ID #:	5384	Br.	01	Next Inspection Date:	2023/07/29
Road Name:	AKOLKOLEX RIVER				
Crossing Name:	AKOLKOLEX R	Total Length (metres):	18.2		
Special Access:		Special Equipment:			
Longitude:	-117 50 22.1	Latitude:	50 56 8.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 04-FEB-20: JRG Feb 4, 2020 Cedar crib built in 1977. Annual monitoring required. IDIR\DMALWAY on 04-FEB-20: .				

Structure Name: N4-002

Site #:	N4-002	Year Superstructure Installed:	1965	Structure Type/Class:	Permanent Bridge
KM:	12.73	User km:	15.50	Last Inspection Date:	2022/07/29
Project File ID #:	5384	Br.	01	Next Inspection Date:	2023/07/29
Road Name:	AKOLKOLEX RIVER				
Crossing Name:	PARMAC Cr	Total Length (metres):	8.1		
Special Access:		Special Equipment:	Peeper Truck		
Longitude:	-117 57 16.0	Latitude:	50 52 21.6		
Superstructure:	Timber - treated stringers	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 09-FEB-21: JRG Feb 9, 2021 Orange painted area on Stringer 1 roughly outlines area of decay. Monitor Stringer 1 for further decay and signs of distress. CBR_Conversion on 05-FEB-20: JRG Feb 5, 2020 Monitor scour under breast wall.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 3 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Management Area:

Structure Name: N4-009

Site #:	N4-009	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	8.04	User km:	8.00	Last Inspection Date:	2022/07/28
Project File ID #:	7764	Br.	01	Next Inspection Date:	2023/07/28
Road Name:	BIGMOUTH				
Crossing Name:	BIG FISH Cr		Total Length (metres):	21.0	
Special Access:			Special Equipment:		
Longitude:	-118 30 51.4		Latitude:	51 49 22.1	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\BPELLETT on 21-MAR-23: BP Mar 21-23 Check damaged curb risers and guard rail support conditions in 2023 routine inspection, and post bridge to no more than 20T if guard rails are not fully supported. IDIR\DMALWAY on 23-FEB-17: Check the upstream underside of deck panel, 3rd one in from the right bank at the curb bracket block location. As it appears it was damaged in the past due to curb impact and was repaired.				

Structure Name: N4-012

Site #:	N4-012	Year Superstructure Installed:	1988	Structure Type/Class:	Temporary Bridge
KM:	17.36	User km:	17.70	Last Inspection Date:	2021/07/31
Project File ID #:	7764	Br.	01	Next Inspection Date:	2023/07/31
Road Name:	BIGMOUTH				
Crossing Name:	Unnamed		Total Length (metres):	8.4	
Special Access:			Special Equipment:		
Longitude:	-118 24 30.5		Latitude:	51 51 7.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 06-FEB-20: JRG Feb 6, 2020 Closely inspect downstream side of left abutment crib for possible scour at each inspection. IDIR\MIPENNER on 15-JAN-16: Annual inspection not required, monitor structure for future scour. Grout repair under abutment in 2003.				

Structure Name: N4-052

Site #:	N4-052	Year Superstructure Installed:	1991	Structure Type/Class:	Permanent Bridge
KM:	28.59	User km:	29.30	Last Inspection Date:	2020/09/08
Project File ID #:	7764	Br.	01	Next Inspection Date:	2023/09/08
Road Name:	BIGMOUTH				
Crossing Name:	BIGMOUTH		Total Length (metres):	26.3	
Special Access:			Special Equipment:		
Longitude:	-118 16 43.9		Latitude:	51 51 6.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 4 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Management Area:

Structure Name: N4-T05

Site #:	N4-084	Year Superstructure Installed:	2016	Structure Type/Class:	Temporary Bridge
KM:	0.60	User km:	0.60	Last Inspection Date:	2021/09/22
Project File ID #:	0604	Br.	03	Next Inspection Date:	2023/09/22
Road Name:	BR 27.1				
Crossing Name:	Nightmare Creek		Total Length (metres):	25.4	
Special Access:			Special Equipment:		
Longitude:	-118 15 20.3		Latitude:	51 35 5.5	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 17-JUN-21: Check log bundle cables for tension.				

Structure Name: N4-T10

Site #:	N4-T10	Year Superstructure Installed:	1999	Structure Type/Class:	Temporary Bridge
KM:	0.37	User km:	3.50	Last Inspection Date:	2022/07/29
Project File ID #:	9675	Br.	03	Next Inspection Date:	2023/07/29
Road Name:	BRANCH 3.1				
Crossing Name:	THOR Cr		Total Length (metres):	16.4	
Special Access:			Special Equipment:		
Longitude:	-118 4 1.9		Latitude:	50 37 50.1	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\BPelletT on 03-FEB-22: BP Feb 3-22 Drill cribs for rot on every inspection. Measure clear distance from bearing timbers to cribs on next inspection. CBR_Conversion on 06-FEB-20: JRG Feb 6, 2020 Carefully inspect log cribs. Try to determine species. Record sap rot and heart rot.				

Structure Name: PS-065

Site #:	N4-017	Year Superstructure Installed:	2020	Structure Type/Class:	Temporary Bridge
KM:	11.24	User km:	7.80	Last Inspection Date:	2021/07/30
Project File ID #:	8065	Br.	01	Next Inspection Date:	2023/07/30
Road Name:	DOWNIE MAIN				
Crossing Name:	LONG Cr		Total Length (metres):	14.4	
Special Access:			Special Equipment:		
Longitude:	-118 17 36.9		Latitude:	51 31 11.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 5 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Management Area:

Structure Name: WO-384

Site #:	N4-016	Year Superstructure Installed:	2019	Structure Type/Class:	Temporary Bridge
KM:	14.44	User km:	4.60	Last Inspection Date:	2021/07/30
Project File ID #:	8065	Br.	01	Next Inspection Date:	2023/07/30
Road Name:	DOWNIE MAIN				
Crossing Name:	BOULDER Cr	Total Length (metres):	11.4		
Special Access:		Special Equipment:			
Longitude:	-118 20 12.3	Latitude:	51 30 52.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: N4-014

Site #:	N4-014	Year Superstructure Installed:	1995	Structure Type/Class:	Temporary Bridge
KM:	15.64	User km:	3.40	Last Inspection Date:	2021/07/30
Project File ID #:	8065	Br.	01	Next Inspection Date:	2023/07/30
Road Name:	DOWNIE MAIN				
Crossing Name:	Unnamed	Total Length (metres):	9.1		
Special Access:		Special Equipment:			
Longitude:	-118 20 59.6	Latitude:	51 30 37.5		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\MIPENNER on 06-FEB-20: JRG Feb 6, 2020 Cedar log cribs built in 1985. Closely inspect condition of cribs at each inspection. Record depth of sap and heart rot where appropriate.				

Structure Name: N4-T12

Site #:	N4-T12	Year Superstructure Installed:	2001	Structure Type/Class:	Permanent Bridge
KM:	0.89	User km:	31.90	Last Inspection Date:	2022/07/30
Project File ID #:	9354	Br.	15	Next Inspection Date:	2023/07/30
Road Name:	DRY CR BR 30.8				
Crossing Name:	Unnamed	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-118 7 14.2	Latitude:	50 42 43.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 23-FEB-19: JRG Feb 23, 2019 Monitor rotation of steel pipe columns at right abutment. CBR_Conversion on 17-FEB-14: Take multiple picture of riprap to ensure stability after original repair completed in 2011. DA March 2013.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 6 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Management Area:

Structure Name: N4-021

Site #:	N4-021	Year Superstructure Installed:	1983	Structure Type/Class:	Major Culvert
KM:	10.71	User km:	11.90	Last Inspection Date:	2022/07/27
Project File ID #:	8196	Br.	01	Next Inspection Date:	2023/07/27
Road Name:	FRISBY MAIN				
Crossing Name:	IRON BRIDGE Cr		Total Length (metres):	18.2	
Special Access:			Special Equipment:		
Longitude:	-118 13 8.1		Latitude:	51 8 37.8	
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:	IDIR\MIPENNER on 11-APR-23: . CBR_Conversion on 17-FEB-14: Measure and document the vertical hieght (at lowest deformed location to culvert floor) of the location of the culvert inlet roof for more accurate monitoring of this issue. Ensure inspection occurs at drier summer months.				

Structure Name: N4-022

Site #:	N4-022	Year Superstructure Installed:	1983	Structure Type/Class:	Major Culvert
KM:	11.94	User km:	13.30	Last Inspection Date:	2022/07/27
Project File ID #:	8196	Br.	01	Next Inspection Date:	2023/07/27
Road Name:	FRISBY MAIN				
Crossing Name:	Unnamed		Total Length (metres):	22.0	
Special Access:			Special Equipment:		
Longitude:	-118 13 2.8		Latitude:	51 9 13.5	
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:	IDIR\BPELLETT on 04-APR-22: BP Apr 4-22 Measure rustline height at inlet and outlet, corrugation profile, and wall gauge at next inspection. CBR_Conversion on 24-FEB-19: JRG Feb 24, 2019 Culvert barrel is out of round with a low point halfway along its length. Measure interior height and width half way through culvert at each inspection. In 2001 height = 1.6 m and width = 2.0 m.				

Structure Name: N4-023

Site #:	N4-023	Year Superstructure Installed:	1983	Structure Type/Class:	Major Culvert
KM:	13.26	User km:	14.50	Last Inspection Date:	2022/07/27
Project File ID #:	8196	Br.	01	Next Inspection Date:	2023/07/27
Road Name:	FRISBY MAIN				
Crossing Name:	Unnamed		Total Length (metres):	28.5	
Special Access:			Special Equipment:		
Longitude:	-118 13 9.5		Latitude:	51 9 54.7	
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:	IDIR\BPELLETT on 11-APR-23: BP Apr 11-23 Measure wall thickness, corrugation profile, and gradient on next annual inspection. IDIR\MIPENNER on 11-APR-23: BP Apr 11-23 Change DA's 2016 recommendation of "inspect every two				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 7 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Management Area:

years due to chronic aggradation blocking inlet and causing risk of culvert/road blowout" to annual inspection due to increase of blockage.

Structure Name: N4-024

Site #:	N4-024	Year Superstructure Installed:	1983	Structure Type/Class:	Major Culvert
KM:	13.71	User km:	14.90	Last Inspection Date:	2022/07/27
Project File ID #:	8196	Br.	01	Next Inspection Date:	2023/07/27
Road Name:	FRISBY MAIN				
Crossing Name:	Unnamed		Total Length (metres):	17.2	
Special Access:			Special Equipment:		
Longitude:	-118 13 5.6		Latitude:	51 10 8.5	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	IDIR\BPellet on 11-APR-23: BP Apr 11-23 Measure wall thickness, corrugation profile, gradient, and cover heights in 2023 inspection.				

Structure Name: N4-T11

Site #:	N4-T11	Year Superstructure Installed:	1999	Structure Type/Class:	Temporary Bridge
KM:	0.54	User km:	2.00	Last Inspection Date:	2021/08/03
Project File ID #:	8636	Br.	01	Next Inspection Date:	2023/08/03
Road Name:	GRIFFITH MAIN				
Crossing Name:	Unnamed		Total Length (metres):	4.3	
Special Access:			Special Equipment:		
Longitude:	-118 14 58.5		Latitude:	50 57 51.2	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans: 1
Planned Inspection Comments:					

Structure Name: N4-070

Site #:	N4-070	Year Superstructure Installed:	2001	Structure Type/Class:	Permanent Bridge
KM:	11.26	User km:	0.80	Last Inspection Date:	2020/09/06
Project File ID #:	0805	Br.	01	Next Inspection Date:	2023/09/06
Road Name:	JORDAN				
Crossing Name:	JORDAN R		Total Length (metres):	42.7	
Special Access:			Special Equipment:		
Longitude:	-118 14 38.8		Latitude:	51 1 25.2	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 8 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Management Area:

Structure Name: N4-066A

Site #:	N4-066	Year Superstructure Installed:	2013	Structure Type/Class:	Permanent Bridge
KM:	8.40	User km:	14.00	Last Inspection Date:	2020/09/06
Project File ID #:	0805	Br.	02	Next Inspection Date:	2023/09/06
Road Name:	JORDAN - KIRKUP				
Crossing Name:	Unknown		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-118 19 32.1		Latitude:	51 2 4.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N4-038

Site #:	N4-038	Year Superstructure Installed:	1992	Structure Type/Class:	Temporary Bridge
KM:	1.31	User km:	1.80	Last Inspection Date:	2021/07/30
Project File ID #:	7667	Br.	01	Next Inspection Date:	2023/07/30
Road Name:	JUMPING CREEK				
Crossing Name:	JUMPING Cr		Total Length (metres):	12.3	
Special Access:			Special Equipment:		
Longitude:	-117 44 59.8		Latitude:	51 10 42.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 28-JAN-22: BP Jan 28-22 Sills don't appear to have been replaced with deck. Monitor their condition and record separately from cribs. IDIR\MIPENNER on 07-FEB-20: JRG Feb 7, 2020 Cedar log cribs built in 1992. Monitor condition.				

Structure Name: TOC0012

Site #:	N4-079	Year Superstructure Installed:	2015	Structure Type/Class:	Temporary Bridge
KM:	27.00	User km:	27.00	Last Inspection Date:	2021/08/03
Project File ID #:	9679	Br.	07	Next Inspection Date:	2023/08/03
Road Name:	KILLEEN				
Crossing Name:	Zeke Cr		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-118 0 59.9		Latitude:	50 33 5.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 9 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Management Area:

Structure Name: N4-039

Site #:	N4-039	Year Superstructure Installed:	1978	Structure Type/Class:	Temporary Bridge
KM:	6.32	User km:	21.80	Last Inspection Date:	2022/07/29
Project File ID #:	9354	Br.	02	Next Inspection Date:	2023/07/29
Road Name:	LIMEKILN				
Crossing Name:	PINGSTON Cr		Total Length (metres):	21.2	
Special Access:			Special Equipment:		
Longitude:	-118 0 1.5		Latitude:	50 29 22.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: To be inspected annually. Crips and pile conditions inspected in May 2011 DA. Bring a drill and sample the crib face with a percentage of rot report in next inspection.				

Structure Name: N4-040

Site #:	N4-040	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	3.71	User km:	3.60	Last Inspection Date:	2020/09/08
Project File ID #:	8263	Br.	01	Next Inspection Date:	2023/09/08
Road Name:	NAGLE MAIN				
Crossing Name:	NAGLE Cr		Total Length (metres):	20.4	
Special Access:			Special Equipment:		
Longitude:	-118 37 28.3		Latitude:	52 3 54.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					

Structure Name: TOC0007

Site #:	N4-073	Year Superstructure Installed:	2021	Structure Type/Class:	Temporary Bridge
KM:	4.60	User km:	37.00	Last Inspection Date:	
Project File ID #:	9617	Br.	02	Next Inspection Date:	2023/08/19
Road Name:	NORMANWOOD BR 37.1				
Crossing Name:	Norman Wood		Total Length (metres):	30.3	
Special Access:			Special Equipment:		
Longitude:	-118 10 54.0		Latitude:	51 38 44.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 10 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Management Area:

Structure Name: N4-071

Site #:	N4-071	Year Superstructure Installed:	1990	Structure Type/Class:	Temporary Bridge
KM:	0.55	User km:	24.50	Last Inspection Date:	2021/08/03
Project File ID #:	9354	Br.	24	Next Inspection Date:	2023/08/03
Road Name:	PAINT LAKE				
Crossing Name:	Sunshine Creek	Total Length (metres):	6.0		
Special Access:		Special Equipment:			
Longitude:	-118 0 26.7	Latitude:	50 28 22.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\BPELLETT on 27-APR-22: BP Apr 27-22 Inspector to thoroughly search for fabricator markings and photograph any found				

Structure Name: WO-4766

Site #:	N4-080	Year Superstructure Installed:	2014	Structure Type/Class:	Permanent Bridge
KM:	1.10	User km:		Last Inspection Date:	2020/09/06
Project File ID #:	9981	Br.	10	Next Inspection Date:	2023/09/06
Road Name:	SHAKETOWN				
Crossing Name:	Begbie Lake Cr	Total Length (metres):	15.2		
Special Access:		Special Equipment:			
Longitude:	-118 10 22.0	Latitude:	50 53 57.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Other	# Spans:	1
Planned Inspection Comments:					

Structure Type/Class Totals

Permanent Bridge Total: 10
Temporary Bridge Total: 15

Major Culvert Total: 4
Woodbox/Log Culvert Total: 0