


WASHOUT CREEK

Sept. 8 1982



Headwaters

← Flow



Headwaters: note darker areas in the valley bottom formerly covered with snow and ice



Bridge Washout

→ Flow



↑ Flow

Location where channel has changed direction.



← New
Channel

← Old
Channel

→ Flow



→ Flow



Looking north Highway 95.

Looking south.

Photo #3 - view of fa



Photo #4 - View of fan area





Looking north Highway 95.

Looking south.



Upstream look at fan.



Debris covered fan.



Russell Schultz's property.



CNR Bridge.